UNITED CLAIMS SERVICE, INC.

26 Japwood Place Garner, NC 27529 (800) 827-8279

Reserve / Status Form

03/14/2023

INSURANCE COMPANY: Auto-Owners COP

INSURED NAME: ANDERSON EYE CARE OF WEST TENNESSEE

INSURED E-MAIL:

LOSS LOCATION: 113 E LOCUST ST, DRESDEN, TN 38225

POLICY #: 0327117019 DATE OF LOSS: 12/10/2021

300-0677709-2021 COMPANY CLAIM #:

UCS FILE NO: S-5161235

TYPE OF LOSS: TORNADO HIT AREA - PORTION OF BUILDING HAS EXCESSIVE DAMAGE, EQUIPMENT WITH WATER

DAMAGE.

ADJUSTER: Michael Knight; insuranceadjustermike@gmail.com; 704-299-5635

CONTACT HISTORY:

DATE ASSIGNED	DATE CONTACTED	APPOINTMENT DATE	DATE INSPECTED
08/04/2022	08/04/2022		

STATUS REPORT:

PLease find the attached notice of Service received on this claim. If you need anything from us on this, please let me know.

Thank You, Tommy Halcom **VP** of Operations United Claims Service 704-918-1400

thalcom@ucsadjusters.com



Division of Business Services Department of State

State of Tennessee 312 Rosa L. Parks AVE, 6th FL Nashville, TN 37243-1102

02/28/2023

KNIGHT, MICHAEL 29 JAP DRIVE GARNER, NC 27529

RE: ANDERSON EYE CARE OF WEST TENNESSEE

VS: MICHAEL KNIGHT (ET. AL)

Notice of Service

The enclosed process, notice or demand is hereby officially served upon you by the Tennessee Secretary of State pursuant to Tennessee law. Please refer to the process, notice or demand for details concerning the legal matter. If you have any questions, please contact the clerk of the court that issued the process, notice or demand.

The process, notice or demand may have a court date and time that you must appear to defend yourself or the number of days from the date of service by which you are required to file an answer. Failure to appear in court at the time specified or failure to file an answer in the given time could result in a default judgement being rendered against you for relief sought in the lawsuit.

The Secretary of State's office cannot give you legal advice. If you need legal advice, please consult a private attorney.

Tre Hargett

Secretary of State

Enclosures: Original Documents

DOCUMENT INFORMATION

SOS Summons #: 13462858

Case #:

92CH1-2023-CV-25551

Certified #:

9489009000276448647926



Weakley County Chancery PO Box 197 116 West Main Street Dresden, TN 38225 (731)364-3454

STATE OF TENNESSEE CIVIL SUMMONS

page 1 of 1

Case Number 92CH1-2023-CV-25551

ANDERSO	ON EYE CARE OF WEST TENNESSEE vs MICHEAL KNIGHT (et. al)
Served On:	
MICHEAL KNIGHT	29 JAP DRIVE
	GARNER, NC 27529
be made within thirty (30) of send a copy to the plaintiff's rendered against you for the Issued: 2/17/2023 Attorney for Plaintiff: D	o defend a civil action filed against you in Weakley County Chancery, Weakley County, Tennessee. Your defense mus ays from the date this summons is served upon you. You are directed to file your defense with the clerk of the court and attorney at the address listed below. If you fail to defend this action by the required date, judgment by default-may be relief sought in the complaint. Clerk / Deputy Clerk - Weakley County Chancer County
	255 LYNNFIELD ROAD STE 226, Memphis, TN 38119
from execution or seizure to listed in TCA §26-2-301. It written list, under oath, of the you thereafter as necessary; issued prior to the filing of wearing apparel (clothing) in Bible, and school books. Sl	NOTICE OF PERSONAL PROPERTY EXEMPTION Tennessee law provides a ten thousand dollar (\$10,000) personal property exemption as well as a homestead exemption satisfy a judgment. The amount of the homestead exemption depends upon your age and the other factors which are a judgment should be entered against you in this action and you wish to claim property as exempt, you must file a neiterns you wish to claim as exempt with the clerk of the court. The list may be filed at any time and may be changed however, unless it is filed before the judgment becomes final, it will not be effective as to any execution or garnishment he list. Certain items are automatically exempt by law and do not need to be listed; these include items of necessary for your self and your family and trunks or other receptacles necessary to contain such apparel, family portraits, the familicular any of these items be seized you would have the right to recover them. If you do not understand your exemption ou may wish to seek the counsel of a lawyer. Please state file number on list.
Mail list to Regina Vano	Cleave, Weakley County Chancery Clerk, Weakley County
issued in this case. Date: 2/17/202	CERTIFICATION (IF APPLICABLE) ley County Chancery Clerk of Weakley County do certify this to be a true and correct copy of the criginal summons Clerk / Deputy Clerk – Weakley County Chancery
OFFICER'S RETURN: F	lease execute this summons and make your return within ninety (90) days of issuance as provided by law.
Leartify that I have served t	nis summons together with the complaint as follows:
Date:	By: Please Print: Officer, Title
Agency Address	Signature 20.7
prepaid, by registered ret in the above styled case, which had been signed by summons to be filed by t	OF SUMMONS BY MAIL: I hereby certify and return that on
	Notary Public / Deputy Clerk (Comm. Expires)
A	
Signature of Plaintiff	Plaintiff's Attorney (or Person Authorized to Serve Process) (Attach return receipt on back)

IN THE CHANCERY COURT OF WEAKLEY COUNTY, TENNESSEE FOR THE TWENTY-SEVENTH JUDICIAL DISTRICT AT DRESDEN

ANDERSON EYE CARE OF WEST TENNESSEE,


Plaintiffs,

CASE NO. 2555

V

AUTO OWNERS INSURANCE COMPANY, and MICHAEL KNIGHT

Defendants,



COMPLAINT TO COMPEL APPRAISAL AND FOR BREACH OF CONTRACT

Comes now, Plaintiff, by and through counsel, and requests this Honorable Court to select an umpire and order the carrier to comply with the appraisal provision and identify a competent appraiser to participate as mandated in the policy appraisal provision; and would show this Honorable Court the following:

- Anderson Eye Care of West Tennessee ("Plaintiff"), is a Tennessee corporation
 with a principal place of business located at 113 East Locust St. Dresden, Tennessee
 38225-1440 Weakley County, Tennessee and owns the insured property located 113 East
 Locust St. Dresden, Tennessee 38225-1440.
- 2. Auto Owners ("Defendant") NAIC Code 18988, is a foreign corporation domiciled in the State of Michigan, with its principal place of business located at 6101 Anacapri Boulevard. Lansing, Michigan 48917, and can be served through the Commissioner of Insurance at 500 James Robertson Parkway, Nashville, Tennessee 37243 pursuant to Tenn. Code Ann. § 56-2-504. Defendant is responsible for the actions of United Claims Service adjuster Mike Knight via operation of the doctrines of respondent superior, actual or apparent agency, employer-employee or master –servant.

- 3. Mike Knight is believed to be an adult resident citizen of Tennessee whose business address is 29 Jap Drive Garner North Carolina 27529, and Mr. Knight may be served with process by any means authorized by Rule of the Tennessee Rules of Civil Procedure.
- 4. Defendants issued Policy No. 184619-03271170-21 to Plaintiffs providing coverage for tornado damage that occurred at the insured location of 113 East Locust Street Dresden, Tennessee 38225-1440, that was in effect on the date of loss of December 10, 2021 that was assigned Claim No. 300-0677709-2021, The policy attached herewith as Exhibit "1".
- 5. Defendants have submitted multiple repair estimates and all have been wholly insufficient; and Defendants and Plaintiff's estimates of costs for the tornado loss are materially different. See collective Exhibits "6", "7", "8", and "9".
- 6. Despite Mr. Knight inspecting the loss multiple times and being provided detailed estimates, photographs, and invoices for costs incurred by the Plaintiff, particularly an invoice from Puro Clean (Exhibit "9"), he still refuses to acknowledge or pay the estimate submitted by Plaintiffs Public Adjuster, or the invoice, but instead substitutes his own estimations knowing they are insufficient and false and that policy benefits which violate Plaintiffs rights under the policy are being delayed and/or denied due to his actions Mr. Knight's actions have cause a lien to be placed on the Plaintiffs property. See Exhibit "9".
- 7. Plaintiff timely demanded an appraisal on August 8, 2022, in writing and named therein competent and impartial appraiser. See Exhibit "2".

1 For purposes of judicial economy, the Declarations Page and Appraisal provision of the policy are attached as Exhibits "1; 2", to preclude the necessity for the Judge to "rifle through" a voluminous policy to locate the limited provisions relevant to this proceeding.

- 8. Defendant's desk adjuster, Randall Wenzel, responded by letter dated August 24, 2022, refusing to participate in the mandatory appraisal by stating that, "We have reviewed the file and are working on a revision to our estimate. We will be in contact soon with that revision. If there is a dispute in the value of the covered repairs, please advise the specific dispute(s).", and "Without satisfactory proof of loss we are unable to agree or disagree at this time and appraisal is premature.". Defendants ended the letter with, "In the event we disagree as to the value of the covered repairs, we will proceed with the appraisal process. We name Andrew McWilliams as our appraiser", but has refused to provide any contact information for Mr. McWilliams to date. Wenzel knows that there is no provision or term in the policy that has these prerequisites prior to appraisal. See Exhibit "4".
- 9. All conditions precedents for Defendants to identify a competent and impartial appraiser and choose a competent and impartial umpire have occurred, yet Defendant refuse to comply and the process cannot proceed as mandated by the policy. A copy of the Demand is attached herewith as Exhibit "2".

COUNT I COMPEL APPRAISAL AND APPOINT UMPIRE

10. The policy appraisal provision provides as follows:

E. LOSS CONDITIONS

2. Appraisal

If we and you disagree on the value of the property or the amount of loss, either may make written demand for an appraisal of the loss. In this event, each party

will select a competent and impartial appraiser. The two appraisers will select an umpire. If they cannot agree, either may request that selection be made by a judge of a court having jurisdiction. The appraisers will state separately the value of the property and amount of loss. If they fail to agree, they will their differences to the umpire. A decision agreed to by any two will be binding. Each party will: a. Pay its chosen appraiser; and b. Bear the other expenses of the appraisal and umpire equally.

If there is an appraisal, we will still retain our right to deny the claim. See Exhibit "3"

11. Participation is mandatory, and both parties are entitled to an expeditious appraisal, pursuant to the policy language, with two competent appraisers and an impartial umpire, as these three are essential to an effective and fair process as was intended by the Defendants who wrote it into the policy.

COUNT II. UMPIRE QUALIFICATIONS

- 12. Although the policy provision does not outline the criteria to be used in the umpire selection process "Generally accepted insurance principles dictate only that 'an umpire selected to arbitrate a loss should be disinterested, unprejudiced, honest, and competent." *Brothers v. Generali Us. Branch*, No. CIV.A. 1:97-CV-798-MHS, 1997 WL 578681, at *3 (N.D. Ga. July 11, 1997) (quoting 6 Appleman, Insurance Law and Practice § 3928, at 554 (1972». The umpire "should be impartial, honest, and competent ..." Corpus Juris Secundum, Insurance § 1897 (2011) See, e.g., 6 Appleman, Insurance Law and Practice § 3928, at 554 (1972); Corpus Juris Secundum, Insurance § 1897 (2011).
- 13. Petitioner respectfully proposes the well-qualified individuals below who have no business or personal relationships with either party, and meet the criteria described herein.
 - a) Ben Perry TN / Dir. Of Appraisals CV attached

- b) Scott Heidelberg TN Certified PLAN Ump/Appr- CV attached
- c) Andy Fraraccio Intrust Claims CV attached
- d) Zach Baker TN The David Group Certified Umpire CV attached
- e) Mary Jo O'Neal TN/Ind. Adj./- Certified Umpire-CV attached.
- f) Chris Williamson TN Restoration GC CV attached.
- g) David Hilsdon Lic. Engineer, P.E. TN CV attached.
- 14. This Honorable Court is authorized by the mutual consent of the parties', and as outlined in the policy appraisal provision, to choose a competent and impartial umpire and/or a competent impartial appraiser, if necessary, upon the request of either party.

COUNT III BREACH OF CONTRACT

- 15. The Plaintiff incorporates the foregoing allegations as if fully set forth herein.
- 16. Defendants materially breached the insurance contract by refusing to participate in the mandatory appraisal process properly demanded by Plaintiff.

COUNT IV PUNITIVE DAMAGES

- 17. The Plaintiff incorporates the foregoing allegations as if fully set forth herein.
- 18. Defendants conduct was reckless in light of the foregoing allegations and entitles Plaintiff to an award of punitive damages.

COUNT V FRAUDULENT INSURANCE ACT

- 19. The Plaintiff incorporates the foregoing allegations as if fully set forth herein.
- 20. Defendants staff adjuster, Randall Wenzel, made false statements and material misrepresentations of facts and policy coverage terms to the insured and Plaintiffs insurance professional / practitioner, in his August 24, 2022 letter, by stating that, "We have reviewed the file and are working on a revision to our estimate. We will be in contact soon with that revision. If there is a dispute in the value of the covered repairs,

please advise the specific dispute(s).", and "Without satisfactory proof of loss we are unable to agree or disagree at this time and appraisal is premature." Wenzel knew at all times that there was no requirement the insured or insurance professional/ practitioner provide a Proof of Loss, eight months past the date of loss, before agreeing to appraisal; nor was such a prerequisite to Defendants mandatory participation in the appraisal process after Plaintiffs proper demand on August 8, 2022. Wenzel's actions constitute violations of the Fraudulent Insurance Act found at §56-53-103(a)(1) and has wrongfully delayed or denied the payment of insurance benefits to Plaintiff. A copy of this letter is incorporated herein by reference as Exhibit "4".

ø

19. On December 28, 2021 and August 4, 2022, Michael Knight, who on information and belief is a resident of the State of Tennessee, and whose business address is 29 Jap Drive Garner North Carolina 27529, while in the Course and scope of his employment with Defendants, presented false information to an insured and an insurance professional related to an insurance claim payment by presenting information and representations the falsity of which he recklessly disregarded knowing that charges to the Plaintiff by PuroClean was a covered cost under extra expense and related coverages, and as shown in his first and second damage repair estimates (Exhibits "6" and "7"), which he submitted for payment knowing that both were inaccurate and failed to substantial charges that Plaintiffs had relied upon the policy benefits to cover, and did so while he had the photos and receipt proving these charges were incurred by the Plaintiff in his possession. Mr. Knight's actions constitute violations of the Fraudulent Insurance Act found at §56-53-103(a)(1) and have wrongfully delayed and denied the payment of

benefits to Plaintiff. A copy of his estimates and the PuroClean invoice are incorporated herein by reference as Exhibits "6", "7", and "9".

20. The actions of Auto Owners, Wenzel, and Knight are part of a pattern or practice of violating the Fraudulent Insurance Act that entitles Plaintiffs to treble damages.

WHEREFORE, ALL PREMISES CONSIDERED, PLAINTIFF requests the court enter an order to compel appraisal, appoint a competent and impartial umpire, award prejudgment interest, post-judgment interest, compensatory damages, attorney fees, treble damages, and other damages and expenses as authorized by Tenn. Code Ann. §56-53-107 of no less than THREE MILLION DOLLARS AND punitive damages of no less than TEN MILLION DOLLARS.

Respectfully submitted,

Drayton Berkley, # 02261

Counsel for Plaintiffs
The Berkley Law Firm, PLLC
1255 Lynnfield Road Ste 226

Memphis, TN 38119,
Phone. 901-322-8706
attorneyberkley@gmail.com

CERTIFICATE OF SERVICE

I do hereby certify that the foregoing document has been served upon the counsel of record or parties pro se in this cause, and as follows:

Department of Commerce and Insurance Attn: Service of Process 500 James Robertson Pkwy Nashville, TN 37243 P: 615.532,5260

E: Service.Process@tn.gov

Mr. Michael Knight
United Claims Service, Inc.
26 Japwood Place
Garner, NC 27529
P: (800) 827-8279
F: (800) 786-8884
insuranceadjustermike@gmail.com
Adjuster for Defendants

This, 16th day of February, 2023

Drayton Berkley, # 02261 Counsel for Plaintiffs The Berkley Law Firm, PLLC Owners





09-01-2021 ssued

TAILORED PROTECTION POLICY DECLARATIONS

INSURANCE COMPANY 6101 ANACAPRI BLVD., LANSING, MI 48917-3999

DRESDEN TN 38225-1440

19-0188-00

ADDRESS 113 E LOCUST ST

AGENCY WESTAN INSURANCE - MARTIN MKT TERR 043

731-587-9993

Renewal Effective

10-22-2021

INSURED ANDERSON EYE CARE OF WEST TENNESSEE

POLICY NUMBER Company Use

184619-03271170-21

03-46-TN-1810

Company Bill

Policy Term

12:01 a.m.

12:01 a.m.

10-22-2021

10-22-2022

In consideration of payment of the premium shown below, this policy is renewed. Please attach this Declarations and attachments to your policy. If you have any questions, please consult with your agent.

SOME OR ALL OF THE LOCATIONS ON THIS POLICY CONTAIN A SEPARATE DEDUCTIBLE FOR EARTHQUAKE WHICH MAY RESULT IN HIGH OUT-OF-POCKET EXPENSES TO YOU.

55039 (11-87)

COMMON POLICY INFORMATION

Business Description:

Optometrist

Entity:

Corporation

Program: Premier Office

THIS POLICY CONSISTS OF THE FOLLOWING COVERAGE PART(S):	PREMIUM
COMMERCIAL PROPERTY COVERAGE	\$5,843.00
COMMERCIAL GENERAL LIABILITY COVERAGE	\$401.00
MINIMUM PREMIUM ADJUSTMENT (GL)	\$203.00
	TOTAL \$6,447.00
PAID IN FULL DISC	COUNT \$583.00
TOTAL POLICY PREMIUM IF PAID II	N FULL \$5,864.00
THIS PREMIUM MAY BE SUBJECT TO ADJUSTMENT.	
The Paid in Full Discount does not apply to fixed fees, statutory charges or minimum premiums.	

Forms that apply to all coverage part(s) shown above (except garage liability, dealer's blanket, commercial automobile, if applicable): 55003 (07-12) 59392 (11-20) IL0017 (11-85)

A 04% Cumulative Multi-Policy Discount applies. Supporting policies are marked with an (X): Comm Umb(X) Comm Auto() WC() Life() Personal(X) Farm().

Countersigned By:

Owners Ins. Co.

AGENCY WESTAN INSURANCE - MARTIN

INSURED ANDERSON EYE CARE OF WEST TENNESSEE

19-0188-00

MKT TERR 043

Page 2 Company Bill Bill

POLICY NUMBER 184619-03271170-21

03-46-TN-1810

09-01-2021

Term 10-22-2021 to 10-22-2022

Issued

COMMERCIAL PROPERTY COVERAGE

55198 (12-10)

54104 (07-87)

ENHANCED PROPERTY PLUS COVERAGE PACKAGE DECLARATION

The coverages and limits below apply separately to each location or sublocation that sustains a loss to covered property and is designated in the Commercial Property Coverage Declarations. No deductible applies to the below Property Plus Coverages.

COVERAGE	LIMIT
ACCOUNTS RECEIVABLE	\$150,000
BAILEES	\$10,000
	\$5,000 PER ITEM
BUSINESS INCOME & EXTRA EXPENSE W/RENTAL	\$100,000
VALUE, INCLUDING NEWLY ACQUIRED LOC'S	
0 HOUR WAITING PERIOD	
DEBRIS REMOVAL	\$50,000
ELECTRONIC DATA PROCESSING EQUIPMENT	\$50,000
EMPLOYEE DISHONESTY	\$25,000
FINE ARTS, COLLECTIBLES AND MEMORABILIA	\$25,000
	\$5,000 PER ITEM
FIRE DEPARTMENT SERVICE CHARGE	\$10,000
FORGERY AND ALTERATION	\$25,000
MONEY AND SECURITIES INSIDE PREMISES	\$25,000
MONEY AND SECURITIES OUTSIDE PREMISES	\$25,000
NEWLY ACQUIRED BUSINESS PERSONAL PROPERTY	\$500,000 FOR 90 DAYS
NEWLY ACQUIRED OR CONSTRUCTED PROPERTY	\$1,000,000 FOR 90 DAYS
ORDINANCE OR LAW	SEE COMMERCIAL PROPERTY
	DECLARATIONS
OUTDOOR PROPERTY	\$20,000
TREES, SHRUBS OR PLANTS	\$1,000 PER ITEM
RADIO OR TELEVISION ANTENNAS	\$15,000
PERSONAL EFFECTS AND PROPERTY OF OTHERS	\$25,000
POLLUTANT CLEAN UP AND REMOVAL	\$50,000
PROPERTY IN TRANSIT	\$50,000
PROPERTY OFF PREMISES	\$50,000
REFRIGERATED PRODUCTS	\$15,000
SALESPERSON'S SAMPLES	\$15,000
	III

Owners Ins. Co.

AGENCY WESTAN INSURANCE - MARTIN

INSURED ANDERSON EYE CARE OF WEST TENNESSEE

19-0188-00

MKT TERR 043

Company Bill

POLICY NUMBER 184619-03271170-21

Issued

03-46-TN-1810

09-01-2021

Term 10-22-2021 to 10-22-2022

55198 (12-10)

		ENF	IANCED PRO	PERTY PLU	S COVERAG	PACKAGI	DECLARAT	ION		
		со	VERAGE					L	IMIT	
UTILITY SERVICES FAILURE								\$100,000		
VALUABLE PAPERS AND RECORDS ON PREMISES									\$100,000	
VALUA	VALUABLE PAPERS AND RECORDS OFF PREMISES						5 8 - 9 - 8 - 8			\$20,000
WATER BACK-UP FROM SEWERS OR DRAINS								\$25,000		
Forms th	nat apply to this	s coverage p	art:							
64004	(12-10)	54198	(12-10)	54334	(12-10)	64020	(12-10)	54189	(12-10)	
54186	(12-10)	54218	(03-13)	54217	(03-13)	54216	(03-13)	54214	(03-13)	
54221	(12-10)	54220	(06-00)	54219	(12-10)	54338	(03-13)	54339	(03-13)	
64010	(12-10)	64000	(12-10)							

Coverages Provided

Insurance at the described premises applies only for coverages for which a limit of insurance is shown.

LOCATION 0001 - BUILDING 0001

Location: 113 E Locust St, Dresden, TN 38225-1440

Secured Interested Parties: None

Rating Information

Territory: 920 Program: Premier Office Protection Class: 04

County: Weakley Construction: Frame Class Code: 0702

Class Rate - Building: 0.382

Class Rate - Pers Prop: 0.374

COVERAGE	COINSURANCE	DEDUCTIBLE	LIMIT	RATE	PREMIUM
BUILDING Causes of Loss			\$331,500		
Basic Group I	80%	\$250		0.232	\$769.00
Basic Group II	80%	\$250		0.304	\$1,008.00
Wind/Hail	80%	\$1,000			
Special	80%	\$250		0.064	\$212.00
Theft	80%	\$250			Included
Earthquake	80%	10%		0.585	\$1,939.00
OPTIONAL COVERAGE					
Inflation Guard Factor Building 1.015					
Replacement Cost				-	
Equipment Breakdown		\$250	See Form 54843		\$114.00
Property Plus Coverage Package		None	See 55198 (12-10)		\$445.00
Tier: Enhanced					

Owners Ins. Co.

AGENCY WESTAN INSURANCE - MARTIN

19-0188-00

MKT TERR 043

Company POLICY NUMBER 184619-03271170-21

Issued

Bill

03-46-TN-1810

09-01-2021

Term 10-22-2021 to 10-22-2022

INSURED	ANDERSON	EYE CARE	OF WEST	TENNESSEE
---------	----------	----------	---------	------------------

COVERAGE	COINSURANCE	DEDUCTIBLE	LIMIT	RATE	PREMIUM
ORDINANCE OR LAW Coverage A-Undamaged Portion		\$250	Incl in Bldg Limit		Included
Coverage B-Demolition		\$250	\$110,000		Included
Coverage C-Increased Cost		\$250	\$110,000	955	Included
PERSONAL PROPERTY Causes of Loss			\$307,690		
Basic Group I	80%	\$250		0.147	\$452.00
Basic Group II	80%	\$250		0.048	\$148.00
Wind/Hail	80%	\$1,000			
Special	80%	\$250		0.060	\$185.00
Theft	80%	\$250			Included
Earthquake	80%	10%		0.131	\$403.00
OPTIONAL COVERAGE					
Replacement Cost					
Inflation Guard Factor Personal Property 1.010					
Equipment Breakdown		\$250	See Form 54843		\$34.00
Property Plus Coverage Package		None	See 55198 (12-10)		\$134.00
Tier: Enhanced					
ORDINANCE OR LAW Coverage D-Tenant's I&B		\$250	\$110,000		Included

59351	(01-15)	54835	(07 - 08)	IL0250	(02 - 89)	IL0003	(07 - 02)	64224	(01-16)
64326	(07-19)	59325	(12-19)	CP0090	(07 - 88)	64000	(12-10)	64013	(12-10)
64010	(12-10)	CP1040	(10-91)	64020	(12-10)	64004	(12-10)	54843	(07-19)
59392	(11-20)								18000

COMMERCIAL PROPERTY COVERAGE - LOCATION 0001 SUMMARY	PREMIUM
TERRORISM - CERTIFIED ACTS SEE FORM: 59351	EXCLUDED
TERRORISM COVERAGE	A STATE OF THE PROPERTY OF THE PARTY OF THE
A PREMIUM CHARGE MAY BE MADE EFFECTIVE 01-01-28 SEE FORMS 54835, 59392	
LOCATION 0001	\$5,843.00

55040 (11-87)

COMMERCIAL GENERAL LIABILITY COVERAGE

COVERAGE	LIMITS OF INSURANCE
General Aggregate	\$2,000,000
(Other Than Products-Completed Operations)	
Products-Completed Operations Aggregate	\$2,000,000
Personal And Advertising Injury	\$1,000,000

17 ppraise



August 8, 2022

Auto Owners Insurance ATN. Randall Wenz P. 844.296.4053 ext. 59495 E. Wezel.randall@aoins.com E. AOCAT.clm@aoins.com

Re: Demand For Appraisal

From:: Named Insured:

Dr, Gwin Anderson 113 East Locust St

Claim Number:

Dresden, TN 38225

Address:

300-0677709-2021

//// TRANSMITTAL VIA EMAIL ////

Mr. Wenz,

In accordance with the Appraisal provision in my policy, and as noted below, there is a dispute regarding the Amount of Loss and value of the property, and within the policy specific language of appraisal as follows:

If we and you disagree on the value of the property or the amount of loss, either may make written demand for an appraisal of the loss. In this event, each party will select a competent and impartial appraiser. The two appraisers will select an umpire. If they cannot agree, either may request that selection be made by a judge of a court having jurisdiction. The appraisers will state separately the value of the property and amount of loss. If they fail to agree, they will submit their differences to the umpire. A decision agreed to by any two will be binding.

Each party will:

- a. Pay its chosen appraiser; and
- b. Bear the other expenses of the appraisal and umpire equally.

If there is an appraisal, we will still retain our right to deny the claim.

I now formally demand Appraisal of the Amount of Loss included in all Coverages and resulting from the tornado occurrence - and designate the following appraiser:

Mary Jo O'Neal 615.849.6400 Maryjo6400@aol.com

Accordingly, please designate your Appraiser within the time frame as described within the Appraisal and have him/her contact Ms. O'Neal to proceed with the panel assembly.

Sincerely,

Dr. Gwin Anderson

Enclosures: Appraisal Demand

CC: Dr. Gwin Anderson M. O'Neal W. Griffin

Agency Code 19-0188-00	X
Total amount of loss payable: \$59,850 + \$80,000 = \$139,850	المندم
EXAMPLE #2 The Deductible and Limits of Insurance are the those in Example #1.	By Drain
Loss to Building #1:	\$70,000
(Exceeds Limit of Insurance plus Deductible) Loss to Building #2: (Exceeds Limit of Insurance plus Deductible)	\$90,000
Loss Payable – Building #1:	\$60,000
(Limit of Insurance) Loss Payable - Building #2: (Limit of Insurance)	\$80,000
Total amount of loss payable:	\$140,000

E. LOSS CONDITIONS

The following conditions apply in addition to the Common Policy Conditions and the Commercial Property Conditions.

1. Abandonment

There can be no abandonment of any property

2. Appraisal

If we and you disagree on the value of the property or the amount of loss, either may make written demand for an appraisal of the loss. In this event, each party will select a competent and impartial appraiser. The two appraisers will select an umpire. If they cannot agree, either may request that selection be made by a judge of a court having jurisdiction. The appraisers will state separately the value of the property and amount of loss. If they fail to agree, they will submit their differences to the umpire. A decision agreed to by any two will be binding. Each party will:

- a. Pay its chosen appraiser; and
- b. Bear the other expenses of the appraisal and umpire equally.

If there is an appraisal, we will still retain our right to deny the claim.

3. Duties In The Event Of Loss Or Damage

- a. You must see that the following are done in the event of loss or damage to Covered Property:
 - (1) Notify the police if a law may have been broken.
 - (2) Give us prompt notice of the loss or damage. Include a description of the property involved.
 - (3) As soon as possible, give us a description of how, when and where the loss or damage occurred.

- (4) Take all reasonable steps to protect the Covered Property from further damage, and keep a record of your expenses necessary to protect the Covered Property, for consideration in the settlement of the claim. This will not increase the Limit of Insurance. However, we will not pay for any subsequent loss or damage resulting from a cause of loss that is not a Covered Cause of Loss. Also, if feasible, set the damaged property aside and in the best possible order for exam-
- (5) At our request, give us complete inventories of the damaged and undamaged property. Include quantities, costs, values and amount of loss claimed.
- (6) As often as may be reasonably required, permit us to inspect the property proving the loss or damage and examine your books and records. Also permit us to take samples of damaged and undamaged property for inspection, testing and analysis, and permit us to make copies from your books and records.
- (7) Send us a signed, sworn proof of loss containing the information we request to investigate the claim. You must do this within 60 days after our request. We will supply you with the necessary
- (8) Cooperate with us in the investigation or settlement of the claim.
- b. We may examine any insured under oath, while not in the presence of any other insured and at such times as may be reasonably required, about any matter relating to this insurance or the claim, including an insured's books and records. In the event of an examination, an insured's answers must be signed.

4. Loss Payment

- a. In the event of loss or damage covered by this Coverage Form, at our option, we will either:
 - (1) Pay the value of lost or damaged property;
 - (2) Pay the cost of repairing or replacing the lost or damaged property, subject to b.
 - (3) Take all or any part of the property at an agreed or appraised value; or

Ex. .4



LIFE . HOME . CAR . BUSINESS

August 24, 2022

Anderson Eye Care of West Tennessee 113 E Locust St Dresden, TN 38225-1440

RE: Claim #: 300-0677709-2021

Policy # 03271170


Insured: Anderson Eye Care of West Tennessee

Loss Location: 113 E Locust St, Dresden, TN 38225-1440

Date of Loss: 12/10/2021

Dear Anderson Eye Care of West Tennessee,

This letter is in reference to a claim that Owners Insurance Company received for wind/tornado damage that occurred on December 10, 2021. At the time of loss, you were insured under policy # 03271170 with effective dates of 10/22/2021 to 10/22/2022.



This correspondence also confirms receipt of your demand for appraisal. Within the email received on August 8, 2022, it stated that you wish to invoke the Appraisal provision of the policy and that you have appointed Mary Jo O'neal as your appraiser. A sworn proof of loss statement was sent to the insureds on 12/13/2021. To date, we have not received a completed proof of loss. Without satisfactory proof of loss we are unable to agree or disagree at this time and appraisal is premature. Please refer to the policy language below:

Tailored Protection Policy

(12-10)

E. LOSS CONDITIONS

The following conditions apply in addition to the Common Policy Conditions and the Commercial Property Conditions.


2. Appraisal

If we and you disagree on the value of the property or the amount of loss, either may make written demand for an appraisal of the loss. In this event, each party will select a competent and impartial appraiser. The two appraisers will select an umpire. If they cannot agree, either may request that selection be made by a judge of a court having jurisdiction. The appraisers will state separately the value of the property and amount of loss. If they fail to agree, they will submit their differences to the umpire. A decision agreed to by any two will be binding. Each party will:

a. Pay its chosen appraiser; and

Catastrophe Claims Branch

6190 South Campus Blvd. | Lansing, MI 48917-9236 p. 844.296.4053 ext: 52296 | f. 517.886.8751 | auto-owners.com AOCAT.clm@aoins.com



b. Bear the other expenses of the appraisal and umpire equally.

If there is an appraisal, we will still retain our right to deny the claim.

3. Duties In The Event Of Loss Or Damage

- a. You must see that the following are done in the event of loss or damage to Covered Property:
 - (5) At our request, give us complete inventories of the damaged and undamaged property. Include quantities, costs, values and amount of loss claimed.
 - (6) As often as may be reasonably required, permit us to inspect the property proving the loss or damage and examine your books and records. Also permit us to take samples of damaged and undamaged property for inspection, testing and analysis, and permit us to make copies from your books and records.
 - (7) Send us a signed, sworn proof of loss containing the information we request to investigate the claim. You must do this within 60 days after our request. We will supply you with the necessary forms.
 - (8) Cooperate with us in the investigation or settlement of the claim.

The 60 day policy deadline to submit these items has now passed; however, Auto-Owners Insurance Company will extend the deadline an additional 30 days. It is therefore necessary for you to submit this documentation

- by September 26, 2022. Your failure to comply with the policy and your obligations within the policy could adversely affect coverage for the loss. Enclosed you will find Proof of Loss.
 - Upon receipt of your claim presentation, we will review the documents and the Proof of Loss submitted. In the event we disagree as to the value of the covered repairs, we will proceed with the appraisal process. We name Andrew McWilliams as our appraiser. We will not, however, agree to appraise any coverage disputes.

This correspondence is not intended to be an exhaustive statement of Owners' position concerning its coverages under the policy. All rights, terms, conditions, and exclusions in your policy are in full force and effect and are completely reserved. No action by any employee, agent, attorney or other person on behalf of Owners Insurance Company; or hired by Owners Insurance Company on your behalf; shall waive or be construed as having waived any right, term, condition, exclusion or any other provision of the policy.

Sincerely,

Randall Wenzel

Branch Claim Representative Auto-Owners Insurance Company

(844) 296-4053 Ext: 59495

CC:

Enclosures:

Proof of Loss



SWORN STATEMENT IN PROOF OF LOSS

1			CLAIM NO	300-0677709-2021
a annihamity in a minibiation	greed that the furnishing of it, does not waive any r	idius of the Company fin	y assistance by any repr	esentative of the
The policy names 9	rderson Eyo Car	efliket Terressee	; as the incured	and is/was effective fron
12:01 a.m. 10/22/21 to	12:01 a.m. <u>10/22/22</u> F	Policy number under which	th you have filed a claim	is <u>03271170-21</u>
Time and Origin: caused by	A Storm Orner los Tornado	s occurred on the lord	lay of <u>Decoule</u> , 20	<u>2 (</u> , at <u>∸</u> □AM □PM
2. Occupancy: The following:	building described or con	taining the property insur	red was occupied for no	other purpose than the
disconding OAM IC	At the time of the loss the rship and no other perso	ne interest of the Insured n or persons had any inte	in the property describe erest therein, lien or enco	d was sole and ombrance thereon,
 Changes: The following policy was written. 	owing changes have occi If none, please say so	urred in the title, use, occ	cupancy or possession o	f the property since the
5. Other Insurance:	List any and all insurance	policies or binders that	Voluor anvone else has t	that may cover any of
the property for whi	ch a claim is included, or	al or written	16	macmay cover any or
6. Damages: Please	itemize the damage or lo	ss within each of these c	ategories:	
Coverage involved	Replacement Cost of Damage	Actual Cash Value of Damage	Total Insurance Under this Policy	Amount Claimed Under this Policy
Building	564,202.50	496,498.20	331, 500.00 / plus	\$524,202.50
Personal Proporty	133,179.97	121,021.12	307,680.00	133,179.97
BI.	149,064.64	~	12 months	149,064.04
EE	205,968.00		12 months	205,968.00
Property Plear PKS.	Panding	Pondi,	Pinden	Panding
TOTALS		\$972,551.36	Policy Limbs pardy	1,052,414.51
	port my claim through the any such submissions are d upon replacement cost, are payable.			
I have not intentionally colors or damage did not of about the loss or tried to be necessary to support	deceive the Company as	illul act or failure to act. S to the extent of the loss	I have not in any manne	r concealed any fact
Subscribed and sworn to	before me this	day of Febr	uary , 2023.	
State of Jennesses	County of he	Notary P	Phylla Ex	P605/11/16/2024
Insured Lawn 4	aun Haderson	7		
maureu	_	TWILL TWILL THE TWILL THE THE		
. (1	PLEASE REFER TO FR	NO LAMETEAGE ON BA	CK BEFORE SIGNING)	
18403 (2-17)	1918182	OF TENNESSEE		

I too reserve(s) all right(s) I may have under law and the incurance point Trum third Proof of Loss does not comply with the policy conditions, you shall inform us within 15 days from the date of the Proof of coss or any definitive will be considered waived. I reserve the right to an appraisal as demanded and to supplement as needed or if other information becomes available or make corrections.

12/14/21

UCS

United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

Anderson Eyecare of West Tennessee Insured:

113 E Locust St Property:

Dresden, TN 38225-1440

61,909.25

(731) 588-3638

E-mail: gena.stallings@yahoo.com

(800) 827-8279

Claim Rep.: Michael Knight

United Claims Services Company:

Business: 26 Japwood Place

Garner, NC 27521

Estimator: Michael Knight

Company: United Claims Services

Business: 26 Japwood Place

Garner, NC 27521

Reference: United Claims Service

Company: Auto Owners **Business:**

P.O. Box 30660 Lansing, MI 48909

Business:

E-mail:

Business: (800) 827-8279

insuranceadjustermike@gmail E-mail:

insuranceadjustermike@gmail.com

.com

(844) 296-4053 x 52296 Business:

E-mail: AOCat@aoins.com

Type of Loss: Tornado Claim Number: 300-0677709-2021 **Policy Number: 0327117019**

Date Contacted: 12/12/2021 12:47 PM

Date Received: 12/12/2021 12:47 PM Date of Loss: 12/10/2021 12:47 PM Date Entered: 12/16/2021 11:45 AM 12/14/2021 12:47 PM Date Inspected:

Price List: TNJA8X JUN21

Restoration/Service/Remodel

161235_ANDERSONEYE Estimate:

NOTICE: This is a repair estimate only and not an offer of settlement. All estimate figures may be subject to company review and approval. Authorization to repair and/or guarantee of payment must come from the insurance company. Please note this estimate reflects the extent of known covered damages to your property. No supplements or additional payment will be issued for any repair of damage not listed in this scope without prior approval. This approval must be obtained prior to your replacement or repair of any additional damages.

Summary on last page



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

161235_ANDERSONEYE Loc 001 Bldg 001 113 E Locust St Building

Front Elevation

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
1a. Siding - cedar shingle	155.00 SF	0.54	0.00	83.70	(0.00)	83.70
1b. Siding - cedar shingle	155.00 SF	6.47	53.80	1,056.65	(158.50)	898.15
2. Seal & paint wood siding	155.00 SF	1.68	6.20	266.60	(88.87)	177.73
3a. Front Windows*	3.00 EA	37.19	0.00	111.57	(0.00)	111.57
3b. Front Windows*	3.00 EA	1,398.66	375.63	4,571.61	(2,285.81)	2,285.80
4a. French door - Exterior - pre-hung unit	2.00 EA	19.06	0.00	38.12	(0.00)	38.12
4b. French door - Exterior - pre-hung unit	2.00 EA	719.47	127.01	1,565.95	(234.89)	1,331.06
5a. Gutter / downspout - aluminum - up to 5"	72.00 LF	0.45	0.00	32.40	(0.00)	32.40
5b. Gutter / downspout - aluminum - up to 5"	72.00 LF	6.90	28.01	524.81	(314.89)	209.92
6a. Gutter guard/screen	72.00 LF	0.33	0.00	23.76	(0.00)	23.76
6b. Gutter guard/screen	72.00 LF	2.86	8.14	214.06	(160.55)	53.51
7. Stud wall - 2" x 4" x 8' - 16" oc	24.00 LF	17.32	40.53	456.21	(45.62)	410.59
8. Carpenter - General Framer - per hour	48.00 HR	57.50	0.00	2,760.00	(0.00)	2,760.00
Allowance to remove the damaged front elevation w make ready for stucco application.	all framing and stuce	o exterior that was	heavily dama	ged in the ever	nt and re-frame t	he wall and
9. Sheathing - plywood - 1/2" - treated	264.00 SF	2.96	76.19	857.63	(85.76)	771.87
10. Synthetic stucco on 1" polystyrene board	264.00 SF	8.30	76.19	2,267.39	(340.11)	1,927.28
11. Seal & paint stucco	264.00 SF	1.34	7.21	360.97	(360.97)	0.00
12. Fascia Board Material*	12.00 LF	0.55	0.64	7.24	(0.72)	6.52
Totals: Front Elevation			799.55	15,198.67	4,076.69	11,121.98

Right Elevation

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
13a. Gutter / downspout - aluminum - up to 5"	50.00 LF	0.45	0.00	22.50	(0.00)	22.50
13b. Gutter / downspout - aluminum - up to 5"	50.00 LF	6.90	19.45	364.45	(218.67)	145.78
14a. Gutter guard/screen	50.00 LF	0.33	0.00	16.50	(0.00)	16.50
14b. Gutter guard/screen	50.00 LF	2.86	5.66	148.66	(111.50)	37.16
15. Stucco / Ext. Plaster Repair - Min. Charge - Lab. and Mat.	1.00 EA	216.04	1.70	217.74	(0.00)	217.74
16. Seal & paint stucco	400.00 SF	1.34	10.92	546.92	(546.92)	0.00
Totals: Right Elevation			37.73	1,316.77	877.09	439.68



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

Rear Elevation

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
17. Clean with pressure/chemical spray - Very heavy	780.00 SF	0.72	1.52	563.12	(0.00)	563.12
Totals: Rear Elevation			1.52	563.12	0.00	563.12

Left Elevation

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
18a. Wood window - casement, 24-32 sf	1.00 EA	37.19	0.00	37.19	(0.00)	37.19
18b. Wood window - casement, 24-32 sf	1.00 EA	1,019.04	89.05	1,108.09	(554.05)	554.04
19a. Wood window - casement, 12-23 sf	1.00 EA	30.12	0.00	30.12	(0.00)	30.12
19b. Wood window - casement, 12-23 sf	1.00 EA	615.80	50.67	666.47	(333.24)	333.23
20a. Soffit & fascia - wood - 2' overhang	16.00 LF	1.02	0.00	16.32	(0.00)	16.32
20b. Soffit & fascia - wood - 2' overhang	16.00 LF	13.83	11.65	232.93	(23.30)	209.63
21. Prime & paint exterior soffit - wood	32.00 SF	2.05	1.15	66.75	(66.75)	0.00
Totals: Left Elevation			152.52	2,157.87	977.34	1,180.53

Roof

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
22. Tear off composition shingles (no haul off)	42.15 SQ	33.35	0.00	1,405.70	(0.00)	1,405.70
This action includes all roofing components. Any additional layers that may be discovered and require	removal must be	e verified prior to a	nv considerat	ion for a suppl	ement.	
23. Roofing felt - 15 lb.	42.15 SQ		23.67	824.10	(741.69)	82.41
24. Roof vent - turbine type	2.00 EA		12.73	196.57	(101.10)	95.47
25. Continuous ridge vent - shingle-over style	159.00 LF	6.13	52.09	1,026.76	(440.04)	586.72
26. Flashing - pipe jack	6.00 EA	28.78	7.10	179.78	(92.46)	87.32
27. Roofer - per hour	16.00 HR	65.59	0.00	1,049.44	(0.00)	1,049.44
Allowance to repair the rotten decking (IX6 framing) and	l potential rafter	repairs that were d	lamaged durin	g the event.		
28. 1" x 6" lumber (.5 BF per LF)	280.00 LF	1.58	43.13	485.53	(58.27)	427.26
29. 3 tab - 25 yr comp. shingle roofing - w/out felt	48.67 SQ	151.34	425.23	7,790.95	(5,609.49)	2,181.46
Starter Course and Ridge Cap are included in waste facto	r.					
30. Drip edge	300.00 LF	1.77	27.50	558.50	(287.23)	271.27
Totals: Roof			591.45	13,517.33	7,330.28	6,187.05
Total: Building			1,582.77	32,753.76	13,261.40	19,492.36
Total: Loc 001 Bldg 001 113 E Locust St			1,582.77	32,753.76	13,261.40	19,492.36
1235_ANDERSONEYE				12	/28/2021	Page:




United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

Interior

Interior

DESCRIPTION	QUANTITY U	NIT PRICE	TAX	RCV	DEPREC.	ACV
31. Content Manipulation charge - per hour	96.00 HR	33.48	0.00	3,214.08	(0.00)	3,214.08
Allowance for six (6) workers working eight (8) hours for and then move back in the items.	or a day to move ite	ms out for carpet	to be replace	d, ceilings re-p	painted and repai	rs made
32. Job-site moving/storage container - 20' long - per month	3.00 MO	185.00	54.11	609.11	(0.00)	609.11
Allowance for three (3) containers to store the contents	while repairs are bei	ng made	·-··			
Total: Interior		-	54.11	3,823.19	0.00	3,823.19



Exam Room

355.44 SF Walls
488.44 SF Walls & Ceiling

14.78 SY Flooring 47.00 LF Ceil. Perimeter Height: 8'

133.00 SF Ceiling 133.00 SF Floor

43.92 LF Floor Perimeter

Door 3' 1" X 6' 8" Opens into HALLWAY

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
33a. Carpet	133.00 SF	0.24	0.00	31.92	(0.00)	31.92
33b. Carpet	133.00 SF	3.18	34.23	457.17	(228.59)	228.58
34a. Baseboard - 3 1/4" stain grade	43.92 LF	0.41	0.00	18.01	(0.00)	18.01
34b. Baseboard - 3 1/4" stain grade	43.92 LF	3.56	8.39	164.75	(5.49)	159.26
35. Stain & finish baseboard	43.92 LF	1.45	0.81	64.49	(21.50)	42.99
36. Paint the ceiling - two coats	133.00 SF	0.89	2.72	121.09	(40.37)	80.72
37. Mask and prep for paint - plastic, paper, tape (per LF)	47.00 LF	1.31	1.19	62.76	(0.00)	62.76
38a. 1/2" drywall - hung, taped, floated, ready for paint	133.00 SF	0.38	0.00	50.54	(0.00)	50.54
38b. 1/2" drywall - hung, taped, floated, ready for paint	133.00 SF	2.12	7.39	289.35	(28.94)	260.41
39. Batt insulation - 12" - R38 - unfaced batt	133.00 SF	1.56	15.30	222.78	(22.28)	200.50
40. Tear out wet insulation, no bagging	133.00 SF	0.49	0.00	65.17	(0.00)	65.17
41. Light fixture	3.00 EA	43.73	0.00	131.19	(0.00)	131.19
42a. Paneling	188.00 SF	0.27	0.00	50.76	(0.00)	50.76
42b. Paneling	188.00 SF	2.10	12.28	407.08	(40.71)	366.37
Totals: Exam Room			82.31	2,137.06	387.88	1,749.18




United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

Conference Room

Height: 8'



516.67 SF Walls 758.92 SF Walls & Ceiling 26.92 SY Flooring


70.00 LF Ceil. Perimeter

242.25 SF Ceiling 242.25 SF Floor

63.50 LF Floor Perimeter

Door Door 3' X 6' 8" 3' 6" X 6' 8" Opens into HALLWAY
Opens into HALLWAY

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
43a. Carpet	242.25 SF	0.24	0.00	58.14	(0.00)	58.14
43b. Carpet	242.25 SF	3.18	62.36	832.72	(416.36)	416.36
44a. Baseboard - 3 1/4" stain grade	63.50 LF	0.41	0.00	26.04	(0.00)	26.04
44b. Baseboard - 3 1/4" stain grade	63.50 LF	3.56	12.13	238.19	(7.94)	230.25
45. Stain & finish baseboard	63.50 LF	1.45	1.18	93.26	(31.08)	62.18
46. Paint the ceiling - two coats	242.25 SF	0.89	4.96	220.56	(73.52)	147.04
47. Mask and prep for paint - plastic, paper, tape (per LF)	70.00 LF	1.31	1.77	93.47	(0.00)	93.47
48. Batt insulation - 12" - R38 - unfaced batt	242,25 SF	1.56	27.87	405.78	(40.58)	365.20
49. Tear out wet insulation, no bagging	242.25 SF	0.49	0.00	118.70	(0.00)	118.70
Totals: Conference Room	=======================================		110.27	2,086.86	569.48	1,517.38



Exam Room

Height: 8'

349.11 SF Walls 477.36 SF Walls & Ceiling 14.25 SY Flooring

46.00 LF Ceil. Perimeter

128.25 SF Ceiling 128.25 SF Floor

43.17 LF Floor Perimeter

Door

2' 10" X 6' 8"

Opens into HALLWAY

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
50a. Carpet	128.25 SF	0.24	0.00	30.78	(0.00)	30.78
50b. Carpet	128.25 SF	3.18	33.01	440.85	(220.43)	220.42
51a. Baseboard - 3 1/4" stain grade	43.17 LF	0.41	0.00	17.70	(0.00)	17.70
51b. Baseboard - 3 1/4" stain grade	43.17 LF	3.56	8.25	161.94	(5.39)	156.55
52. Stain & finish baseboard	43.17 LF	1.45	0.80	63.40	(21.14)	42.26
53. Paint the ceiling - two coats	128.25 SF	0.89	2.63	116.77	(38.93)	77.84
54. Mask and prep for paint - plastic, paper, tape (per LF)	46.00 LF	1.31	1.17	61.43	(0.00)	61.43
55. Batt insulation - 12" - R38 - unfaced batt	128.25 SF	1.56	14.76	214.83	(21.49)	193.34
56. Tear out wet insulation, no bagging	128.25 SF	0.49	0.00	62.84	(0.00)	62.84




United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Exam Room

DESCRIPTION	QUANTITY UNIT PRICE	TAX	RCV	DEPREC.	ACV
Totals: Exam Room		60.62	1,170.54	307.38	863.16



Storage Area/Room
304.00 SF Walls

394.25 SF Walls & Ceiling 10.03 SY Flooring 38.00 LF Ceil. Perimeter 90.25 SF Ceiling 90.25 SF Floor

38.00 LF Floor Perimeter

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
57a. Carpet	90.25 SF	0.24	0.00	21.66	(0.00)	21.66
57b. Carpet	90.25 SF	3.18	23.23	310.23	(155.12)	155.11
58a. Baseboard - 3 1/4" stain grade	38.00 LF	0.41	0.00	15.58	(0.00)	15.58
58b. Baseboard - 3 1/4" stain grade	38.00 LF	3.56	7.26	142.54	(4.75)	137.79
59. Stain & finish baseboard	38.00 LF	1.45	0.70	55.80	(18.60)	37.20
60. Paint the ceiling - two coats	90.25 SF	0.89	1.85	82.17	(27.39)	54.78
61. Mask and prep for paint - plastic, paper, tape (per LF)	38.00 LF	1.31	0.96	50.74	(0.00)	50.74
62. Batt insulation - 12" - R38 - unfaced batt	90.25 SF	1.56	10.38	151.17	(15.12)	136.05
63. Tear out wet insulation, no bagging	90.25 SF	0.49	0.00	44.22	(0.00)	44.22
Totals: Storage Area/Room			44.38	874.11	220.98	653.13



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

TT	_ 11	
	91	₹.7

Height: 8'

Waitin	g satnroc	Dimitora prise Area.	
4' 10"	- 5"	Flam Roo	

440.16 SF Walls 579.31 SF Walls & Ceiling 15.46 SY Flooring 139.15 SF Ceiling 139.15 SF Floor

73.42 LF Ceil. Perimeter

51.34 LF Floor Perimeter

Door	3' 1" X 6' 8"
Missing Wall	3' 10" X 8'
Door	3' 6" X 6' 8"
Door	3' 1" X 6' 8"
Door	3' 1" X 6' 8"
Door	3' X 6' 8"
Door	3' 6" X 6' 8"
Door	2' 10" X 6' 8"

Waiting

Opens into BATHROOM1
Opens into HALLWAY1
Opens into WAITING
Opens into Exterior
Opens into EXAM_ROOM1
Opens into CONFERENCE_R
Opens into CONFERENCE_R
Opens into EXAM_ROOM2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
64a. Carpet	139.15 SF	0.24	0.00	33.40	(0.00)	33.40
64b. Carpet	139.15 SF	3.18	35.82	478.32	(239.16)	239.16
65a. Baseboard - 3 1/4" stain grade	51.34 LF	0.41	0.00	21.05	(0.00)	21.05
65b. Baseboard - 3 1/4" stain grade	51.34 LF	3.56	9.81	192.58	(6.42)	186.16
66. Stain & finish baseboard	51.34 LF	1.45	0.95	75.39	(25.13)	50.26
67. Paint the ceiling - two coats	139.15 SF	0.89	2.85	126.69	(42.23)	84.46
68. Mask and prep for paint - plastic, paper, tape (per LF)		1,31	1.86	98.04	(0.00)	98.04
69. Batt insulation - 12" - R38 - unfaced batt	139.15 SF	1.56	16.01	233.08	(23.31)	209.77
70. Tear out wet insulation, no bagging	139.15 SF	0.49	0.00	68.18	(0.00)	68.18
Totals: Hallway			67.30	1,326.73	336.25	990.48

Door

230.00 SF Walls
291.50 SF Walls & Ceiling
6.83 SY Flooring

61.50 SF Ceiling 61.50 SF Floor

28.17 LF Floor Perimeter

3' 6" X 6' 8"

31.67 LF Ceil. Perimeter

Opens into HALLWAY

DESCRIPTION	QUANTITY UNI	T PRICE	TAX	RCV	DEPREC.	ACV
71a. Carpet	61.50 SF	0.24	0.00	14.76	(0.00)	14.76
71b. Carpet	61.50 SF	3.18	15.83	211.40	(105.71)	105.69

161235 ANDERSONEYE

12/28/2021

Page: 7

Height: 8'




United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Waiting

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
72a. Baseboard - 3 1/4" stain grade	28.17 LF	0.41	0.00	11.55	(0.00)	11.55
72b. Baseboard - 3 1/4" stain grade	28.17 LF	3.56	5.38	105.67	(3.52)	102.15
73. Stain & finish baseboard	28.17 LF	1.45	0.52	41.37	(13.79)	27.58
74. Paint the ceiling - two coats	61.50 SF	0.89	1.26	56.00	(18.67)	37.33
75. Mask and prep for paint - plastic, paper, tape (per LF)	31.67 LF	1.31	0.80	42.29	(0.00)	42.29
76. Batt insulation - 12" - R38 - unfaced batt	61.50 SF	1.56	7.08	103.02	(10.30)	92.72
77. Tear out wet insulation, no bagging	61.50 SF	0.49	0.00	30.14	(0.00)	30.14
Totals: Waiting			30.87	616.20	151.99	464.21



264.56 SF Walls 358.31 SF Walls & Ceiling

10.42 SY Flooring 38.83 LF Ceil. Perimeter Height: 8'

93.75 SF Ceiling 93.75 SF Floor

31.92 LF Floor Perimeter

3' 6" X 6' 8" Door 3' 5" X 6' 8" Door

Office

Opens into OFFICE2 Opens into HALLWAY1


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
78a. Carpet	93.75 SF	0.24	0.00	22.50	(0.00)	22.50
78b. Carpet	93.75 SF	3.18	24.13	322.26	(161.14)	161.12
79a. Baseboard - 3 1/4" stain grade	31.92 LF	0.41	0.00	13.09	(0.00)	13.09
79b. Baseboard - 3 1/4" stain grade	31.92 LF	3.56	6.10	119.74	(3.99)	115.75
80. Stain & finish baseboard	31.92 LF	1.45	0.59	46.87	(15.63)	31.24
81. Paint the ceiling - two coats	93.75 SF	0.89	1.92	85.36	(28.45)	56.91
82. Mask and prep for paint - plastic, paper, tape (per LF)	38.83 LF	1.31	0.98	51.85	(0.00)	51.85
83. Batt insulation - 12" - R38 - unfaced batt	93.75 SF	1.56	10.79	157.04	(15.71)	141.33
84. Tear out wet insulation, no bagging	93.75 SF	0.49	0.00	45.94	(0.00)	45.94
Totals: Office			44.51	864.65	224.92	639.73



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

4'2" Hallway	_					Height: 8'
6:	59.11 SF Walls			217.54 SF	Ceiling	
8	76.65 SF Walls &	Ceiling		217.54 SF	Floor	
	24.17 SY Flooring	_		75.33 LF	Floor Perimete	r
ic fil ic fil ii fil ii fil katen	17.67 LF Ceil. Pe	rimeter				
Door	3' 6" X 6' 8"		Opens into	OFFICE2		
Door	3' 5" X 6' 8"		Opens into	OFFICE3		
Missing Wall	3' 10" X 8'		Opens into	HALLWA	·Υ	
Door	3' 1" X 6' 8"		Opens into FILES			
Door	3' 3" X 6' 8"	Opens into EXAM_ROOM Opens into BATHROOM				
Door	3' 3" X 6' 8"					
Missing Wall - Goes to Floor	25' 10" X 6' 8"		Opens into	DISPLAY	_ROOM	
DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
85a. Carpet	217.54 SF	0.24	0.00	52.21	(0.00)	52.21
85b. Carpet	217.54 SF	3.18	56.00	747.78	(373.89)	373.89
86a. Baseboard - 3 1/4" stain grade	75.33 LF	0.41	0.00	30.89	(0.00)	30.89
86b. Baseboard - 3 1/4" stain grade	75.33 LF	3.56	14.40	282.57	(9.42)	273.15
87. Stain & finish baseboard	75.33 LF	1.45	1.40	110.63	(36.88)	73.75
88. Paint the ceiling - two coats	217.54 SF	0.89	4.45	198.06	(66.02)	132.04
89. Mask and prep for paint - plastic, paper, tape (per	LF) 117.67 LF	1.31	2.98	157.13	(0.00)	157.13
90. Batt insulation - 12" - R38 - unfaced batt	217.54 SF	1.56	25.03	364.39	(36.44)	327.95
91. Tear out wet insulation, no bagging	217.54 SF	0.49	0.00	106.59	(0.00)	106.59



Totals: Hallway

Office

385.33 SF Walls 547.33 SF Walls & Ceiling 18.00 SY Flooring

54.00 LF Ceil. Perimeter

Height: 8'

1,527.60

522.65

162.00 SF Ceiling 162.00 SF Floor

2,050.25

47.00 LF Floor Perimeter

Door Door 3' 6" X 6' 8" 3' 6" X 6' 8" Opens into OFFICE3
Opens into HALLWAY1

104.26

DESCRIPTION	QUANTITY UNI	T PRICE	TAX	RCV	DEPREC.	ACV
92a. Carpet	162.00 SF	0.24	0.00	38.88	(0.00)	38.88
92b. Carpet	162.00 SF	3.18	41.70	556.86	(278.43)	278.43

161235_ANDERSONEYE

12/28/2021

Page: 9



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Office

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
93a. Baseboard - 3 1/4" stain grade	47.00 LF	0.41	0.00	19.27	(0.00)	19.27
93b. Baseboard - 3 1/4" stain grade	47.00 LF	3.56	8.98	176.30	(5.88)	170.42
94. Stain & finish baseboard	47.00 LF	1.45	0.87	69.02	(23.01)	46.01
95. Paint the ceiling - two coats	162.00 SF	0.89	3.32	147.50	(49.17)	98.33
96. Mask and prep for paint - plastic, paper, tape (per LF)	54.00 LF	1.31	1.37	72.11	(0.00)	72.11
97. Batt insulation - 12" - R38 - unfaced batt	162.00 SF	1.56	18.64	271.36	(27.13)	244.23
98. Tear out wet insulation, no bagging	162.00 SF	0.49	0.00	79.38	(0.00)	79.38
Totals: Office			74.88	1,430.68	383.62	1,047.06

9	- -
Receptionist	8. 10

Receptionist

280.00 SF Walls
356.50 SF Walls & Ceiling
8.50 SY Flooring
35.00 LF Ceil. Perimeter

76.50 SF Ceiling 76.50 SF Floor 35.00 LF Floor Perimeter

Height: 8'


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
99a. Carpet	76.50 SF	0.24	0.00	18.36	(0.00)	18.36
99b. Carpet	76.50 SF	3.18	19.69	262.96	(131.49)	131.47
100a. Baseboard - 3 1/4" stain grade	35.00 LF	0.41	0.00	14.35	(0.00)	14.35
100b. Baseboard - 3 1/4" stain grade	35.00 LF	3.56	6.69	131.29	(4.37)	126.92
101. Stain & finish baseboard	35.00 LF	1.45	0.65	51.40	(17.14)	34.26
102. Paint the ceiling - two coats	76.50 SF	0.89	1.57	69.66	(23.22)	46.44
103. Mask and prep for paint - plastic, paper, tape (per LF)	35.00 LF	1.31	0.89	46.74	(0.00)	46.74
104. Batt insulation - 12" - R38 - unfaced batt	76.50 SF	1.56	8.80	128.14	(12.81)	115.33
105. Tear out wet insulation, no bagging	76.50 SF	0.49	0.00	37.49	(0.00)	37.49
Totals: Receptionist			38.29	760.39	189.03	571.36



United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884



Waiting

301.33 SF Walls

404.83 SF Walls & Ceiling

11.50 SY Flooring

41.00 LF Ceil. Perimeter

Height: 8'

103.50 SF Ceiling 103.50 SF Floor

37.00 LF Floor Perimeter

Door

4' X 6' 8"

Opens into Exterior

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
106a, Carpet	103.50 SF	0.24	0.00	24.84	(0.00)	24.84
106b. Carpet	103.50 SF	3.18	26.64	355.77	(177.89)	177.88
107a. Baseboard - 3 1/4" stain grade	37.00 LF	0.41	0.00	15.17	(0.00)	15.17
107b. Baseboard - 3 1/4" stain grade	37.00 LF	3.56	7.07	138.79	(4.63)	134.16
108. Stain & finish baseboard	37.00 LF	1.45	0.69	54.34	(18.11)	36.23
109. Paint the ceiling - two coats	103.50 SF	0.89	2.12	94.24	(31.42)	62.82
110. Mask and prep for paint - plastic, paper, tape (per LF)	41.00 LF	1.31	1.04	54.75	(0.00)	54.75
111. Batt insulation - 12" - R38 - unfaced batt	103.50 SF	1.56	11.91	173.37	(17.34)	156.03
112. Tear out wet insulation, no bagging	103.50 SF	0.49	0.00	50.72	(0.00)	50.72
Totals: Waiting			49.47	961.99	249.39	712.60



Display Room

1121.97 SF Walls

1556.74 SF Walls & Ceiling

48.31 SY Flooring

171.29 LF Ceil. Perimeter

Height: 8'

434.77 SF Ceiling 434.77 SF Floor

134.04 LF Floor Perimeter

Missing Wall - Goes to Floor

Door Missing Wall - Goes to Floor

Missing Wall - Goes to Floor

4' 1" X 6' 8"

3' 6" X 6' 8"

25' 10" X 6' 8"

3' 10" X 6' 8"

Opens into OFFICE1 Opens into Exterior

Opens into HALLWAY1

Opens into Exterior

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	RCV	DEPREC.	ACV
113a. Carpet	434.77 SF	0.24	0.00	104.34	(0.00)	104.34
113b. Carpet	434.77 SF	3.18	111.91	1,494.48	(747.25)	747.23
114a. Baseboard - 3 1/4" stain grade	134.04 LF	0.41	0.00	54.96	(0.00)	54.96
114b. Baseboard - 3 1/4" stain grade	134.04 LF	3.56	25.62	502.80	(16.76)	486.04
115. Stain & finish baseboard	134.04 LF	1.45	2.48	196.84	(65.62)	131.22
116. Paint the ceiling - two coats	434.77 SF	0.89	8.90	395.85	(131.95)	263.90

161235_ANDERSONEYE

12/28/2021

Page: 11




United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

Office

CONTINUED - Display Room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
117. Mask and prep for paint - plastic, paper, tape (per LF)	171.29 LF	1.31	4.34	228.73	(0.00)	228.73
118. Batt insulation - 12" - R38 - unfaced batt	434.77 SF	1.56	50.02	728.26	(72.82)	655.44
119. Tear out wet insulation, no bagging	434.77 SF	0.49	0.00	213.04	(0.00)	213.04
Totals: Display Room			203.27	3,919.30	1,034.40	2,884.90



377.33 SF Walls
515.88 SF Walls & Ceiling
15.39 SY Flooring
47.17 LF Ceil. Perimeter

138.54 SF Ceiling 138.54 SF Floor 47.17 LF Floor Perimeter

Height: 8'

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
120a. Carpet	138.54 SF	0.24	0.00	33.25	(0.00)	33.25
120b. Carpet	138.54 SF	3.18	35.66	476.22	(238.11)	238.11
121a. Baseboard - 3 1/4" stain grade	47.17 LF	0.41	0.00	19.34	(0.00)	19.34
121b. Baseboard - 3 1/4" stain grade	47.17 LF	3.56	9.01	176.94	(5.90)	171.04
122. Stain & finish baseboard	47.17 LF	1.45	0.87	69.27	(23.09)	46.18
123. Paint the ceiling - two coats	138.54 SF	0.89	2.84	126.14	(42.05)	84.09
124. Mask and prep for paint - plastic, paper, tape (per LF)	47.17 LF	1.31	1.20	62.99	(0.00)	62.99
125. Batt insulation - 12" - R38 - unfaced batt	138.54 SF	1.56	15.94	232.06	(23.20)	208.86
126. Tear out wet insulation, no bagging	138.54 SF	0.49	0.00	67.88	(0.00)	67.88
Totals: Office			65.52	1,264.09	332.35	931.74


161235_ANDERSONEYE 12/28/2021 Page: 12



United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884



Bathroom		
	249.23 SF W	alls
	220 02 SE W	alle & Ca

70.80 SF Ceiling

320.03 SF Walls & Ceiling

70.80 SF Floor


7.87 SY Flooring 33.72 LF Ceil. Perimeter 30.64 LF Floor Perimeter

Door

3' 1" X 6' 8"

Opens into HALLWAY

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
127. Paint the ceiling - two coats	70.80 SF	0.89	1.45	64.46	(21.48)	42.98
128. Mask and prep for paint - plastic, paper, tape (per LF)	33.72 LF	1.31	0.86	45.03	(0.00)	45.03
129. Batt insulation - 12" - R38 - unfaced batt	70.80 SF	1.56	8.15	118.60	(11.87)	106.73
130. Tear out wet insulation, no bagging	70.80 SF	0.49	0.00	34.69	(0.00)	34.69
Totals: Bathroom			10.46	262.78	33.35	229.43



Janitorial

Height: 8'

Height: 8'

244.89 SF Walls

311.70 SF Walls & Ceiling

7.42 SY Flooring

33.67 LF Ceil. Perimeter

66.81 SF Ceiling

66.81 SF Floor

30.00 LF Floor Perimeter

Door

3' 8" X 6' 8"

Opens into Exterior


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
131. Paint the ceiling - two coats	66.81 SF	0.89	1.37	60.83	(20.28)	40.55
132. Mask and prep for paint - plastic, paper, tape (per LF)	33.67 LF	1.31	0.85	44.96	(0.00)	44.96
133. Batt insulation - 12" - R38 - unfaced batt	66.81 SF	1.56	7.69	111.91	(11.19)	100.72
134. Tear out wet insulation, no bagging	66.81 SF	0.49	0.00	32.74	(0.00)	32.74
Totals: Janitorial			9.91	250.44	31.47	218.97



United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884



200.00.00.00.11

299.09 SF Walls

397.92 SF Walls & Ceiling

10.98 SY Flooring

39.96 LF Ceil. Perimeter

Height: 8'

98.83 SF Ceiling

98.83 SF Floor


36.87 LF Floor Perimeter

Door

3' 1" X 6' 8"

Opens into HALLWAY1

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
135a. Carpet	98.83 SF	0.24	0.00	23.72	(0.00)	23.72
135b. Carpet	98.83 SF	3.18	25.44	339.72	(169.86)	169.86
136a. Baseboard - 3 1/4" stain grade	36.87 LF	0.41	0.00	15.12	(0.00)	15.12
136b. Baseboard - 3 1/4" stain grade	36.87 LF	3.56	7.05	138.31	(4.62)	133.69
137. Stain & finish baseboard	36.87 LF	1.45	0.68	54.14	(18.05)	36.09
138. Paint the ceiling - two coats	98.83 SF	0.89	2.02	89.98	(29.99)	59.99
139. Mask and prep for paint - plastic, paper, tape (per LF)	39.96 LF	1.31	1.01	53.36	(0.00)	53.36
140. Batt insulation - 12" - R38 - unfaced batt	98.83 SF	1.56	11.37	165.54	(16.56)	148.98
141. Tear out wet insulation, no bagging	98.83 SF	0.49	0.00	48.43	(0.00)	48.43
Totals: Files			47.57	928.32	239.08	689.24



Exam Room

279.05 SF Walls

364.74 SF Walls & Ceiling

9.52 SY Flooring

37.59 LF Ceil. Perimeter

Height: 8'

85.70 SF Ceiling

85.70 SF Floor

34.34 LF Floor Perimeter

Door

3' 3" X 6' 8"

Opens into HALLWAY1

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
142a. Carpet	85.70 SF	0.24	0.00	20.57	(0.00)	20.57
142b. Carpet	85.70 SF	3.18	22.06	294.59	(147.30)	147.29
143a. Baseboard - 3 1/4" stain grade	34.34 LF	0.41	0.00	14.08	(0.00)	14.08
143b. Baseboard - 3 1/4" stain grade	34.34 LF	3.56	6.56	128.81	(4.30)	124.51
144. Stain & finish baseboard	34.34 LF	1.45	0.64	50.43	(16.81)	33.62
145. Paint the ceiling - two coats	85.70 SF	0.89	1.76	78.03	(26.01)	52.02
146. Mask and prep for paint - plastic, paper, tape (per	37.59 LF	1.31	0.95	50.19	(0.00)	50.19
LF) 147. Batt insulation - 12" - R38 - unfaced batt	85.70 SF	1.56	9.86	143.55	(14.36)	129.19
148. Tear out wet insulation, no bagging	85.70 SF	0.49	0.00	41.99	(0.00)	41.99

161235_ANDERSONEYE

12/28/2021

Page: 14



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Exam Room

DESCRIPTION	340	QUANTITY UNIT PRICE	TAX	RCV	DEPREC.	ACV
Totals: Exam Room			41.83	822.24	208.78	613.46

Hailway in Bathroom

Bathroom


219.85 SF Walls 265.15 SF Walls & Ceiling 5.03 SY Flooring 30.19 LF Ceil. Perimeter Height: 8'

45.31 SF Ceiling 45.31 SF Floor

26.94 LF Floor Perimeter

Door 3' 3" X 6' 8" Opens into HALLWAY1

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
149. Paint the ceiling - two coats	45.31 SF	0.89	0.93	41.26	(13.75)	27.51
150. Mask and prep for paint - plastic, paper, tape (per LF)	30.19 LF	1.31	0.77	40.32	(0.00)	40.32
151. Batt insulation - 12" - R38 - unfaced batt	45.31 SF	1.56	5.21	75.89	(7.59)	68.30
152. Tear out wet insulation, no bagging	45.31 SF	0.49	0.00	22.20	(0.00)	22.20
Totals: Bathroom			6.91	179.67	21.34	158.33



Storage A	rea/Room	
-----------	----------	--

432.13 SF Walls 613.48 SF Walls & Ceiling 20.15 SY Flooring 54.02 LF Ceil. Perimeter Height: 8'

181.35 SF Ceiling 181.35 SF Floor

54.02 LF Floor Perimeter

DESCRIPTION	QUANTITY U	NIT PRICE	TAX	RCV	DEPREC.	ACV
153a. Carpet	181.35 SF	0.24	0.00	43.52	(0.00)	43.52
153b. Carpet	181.35 SF	3.18	46.68	623.37	(311.69)	311.68
154a. Baseboard - 3 1/4" stain grade	54.02 LF	0.41	0.00	22.15	(0.00)	22.15
154b. Baseboard - 3 1/4" stain grade	54.02 LF	3.56	10.32	202.63	(6.75)	195.88
155. Stain & finish baseboard	54.02 LF	1.45	1.00	79.33	(26.44)	52.89
156. Paint the ceiling - two coats	181.35 SF	0.89	3.71	165.11	(55.04)	110.07
51235_ANDERSONEYE				12/	28/2021	Page: 1




United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Storage Area/Room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
157. Mask and prep for paint - plastic, paper, tape (per LF)	54.02 LF	1.31	1.37	72.14	(0.00)	72.14
158. Batt insulation - 12" - R38 - unfaced batt	181.35 SF	1.56	20.86	303.77	(30.38)	273.39
159. Tear out wet insulation, no bagging	181.35 SF	0.49	0.00	88.86	(0.00)	88.86
Totals: Storage Area/Room			83.94	1,600.88	430.30	1,170.58



Office

324.33 SF Walls 461.83 SF Walls & Ceiling

15.28 SY Flooring 47.00 LF Ceil. Perimeter Height: 8'

137.50 SF Ceiling 137.50 SF Floor

39.25 LF Floor Perimeter

Missing Wall - Goes to Floor

Door

4' 1" X 6' 8" 3' 8" X 6' 8" Opens into DISPLAY_ROOM
Opens into Exterior

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
160a. Carpet	137.50 SF	0.24	0.00	33.00	(0.00)	33.00
160b. Carpet	137.50 SF	3.18	35.39	472.64	(236.33)	236.31
161a. Baseboard - 3 1/4" stain grade	39.25 LF	0.41	0.00	16.09	(0.00)	16.09
161b. Baseboard - 3 1/4" stain grade	39.25 LF	3.56	7.50	147.23	(4.91)	142.32
162. Stain & finish baseboard	39.25 LF	1.45	0.73	57.64	(19.21)	38.43
163. Paint the ceiling - two coats	137.50 SF	0.89	2.82	125.20	(41.73)	83.47
164. Mask and prep for paint - plastic, paper, tape (per LF)	47.00 LF	1.31	1.19	62.76	(0.00)	62.76
165. Batt insulation - 12" - R38 - unfaced batt	137.50 SF	1.56	15.82	230.32	(23.03)	207.29
166. Tear out wet insulation, no bagging	137.50 SF	0.49	0.00	67.38	(0.00)	67.38
Totals: Office			63.45	1,212.26	325.21	887.05
Total: Interior			1,294.13	28,542.63	6,199.85	22,342.78

Dumpster

DESCRIPTION161235_ANDERSONEYE

QUANTITY UNIT PRICE

TAX

RCV DEPREC.

ACV

12/28/2021

Page: 16



CONTINUED - Dumpster

DESCRIPTION	·	QU.	ANTITY	UNIT PRICE	TAX	RCV	DEPREC.	ACV
167. Dumpster I	load - Approx. 40 yards, 7-8 tons of	-	1.00 EA	613.46	0.00	613.46	(0.00)	613.46
Allowance for or	ne (1) dumpster for the roof and for t	he interior	debris.Co	nsideration for the	removal/hauling	g of all const	ruction/repair rela	ited debris.
Totals: Dumps	ter				0.00	613.46	0.00	613.46
Line Item Total	s: 161235_ANDERSONEYE				2,876.90	61,909.85	19,461.25	42,448.60
Grand Tota	ll Areas:							
7,633.58	SF Walls	2,707.29	SF Ceil	ing	10,340.8	7 SF Wal	lls and Ceiling	
2,707.29	SF Floor	300.81	SY Flo	oring	927.6	0 LF Floo	or Perimeter	
0.00	SF Long Wall	0.00	SF Sho	rt Wall	1,087.1	8 LF Cei	l. Perimeter	
2,707.29	Floor Area	2,934.84	Total A	rea	7,633.5	8 Interior	Wall Area	
2,298.21	Exterior Wall Area	271.47	Exterio Walls	r Perimeter of				
0.00	Surface Area	0.00	Numbe	r of Squares	0.0	00 Total P	erimeter Length	ı

0.00 Total Hip Length

0.00 Total Ridge Length



UCS

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

Recap of Taxes

	Material Sales Tax (9.75%)	P Ppty Material Tax (9.75%)	P Ppty Cleaning Tax (9.75%)	Storage Rental Tax (9.75%)	Food Tax (7.75%)
Line Items	2,822.79	0.00	0.00	54.11	0.00
Total	2,822.79	0.00	0.00	54.11	0.00



UCS

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

Recap by Room

Estimate: 161235_ANDERSONEYE

Area: Loc 001 Bldg 001 113 E Locust St

Area: Building	14,399.12	24.39%
Front Elevation	1,279.04	2.17%
Right Elevation	561.60	0.95%
Rear Elevation	2,005.35	3.40%
Left Elevation	12,925.88	21.90%
Roof	12,925.00	21.50 70
Area Subtotal: Building	31,170.99	52.80%
Area Subtotal: Loc 001 Bldg 001 113 E Locust St	31,170.99	52.80%
rea: Interior	3,769.08	6.38%
Exam Room	2,054.75	3.48%
Conference Room	1,976.59	3.35%
Exam Room	1,109.92	1.88%
Storage Area/Room	829.73	1.41%
Hallway	1,259.43	2.13%
Waiting	585.33	0.99%
Office	820.14	1.39%
Hallway	1,945.99	3.30%
Office	1,355.80	2.30%
Receptionist	722.10	1.22%
Waiting	912.52	1.55%
Display Room	3,716.03	6.29%
Office	1,198.57	2.03%
Bathroom	252.32	0.43%
Janitorial	240.53	0.41%
Files	880.75	1.49%
Exam Room	780.41	1.32%
Bathroom	172.76	0.29%
Storage Area/Room	1,516.94	2.57%
Office	1,148.81	1.95%
Area Subtotal: Interior	27,248.50	46.16%
Dumpster	613.46	1.04%
subtotal of Areas	59,032.95	100.00%
2441	59,032.95	100.00%
otal		
1235_ANDERSONEYE	12/28/2021	Page

Phone: (800) 827-8279 Fax: (800) 786-8884

Recap by Category with Depreciation

Items	RCV	Deprec.	ACV
CLEANING	561.60		561.60
CONTENT MANIPULATION	3,769.08		3,769.08
GENERAL DEMOLITION	4,809.51		4,809.51
DOORS	1,438.94	215.84	1,223.10
DRYWALL	281.96	28.20	253.76
FLOOR COVERING - CARPET	8,027.56	4,013.82	4,013.74
FINISH CARPENTRY / TRIMWORK	2,990.56	99.70	2,890.86
FRAMING & ROUGH CARPENTRY	4,406.12	173.46	4,232.66
INSULATION	4,223.37	422.35	3,801.02
LIGHT FIXTURES	131.19		131.19
PANELING & WOOD WALL FINISHES	394.80	39.48	355.32
PAINTING	6,267.57	2,251.37	4,016.20
ROOFING	11,077.78	6,897.88	4,179.90
SIDING	1,002.85	150.43	852.42
SOFFIT, FASCIA, & GUTTER	1,412.00	788.90	623.10
STUCCO & EXTERIOR PLASTER	2,407.24	328.68	2,078.56
WINDOWS - WOOD	5,830.82	2,915.41	2,915.41
Subtotal	59,032.95	18,325.52	40,707.43
Material Sales Tax	2,822.79	1,135.73	1,687.06
Storage Rental Tax	54.11		54.11
Total	61,909.85	19,461.25	42,448.60

NOTICE: This is an estimate for repairs and a copy of this document does not constitute settlement of the claim. The above figures may be subject to additional company review and approval. The loss will be settled on an actual cash value basis and the policy may contain a replacement cost provision. If it contains such a provision, full cost of replacement can be considered if the property is actually replaced. You have the right to make further claim under this provision as outlined in the policy. All policy terms and conditions apply to this claim.

161235_ANDERSONEYE 12/28/2021 Page: 21

≅ (>

Waiting 3



UCS

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

Summary for Loc 001 Bldg 001 113 E Locust St

Line Item Total	59,032.95
Material Sales Tax	2,822.79
Storage Rental Tax	54.11
Replacement Cost Value	\$61,909.85
Less Depreciation	(19,461.25)
Actual Cash Value	\$42,448.60
Less Deductible	(1,000.00)
Net Claim	\$41,448.60
Total Recoverable Depreciation	19,461.25
Net Claim if Depreciation is Recovered	\$60,909.85

Michael Knight

12/28/2021 Page: 18

Knisht 2m

(731) 588-3638

(800) 827-8279

(800) 827-8279

.com

E-mail:

Business:

E-mail:

Business:

Business:

E-mail:

E-mail:

gena.stallings@yahoo.com

insuranceadjustermike@gmail.com

insuranceadjustermike@gmail

(844) 296-4053 x 52296

AOCat@aoins.com

United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

\$218,816.22 Form Home: (731) 588-3 Phone: (800) 827-8279 Fax: (800) 786-8884

Anderson Eyecare of West Tennessee Insured:

113 E Locust St Property:

Dresden, TN 38225-1440

Claim Rep.: Michael Knight

United Claims Services Company:

Business: 26 Japwood Place Garner, NC 27521

Michael Knight Estimator:

United Claims Services Company:

26 Japwood Place Business:

Garner, NC 27521

United Claims Service Reference:

Auto Owners Company: Business: P.O. Box 30660

Lansing, MI 48909

Type of Loss: Tornado Policy Number: 0327117019 Claim Number: 300-0677709-2021

12/12/2021 12:47 PM Date Contacted:

12/12/2021 12:47 PM Date Received: Date of Loss: 12/10/2021 12:47 PM Date Entered: 12/16/2021 11:45 AM 12/14/2021 12:47 PM Date Inspected:

Price List: TNJA8X JUN22

Restoration/Service/Remodel

S 5 ANDERSON-EYE-1 Estimate:

NOTICE: This is a repair estimate only and not an offer of settlement. All estimate figures may be subject to company review and approval. Authorization to repair and/or guarantee of payment must come from the insurance company. Please note this estimate reflects the extent of known covered damages to your property. No supplements or additional payment will be issued for any repair of damage not listed in this scope without prior approval. This approval must be obtained prior to your replacement or repair of any additional damages.



5_5_ANDERSON-EYE-1 Loc 001 Bldg 001 113 E Locust St

Building

Front Elevation

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
1. Siding - cedar shingle	155.00 SF	9.12	82.97	299.32	1,795.89	(253.21)	1,542.68
2. Seal & paint wood siding	155.00 SF	1.89	7.10	60.02	360.07	(120.02)	240.05
3. French door - Exterior - pre-hung unit	2.00 EA	843.03	146.19	366.44	2,198.69	(322.44)	1,876.25
4. Gutter / downspout - aluminum - up to 5"	72.00 LF	7.84	30.26	118.96	713.70	(403.33)	310.37
5. Gutter guard/screen	72.00 LF	3.30	8.14	49.14	294.88	(197.85)	97.03
6. Stud wali - 2" x 4" x 8' - 16" oc	24.00 LF	14.12	33.04	74.38	446.30	(44.63)	401.67
7. Carpenter - General Framer - per hour	48.00 HR	61.52	0.00	590.60	3,543.56	(0.00)	3,543.56
Allowance to remove the damaged front el make ready for stucco application.	evation wall fra	ming and stucco ex	terior that was	s heavily dama	ged in the ever	nt and re-frame t	he wall and
8. Sheathing - plywood - 1/2" - treated	264.00 SF	2.16	55.60	125.16	751.00	(75.10)	675.90
9. Synthetic stucco on 1" polystyrene board	264.00 SF	8.64	76.96	471.60	2,829.52	(424.42)	2,405.10
10. Seal & paint stucco	264.00 SF	1.48	7.46	79.64	477.82	(477.82)	0.00
11. Fascia Board Material*	12.00 LF	0.53	0.62	1.40	8.38	(0.84)	7.54
Begin Supplement by Mike Knight on	05/12/2022						
12. Temporary shoring post - Screw jack (per day)	56.00 DA	39.42	0.00	441.50	2,649.02	(0.00)	2,649.02
13. House wrap (air/moisture barrier)	264.00 SF	0.32	4.63	17.82	106.93	(0.00)	106.93
14. Stucco color coat (Redash) - coarse texture ***End Supplement by Mike Knight on 05	264.00 SF 5/12/2022***	3.77	14.41	201.94	1,211.63	(0.00)	1,211.63
Totals: Front Elevation			467.38	2,897.92	17,387.39	2,319.66	15,067.73

Right Elevation

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
15. Gutter / downspout - aluminum - up to 5"	50.00 LF	7.84	21.01	82.60	495.61	(280.09)	215.52
16. Gutter guard/screen	50.00 LF	3.30	5.66	34.14	204.80	(137.40)	67.40
17. Stucco / Ext. Plaster Repair - Min. Charge - Lab. and Mat.	1.00 EA	231.80	2.14	46.78	280.72	(0.00)	280.72
18. Seal & paint stucco	400.00 SF	1.48	11.31	120.66	723.97	(723.97)	0.00
Totals: Right Elevation			40.12	284.18	1,705.10	1,141.46	563.64

S_5_ANDERSON-EYE-1 8/4/2022 Page: 2,



United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

Rear Elevation

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
19. Clean with pressure/chemical spray - Very heavy	780.00 SF	0.78	1.52	121.98	731.90	(0.00)	731.90
Begin Supplement by Mike Knight on	05/12/2022						
20. Seal & paint stucco	264.00 SF	1.48	7.46	79.64	477.82	(477.82)	0.00
21. Stucco / Ext. Plaster Repair - Min. Charge - Lab. and Mat.	1.00 EA	231.80	2.14	46.78	280.72	(0.00)	280.72
End Supplement by Mike Knight on 0	5/12/2022						
Totals: Rear Elevation			11.12	248.40	1,490.44	477.82	1,012.62

Left Elevation

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
22. Soffit & fascia - wood - 2' overhang 23. Prime & paint exterior soffit - wood	16.00 LF 32.00 SF	15.28 2.29	11.72 1.34	51.22 14.92	307.42 89.54	(28.65) (89.54)	278.77 0.00
Totals: Left Elevation			13.06	66.14	396.96	118.19	278.77

Roof

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
24. Tear off composition shingles (no haul off)	42.15 SQ	35.83	0.00	302.04	1,812.27	(0.00)	1,812.27
This action includes all roofing components Any additional layers that may be discovered	s. ed and require r	emoval must be ver	ified prior to	any considerat	ion for a supp	ement.	
25. Roofing felt - 15 lb.	42.15 SQ		25.81	175.44	1,052.68	(947.42)	105.26
26. Roof vent - turbine type	2.00 EA	93.30	12.73	39.86	239.19	(123.02)	116.17
27. Continuous ridge vent - shingle-over style	159.00 LF	6.27	52.09	209.80	1,258.82	(539.50)	719.32
28. Flashing - pipe jack	6.00 EA	29.65	7.10	37.00	222.00	(114.16)	107.84
29. Roofer - per hour	16.00 HR	69.01	0.00	220.84	1,325.00	(0.00)	1,325.00
Allowance to repair the rotten decking (1Xe	6 framing) and	potential rafter repa	irs that were o	lamaged durin	g the event.		
30. 1" x 6" lumber (.5 BF per LF)	280.00 LF	1.53	41.77	94.04	564.21	(67.70)	496.51
31. 3 tab - 25 yr comp. shingle roofing - w/out felt	48.67 SQ	167.21	485.21	1,724.66	10,347.98	(7,450.55)	2,897.43
Starter Course and Ridge Cap are included	in waste factor.						
32. Drip edge	300.00 LF	1.97	32.18	124.64	747.82	(384.59)	363.23
Begin Supplement by Mike Knight on C	3/16/2022						
33. Tarp - all-purpose poly - per sq ft (lab/mat) - after hrs	3,000.00 SF	0.88	84.83	544.96	3,269.79	(0.00)	3,269.79
_5_ANDERSON-EYE-1						8/4/2022	Page



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Roof

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
End Supplement by Mike Knight on 0	3/16/2022						
Begin Supplement by Mike Knight on	05/12/2022						
34. Asphalt starter - universal starter course	300.00 LF	1.25	14.33	77.86	467.19	(420.48)	46.71
35. Ridge cap - Standard profile - composition shingles	159.00 LF	3.83	34.42	128.68	772.07	(463.23)	308.84
End Supplement by Mike Knight on 0	5/12/2022						
Totals: Roof			790.47	3,679.82	22,079.02	10,510.65	11,568.37

Windows

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Begin Supplement 05/12/2022 Separate folder for windows added to make	comparison to	Contractors Estima	ite Easier for a	II to review			
Removal							
36. Wood window - single hung, 9-12 sf	2.00 EA	32.36	0.00	12.94	77.66	(0.00)	77.66
37. Wood window - double hung, 9-12 sf	4.00 EA	32.36	0.00	25.88	155.32	(0.00)	155.32
38. Wood window - single hung, 20-28 sf	1.00 EA	39.97	0.00	8.00	47.97	(0.00)	47.97
39. Specialty wood window unit, 63-70 sf*	1.00 EA	39.97	0.00	8.00	47.97	(0.00)	47.97
Installation							
40. 2" x 4" lumber - treated (.667 BF per LF)	126.65 LF	3.17	18.77	84.06	504.31	(0.00)	504.31
Material for window bucking							
41. Carpentry - General Laborer - per hour	8.00 HR	36.43	0.00	58.28	349.72	(0.00)	349.72
Labor to remove and replace window bucking	ng						
42. Wood window - single hung, 9-12 sf	2.00 EA	565.65	92.32	244.72	1,468.34	(0.00)	1,468.34
43. Wood window - double hung, 9-12 sf	4.00 EA	666.27	223.89	577.80	3,466.77	(0.00)	3,466.77
44. Wood window - single hung, 20-28 sf	1.00 EA	878.91	73.70	190.52	1,143.13	(0.00)	1,143.13
45. Specialty wood window unit, 63-70 sf*	1.00 EA	2,957.61	278.38	647.20	3,883.19	(0.00)	3,883.19
46. Add. charge for a retrofit window, 3-11 sf - difficult	4.00 EA	147.93	5.23	119.38	716.33	(0.00)	716.33
47. Add. charge for a retrofit window, 12-23 sf - difficult	3.00 EA	202.98	7.02	123.18	739.14	(0.00)	739.14
48. Add. charge for a retrofit window, 63-70 sf - difficult*	1.00 EA	260.58	3.42	52.80	316.80	(0.00)	316.80



CONTINUED - Windows

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
49. Additional charge for wood window	6.83 LF	19.61	10.70	28.92	173.56	(0.00)	173.56
mullion - per LF 50. Flashing - Sill flashing - moldable tape	126.65 LF	7.17	33.83	188.38	1,130.29	(0.00)	1,130.29
The entire opening of each window must be	e flashed. This	would be installed	inside the win	dow frame ope	ening.		
51. Metal Z flashing / drip cap	49.51 LF		3.57	28.74	172.43	(0.00)	172.43
Metal flashing required above all openings							
52. Flashing - Sill flashing - moldable tape	126.65 LF	7.17	33.83	188.38	1,130.29	(0.00)	1,130.29
This is required to flash the outside window	vs where the na	il flange is located.					
53. Caulking - acrylic	126.65 LF		1.73	62.40	374.42	(0.00)	374.42
To caulk around the windows							
54. Urethane foam sealant	126.65 LF	0.88	2.96	22.90	137.31	(0.00)	137.31
Non-expanding foam is required around the	e frames of all r	new windows.					
End Supplement by Mike Knight on 05	/12/2022						
Totals: Windows			789.35	2,672.48	16,034.95	0.00	16,034.95
Total: Building			2,111.50	9,848.94	59,093.86	14,567.78	44,526.08
Total: Loc 001 Bldg 001 113 E Locust S	t s		2,111.50	9,848.94	59,093.86	14,567.78	44,526.08

Interior

Interior

DESCRIPTION	QUANTITY U	NIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
55. Content Manipulation charge - per hour	96.00 HR	36.43	0.00	0.00	3,497.28	(0.00)	3,497.28
Allowance for six (6) workers working eight and then move back in the items.	at (8) hours for a c	lay to move item	s out for carpet	to be replace	d, ceilings re-p		
56. Job-site moving/storage container - 20' long - per month	3.00 MO	205.00	59.96	0.00	674.96	(0.00)	674.96
Allowance for three (3) containers to store to	he contents while	repairs are being	g made				
Begin Supplement by Mike Knight on 0	3/16/2022						
57. Provide box & tape - large size	127.00 EA	4.22	109.60	0.00	645.54	(0.00)	645.54
58. Provide box & tape - medium size	170.00 EA	3.16	109.86	0.00	647.06	(0.00)	647.06
59. Content Manipulation charge - per hour	84.00 HR	36.43	0.00	0.00	3,060.12	(0.00)	3,060.12
Additional content manipulation in supplementary	nent						
60. Porta Potty*	1.00 EA						PWI
_5_ANDERSON-EYE-1					1	8/4/2022	Page:



UCS

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Interior

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
61. Bubble Wrap - Add-on cost for fragile items*	2,250.00 LF	0.17	78.22	0.00	460.72	(0.00)	460.72
62. Equipment setup, take down, and monitoring (hourly charge)	15.00 HR	49.35	0.00	0.00	740.25	(0.00)	740.25
63. Utility Dump Bed to take trash to dumpster for one (1) month*	1.00 EA	2,000.00	195.00	0.00	2,195.00	(0.00)	2,195.00
64. Air mover (per 24 hour period) - No monitoring	120.00 EA	25.25	0.00	0.00	3,030.00	(0.00)	3,030.00
65. Dehumidifier (per 24 hour period) - Large - No monitoring	65.00 EA	72.75	0.00	0.00	4,728.75	(0.00)	4,728.75
66. Generator - 10-30KW (per day - 24 hour) - no monitoring	5.00 DA						PWI
67. Generator Fuel Charge*	225.00 EA						PWI
End Supplement by Mike Knight on 03.	/16/2022						
Total: Interior			552.64	0.00	19,679.68	0.00	19,679.68

Front hallway	File room	Height: 8
10101	360.33 SF Walls	180.42 SF Ceiling
om Elle room	540.75 SF Walls & Ceiling	180.42 SF Floor
u (1) 5.	20.05 SY Flooring	44.42 LF Floor Perimeter
17' 8"	49.42 LF Ceil. Perimeter	
Door	2' 6" X 7'	Opens into ENTRANCE2
Door	2' 6" X 7'	Opens into FRONT_HALLW2
7' 6"	Subroom: File room (1)	Height: 8
8' 2"	128.00 SF Walls	48.96 SF Ceiling
	176.96 SF Walls & Ceiling	48.96 SF Floor
File room (1)	5.44 SY Flooring	16.00 LF Floor Perimeter
7' 10"	16.00 LF Ceil. Perimeter	
Missing Wall	6' 3" X 8'	Opens into FRONT_DESK2
Missing Wall	6' 3" X 8'	Opens into FILE_ROOM2
DESCRIPTION	QUANTITY UNIT PRICE T	TAX O&P RCV DEPREC. ACV



S_5_ANDERSON-EYE-1

UCS

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - File room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
68. Outlet or switch - Detach & reset	13.00 EA	16.28	0.00	42.32	253.96	(0.00)	253.96
69. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA	13.33	0.00	5.34	32.00	(0.00)	32.00
Begin Drywall Repairs							
Removal							
70. Mask and prep for paint - plastic, paper, tape (per LF)	130.83 LF	1.44	3.44	38.36	230.20	(76.73)	153.47
71. Tear out wet drywall, cleanup, bag - Cat 3	717.71 SF	1.25	11.20	181.66	1,090.00	(0.00)	1,090.00
Walls/Ceiling							
72. Tear out and bag wet insulation - Category 3 water	373.38 SF	1.06	2.18	79.60	477.56	(0.00)	477.56
Ceiling and Exterior Facing Wall							
Installation							
73. Apply anti-microbial agent to more than the walls and ceiling	947.08 SF	0.24	3.69	46.20	277.19	(0.00)	277.19
Application of antimicrobial to the water d	amaged space b	efore installation of	new drywall	and insulation.			
74. 5/8" drywall - hung, taped, ready for texture	229.38 SF	2.20	14.54	103.82	623.00	(20.76)	602.24
5/8 for the ceiling							
75. Blown-in insulation - 10" depth - R26	229.38 SF	1.08	17.67	53.08	318.48	(10.61)	307.87
Blown-in for the ceiling							
76. Batt insulation - 6" - R19 - unfaced batt	144.00 SF	1.00	9.97	30.80	184.77	(6.15)	178.62
77. 1/2" drywall - hung, taped, ready for texture	488.33 SF	2.10	29.04	210.90	1,265.43	(42.17)	1,223.26
78. Texture drywall - smooth / skim coat	229.38 SF	1.33	2.24	61.46	368.78	(12.28)	356.50
For the ceiling							
79. Clean the ceiling	229.38 SF	0.34	0.22	15.64	93.85	(0.00)	93.85
Ceiling/walls must be cleaned prior to appl	ication of paint	•					
80. Paint the ceiling - two coats	229.38 SF	1.00	5.37	46.96	281.71	(93.91)	187.80
81. Final cleaning - construction - Residential	458.75 SF		0.00	23.86	143.14	(0.00)	143.14
This final clean is for the drywall repair pro	ocess. Addition	al final clean line it	ems may be no	ecessary for ot	her repair pro	cesses.	
Begin Carpet Repairs							
Removal							
82. Tear out trim and bag for disposal - up to Cat 3	60.42 LF	0.86	1.06	10.62	63.64	(0.00)	63.64
83. Tear out baseboard and bag for disposal - up to Cat 3	60.42 LF	0.86	1.06	10.62	63.64	(0.00)	63.64

Page: 7

8/4/2022



United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - File room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
84. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	229.38 SF	1.35	1.34	62.20	373.20	(0.00)	373.20
85. Carpet	263.78 SF	3.27	69.70	186.46	1,118.72	(559.37)	559.35
86. Baseboard - 3 1/4"	60.42 LF	3.28	9.78	41.60	249.56	(8.32)	241.24
87. Paint baseboard - two coats	60.42 LF	1.49	0.82	18.16	109.01	(36.34)	72.67
To move contents back in.							

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: File room	183,32	1.269.66	7.617.84	866.64	6.751.20

Tfi	12' 6"
	6. I
2.4"	<u> </u>
12	Back exit
	3.5.
1	9:2:

222.50 SF Walls 110.00 SF Ceiling 332.50 SF Walls & Ceiling 110.00 SF Floor

12.22 SY Flooring33.33 LF Ceil. Perimeter

26.83 LF Floor Perimeter

Height: 8'

Missing Wall 9' 2" X 8'
Missing Wall - Goes to Floor 4' X 6' 8"
Door 2' 6" X 7'

Back exit

Opens into GLASSES_ROO2
Opens into KITCHEN2
Opens into Exterior

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
88. Outlet or switch - Detach & reset	6.00 EA	16.28	0.00	19.54	117.22	(0.00)	117.22
89. Cold air return cover - Detach & reset	1.50 EA	18.21	0.00	5.46	32.78	(0.00)	32.78
90. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA	88.02	0.00	17.60	105.62	(0.00)	105.62
91. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
Begin Drywall Repairs							
Removal							
92. Mask and prep for paint - plastic, paper, tape (per LF)	66.67 LF	1.44	1.76	19.56	117.32	(39.11)	78.21
93. Tear out wet drywall, cleanup, bag - Cat 3 Walls/Ceiling	332.50 SF	1.25	5.19	84.16	504.98	(0.00)	504.98

S_5_ANDERSON-EYE-1

8/4/2022 ' Page: 8



United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Back exit

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
94. Tear out and bag wet insulation - Category 3 water	286.00 SF	1.06	1.67	60.98	365.81	(0.00)	365.81
Walls/Ceiling							
Installation							100.51
95. Apply anti-microbial agent to more than the walls and ceiling	442.50 SF	0.24	1.73	21.58	129.51	(0.00)	129.51
Application of antimicrobial to the water d	amaged space b	efore installation of					
96. 5/8" drywall - hung, taped, ready for texture	110.00 SF	2.20	6.97	49.80	298.77	(9.96)	288.81
5/8 for the ceiling						(5.00)	1.47.66
97. Blown-in insulation - 10" depth - R26	110.00 SF	1.08	8.47	25.46	152.73	(5.08)	147.65
Blown-in for the ceiling							
98. Batt insulation - 6" - R19 - unfaced batt	176.00 SF	1.00	12.18	37.64	225.82	(7.54)	218.28
Allowance for exterior walls.							
99. 1/2" drywall - hung, taped, ready for texture	222.50 SF	2.10	13.23	96.10	576.58	(19.22)	557.36
100. Texture drywall - smooth / skim coat	110.00 SF	1.33	1.07	29.48	176.85	(5.90)	170.95
For the ceiling							
101. Clean the ceiling	110.00 SF	0.34	0.11	7.50	45.01	(0.00)	45.01
Ceiling/walls must be cleaned prior to app	lication of paint.						
102. Paint the ceiling - two coats	110.00 SF	1.00	2.57	22.52	135.09	(45.03)	90.06
103. Final cleaning - construction - Residential	220.00 SF	0.26	0.00	11.44	68.64	(0.00)	68.64
This final clean is for the drywall repair pr	ocess. Addition	al final clean line ite	ems may be ne	cessary for oth	er repair prod	cesses.	
Begin Carpet Repairs							
Removal							
104. Exterior door - metal - insulated - flush or panel style	1.00 EA		0.00	4.10	24.57	(0.00)	24.57
105. Tear out trim and bag for disposal - up to Cat 3	26.83 LF	0.86	0.47	4.72	28.26	(0.00)	28.20
106. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	1.20	7.21	(0.00)	7.21
107. Tear out baseboard and bag for disposal - up to Cat 3	26.83 LF		0.47	4.72	28.26	(0.00)	28.20
108. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	110.00 SF	1.35	0.64	29.82	178.96	(0.00)	178.90
109. Tear out wet carpet pad, cut/bag - Category 3 water	110.00 SF		0.64	16.18	97.12	(0.00)	97.12
Application of antimicrobial to the water of	lamaged space b	efore installation of	new drywall a	nd insulation.			
110. Carpet	126.50 SF	3.27	33.42	89.42	536.50	(268.26)	268.24
111. Baseboard - 3 1/4"	26.83 LF	3.28	4.34	18.46	110.80	(3.69)	107.11
5_ANDERSON-EYE-1						8/4/2022	Pag



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Back exit

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
112. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
113. Exterior door - metal - insulated - flush or panel style	1.00 EA	72.86	0.00	14.58	87.44	(4.36)	83.08
114. Paint baseboard - two coats	26.83 LF	1.49	0.37	8.08	48.43	(16.15)	32.28
115. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
116. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Back exit	108.59	752.74	4,516.16	460.31	4,055.85

Entrai	ıce						Height: 8'	
f	203.92 S	F Walls			111.11 SF	Ceiling		
Entrance	315.03 S	F Walls & Ce	iling	111.11 SF Floor				
	12.35 S	Y Flooring	_	26.83 LF Floor Perimeter				
7 2 4 8 7	31.83 L	F Ceil. Perim	eter					
Door	2' 6" 2	K 7'		Opens into	FILE_RO	OM2		
Door	2' 6" 2	K 7'		Opens into	Exterior			
Window	5' 3" 2	K 3'		Opens into	Exterior			
Missing Wall	10' 8"	X 8'		Opens into	FRONT_I	IALLW2		
DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV	
Accessories								
117. Light fixture - Detach & reset	1.00 EA	45.40	0.00	9.08	54.48	(0.00)	54.48	
118. Outlet or switch - Detach & reset	5.00 EA	16.28	0.00	16.28	97.68	(0.00)	97.68	
119. Cold air return cover - Detach & reset	1.00 EA	18.21	0.00	3.64	21.85	(0.00)	21.85	
Begin Drywall Repairs								
Removal								
120. Mask and prep for paint - plastic, paper, tape (per LF)	63.67 LF	1.44	1.68	18.68	112.04	(37.34)	74.70	
121. Tear out wet drywall, cleanup, bag - Cat 3	315.03 SF	1.25	4.91	79.74	478.44	(0.00)	478.44	
S_5_ANDERSON-EYE-1					8	8/4/2022	Page: 10	

CONTINUED - Entrance

Mails/Ceiling	RIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
12.1 Fear than and togget in sunantons 1.0	Ceiling							
		111.11 SF	1.06	0.65	23.70	142.13	(0.00)	142.13
123. Apply anti-microbial agent to more 426.14 SF 0.24 1.66 20.80 124.73 (0.00) than the walls and celling Application of antimicrobial to the water damaged space before installation of new drywall and insulation.	Ceiling							
12.5 Apply anniminate agent to more 12.5 Apply annimination 12.5			0.04	1.77	20.90	124 73	(0.00)	124.73
124. 5/8" drywall - hung, taped, ready for 111.11 SF 2.20 7.04 50.28 301.76 (10.06) texture 125. Blown-in insulation - 10" depth - R26 111.11 SF 1.08 8.56 25.72 154.28 (5.15)	e walls and ceiling					124.73	(0.00)	124.73
124. 178 diyear Finding, taped, ready for 111.11 SF 1.08 8.56 25.72 154.28 (5.15)						201.76	(10.06)	291.70
125. Blown-in insulation - 10" depth - R26 111.11 SF 1.08 8.56 25.72 154.28 (5.15)	= :	111.11 SF	2.20	7.04	50.28	301.76	(10.00)	291.70
12.5 Stawline in Institution 1.00 EA 17.92 1.00 1.20	the ceiling						(= . =)	140.13
126. Clean stud wall 203.92 SF 0.74 0.40 30.26 181.56 (0.00) 127. Batt insulation - 6" - R19 - unfaced 203.92 SF 1.00 14.12 43.60 261.64 (8.73) batt 128. 1/2" drywall - hung, taped, ready for 203.92 SF 2.10 12.13 88.06 528.42 (17.61) texture 129. Texture drywall - smooth / skim coat 111.11 SF 1.33 1.08 29.78 178.64 (5.97) For the ceiling 110.11 SF 0.34 0.11 7.58 45.47 (0.00) Ceiling/walls must be cleaned prior to application of paint. 131. Paint the ceiling - two coats 111.11 SF 1.00 2.60 22.74 136.45 (45.49) 132. Final cleaning - construction - 222.22 SF 0.26 0.00 11.56 69.34 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) up to Cat 3 135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 32"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 32"to36"wide - paint grade 137. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	Blown-in insulation - 10" depth - R26	111.11 SF	1.08	8.56	25.72	154.28	(5.15)	149.13
12. 12. 12. 12. 13. 12. 13. 13. 13. 14.	-in for the ceiling							101.56
batt batt batt batt batt batt batt batt	Clean stud wall	203.92 SF	0.74				•	181.56
texture texture 129. Texture drywall - smooth / skim coat 111.11 SF 1.33 1.08 29.78 178.64 (5.97) For the ceiling 130. Clean the ceiling 111.11 SF 0.34 0.11 7.58 45.47 (0.00) Ceiling/walls must be cleaned prior to application of paint. 131. Paint the ceiling - two coats 111.11 SF 1.00 2.60 22.74 136.45 (45.49) 132. Final cleaning - construction - 222.22 SF 0.26 0.00 11.56 69.34 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) up to Cat 3 135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 32"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) disposal - up to Cat 3 137. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	Batt insulation - 6" - R19 - unfaced	203.92 SF	1.00	14.12	43.60	261.64		252.91
130. Clean the ceiling 130. Clean the ceiling 131. Paint the ceiling 131. Paint the ceiling - two coats 132. Final cleaning - construction - 222.22 SF 10.26 10.00 11.50 11.50	·	203.92 SF	2.10	12.13	88.06	528.42	•	510.81
130. Clean the ceiling 111.11 SF 0.34 0.11 7.58 45.47 (0.00) Ceiling/walls must be cleaned prior to application of paint. 131. Paint the ceiling - two coats 111.11 SF 1.00 2.60 22.74 136.45 (45.49) 132. Final cleaning - construction - 222.22 SF 0.26 0.00 11.56 69.34 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Removal 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 137. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 138. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) 139. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) 130. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 130. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 130. Tear out wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	Texture drywall - smooth / skim coat	111.11 SF	1.33	1.08	29.78	178.64	(5.97)	172.67
Ceiling/walls must be cleaned prior to application of paint. 131. Paint the ceiling - two coats 111.11 SF 1.00 2.60 22.74 136.45 (45.49) 132. Final cleaning - construction - 222.22 SF 0.26 0.00 11.56 69.34 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 132 "to36" wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) disposal - up to Cat 3 137. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) cut/bag - Cat 3 water 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36" wide - paint grade 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	e ceiling							
131. Paint the ceiling - two coats 111.11 SF 1.00 2.60 22.74 136.45 (45.49) 132. Final cleaning - construction - 222.22 SF 0.26 0.00 11.56 69.34 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) up to Cat 3 135. Door opening (jamb & casing) - 32"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 139. Tear out wet non-salv. gluedn. cpt, cpt, cut yluedn. cpt, cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	Clean the ceiling	111.11 SF	0.34	0.11	7.58	45.47	(0.00)	45.47
131. Paint the Ceining - two coars 132. Final cleaning - construction - 222.22 SF 0.26 0.00 11.56 69.34 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs Removal 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) up to Cat 3 135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 32"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) disposal - up to Cat 3 137. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	g/walls must be cleaned prior to applic	ation of paint.						
Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Removal 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) up to Cat 3 15. Door opening (jamb & casing) - 1.00 EA 16. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 22"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) disposal - up to Cat 3 137. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	Paint the ceiling - two coats	111.11 SF	1.00	2.60	22.74	136.45	(45.49)	90.96
Removal 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 120 12	Final cleaning - construction -	222.22 SF	0.26	0.00	11.56	69.34	(0.00)	69.34
Removal 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 120 32"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 137. Tear out wet non-salv. gluedn. cpt, cpt, consider a line of the consideration of the	nal clean is for the drywall repair proc	ess. Addition	al final clean line ite	ems may be ne	cessary for oth	er repair prod	cesses.	
Removal 133. Interior door unit 1.00 EA 17.92 0.00 3.58 21.50 (0.00) 134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 120 32"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) 137. Tear out wet non-salv. gluedn. cpt, cpt, consider a line of the consideration of the	·							
134. Tear out trim and bag for disposal - 26.83 LF 0.86 0.47 4.72 28.26 (0.00) up to Cat 3 135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 32"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) disposal - up to Cat 3 137. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	•							
up to Cat 3 135. Door opening (jamb & casing) - 1.00 EA 1.00 EA	nterior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
135. Door opening (jamb & casing) - 1.00 EA 6.01 0.00 1.20 7.21 (0.00) 32"to36"wide - paint grade 136. Tear out baseboard and bag for 26.83 LF 0.86 0.47 4.72 28.26 (0.00) disposal - up to Cat 3 137. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)		26.83 LF	0.86	0.47	4.72	28.26	(0.00)	28.26
disposal - up to Cat 3 137. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	Door opening (jamb & casing) -	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
137. Tear out wet non-salv. gluedn. cpt, 111.11 SF 1.35 0.65 30.14 180.79 (0.00) cut/bag - Cat 3 water 138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 1.00 EA 48.59 0.00 9.72 58.31 (2.91)		26.83 LF	0.86	0.47	4.72	28.26	(0.00)	28.26
138. Carpet 127.78 SF 3.27 33.76 90.32 541.92 (270.96) 139. Baseboard - 3 1/4" 26.83 LF 3.28 4.34 18.46 110.80 (3.69) 140. Door opening (jamb & casing) - 32"to36"wide - paint grade 1.00 EA 165.62 12.03 35.52 213.17 (7.10) 32"to36"wide - paint grade 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	Fear out wet non-salv. gluedn. cpt,	111.11 SF	1.35	0.65	30.14	180.79		180.79
140. Door opening (jamb & casing) - 32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	=	127.78 SF	3.27	33.76	90.32	541.92	•	270.96
32"to36"wide - paint grade 141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)	*	26.83 LF	3.28	4.34	18.46	110.80		107.11
141. Interior door unit 1.00 EA 48.59 0.00 9.72 58.31 (2.91)		1.00 EA	165.62	12.03	35.52	213.17		206.07
5 ANDERSON_EVE_1 \$/4/2022	• •	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
D_VIADEVPON-F I F-I	NDERSON-EYE-I					;	8/4/2022	Page: 11



United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Entrance


DESCRIPTION	QUANTITY UN	IIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
142. Paint baseboard - two coats	26.83 LF	1.49	0.37	8.08	48.43	(16.15)	32.28
143. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
144. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Entrance	108.29	702.42	4,214.28	460.07	3,754,21



Utility room

235.83 SF Walls 296.73 SF Walls & Ceiling

6.77 SY Flooring

31.67 LF Ceil. Perimeter

Height: 8'

60.90 SF Ceiling 60.90 SF Floor

29.17 LF Floor Perimeter

2' 6" X 7' Opens into SIDE_HALLWA2

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Begin Drywall Repairs							
Removal							
145. Mask and prep for paint - plastic, paper, tape (per LF)	63.33 LF	1.44	1.67	18.58	111.45	(37.16)	74.29
146. Tear out wet drywall, cleanup, bag - Cat 3	296.73 SF	1.25	4.63	75.10	450.64	(0.00)	450.64
Walls/Ceiling							
147. Tear out and bag wet insulation - Category 3 water	296.73 SF	1.06	1.74	63.24	379.51	(0.00)	379.51
Walls/Ceiling							
Installation							
148. Apply anti-microbial agent to more than the walls and ceiling	357.62 SF	0.24	1.39	17.44	104.66	(0.00)	104.66
Application of antimicrobial to the water da	maged space before	installation of	new drywall a	nd insulation.			
149. 5/8" drywall - hung, taped, ready for texture	60.90 SF	2.20	3.86	27.58	165.42	(5.52)	159.90
5/8 for the ceiling							
150. Blown-in insulation - 10" depth - R26	60.90 SF	1.08	4.69	14.10	84.56	(2.81)	81.75
_5_ANDERSON-EYE-1					8	3/4/2022	Page: 12



Phone: (800) 827-8279 Fax: (800) 786-8884


CONTINUED - Utility room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Blown-in for the ceiling			<u></u>				
151. 1/2" drywall - hung, taped, ready for texture	235.83 SF	2.10	14.03	101.84	611.11	(20.38)	590.73
152. Texture drywall - smooth / skim coat	60.90 SF	1.33	0.59	16.32	97.91	(3.26)	94.65
For the ceiling							
153. Clean the ceiling	60.90 SF	0.34	0.06	4.16	24.93	(0.00)	24.93
Ceiling/walls must be cleaned prior to appl	ication of paint						
154. Paint the ceiling - two coats	60.90 SF	1.00	1.43	12.46	74.79	(24.94)	49.85
155. Final cleaning - construction - Residential	121.79 SF	0.26	0.00	6.34	38.01	(0.00)	38.01
This final clean is for the drywall repair pro	cess. Addition	al final clean line ite	ems may be ne	cessary for otl	ner repair proc	esses.	
Begin Carpet Repairs							
Removal							
156. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
157. Tear out trim and bag for disposal - up to Cat 3	29.17 LF	0.86	0.51	5.12	30.72	(0.00)	30.72
158. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
159. Tear out baseboard and bag for disposal - up to Cat 3	29.17 LF	0.86	0.51	5.12	30.72	(0.00)	30.72
160. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	60.90 SF	1.35	0.36	16.52	99.10	(0.00)	99.10
161. Carpet	70.03 SF	3.27	18.50	49.50	297.00	(148.51)	148.49
162. Baseboard - 3 1/4"	29.17 LF	3.28	4.72	20.08	120.48	(4.01)	116.47
163. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
164. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
165. Paint baseboard - two coats	29.17 LF	1.49	0.40	8.78	52.64	(17.54)	35.10
166. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
167. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51
To move contents back in.							
This final clean is for the drywall repair pro	ocess. Addition	nal final clean line it	ems may be ne	ecessary for ot	her repair pro	cesses.	
Installation							
Totals: Utility room			72.38	526.76	3,160.56	303.05	2,857.51



Phone: (800) 827-8279 Fax: (800) 786-8884

Bathroom



162.50 SF Walls 193.06 SF Walls & Ceiling 3.40 SY Flooring

22.50 LF Ceil. Perimeter

30.56 SF Ceiling 30.56 SF Floor 20.00 LF Floor Perimeter

Opens into KITCHEN2

Height: 8'

Door 2' 6" X 7'

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
168. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
169. Toilet - Detach & reset	1.00 EA	207.76	0.73	41.70	250.19	(0.00)	250.19
170. Outlet or switch - Detach & reset	2.00 EA	16.28	0.00	6.52	39.08	(0.00)	39.08
Begin Drywall Repairs						, ,	
Removal							
171. Mask and prep for paint - plastic, paper, tape (per LF)	45.00 LF	1.44	1.18	13.20	79.18	(26.39)	52.79
172. Tear out wet drywall, cleanup, bag - Cat 3	193.06 SF	1.25	3.01	48.86	293.20	(0.00)	293.20
Walls/Ceiling							
173. Tear out and bag wet insulation - Category 3 water	30.56 SF	1.06	0.18	6.52	39.09	(0.00)	39.09
Walls/Ceiling							
Installation 174. Apply anti-microbial agent to more	223.61 SF	0.24	0.87	10.92	65.46	(0.00)	65.46
than the walls and ceiling	223.01 SF	0.24	0.67	10.92	03.40	(0.00)	03.40
Application of antimicrobial to the water da	maged space be	efore installation of	new drywall a	nd insulation.			
175. 5/8" drywall - hung, taped, ready for texture	30.56 SF	2.20	1.94	13.82	82.99	(2.76)	80.23
5/8 for the ceiling							
176. Blown-in insulation - 10" depth - R26	30.56 SF	1.08	2.35	7.08	42.43	(1.42)	41.01
Blown-in for the ceiling							
177. Clean stud wall	162.50 SF	0.74	0.32	24.12	144.69	(0.00)	144.69
178. 1/2" drywall - hung, taped, ready for texture	162.50 SF	2.10	9.67	70.20	421.12	(14.04)	407.08
179. Texture drywall - smooth / skim coat	30.56 SF	1.33	0.30	8.18	49.12	(1.64)	47.48
For the ceiling						, ,	
180. Clean the ceiling	30.56 SF	0.34	0.03	2.08	12.50	(0.00)	12.50
Ceiling/walls must be cleaned prior to appli	cation of paint.					` ,	
181. Paint the ceiling - two coats	30.56 SF	1.00	0.71	6.26	37.53	(12.51)	25.02
182. Final cleaning - construction - Residential	91.67 SF	0.26	0.00	4.76	28.59	(0.00)	28.59

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Begin Sink Repair

Removal

S_5_ANDERSON-EYE-1

8/4/2022

Page: 14



United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Bathroom

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
183. Sink - wall mounted	1.00 EA	35.83	0.00	7.16	42.99	(0.00)	42.99
Installation							
184. Sink - single	1.00 EA	91.87	0.00	18.38	110.25	(11.03)	99.22
Begin Carpet Repairs							
Removal							
185. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
186. Tear out trim and bag for disposal - up to Cat 3	20.00 LF	0.86	0.35	3.52	21.07	(0.00)	21.07
187. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
188. Tear out baseboard and bag for disposal - up to Cat 3	20.00 LF	0.86	0.35	3.52	21.07	(0.00)	21.07
189. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	30.56 SF	1.35	0.18	8.30	49.74	(0.00)	49.74
190. Carpet	35.14 SF	3.27	9.28	24.84	149.03	(74.52)	74.51
191. Baseboard - 3 1/4"	20.00 LF	3.28	3.24	13.76	82.60	(2.76)	79.84
192. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
193. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
194. Paint baseboard - two coats	20.00 LF	1.49	0.27	6.02	36.09	(12.02)	24.07
195. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
196. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Bathroom	48.25	416.86	2,500.91	198.01	2,302.90
rotais. Datin com			•		

S_5_ANDERSON-EYE-1 8/4/2022 Page: 15



S_5_ANDERSON-EYE-1

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

	•								
₩orks	hop						Height: 8'		
### ### ### ##########################	574.2	3 SF Walls 1 SF Walls & Co	eiling		186.38 SF 186.38 SF	Floor			
ok close 1 % 11.7"		7 LF Ceil. Perim	neter	50.17 LF Floor Perimeter					
Door	2'	6" X 7'		Opens int	o BOOK_C	LOSET			
Window	3'	1" X 3'		Opens int	o Exterior				
Window	3'	1" X 3'		Opens int	o Exterior				
Door	2'	6" X 7'		Opens int	o BOSS_OF	FFICE2			
DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV		
Accessories									
197. Outlet or switch - Detach & reset	16.00 EA	16.28	0.00	52.10	312.58	(0.00)	312.58		
198. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99		
199. Fluorescent light fixture - 6' & 8' - Detach & reset	4.00 EA	88.02	0.00	70.42	422.50	(0.00)	422.50		
200. Cold air return cover - Detach & reset	1.00 EA	18.21	0.00	3.64	21.85	(0.00)	21.85		
Begin Drywall Repairs									
Removal 201. Mask and prep for paint - plastic, paper, tape (per LF)	110.33 LF	1.44	2.90	32.36	194.14	(64.71)	129.43		
202. Floor protection - plastic and tape -	186.38 SF	0.32	2.18	12.36	74.18	(24.73)	49.45		
203. Shelving - 24" - in place	84.00 LF	0.58	0.00	9.74	58.46	(0.00)	58.46		
204. Tear out wet drywall, cleanup, bag - Cat 3	574.21 SF	1.25	8.96	145.36	872.08	(0.00)	872.08		
Walls/Ceiling 205. Tear out and bag wet insulation - Category 3 water	128.00 SF	1.06	0.75	27.30	163.73	(0.00)	163.73		
Exterior Wall									
Installation									
206. Apply anti-microbial agent to more than the walls and ceiling	760.58 SF	0.24	2.97	37.10	222.61	(0.00)	222.61		
Application of antimicrobial to the water da	maged space be		new drywall a	and insulation.					
207. 5/8" drywall - hung, taped, ready for texture	186.38 SF	2.20	11.81	84.36	506.21	(16.88)	489.33		
5/8 for the ceiling	107 30 05	1.00	11.00	40.4	050 70	/0.541			
208. Blown-in insulation - 10" depth - R26 Blown-in for the ceiling	186.38 SF	1.08	14.36	43.14	258.79	(8.63)	250.16		
209. Clean stud wall	387.83 SF	0.74	0.76	57.56	2/5 21	(0.00)	245 21		
210. Batt insulation - 6" - R19 - unfaced	128.00 SF	1.00	8.86	27.38	345.31 164.24	(0.00) (5.49)	345.31 158.75		
batt 211. 1/2" drywall - hung, taped, ready for	387.83 SF	2.10	23.07	167.50	1,005.01	(33.50)	971.51		
texture	22.,000		_5.07	.07.00	1,000.01	(55.50)	,,1.31		

Page: 16

8/4/2022



S_5_ANDERSON-EYE-1

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Workshop

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
212. Shelving - 24" - in place	84.00 LF	5.58	0.00	93.74	562.46	(18.74)	543.72
213. Texture drywall - smooth / skim coat	186.38 SF	1.33	1.82	49.94	299.65	(9.98)	289.67
For the ceiling							
214. Clean the ceiling	186.38 SF	0.34	0.18	12.72	76.27	(0.00)	76.27
Ceiling/walls must be cleaned prior to apple	ication of paint	•					
215. Paint the ceiling - two coats	186.38 SF	1.00	4.36	38.16	228.90	(76.30)	152.60
216. Final cleaning - construction - Residential	559.13 SF	0.26	0.00	29.08	174.45	(0.00)	174.45
This final clean is for the drywall repair pro	cess. Addition	al final clean line it	ems may be ne	cessary for ot	her repair proc	cesses.	
Begin Cabinetry Repair							
Removal							
217. Sink faucet - Kitchen	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
218. P-trap assembly - ABS (plastic)	1.00 EA	7.16	0.00	1.44	8.60	(0.00)	8.60
219. Sink - single	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
220. 6" backsplash for flat laid countertop	16.00 LF	0.86	0.00	2.76	16.52	(0.00)	16.52
221. Countertop - flat laid plastic laminate	16.00 LF	4.12	0.00	13.18	79.10	(0.00)	79.10
222. Cabinetry - lower (base) units	16.00 LF	7.17	0.00	22.94	137.66	(0.00)	137.66
223. Cabinetry - upper (wall) units	7.00 LF	7.17	0.00	10.04	60.23	(0.00)	60.23
Installation							
224. Cabinetry - lower (base) units	16.00 LF	222.16	295.42	770.00	4,619.98	(462.00)	4,157.98
225. Countertop - flat laid plastic laminate	16.00 LF	40.57	45.65	138.96	833.73	(277.91)	555.82
226. 6" backsplash for flat laid countertop	16.00 LF	10.62	12.60	36.50	219.02	(73.00)	146.02
227. Sink - single	1.00 EA	91.87	0.00	18.38	110.25	(11.03)	99.22
228. P-trap assembly - ABS (plastic)	1.00 EA	45.94	0.00	9.18	55.12	(11.03)	44.09
229. Cabinetry - upper (wall) units	7.00 LF	32.79	0.00	45.90	275.43	(27.53)	247.90
This final clean is for the drywall repair pro	ocess. Addition	ial final clean line it	ems may be no	ecessary for ot	her repair pro	cesses.	
Begin Carpet/Vinyl Floor Repairs							
Removal							
230. Tear out trim and bag for disposal - up to Cat 3	50.17 LF	0.86	0.88	8.82	52.85	(0.00)	52.85
231. Interior door unit	2.00 EA	17.92	0.00	7.16	43.00	(0.00)	43.00
232. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	6.01	0.00	2.40	14.42	(0.00)	14.42
233. Tear out baseboard and bag for disposal - up to Cat 3	50.17 LF	0.86	0.88	8.82	52.85	(0.00)	52.85
234. Tear out non-salv vinyl, cut & bag - Category 3 water	98.00 SF		0.57	36.78	220.61	(0.00)	220.61
235. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	186.38 SF		1.09	50.54	303.24	(0.00)	303.24
236. Carpet	214.33 SF	3.27	56.63	151.50	908.99	(454.51)	454.48

8/4/2022

Page: 17



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Workshop


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
237. Vinyl floor covering (sheet goods)	98.00 SF	2.89	19.49	60.54	363.25	(36.33)	326.92
238. Baseboard - 3 1/4"	50.17 LF	3.28	8.12	34.54	207.22	(6.92)	200.30
239. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	165.62	24.06	71.06	426.36	(14.20)	412.16
240. Interior door unit	2.00 EA	48.59	0.00	19.44	116.62	(5.84)	110.78
241. Paint door slab only - 2 coats (per side)	2.00 EA	38.60	1.57	15.76	94.53	(31.51)	63.02
242. Paint baseboard - two coats	50.17 LF	1.49	0.68	15.10	90.53	(30.19)	60.34
243. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA	32.40	0.95	13.16	78.91	(26.30)	52.61

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Workshop 551.57 2,568.68 15,411.43 1,727.26 13,684.17



Bathroom 2

222.83 SF Walls279.75 SF Walls & Ceiling6.32 SY Flooring

30.04 LF Ceil. Perimeter

Height: 8'

56.91 SF Ceiling 56.91 SF Floor

27.54 LF Floor Perimeter

Door 2' 6" X 7' Opens into SIDE_HALLWA2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
244. Handicap grab bar - Detach & reset	0.50 EA	30.21	0.00	3.02	18.13	(0.00)	18.13
245. Soap/hand sanitizer dispenser - wall mounted	1.00 EA	13.76	0.00	2.76	16.52	(0.00)	16.52
246. Paper towel dispenser	1.00 EA	14.34	0.00	2.86	17.20	(0.00)	17.20
Remove							
247. Paper towel dispenser	1.00 EA	18.88	0.00	3.78	22.66	(5.66)	17.00
Install							
248. Outlet or switch - Detach & reset	2.00 EA	16.28	0.00	6.52	39.08	(0.00)	39.08
249. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
250. Toilet - Detach & reset	1.00 EA	207.76	0.73	41.70	250.19	(0.00)	250.19
5_ANDERSON-EYE-1					8	Page: 1	



CONTINUED - Bathroom 2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
251. Bathroom mirror - Detach & reset	15.00 SF	8.39	0.00	25.18	151.03	(0.00)	151.03
Begin Drywall Repairs							
Removal							
252. Mask and prep for paint - plastic, paper, tape (per LF)	60.08 LF	1.44	1.58	17.62	105.72	(35.25)	70.47
253. Tear out wet drywall, cleanup, bag - Cat 3	279.75 SF	1.25	4.36	70.82	424.87	(0.00)	424.87
Walls/Ceiling							
254. Tear out and bag wet insulation - Category 3 water	56.91 SF	1.06	0.33	12.12	72.77	(0.00)	72.77
Walls/Ceiling							
Installation							
255. Apply anti-microbial agent to more than the walls and ceiling	336.66 SF	0.24	1.31	16.42	98.53	(0.00)	98.53
Application of antimicrobial to the water da	maged space b						
256. Clean stud wall	502.58 SF	0.74	0.98	74.58	447.47	(0.00)	447.47
257. 5/8" drywall - hung, taped, ready for texture	56.91 SF	2.20	3.61	25.76	154.57	(5.15)	149.42
5/8 for the ceiling							
258. Blown-in insulation - 10" depth - R26	56.91 SF	1.08	4.38	13.18	79.02	(2.64)	76.38
Blown-in for the ceiling							
259. Batt insulation - 6" - R19 - unfaced batt	222.83 SF	1.00	15.43	47.64	285.90	(9.52)	276.38
260. 1/2" drywall - hung, taped, ready for texture	222.83 SF	2.10	13.25	96.24	577.43	(19.24)	558.19
261. Texture drywall - smooth / skim coat	56.91 SF	1.33	0.55	15.26	91.50	(3.04)	88.46
For the ceiling							
262. Clean the ceiling	56.91 SF	0.34	0.06	3.90	23.31	(0.00)	23.31
Ceiling/walls must be cleaned prior to appli	cation of paint.						
263. Paint the ceiling - two coats	56.91 SF	1.00	1.33	11.64	69.88	(23.29)	46.59
264. Final cleaning - construction - Residential	170.74 SF	0.26	0.00	8.88	53.27	(0.00)	53.27
This final clean is for the drywall repair pro	cess. Addition	al final clean line it	ems may be ne	cessary for oth	er repair prod	cesses.	
Begin Sink Repair							
Removal							
265. Sink - wall mounted	1.00 EA	35.83	0.00	7.16	42.99	(0.00)	42.99
Installation							
266. Sink - single	1.00 EA	91.87	0.00	18.38	110.25	(11.03)	99.22
Begin Tile Repairs							
Removal							
267. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
5_ANDERSON-EYE-1					:	8/4/2022	Page:



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Bathroom 2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
268. Tear out trim and bag for disposal - up to Cat 3	27.54 LF	0.86	0.48	4.84	29.00	(0.00)	29.00
269. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
270. Tear out baseboard and bag for disposal - up to Cat 3	27.54 LF	0.86	0.48	4.84	29.00	(0.00)	29.00
271. Tear out non-salvageable tile floor & bag - Cat 3 water	56.91 SF	4.86	1.05	55.54	333.17	(0.00)	333.17
Application of antimicrobial to the water da	amaged space b	efore installation o	f new drywall a	and insulation.			
272. Tile floor covering	56.91 SF	8.73	26.80	104.72	628.34	(31.42)	596.92
273. Baseboard - 3 1/4"	27.54 LF	3.28	4.46	18.96	113.75	(3.80)	109.95
274. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
275. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
276. Paint baseboard - two coats	27.54 LF	1.49	0.38	8.28	49.69	(16.57)	33.12
277. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
278. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51
To move contents back in.							
This final clean is for the drywall repair pro	ocess. Addition	al final clean line i	tems may be no	ecessary for oth	er repair proc	cesses.	

Installation

Totals: Bathroom 2	94.84	789.74	4.738.14	205.53	4.532.61

S_5_ANDERSON-EYE-1 8/4/2022 Page: 20



freak room	Side hallway	Height: 8'				
Se ility roon =	669.57 SF Walls	232.33 SF Ceiling				
A Manual Parish	901.89 SF Walls & Ceiling	232.33 SF Floor				
halfing	25.81 SY Flooring	80.89 LF Floor Perimeter				
Patient room to	103.31 LF Ceil. Perimeter					
Exam room 2 Missing Wall	4' 7 1/16" X 8'	Opens into FRONT_HALLW2				
Door	2' 5" X 7'	Opens into PATIENT_ROO2				
Door	2' 6" X 7'	Opens into EXAM_ROOM_2				
Door	2' 6" X 7'	Opens into EXAM_ROOM_1				
Door	2' 6" X 7'	Opens into LIBRARY2				
Door	2' 6" X 7'	Opens into LIBRARY2				
Door	2' 6" X 7'	Opens into Exterior				
Door	2' 6" X 7'	Opens into BREAK_ROOM2				
Door	2' 6" X 7'	Opens into UTILITY_ROO2				
Door	2' 6" X 7'	Opens into BATHROOM_2				
11 14	Subroom: Side hallway (1)	Height: 8'				
1' 6" 2 1' 5"	43.00 SF Walls	17.54 SF Ceiling				
	60.54 SF Walls & Ceiling	17.54 SF Floor				
Side hallway (1)	1.95 SY Flooring	4.75 LF Floor Perimeter				
5' 5"	9.75 LF Ceil. Perimeter					
Missing Wall	2' 4" X 8'	Opens into SIDE_HALLWA2				
Door	2' 6" X 7'	Opens into Exterior				

Missing Wall	2' 4" X 8'	Opens into SIDE_HALLWA2
Door	2' 6" X 7'	Opens into Exterior
Door	2' 6" X 7'	Opens into BOSS_OFFICE2
Missing Wall	5' 5" X 8'	Opens into CLOSET2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
279. Outlet or switch - Detach & reset	6,00 EA	16.28	0.00	19.54	117.22	(0.00)	117.22
280. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA	13.33	0.00	5.34	32.00	(0.00)	32.00
281. Smoke detector - Detach & reset	2.00 EA	43.96	0.00	17.58	105.50	(0.00)	105.50
282. Light fixture - Detach & reset	2.00 EA	45.40	0.00	18.16	108.96	(0.00)	108.96
283. Thermostat - Detach & reset	2.00 EA	44.58	0.00	17.84	107.00	(0.00)	107.00
Begin Drywall Repairs							
Removal 284. Mask and prep for paint - plastic,	226.12 LF	1.44	5.95	66.32	397.88	(132.62)	265.26
paper, tape (per LF) 285. Tear out wet drywall, cleanup, bag - Cat 3	962.44 SF	1.25	15.01	243.62	1,461.68	(0.00)	1,461.68
Walls/Ceiling							

S_5_ANDERSON-EYE-1

8/4/2022

Page: 21,



CONTINUED - Side hallway

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
286. Tear out and bag wet insulation - Category 3 water Walls/Ceiling	249.87 SF	1.06	1.46	53.28	319.60	(0.00)	319.60
Installation							
287. Apply anti-microbial agent to more than the walls and ceiling	1,212.30 SF	0.24	4.73	59.14	354.82	(0.00)	354.82
Application of antimicrobial to the water da	maged space b	efore installation of	f new drywall	and insulation			
288. 5/8" drywall - hung, taped, ready for texture	249.87 SF	2.20	15.84	113.10	678.65	(22.61)	656.04
5/8 for the ceiling							
289. Blown-in insulation - 10" depth - R26	249.87 SF	1.08	19.25	57.84	346.95	(11.56)	335.39
Blown-in for the ceiling							
290. Batt insulation - 6" - R19 - unfaced batt	712.57 SF	1.00	49.33	152.38	914.28	(30.47)	883.81
291. 1/2" drywall - hung, taped, ready for texture	712.57 SF	2.10	42.38	307.76	1,846.54	(61.55)	1,784.99
292. Texture drywall - smooth / skim coat	249.87 SF	1.33	2.44	66.94	401.71	(13.40)	388.31
For the ceiling							
293. Clean the ceiling	249.87 SF	0.34	0.24	17.04	102.24	(0.00)	102.24
Ceiling/walls must be cleaned prior to applie	cation of paint.						
294. Paint the ceiling - two coats	249.87 SF	1.00	5.85	51.16	306.88	(102.30)	204.58
295. Final cleaning - construction - Residential	749.61 SF	0.26	0.00	38.98	233.88	(0.00)	233.88
This final clean is for the drywall repair production	cess. Addition	al final clean line it	ems may be no	ecessary for ot	her repair proc	esses.	
Begin Cabinetry Repair							
Removal							
296. Cabinetry - upper (wall) units	14.00 LF	7.17	0.00	20.08	120.46	(0.00)	120.46
297. Cabinetry - lower (base) units	9.00 LF	7.17	0.00	12.90	77.43	(0.00)	77.43
298. Countertop - flat laid plastic laminate	9.00 LF	4.12	0.00	7.42	44.50	(0.00)	44.50
299. 6" backsplash for flat laid countertop	9.00 LF	0.86	0.00	1.54	9.28	(0.00)	9.28
Installation							
300. Cabinetry - lower (base) units	9.00 LF	222.16	166.17	433.12	2,598.73	(259.88)	2,338.85
301. Countertop - flat laid plastic laminate	9.00 LF	40.57	25.68	78.16	468.97	(156.33)	312.64
302. 6" backsplash for flat laid countertop	9.00 LF	10.62	7.09	20.54	123.21	(41.06)	82.15
303. Cabinetry - upper (wall) units	14.00 LF	147.41	156.46	444.04	2,664.24	(266.42)	2,397.82
This final clean is for the drywall repair prod	cess. Addition	al final clean line it	ems may be no	ecessary for ot	her repair proc	esses.	
Begin Carpet Repairs							
Removal							
304. Interior door unit	11.00 EA	17.92	0.00	39.42	236.54	(0.00)	236.54
305. Tear out trim and bag for disposal - up to Cat 3	85.64 LF	0.86	1.50	15.04	90.19	(0.00)	90.19
5_ANDERSON-EYE-1					8	3/4/2022	Page: 22



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Side hallway


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
306. Door opening (jamb & casing) - 32"to36"wide - paint grade	11.00 EA	6.01	0.00	13.22	79.33	(0.00)	79.33
307. Tear out baseboard and bag for disposal - up to Cat 3	85.64 LF	0.86	1.50	15.04	90.19	(0.00)	90.19
308. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	249.87 SF	1.35	1.46	67.76	406.54	(0.00)	406.54
309. Carpet	287.35 SF	3.27	75.93	203.10	1,218.66	(609.35)	609.31
310. Baseboard - 3 1/4"	85.64 LF	3.28	13.86	58.96	353.72	(11.78)	341.94
311. Door opening (jamb & casing) - 32"to36"wide - paint grade	11.00 EA	165.62	132.34	390.82	2,344.98	(78.16)	2,266.82
312. Interior door unit	11.00 EA	48.59	0.00	106.90	641.39	(32.06)	609.33
313. Paint baseboard - two coats	85.64 LF	1.49	1.17	25.76	154.53	(51.50)	103.03
314. Paint door/window trim & jamb - 2 coats (per side)	11.00 EA	32.40	5.23	72.32	433.95	(144.64)	289.31
315. Paint door slab only - 2 coats (per side)	11.00 EA	38.60	8.62	86.64	519.86	(173.28)	346.58

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Side hallway 759.49 3,418.80 20,512.49 2,198.97 18,313.52



Electric room

9.08 SF Walls 58.30 SF Ceiling

229.08 SF Walls 287.38 SF Walls & Ceiling 6.48 SY Flooring 30.82 LF Ceil. Perimeter

58.30 SF Floor 28.32 LF Floor Perimeter

Height: 8'

Door 2' 6" X 7' Opens into FRONT_HALLW2

DESCRIPTION	QUANTITY UN	HT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
316. Light fixture - Detach & reset	1.00 EA	45.40	0.00	9.08	54.48	(0.00)	54.48
317. Outlet or switch - Detach & reset	3.00 EA	16.28	0.00	9.76	58.60	(0.00)	58.60
318. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
319. Breaker panel - 200 amp	1.00 EA	140.43	0.00	28.08	168.51	(0.00)	168.51
Remove							
5 ANDERSON-EYE-1					8	Page: 23	



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Electric room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
320. Breaker panel - 200 amp	1.00 EA	822.69	0.00	164.54	987.23	(164.54)	822.69
Reset							
Begin Drywall Repairs							
Removal							
321. Mask and prep for paint - plastic, paper, tape (per LF)	61.65 LF	1.44	1.62	18.08	108.48	(36.15)	72.33
322. Tear out wet drywall, cleanup, bag - Cat 3	287.38 SF	1.25	4.48	72.74	436.45	(0.00)	436.45
Walls/Ceiling							
323. Tear out and bag wet insulation - Category 3 water	58.30 SF	1.06	0.34	12.42	74.56	(0.00)	74.56
Walls/Ceiling							
Installation							
324. Apply anti-microbial agent to more than the walls and ceiling	345.68 SF	0.24	1.35	16.88	101.19	(0.00)	101.19
Application of antimicrobial to the water da	maged space be	efore installation of	new drywall a	ind insulation.			
325. 5/8" drywall - hung, taped, ready for texture 5/8 for the ceiling	58.30 SF	2.20	3.70	26.40	158.36	(5.28)	153.08
326. Blown-in insulation - 10" depth - R26	58.30 SF	1.08	4.49	12.50	90.05	(2.71)	70.24
Blown-in for the ceiling	36.30 SF	1.00	4.49	13.50	80.95	(2.71)	78.24
327. Clean stud wall	229.08 SF	0.74	0.45	24.00	202.07	(0.00)	202.07
328. Batt insulation - 6" - R19 - unfaced	229.08 SF	1.00	0.45	34.00	203.97	(0.00)	203.97
batt	229.00 31	1.00	15.86	49.00	293.94	(9.81)	284.13
329. 1/2" drywall - hung, taped, ready for texture	229.08 SF	2.10	13.62	98.94	593.63	(19.79)	573.84
330. Texture drywall - smooth / skim coat	58.30 SF	1.33	0.57	15.62	93.73	(3.12)	90.61
For the ceiling							
331. Clean the ceiling	58.30 SF	0.34	0.06	3.98	23.86	(0.00)	23.86
Ceiling/walls must be cleaned prior to appli	cation of paint.						
332. Paint the ceiling - two coats	58.30 SF	1.00	1.36	11.94	71.60	(23.86)	47.74
333. Final cleaning - construction - Residential	116.60 SF	0.26	0.00	6.06	36.38	(0.00)	36.38
This final clean is for the drywall repair pro	cess. Addition	al final clean line ite	ems may be ne	cessary for oth	er repair proc	esses.	
Begin Carpet Repairs							
Removal							
334. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
335. Tear out trim and bag for disposal - up to Cat 3	28.32 LF	0.86	0.50	4.98	29.84	(0.00)	29.84
336. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Electric room


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
337. Tear out baseboard and bag for disposal - up to Cat 3	28.32 LF	0.86	0.50	4.98	29.84	(0.00)	29.84
338. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	58.30 SF	1.35	0.34	15.80	94.85	(0.00)	94.85
339. Carpet	67.04 SF	3.27	17.71	47.38	284.31	(142.17)	142.14
340. Baseboard - 3 1/4"	28.32 LF	3.28	4.58	19.50	116.97	(3.91)	113.06
341. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
342. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
343. Paint baseboard - two coats	28.32 LF	1.49	0.39	8.52	51.11	(17.04)	34.07
344. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
345. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Electric room	85.21	759.32	4,555.74	467.30	4,088.44



115.67	SF Walls
137.82	SF Walls & Ceiling
2.46	SY Flooring
18.83	LF Ceil. Perimeter

22.15	SF Ceiling
22.15	SF Floor
13.83	LF Floor Perimeter

Door	
Door	

2' 6" X 7' 2' 6" X 7' Opens into KITCHEN2
Opens into WORKSHOP

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories				2.24	10.54	(0.00)	19.54
346. Outlet or switch - Detach & reset	1.00 EA	16.28	0.00	3.26	19.54	(0.00)	
347. Light fixture - Detach & reset	1.00 EA	45.40	0.00	9.08	54.48	(0.00)	54.48
Begin Drywall Repairs							
Removal							
348. Mask and prep for paint - plastic, paper, tape (per LF)	37.67 LF	1.44	0.99	11.04	66.27	(22.09)	44.18

S_5_ANDERSON-EYE-1

8/4/2022

Page: 25

Height: 8'



CONTINUED - Book closet

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
349. Floor protection - plastic and tape - 10 mil	22.15 SF	0.32	0.26	1.48	8.83	(2.95)	5.88
350. Shelving - 24" - in place	24.00 LF	0.58	0.00	2.78	16.70	(0.00)	16.70
351. Tear out wet drywall, cleanup, bag - Cat 3	137.82 SF	1.25	2.15	34.90	209.33	(0.00)	209.3
Walls/Ceiling							
352. Tear out and bag wet insulation - Category 3 water	22.15 SF	1.06	0.13	4.72	28.33	(0.00)	28.3
Walls/Ceiling							
Installation 353. Apply anti-microbial agent to more than the walls and ceiling	159.97 SF	0.24	0.62	7.80	46.81	(0.00)	46.8
Application of antimicrobial to the water da	maged space b	efore installation of	new drywall a	nd insulation			
354. 5/8" drywall - hung, taped, ready for texture	22.15 SF	2.20	1.40	10.02	60.15	(2.01)	58.1
5/8 for the ceiling							
355. Blown-in insulation - 10" depth - R26	22.15 SF	1.08	1.71	5.12	30.75	(1.04)	29.7
Blown-in for the ceiling							
356. 1/2" drywall - hung, taped, ready for exture	115.67 SF	2.10	6.88	49.96	299.75	(9.99)	289.7
357. Texture drywall - smooth / skim coat	22.15 SF	1.33	0.22	5.94	35.62	(1.19)	34.4
For the ceiling							
358. Shelving - 24" - in place	13.83 LF	12.20	8.93	35.52	213.18	(7.10)	206.0
559. Clean the ceiling	22.15 SF	0.34	0.02	1.50	9.05	(0.00)	9.0
Ceiling/walls must be cleaned prior to appli	cation of paint.						
360. Paint the ceiling - two coats	22.15 SF	1.00	0.52	4.54	27.21	(9.07)	18.1
61. Final cleaning - construction - Residential	44.31 SF	0.26	0.00	2.30	13.82	(0.00)	13.8
This final clean is for the drywall repair pro-	cess. Addition:	al final clean line ite	ms may be nee	cessary for oth	er repair proc	esses.	
Begin Carpet Repairs							
Removal							
62. Interior door unit	2.00 EA	17.92	0.00	7.16	43.00	(0.00)	43.0
63. Tear out trim and bag for disposal - up to Cat 3	13.83 LF	0.86	0.24	2.42	14.55	(0.00)	14.5
64. Door opening (jamb & casing) - 2"to36"wide - paint grade	2.00 EA	6.01	0.00	2.40	14.42	(0.00)	14.4
65. Tear out baseboard and bag for isposal - up to Cat 3	13.83 LF	0.86	0.24	2.42	14.55	(0.00)	14.5
666. Tear out wet non-salv. gluedn. cpt, out/bag - Cat 3 water	22.15 SF	1.35	0.13	6.00	36.03	(0.00)	36.0
667. Carpet	25.48 SF	3.27	6.73	18.00	108.05	(54.03)	54.0
368. Baseboard - 3 1/4"	13.83 LF	3.28	2.24	9.52	57.12	(1.90)	55.2
5 ANDERSON-EYE-1					5	3/4/2022	Page



United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Book closet


DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
369. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	165.62	24.06	71.06	426.36	(14.20)	412.16
370. Interior door unit	2.00 EA	48.59	0.00	19.44	116.62	(5.84)	110.78
371. Paint baseboard - two coats	13.83 LF	1.49	0.19	4.16	24.96	(8.31)	16.65
372. Paint door/window trim & jamb - 2	2.00 EA	32.40	0.95	13.16	78.91	(26.30)	52.61
coats (per side) 373. Paint door slab only - 2 coats (per side)	2.00 EA	38.60	1.57	15.76	94.53	(31.51)	63.02

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Book closet	60.18	361.46	2,168.92	197.53	1,971.39



Paper room

269.08 SF Walls

349.24 SF Walls & Ceiling

8.91 SY Flooring

35.82 LF Ceil. Perimeter

Height: 8'

80.16 SF Ceiling 80.16 SF Floor

33.32 LF Floor Perimeter

Door

2' 6" X 7'

Opens into FRONT_HALLW2

QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
5.00 EA	16.28	0.00	16.28	97.68	(0.00)	97.68
1.00 EA	88.02	0.00	17.60	105.62	(0.00)	105.62
1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
71.65 LF	1.44	1.89	21.02	126.09	(42.02)	84.07
80.16 SF	0.32	0.94	5.32	31.91	(10.64)	21.27
349.24 SF	1.25	5.45	88.42	530.42	(0.00)	530.42
	5.00 EA 1.00 EA 1.00 EA 71.65 LF 80.16 SF	1.00 EA 88.02 1.00 EA 13.33 71.65 LF 1.44 80.16 SF 0.32	5.00 EA 16.28 0.00 1.00 EA 88.02 0.00 1.00 EA 13.33 0.00 71.65 LF 1.44 1.89 80.16 SF 0.32 0.94	5.00 EA 16.28 0.00 16.28 1.00 EA 88.02 0.00 17.60 1.00 EA 13.33 0.00 2.66 71.65 LF 1.44 1.89 21.02 80.16 SF 0.32 0.94 5.32	5.00 EA 16.28 0.00 16.28 97.68 1.00 EA 88.02 0.00 17.60 105.62 1.00 EA 13.33 0.00 2.66 15.99 71.65 LF 1.44 1.89 21.02 126.09 80.16 SF 0.32 0.94 5.32 31.91	5.00 EA 16.28 0.00 16.28 97.68 (0.00) 1.00 EA 88.02 0.00 17.60 105.62 (0.00) 1.00 EA 13.33 0.00 2.66 15.99 (0.00) 71.65 LF 1.44 1.89 21.02 126.09 (42.02) 80.16 SF 0.32 0.94 5.32 31.91 (10.64)

S_5_ANDERSON-EYE-1

8/4/2022

Page: 27



CONTINUED - Paper room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
380. Tear out and bag wet insulation - Category 3 water Walls/Ceiling	80.16 SF	1.06	0.47	17.10	102.54	(0.00)	102.54
Installation							
381. Apply anti-microbial agent to more than the walls and ceiling	429.40 SF	0.24	1.68	20.96	125.70	(0.00)	125.70
Application of antimicrobial to the water da	maged space be	efore installation of	new drywall a	nd insulation.			
382. 5/8" drywall - hung, taped, ready for texture	80.16 SF	2.20	5.08	36.30	217.73	(7.27)	210.46
5/8 for the ceiling							
383. Blown-in insulation - 10" depth - R26	80.16 SF	1.08	6.17	18.56	111.30	(3.72)	107.58
Blown-in for the ceiling							
384. Clean stud wall	269.08 SF	0.74	0.52	39.92	239.56	(0.00)	239.56
385. 1/2" drywall - hung, taped, ready for texture	269.08 SF	2.10	16.00	116.22	697.29	(23.25)	674.04
386. Texture drywall - smooth / skim coat For the ceiling	80.16 SF	1.33	0.78	21.48	128.87	(4.30)	124.57
387. Clean the ceiling	80.16 SF	0.34	0.08	5.48	32.81	(0.00)	32.81
Ceiling/walls must be cleaned prior to appli	cation of paint.					(0.00)	52.01
388. Paint the ceiling - two coats	80.16 SF	1.00	1.88	16.42	98.46	(32.83)	65.63
389. Final cleaning - construction - Residential	160.32 SF	0.26	0.00	8.34	50.02	(0.00)	50.02
This final clean is for the drywall repair pro-	cess. Additiona	al final clean line ite	ms may be ne	cessary for oth	er repair proc	esses.	
Begin Carpet Repairs			•	•	• •		
Removal							
390. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
391. Tear out trim and bag for disposal - up to Cat 3	33.32 LF	0.86	0.59	5.86	35.11	(0.00)	35.11
392. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
393. Tear out baseboard and bag for disposal - up to Cat 3	33.32 LF	0.86	0.59	5.86	35.11	(0.00)	35.11
394. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	80.16 SF	1.35	0.47	21.74	130.43	(0.00)	130.43
395. Carpet	92.18 SF	3.27	24.36	65.16	390.95	(195.48)	195.47
396. Baseboard - 3 1/4"	33.32 LF	3.28	5.39	22.94	137.62	(4.58)	133.04
397. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
398. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
399. Paint baseboard - two coats	33.32 LF	1.49	0.45	10.04	60.14	(20.04)	40.10
400. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
5 ANDERSON-EYE-1					c	3/4/2022	Page: 28



United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884


CONTINUED - Paper room

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
401. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51
To move contents back in.							
m, a, , , , a, , , , , , , , , , , , , ,	4.4.4141	l . l lima it		account for other	e rangir nroc	200000	

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

86.08 648.16 3,888.26 383.05 3,505.21 Totals: Paper room



Bathroom 1

186.41 SF Walls 221.39 SF Walls & Ceiling 3.89 SY Flooring

25.49 LF Ceil. Perimeter

Height: 8'

34.98 SF Ceiling 34.98 SF Floor

22.99 LF Floor Perimeter

2' 6" X 7' Opens into FRONT_HALLW2 Door

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
402. Soap/hand sanitizer dispenser - wall mounted	1.00 EA	13.76	0.00	2.76	16.52	(0.00)	16.52
403. Paper towel dispenser	1.00 EA	14.34	0.00	2.86	17.20	(0.00)	17.20
Remove 404. Paper towel dispenser	1.00 EA	18.88	0.00	3.78	22.66	(5.66)	17.00
<u>Install</u>							
405. Outlet or switch - Detach & reset	2.00 EA	16.28	0.00	6.52	39.08	(0.00)	39.08
406. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
407. Toilet - Detach & reset	1.00 EA	207.76	0.73	41.70	250.19	(0.00)	250.19
Begin Drywall Repairs							
Removal							
408. Mask and prep for paint - plastic, paper, tape (per LF)	50.98 LF	1.44	1.34	14.94	89.69	(29.90)	59.79
409. Tear out wet drywall, cleanup, bag - Cat 3	221.39 SF	1.25	3.45	56.04	336.23	(0.00)	336.23
Walls/Ceiling							
410. Tear out and bag wet insulation - Category 3 water	34.98 SF	1.06	0.20	7.46	44.74	(0.00)	44.74
Walls/Ceiling							
S_5_ANDERSON-EYE-1					1	8/4/2022	Page: 2



CONTINUED - Bathroom 1

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Installation							
111. Apply anti-microbial agent to more han the walls and ceiling	256.37 SF	0.24	1.00	12.50	75.03	(0.00)	75.0
Application of antimicrobial to the water da	ımaged space b	efore installation of	new drywall a	nd insulation.			
112. 5/8" drywall - hung, taped, ready for exture	34.98 SF	2.20	2.22	15.84	95.02	(3.16)	91.80
5/8 for the ceiling							
113. Blown-in insulation - 10" depth - R26	34.98 SF	1.08	2.69	8.10	48.57	(1.63)	46.9
Blown-in for the ceiling							
114. Clean stud wall	186.41 SF	0.74	0.36	27.66	165.96	(0.00)	165.9
115. Batt insulation - 6" - R19 - unfaced patt	186.41 SF	1.00	12.90	39.86	239.17	(7.96)	231.2
116. 1/2" drywall - hung, taped, ready for exture	186.41 SF	2.10	11.09	80.52	483.07	(16.10)	466.9
117. Texture drywall - smooth / skim coat For the ceiling	34.98 SF	1.33	0.34	9.36	56.22	(1.88)	54.3
18. Clean the ceiling	34.98 SF	0.34	0.03	2.38	14.30	(0.00)	14.3
Ceiling/walls must be cleaned prior to appli	cation of paint.					(0.00)	*
19. Paint the ceiling - two coats	34.98 SF	1.00	0.82	7.16	42.96	(14.31)	28.6
20. Final cleaning - construction -	104.94 SF	0.26	0.00	5.46	32.74	(0.00)	32.7
This final clean is for the drywall repair pro	cess. Addition	al final clean line ite	ms may be nee	cessary for othe	er repair proc	esses.	
Begin Sink Repair				·	•		
Removal							
121. Sink - wall mounted	1.00 EA	35.83	0.00	7.16	42.99	(0.00)	42.9
Installation						•	
122. Sink - single	1.00 EA	91.87	0.00	18.38	110.25	(11.03)	99.2
Begin Tile Repairs						•	
Removal							
23. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.5
24. Tear out trim and bag for disposal - up to Cat 3	22.99 LF	0.86	0.40	4.04	24.21	(0.00)	24.2
225. Door opening (jamb & casing) - 2"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.2
26. Tear out baseboard and bag for lisposal - up to Cat 3	22.99 LF	0.86	0.40	4.04	24.21	(0.00)	24.2
	34.98 SF	4.86	0.65	34.14	204.79	(0.00)	
27. Tear out non-salvageable tile floor & ag - Cat 3 water							204.7
pag - Cat 3 water	maged space be	efore installation of	new drywall ai	nd insulation.			204.7
pag - Cat 3 water Application of antimicrobial to the water da	maged space be 34.98 SF	efore installation of 8.73	new drywall ai 16.47	nd insulation. 64.38	386.23	(19.31)	
127. Tear out non-salvageable tile floor & pag - Cat 3 water Application of antimicrobial to the water da 128. Tile floor covering 129. Baseboard - 3 1/4"			-		386.23 94.95	(19.31) (3.15)	204.75 366.9 91.8



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Bathroom 1


DESCRIPTION	QUANTITY U	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
430. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
431. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
432. Paint baseboard - two coats	22.99 LF	1.49	0.31	6.92	41.49	(13.82)	27.67
433. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
434. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

_	_		
Ins	·tal	nti.	a 24

Totals: Bathroom 1	72.41	566.92	3,401.37	166.83	3,234.54



Patient room

241.02 SF Walls 308.09 SF Walls & Ceiling 7.45 SY Flooring 32.24 LF Ceil. Perimeter Height: 8'

67.07 SF Ceiling 67.07 SF Floor

29.83 LF Floor Perimeter

Door 2' 5" X 7' Opens into SIDE_HALLWA2

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
435. Light fixture - Detach & reset	1.00 EA	45.40	0.00	9.08	54.48	(0.00)	54.48
436. Outlet or switch - Detach & reset	8.00 EA	16.28	0.00	26.04	156.28	(0.00)	156.28
437. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
Begin Drywall Repairs							
Removal							
438. Mask and prep for paint - plastic, paper, tape (per LF)	64.48 LF	1.44	1.70	18.92	113.47	(37.82)	75.65
139. Tear out wet drywall, cleanup, bag - Cat 3	308.09 SF	1.25	4.81	77.98	467.90	(0.00)	467.90
Walls/Ceiling							
140. Tear out and bag wet insulation - Category 3 water Walls/Ceiling	67.07 SF	1.06	0.39	14.30	85.78	(0.00)	85.78
5_ANDERSON-EYE-1					1	8/4/2022	Page:



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Patient room

DESCRIPTION	QUANTITY U	NIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Installation							
441. Apply anti-microbial agent to more than the walls and ceiling	375.16 SF	0.24	1.46	18.30	109.80	(0.00)	109.80
Application of antimicrobial to the water da	maged space befor	e installation of	new drywali a	nd insulation.			
442. 5/8" drywall - hung, taped, ready for texture	67.07 SF	2.20	4.25	30.38	182.18	(6.08)	176.10
5/8 for the ceiling							
143. Blown-in insulation - 10" depth - R26	67.07 SF	1.08	5.17	15.52	93.13	(3.10)	90.03
Blown-in for the ceiling							
444. Clean stud wall	241.02 SF	0.74	0.47	35.78	214.60	(0.00)	214.60
145. 1/2" drywall - hung, taped, ready for exture	241.02 SF	2.10	14.33	104.08	624.55	(20.81)	603.74
146. Texture drywall - smooth / skim coat	67.07 SF	1.33	0.65	17.98	107.83	(3.59)	104.24
For the ceiling							
147. Clean the ceiling	67.07 SF	0.34	0.07	4.58	27.45	(0.00)	27.4
Ceiling/walls must be cleaned prior to applie	cation of paint.						
448. Paint the ceiling - two coats	67.07 SF	1.00	1.57	13.74	82.38	(27.46)	54.92
149. Final cleaning - construction - Residential	134.14 SF	0.26	0.00	6.98	41.86	(0.00)	41.86
This final clean is for the drywall repair pro-	cess. Additional fi	nal clean line ite	ms may be ne	cessary for oth	er repair proc	esses.	
Begin Carpet Repairs							
Removal							
450. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
451. Tear out trim and bag for disposal - up to Cat 3	29.83 LF	0.86	0.52	5.24	31.41	(0.00)	31.4
452. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.2
453. Tear out baseboard and bag for disposal - up to Cat 3	29.83 LF	0.86	0.52	5.24	31.41	(0.00)	31.4
454. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	67.07 SF	1.35	0.39	18.18	109.11	(0.00)	109.1
455. Carpet	77.13 SF	3.27	20.38	54.52	327.12	(163.56)	163.5
456. Baseboard - 3 1/4"	29.83 LF	3.28	4.83	20.52	123.19	(4.10)	119.09
457. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.0
458. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.4
459. Paint baseboard - two coats	29.83 LF	1.49	0.41	8.98	53.84	(17.96)	35.8
460. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.3
461. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.5
To move contents back in.							
5_ANDERSON-EYE-1					8	8/4/2022	Page



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Patient room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV	
This final clean is for the drywall repair pro <u>Installation</u>	ocess. Additiona	l final clean line ite	ms may be no	ecessary for otl	her repair proc	esses.		
Totals: Patient room			75.21	573.48	3,440.67	323.40	3,117.27	
Librar	ry						Height: 8'	
<u> </u>	546.33	SF Walls			217.61 SF	Ceiling		
Harrier V	763.94	SF Walls & Ce	iling		217.61 SF	Floor		
- Figure 1		SY Flooring	8	67.67 LF Floor Perimeter				
halling &		72.67 LF Ceil. Perimeter						
り Door	2' 6" X 7'			Opens int	o SIDE_HA	LLWA2		
Door	2' 6	5" X 7"		Opens into SIDE_HALLWA2				
DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV	
Accessories		<u> </u>						
462. Heat/AC register - Mechanically attached - Detach & reset	3.00 EA	13.33	0.00	8.00	47.99	(0.00)	47.99	
463. Recessed light fixture - Detach & reset entire unit	6.00 EA	95.19	0.00	114.22	685.36	(0.00)	685.36	
464. Fluorescent light fixture - 6' & 8' - Detach & reset	2.00 EA	88.02	0.00	35.20	211.24	(0.00)	211.24	
465. Outlet or switch - Detach & reset	22.00 EA	16.28	0.00	71.64	429.80	(0.00)	429.80	
Begin Drywall Repairs								
Removal						(0.5.5.1)	150 10	
466. Mask and prep for paint - plastic, paper, tape (per LF)	145.33 LF	1.44	3.83	42.62	255.73	(85.24)	170.49	
467. Tear out wet drywall, cleanup, bag - Cat 3	763.94 SF	1.25	11.92	193.36	1,160.21	(0.00)	1,160.21	
Walls/Ceiling								

1.06

0.24

497.61 SF

981.56 SF

Application of antimicrobial to the water damaged space before installation of new drywall and insulation.

106.08

47.88

2.91

3.83

636.46

287.28

(0.00)

(0.00)

636.46

287.28

than the walls and ceiling

Category 3 water
Ceiling & Exterior Walls
Installation

468. Tear out and bag wet insulation -

469. Apply anti-microbial agent to more



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Library

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
470. 5/8" drywall - hung, taped, ready for texture	217.61 SF	2.20	13.79	98.50	591.03	(19.70)	571.33
5/8 for the ceiling							
471. Blown-in insulation - 10" depth - R26	217.61 SF	1.08	16.76	50.36	302.14	(10.07)	292.07
Blown-in for the ceiling						, ,	
472. Batt insulation - 6" - R19 - unfaced batt	280.00 SF	1.00	19.38	59.88	359.26	(11.98)	347.28
473. 1/2" drywall - hung, taped, ready for texture	546.33 SF	2.10	32.49	235.96	1,415.74	(47.18)	1,368.56
474. Paneling	546.33 SF	2.20	36.22	247.62	1,485.77	(49.53)	1,436.24
475. Texture drywall - smooth / skim coat	217.61 SF	1.33	2.12	58.30	349.84	(11.66)	338.18
For the ceiling							
476. Clean the ceiling	217.61 SF	0.34	0.21	14.84	89.04	(0.00)	89.04
Ceiling/walls must be cleaned prior to appli	cation of paint.						
477. Paint the ceiling - two coats	217.61 SF	1.00	5.09	44.54	267.24	(89.08)	178.16
478. Final cleaning - construction - Residential	435.22 SF	0.26	0.00	22.64	135.80	(0.00)	135.80
This final clean is for the drywall repair pro	cess. Addition	al final clean line it	ems may be no	ecessary for otl	her repair proc	esses.	
Begin Carpet Repairs							
Removal							
479. Interior door unit	2.00 EA	17.92	0.00	7.16	43.00	(0.00)	43.00
480. Tear out trim and bag for disposal - up to Cat 3	67.67 LF	0.86	1.19	11.88	71.27	(0.00)	71.27
481. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	6.01	0.00	2.40	14.42	(0.00)	14.42
482. Tear out baseboard and bag for disposal - up to Cat 3	67.67 LF	0.86	1.19	11.88	71.27	(0.00)	71.27
483. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	217.61 SF	1.35	1.27	59.02	354.06	(0.00)	354.06
484. Carpet	250.25 SF	3.27	66.12	176.88	1,061.32	(530.66)	530.66
485. Baseboard - 3 1/4"	67.67 LF	3.28	10.95	46.60	279.51	(9.33)	270.18
486. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	165.62	24.06	71.06	426.36	(14.20)	412.16
487. Interior door unit	2.00 EA	48.59	0.00	19.44	116.62	(5.84)	110.78
488. Paint baseboard - two coats	67.67 LF	1.49	0.92	20.34	122.09	(40.70)	81.39
489. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA	32.40	0.95	13.16	78.91	(26.30)	52.61
490. Paint door slab only - 2 coats (per side)	2.00 EA	38.60	1.57	15.76	94.53	(31.51)	63.02
Tr							

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Library

DESCRIPTION	QUANTITY UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Totals: Library		256.77	1,907.22	11,443.29	982.98	10,460.31

8' 7" X 3'

2' 6" X 7'

2' 6" X 7'

5' 7" X 3' 3"

Waiting room 366.44 SF Walls 545.99 SF Walls & Ceiling Waiting room 19.95 SY Flooring 55.67 LF Ceil. Perimeter

179.55 SF Ceiling 179.55 SF Floor

50.67 LF Floor Perimeter

8/4/2022

Page: 35

Height: 8'

Window Door Missing Wall - Goes to neither Floor/Ceiling Door

S_5_ANDERSON-EYE-1

Opens into Exterior Opens into Exterior Opens into FRONT_DESK2 Opens into GLASSES_ROO2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
491. Outlet or switch - Detach & reset	7.00 EA	16.28	0.00	22.80	136.76	(0.00)	136.76
492. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA	13.33	0.00	5.34	32.00	(0.00)	32.00
493. Recessed light fixture - Detach & reset entire unit	2.00 EA	95.19	0.00	38.08	228.46	(0.00)	228.46
Begin Drywall Repairs							
Removal							
494. Mask and prep for paint - plastic, paper, tape (per LF)	111.33 LF	1.44	2.93	32.64	195.89	(65.30)	130.59
495. Ceiling fan & light	1.00 EA	18.02	0.00	3.60	21.62	(0.00)	21.62
496. Tear out wet drywall, cleanup, bag - Cat 3	545.99 SF	1.25	8.52	138.20	829.21	(0.00)	829.21
Walls/Ceiling							
497. Tear out and bag wet insulation - Category 3 water	299.55 SF	1.06	1.75	63.86	383.13	(0.00)	383.13
Ceiling & Exterior Walls							
Installation							
498. Apply anti-microbial agent to more than the walls and ceiling	725.53 SF	0.24	2.83	35.38	212.34	(0.00)	212.34
Application of antimicrobial to the water d	amaged space be	efore installation of	new drywall a	and insulation.			
499. 5/8" drywall - hung, taped, ready for texture	179.55 SF	2.20	11.38	81.28	487.67	(16.25)	471.42



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Waiting room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
5/8 for the ceiling	,						
500. Blown-in insulation - 10" depth - R26	179.55 SF	1.08	13.83	41.54	249.28	(8.30)	240.98
Blown-in for the ceiling						(,	
501. Batt insulation - 6" - R19 - unfaced batt	120.00 SF	1.00	8.31	25.66	153.97	(5.14)	148.83
502. 1/2" drywall - hung, taped, ready for texture	366.44 SF	2.10	21.79	158.26	949.57	(31.66)	917.91
503. Texture drywall - smooth / skim coat	179.55 SF	1.33	1.75	48.12	288.67	(9.62)	279.05
For the ceiling						` ,	
504. Clean the ceiling	179.55 SF	0.34	0.18	12.26	73.49	(0.00)	73.49
Ceiling/walls must be cleaned prior to appl	ication of paint.					, ,	
505. Paint the ceiling - two coats	179.55 SF	1.00	4.20	36.76	220.51	(73.51)	147.00
506. Ceiling fan & light	1.00 EA	303.15	12.43	63.12	378.70	(94.68)	284.02
507. Final cleaning - construction - Residential	359.10 SF	0.26	0.00	18.68	112.05	(0.00)	112.05
This final clean is for the drywall repair pro	cess. Addition	al final clean line it	ems may be no	ecessary for oth	er repair proc	esses.	
Begin Carpet Repairs				•	• •		
<u>Removal</u>							
508. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
509. Exterior door - metal - insulated - flush or panel style	1.00 EA	20.47	0.00	4.10	24.57	(0.00)	24.57
510. Tear out trim and bag for disposal - up to Cat 3	50.67 LF	0.86	0.89	8.90	53.37	(0.00)	53.37
511. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	6.01	0.00	2.40	14.42	(0.00)	14.42
512. Tear out baseboard and bag for disposal - up to Cat 3	50.67 LF	0.86	0.89	8.90	53.37	(0.00)	53.37
513. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	179.55 SF	1.35	1.05	48.70	292.14	(0.00)	292.14
514. Carpet	206.48 SF	3.27	54.56	145.96	875.71	(437.86)	437.85
515. Baseboard - 3 1/4"	50.67 LF	3.28	8.20	34.88	209.28	(6.97)	202.31
516. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	165.62	24.06	71.06	426.36	(14.20)	412.16
517. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
518. Exterior door - metal - insulated - flush or panel style	1.00 EA	72.86	0.00	14.58	87.44	(4.36)	83.08
519. Paint baseboard - two coats	50.67 LF	1.49	0.69	15.24	91.43	(30.48)	60.95
520. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA	32.40	0.95	13.16	78.91	(26.30)	52.61
521. Paint door slab only - 2 coats (per side)	2.00 EA	38.60	1.57	15.76	94.53	(31.51)	63.02
To move contents back in.							




United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Waiting room

DESCRIPTION	QUANTITY UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV				
This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Installation										
Installation		*								



Exam room 1

362.50 SF Walls 496.18 SF Walls & Ceiling 14.85 SY Flooring 47.50 LF Ceil. Perimeter 133.68 SF Ceiling 133.68 SF Floor 45.00 LF Floor Perimeter

Height: 8'

Door

2' 6" X 7'

Opens into SIDE_HALLWA2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories		***		-			
522. Recessed light fixture - Detach & reset entire unit	2.00 EA	95.19	0.00	38.08	228.46	(0.00)	228.46
523. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA	88.02	0.00	17.60	105.62	(0.00)	105.62
524. Soap/hand sanitizer dispenser - wall mounted	1.00 EA	13.76	0.00	2.76	16.52	(0.00)	16.52
525. Paper towel dispenser	1.00 EA	14.34	0.00	2.86	17.20	(0.00)	17.20
Remove							
526. Paper towel dispenser	1.00 EA	18.88	0.00	3.78	22.66	(5.66)	17.00
Reset							
527. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
528. Outlet or switch - Detach & reset	14.00 EA	16.28	0.00	45.58	273.50	(0.00)	273.50
Begin Drywall Repairs							
Removal							
529. Mask and prep for paint - plastic, paper, tape (per LF)	95.00 LF	1.44	2.50	27.86	167.16	(55.71)	111.45
530. Tear out wet drywall, cleanup, bag - Cat 3	496.18 SF	1.25	7.74	125.58	753.55	(0.00)	753.55
Walls/Ceiling							
531. Tear out and bag wet insulation - Category 3 water	333.68 SF	1.06	1.95	71.14	426.79	(0.00)	426.79
Ceiling & Exterior Walls							
S_5_ANDERSON-EYE-1					8	3/4/2022	Page: 3



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Exam room 1

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Installation						-	
532. Apply anti-microbial agent to more than the walls and ceiling	629.86 SF	0.24	2.46	30.74	184.37	(0.00)	184.37
Application of antimicrobial to the water da	maged space b	efore installation of	new drywall a	and insulation.			
533. Clean stud wall	496.18 SF	0.74	0.97	73.64	441.78	(0.00)	441.78
534. 5/8" drywall - hung, taped, ready for texture	133.68 SF	2.20	8.47	60.52	363.09	(12.10)	350.99
5/8 for the ceiling	•						
535. Blown-in insulation - 10" depth - R26	133.68 SF	1.08	10.30	30.94	185.61	(6.19)	179.42
Blown-in for the ceiling							
536. Batt insulation - 6" - R19 - unfaced batt	200.00 SF	1.00	13.85	42.78	256.63	(8.55)	248.08
537. 1/2" drywall - hung, taped, ready for texture	362.50 SF	2.10	21.56	156.58	939.39	(31.32)	908.07
538. Texture drywall - smooth / skim coat For the ceiling	133.68 SF	1.33	1.30	35.82	214.91	(7.17)	207.74
539. Clean the ceiling	133.68 SF	0.34	0.13	9.12	54.70	(0.00)	54.70
Ceiling/walls must be cleaned prior to appli	cation of paint.					` ,	
540. Paint the ceiling - two coats	133.68 SF	1.00	3.13	27.36	164.17	(54.72)	109.45
541. Final cleaning - construction - Residential	267.36 SF	0.26	0.00	13.90	83.41	(0.00)	83.41
This final clean is for the drywall repair pro	cess. Addition	al final clean line ite	ems may be ne	cessary for oth	er repair proc	esses.	
Begin Carpet Repairs							
Removal							
542. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
543. Tear out trim and bag for disposal - up to Cat 3	45.00 LF	0.86	0.79	7.90	47.39	(0.00)	47.39
544. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
545. Tear out baseboard and bag for disposal - up to Cat 3	45.00 LF	0.86	0.79	7.90	47.39	(0.00)	47.39
546. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	133.68 SF	1.35	0.78	36.26	217.51	(0.00)	217.51
547. Carpet	153.73 SF	3.27	40.62	108.66	651.98	(326.00)	325.98
548. Baseboard - 3 1/4"	45.00 LF	3.28	7.28	30.98	185.86	(6.20)	179.66
549. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
550. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
551. Paint baseboard - two coats	45.00 LF	1.49	0.61	13.54	81.20	(27.07)	54.13
552. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30




Phone: (800) 827-8279 Fax: (800) 786-8884

Front Desk

CONTINUED - Exam room 1

DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
553. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51
To move contents back in.							
This final clean is for the drywall repair p	process. Additional fit	nal clean line ite	ms may be nec	essary for other	er repair proc	esses.	
Installation							

Totals: Exam room 1	138.52	1,089.02	6,533.75	579.61	5,954.14



213.60 SF Walls 300.92 SF Walls & Ceiling 9.70 SY Flooring 31.25 LF Ceil. Perimeter

87.31 SF Ceiling 87.31 SF Floor 31.25 LF Floor Perimeter

Height: 8'

Missing Wall - Goes to neither Floor/Ceiling 5' 7" X 3' 3"

Window 6' 1" X 3'

Missing Wall 6' 3" X 8'

Opens into WAITING_ROO2

Opens into Exterior
Opens into ROOM2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
554. Fluorescent light fixture - 6' & 8' - Detach & reset	2.00 EA	88.02	0.00	35.20	211.24	(0.00)	211.24
555. Outlet or switch - Detach & reset	6.00 EA	16.28	0.00	19.54	117.22	(0.00)	117.22
556. Heat/AC register - Mechanically attached - Detach & reset Begin Drywall Repairs	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
Removal							
557. Mask and prep for paint - plastic, paper, tape (per LF)	62.50 LF	1.44	1.65	18.34	109.99	(36.67)	73.32
558. Tear out wet drywall, cleanup, bag - Cat 3	300.92 SF	1.25	4.69	76.18	457.02	(0.00)	457.02
Walls/Ceiling							
559. Tear out and bag wet insulation - Category 3 water	87.31 SF	1.06	0.51	18.62	111.68	(0.00)	111.68
Walls/Ceiling							
Installation							
560. Apply anti-microbial agent to more than the walls and ceiling	388.23 SF	0.24	1.51	18.94	113.63	(0.00)	113.63
_5_ANDERSON-EYE-1					8	3/4/2022	Page: 3



United Claims Service, Inc.

26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Front Desk

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Application of antimicrobial to the water da	maged space b	efore installation of	new drywall a	and insulation.			
561. 5/8" drywall - hung, taped, ready for texture	87.31 SF	2.20	5.53	39.52	237.13	(7.90)	229.23
5/8 for the ceiling							
562. Blown-in insulation - 10" depth - R26	87.31 SF	1.08	6.72	20.20	121.21	(4.04)	117.17
Blown-in for the ceiling							
563. 1/2" drywall - hung, taped, ready for texture	213.60 SF	2.10	12.70	92.26	553.52	(18.45)	535.07
564. Texture drywall - smooth / skim coat	87.31 SF	1.33	0.85	23.40	140.37	(4.68)	135.69
For the ceiling							
565. Clean the ceiling	87.31 SF	0.34	0.08	5.96	35.73	(0.00)	35.73
Ceiling/walls must be cleaned prior to applic	cation of paint.						
566. Paint the ceiling - two coats	87.31 SF	1.00	2.04	17.86	107.21	(35.74)	71.47
567. Final cleaning - construction - Residential	174.63 SF	0.26	0.00	9.08	54.48	(0.00)	54.48
This final clean is for the drywall repair pro-	cess. Addition	al final clean line ite	ms may be ne	cessary for ot	her repair proc	esses.	
Begin Carpet Repairs							
Removal							
568. Tear out trim and bag for disposal - up to Cat 3	31.25 LF	0.86	0.55	5.50	32.93	(0.00)	32.93
569. Door opening (jamb & casing) - 36"to60"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
570. Tear out baseboard and bag for disposal - up to Cat 3	31.25 LF	0.86	0.55	5.50	32.93	(0.00)	32.93
571. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	87.31 SF	1.35	0.51	23.68	142.06	(0.00)	142.06
572. Carpet	100.41 SF	3.27	26.53	70.96	425.83	(212.92)	212.91
573. Baseboard - 3 1/4"	31.25 LF	3.28	5.06	21.52	129.08	(4.31)	124.77
574. Door opening (jamb & casing) - 36"to60"wide - paint grade	1.00 EA	195.96	14.17	42.04	252.17	(8.40)	243.77
575. Paint baseboard - two coats	31.25 LF	1.49	0.43	9.40	56.39	(18.80)	37.59
576. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
To move contents back in.							
This final clean is for the drywall repair prod	ess. Addition	al final clean line ite	ms may be ne	cessary for ot	her repair proc	esses.	
Installation							
Totals: Front Desk			84.56	584.14	3,504.48	365.07	3,139.41

S_5_ANDERSON-EYE-1




UCS

United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

A/C room



S_5_ANDERSON-EYE-1

161.17 SF Walls

188.67 SF Walls & Ceiling

3.06 SY Flooring

22.33 LF Ceil. Perimeter

Height: 8'

27.50 SF Ceiling 27.50 SF Floor

19.83 LF Floor Perimeter

8/4/2022

Page: 41

Door	2' 6" X 7'	Opens into FRONT_HALLW2
------	------------	-------------------------

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
577. Light fixture - Detach & reset	1.00 EA	45.40	0.00	9.08	54.48	(0.00)	54.48
Begin Drywall Repairs							
Removal							
578. Mask and prep for paint - plastic, paper, tape (per LF)	44.67 LF	1.44	1.18	13.10	78.60	(26.19)	52.41
579. Tear out wet drywall, cleanup, bag - Cat 3	188.67 SF	1.25	2.94	47.74	286.52	(0.00)	286.52
Walls/Ceiling							
580. Tear out and bag wet insulation - Category 3 water Walls/Ceiling	27.50 SF	1.06	0.16	5.88	35.19	(0.00)	35.19
Installation							
581. Apply anti-microbial agent to more than the walls and ceiling	216.17 SF	0.24	0.84	10.54	63.26	(0.00)	63.26
Application of antimicrobial to the water da	amaged space b	efore installation of	f new drywall a	nd insulation.			
582. 5/8" drywall - hung, taped, ready for texture	27.50 SF	2.20	1.74	12.44	74.68	(2.50)	72.18
5/8 for the ceiling							
583. Blown-in insulation - 10" depth - R26	27.50 SF	1.08	2.12	6.36	38.18	(1.28)	36.90
Blown-in for the ceiling							
584. Batt insulation - 6" - R19 - unfaced batt	161.17 SF	1.00	11.16	34.48	206.81	(6.88)	199.93
585. 1/2" drywall - hung, taped, ready for texture	161.17 SF	2.10	9.59	69.62	417.67	(13.92)	403.75
586. Texture drywall - smooth / skim coat	27.50 SF	1.33	0.27	7.38	44.23	(1.47)	42.76
For the ceiling							
587. Clean the ceiling	27.50 SF	0.34	0.03	1.88	11.26	(0.00)	11.26
Ceiling/walls must be cleaned prior to appl	ication of paint.	•					
588. Paint the ceiling - two coats	27.50 SF	1.00	0.64	5.62	33.76	(11.26)	22.50
589. Final cleaning - construction - Residential	55.00 SF	0.26	0.00	2.86	17.16	(0.00)	17.16
This final clean is for the drywall repair pro	ocess. Addition	al final clean line it	ems may be ne	cessary for oth	er repair prod	cesses.	
Begin Carpet Repairs							
Removal							
590. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - A/C room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
591. Tear out trim and bag for disposal - up to Cat 3	19.83 LF	0.86	0.35	3.50	20.90	(0.00)	20.90
592. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
593. Tear out baseboard and bag for disposal - up to Cat 3	19.83 LF	0.86	0.35	3.50	20.90	(0.00)	20.90
594. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	27.50 SF	1.35	0.16	7.46	44.75	(0.00)	44.75
595. Carpet	31.63 SF	3.27	8.36	22.36	134.15	(67.08)	67.07
596. Baseboard - 3 1/4"	19.83 LF	3.28	3.21	13.64	81.89	(2.74)	79.15
597. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
598. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
599. Paint baseboard - two coats	19.83 LF	1.49	0.27	5.98	35.80	(11.94)	23.86
600. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
601. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

			_		
: A/C room	56.66	347.90	2.087.10	184.18	1.902.92



311.67	SF Walls
447.75	SF Walls & Ceiling
15.12	SY Flooring
46.67	LF Ceil. Perimeter

136.08	SF	Ceiling
136.08	SF	Floor
37.67	LF	Floor Perimeter

Height: 8'

Missing Wall - Goes to Floor	4' X 6' 8"
Door	2' 6" X 7'
Door	2' 6" X 7'

Kitchen

Opens into BACK_EXIT
Opens into BOOK_CLOSET
Opens into BATHROOM2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories 602. Outlet or switch - Detach & reset	12.00 EA	16.28	0.00	39.08	234.44	(0.00)	234.44

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Kitchen

DESCRIPTION	QUANTITY U	NIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
603. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
604. Fluorescent light fixture - 6' & 8' - Detach & reset	3.00 EA	88.02	0.00	52.82	316.88	(0.00)	316.88
Begin Drywall Repairs							
Removal			2.46	27.10	164.24	(54.74)	109.50
605. Mask and prep for paint - plastic, paper, tape (per LF)	93.33 LF	1.44	2.46	27.38		• •	680.01
606. Tear out wet drywall, cleanup, bag - Cat 3	447.75 SF	1.25	6.98	113.34	680.01	(0.00)	080.01
Walls/Ceiling					****	(0.00)	206.04
607. Tear out and bag wet insulation - Category 3 water	232.08 SF	1.06	1.36	49.48	296.84	(0.00)	296.84
Ceiling & Exterior Walls							
Installation		0.01	2.20	20.40	170.00	(0.00)	170.88
608. Apply anti-microbial agent to more than the walls and ceiling	583.83 SF	0.24	2.28	28.48	170.88	(0.00)	1/0.88
Application of antimicrobial to the water da						(10.22)	267.25
609. 5/8" drywall - hung, taped, ready for texture	136.08 SF	2.20	8.62	61.60	369.60	(12.33)	357.27
5/8 for the ceiling							
610. Blown-in insulation - 10" depth - R26	136.08 SF	1.08	10.48	31.50	188.95	(6.31)	182.64
Blown-in for the ceiling							
611. Clean stud wall	311.67 SF	0.74	0.61	46.24	277.49	(0.00)	277.49
612. Batt insulation - 6" - R19 - unfaced batt	96.00 SF	1.00	6.65	20.54	123.19	(4.10)	119.09
613. 1/2" drywall - hung, taped, ready for texture	311.67 SF	2.10	18.54	134.60	807.65	(26.92)	780.73
614. Texture drywall - smooth / skim coat	136.08 SF	1.33	1.33	36.46	218.78	(7.29)	211.49
For the ceiling							
615. Clean the ceiling	136.08 SF	0.34	0.13	9.28	55.68	(0.00)	55.68
Ceiling/walls must be cleaned prior to appl	ication of paint.						
616. Paint the ceiling - two coats	136.08 SF	1.00	3.18	27.86	167.12	(55.70)	111.42
617. Final cleaning - construction - Residential	408.25 SF	0.26	0.00	21.24	127.39	(0.00)	127.39
This final clean is for the drywall repair pro	cess. Additional	final clean line ite	ems may be no	ecessary for oth	er repair pro	cesses.	
Begin Cabinetry Repair							
Removal							
618. Sink faucet - Kitchen	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
619. Sink - double basin	1.00 EA	19.11	0.00	3.82	22.93	(0.00)	22.93
620. 6" backsplash for flat laid countertop	13.00 LF	0.86	0.00	2.24	13.42	(0.00)	13.42
621. Countertop - flat laid plastic laminate	13.00 LF	4.12	0.00	10.72	64.28	(0.00)	64.28
5_ANDERSON-EYE-1					;	8/4/2022	Page:



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Kitchen


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
622. Cabinetry - lower (base) units	13.00 LF	7.17	0.00	18.64	111.85	(0.00)	111.85
623. Shelving - 24" - in place	8.00 LF	0.58	0.00	0.92	5.56	(0.00)	5.56
624. Shelving - wire (vinyl coated)	21.00 LF	3.12	0.00	13.10	78.62	(0.00)	78.62
Installation						, ,	
625. Cabinetry - lower (base) units	13.00 LF	222.16	240.03	625.62	3,753.73	(375.37)	3,378.36
626. Countertop - flat laid plastic laminate	13.00 LF	40.57	37.09	112.90	677.40	(225.80)	451.60
627. 6" backsplash for flat laid countertop	13.00 LF	10.62	10.24	29.66	177.96	(59.31)	118.65
628. Sink - double basin	1.00 EA	98.43	0.00	19.68	118.11	(11.80)	106.31
629. Shelving - 24" - in place	8.00 LF	5.58	0.00	8.92	53.56	(1.79)	51.77
630. Shelving - wire (vinyl coated)	21.00 LF	5.70	0.00	23.94	143.64	(4.79)	138.85
This final clean is for the drywall repair pro	cess. Addition	al final clean line it	ems may be n	ecessary for ot	her repair proc		
Begin Carpet Repairs			-	•			
Removal							
631. Interior door unit	2.00 EA	17.92	0.00	7.16	43.00	(0.00)	43.00
632. Tear out trim and bag for disposal - up to Cat 3	37.67 LF	0.86	0.66	6.62	39.68	(0.00)	39.68
633. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	6.01	0.00	2.40	14.42	(0.00)	14.42
634. Tear out baseboard and bag for disposal - up to Cat 3	37.67 LF	0.86	0.66	6.62	39.68	(0.00)	39.68
635. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	136.08 SF	1.35	0.80	36.90	221.41	(0.00)	221.41
636. Carpet	156.50 SF	3.27	41.35	110.64	663.75	(331.88)	331.87
637. Baseboard - 3 1/4"	37.67 LF	3.28	6.10	25.94	155.60	(5.18)	150.42
638. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA	165.62	24.06	71.06	426.36	(14.20)	412.16
639. Interior door unit	2.00 EA	48.59	0.00	19.44	116.62	(5.84)	110.78
640. Paint baseboard - two coats	37.67 LF	1.49	0.51	11.32	67.96	(22.66)	45.30
641. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA	32.40	0.95	13.16	78.91	(26.30)	52.61
642. Paint door slab only - 2 coats (per side)	2.00 EA	38.60	1.57	15.76	94.53	(31.51)	63.02
To move contents back in.							
This final clean is for the drywall repair pro	cess. Addition	al final clean line it	ems may be n	ecessary for ot	her repair proc	esses.	
Installation			-	•	- •		
Totals: Kitchen		'''''''''''''''''''''''''''''''''''''	426.64	1,903.32	11,419.61	1,283.82	10,135.79
- vinisi sattliti			720.07	1,703.34	11,717.01	1,203.02	10,133./9



United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884



Exam room 2

Height: 8'

354.50 SF Walls 484.00 SF Walls & Ceiling 14.39 SY Flooring 46.50 LF Ceil. Perimeter 129.50 SF Ceiling 129.50 SF Floor 44.00 LF Floor Perimeter

Door

2' 6" X 7'

Opens into SIDE_HALLWA2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories	-						
643. Soap/hand sanitizer dispenser - wall mounted	1.00 EA	13.76	0.00	2.76	16.52	(0.00)	16.52
644. Paper towel dispenser	1.00 EA	14.34	0.00	2.86	17.20	(0.00)	17.20
Remove							15.00
645. Paper towel dispenser	1.00 EA	18.88	0.00	3.78	22.66	(5.66)	17.00
Reset							
646. Outlet or switch - Detach & reset	10.00 EA	16.28	0.00	32.56	195.36	(0.00)	195.36
647. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
648. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA	88.02	0.00	17.60	105.62	(0.00)	105.62
Begin Drywall Repairs							
Removal							
649. Mask and prep for paint - plastic, paper, tape (per LF)	93.00 LF	1.44	2.45	27.28	163.65	(54.56)	109.09
650. Tear out wet drywall, cleanup, bag - Cat 3	484.00 SF	1.25	7.55	122.52	735.07	(0.00)	735.07
Walls/Ceiling							
651. Tear out and bag wet insulation - Category 3 water	241.50 SF	1.06	1.41	51.48	308.88	(0.00)	308.88
Ceiling & Exterior Walls							
Installation							
652. Apply anti-microbial agent to more than the walls and ceiling	613.50 SF	0.24	2.39	29.92	179.55	(0.00)	179.55
Application of antimicrobial to the water da	maged space be	efore installation of	new drywall a	ınd insulation.			
653. 5/8" drywall - hung, taped, ready for texture	129.50 SF	2.20	8.21	58.62	351.73	(11.73)	340.00
5/8 for the ceiling							
654. Blown-in insulation - 10" depth - R26	129.50 SF	1.08	9.98	29.98	179.82	(5.99)	173.83
Blown-in for the ceiling							
655. Batt insulation - 6" - R19 - unfaced batt	354.50 SF	1.00	24.54	75.80	454.84	(15.16)	439.68
656. 1/2" drywall - hung, taped, ready for texture	354.50 SF	2.10	21.08	153.12	918.65	(30.62)	888.03
657. Texture drywall - smooth / skim coat	129.50 SF	1.33	1.26	34.70	208.20	(6.94)	201.26
For the ceiling							
658. Clean the ceiling	129.50 SF	0.34	0.13	8.82	52.98	(0.00)	52.98 Page: 4



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Exam room 2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Ceiling/walls must be cleaned prior to app	lication of paint.						
659. Paint the ceiling - two coats	129.50 SF	1.00	3.03	26.50	159.03	(53.02)	106.01
660. Final cleaning - construction - Residential	259.00 SF	0.26	0.00	13.46	80.80	(0.00)	80.80
This final clean is for the drywall repair pr	ocess. Addition:	al final clean line it	ems may be ne	ecessary for oth	er repair proc	esses.	
Begin Carpet Repairs							
Removal							
661. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
662. Tear out trim and bag for disposal - up to Cat 3	44.00 LF	0.86	0.77	7.72	46.33	(0.00)	46.33
663. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
664. Tear out baseboard and bag for disposal - up to Cat 3	44.00 LF	0.86	0.77	7.72	46.33	(0.00)	46.33
665. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	129.50 SF	1.35	0.76	35.12	210.71	(0.00)	210.71
666. Carpet	148.93 SF	3.27	39.35	105.28	631.63	(315.82)	315.81
667. Baseboard - 3 1/4"	44.00 LF	3.28	7.12	30.28	181.72	(6.05)	175.67
668. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
669. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
670. Paint baseboard - two coats	44.00 LF	1.49	0.60	13.24	79.40	(26.47)	52.93
671. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
672. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51
To move contents back in.							
This final clean is for the drywall repair pr	ocess. Additions	al final clean line ito	ems may be ne	cessary for oth	er repair proc	esses.	
Installation			,		pan proc		

8/4/2022

144.69

958.26

5,749.58

S_5_ANDERSON-EYE-1

Totals: Exam room 2

570.94


5,178.64



United Claims Service, Inc. 26 Japwood Place

Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884



Glasses room

Height: 8'

508.46 SF Walls 864.94 SF Walls & Ceiling 39.61 SY Flooring 65.74 LF Ceil. Perimeter 356.49 SF Ceiling 356.49 SF Floor

63.24 LF Floor Perimeter

Missing Wall Missing Wall Door 9' 2" X 8' 4' 7 1/16" X 8' 2' 6" X 7' Opens into BACK_EXIT
Opens into FRONT_HALLW2
Opens into WAITING_ROO2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
673. Outlet or switch - Detach & reset	6.00 EA	16.28	0.00	19.54	117.22	(0.00)	117.22
674. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA	13.33	0.00	5.34	32.00	(0.00)	32.00
675. Drinking fountain	1.00 EA	77.47	0.00	15.50	92.97	(0.00)	92.97
Remove							
676. Drinking fountain	1.00 EA	162.13	0.00	32.42	194.55	(64.84)	129.71
Install							
677. Fluorescent light fixture - 6' & 8' - Detach & reset	4.00 EA	88.02	0.00	70.42	422.50	(0.00)	422.50
Begin Drywall Repairs							
Removal							
678. Mask and prep for paint - plastic, paper, tape (per LF)	131.49 LF	1.44	3.46	38.58	231.39	(77.13)	154.26
679. Tear out wet drywall, cleanup, bag - Cat 3	864.94 SF	1.25	13.49	218.94	1,313.61	(0.00)	1,313.61
Walls/Ceiling							
680. Tear out and bag wet insulation - Category 3 water	468.49 SF	1.06	2.74	99.86	599.20	(0.00)	599.20
Ceiling & Exterior Walls							
Installation							
681. Apply anti-microbial agent to more than the walls and ceiling	1,221.43 SF	0.24	4.76	59.58	357.48	(0.00)	357.48
Application of antimicrobial to the water da	maged space be	efore installation of	f new drywall a	and insulation.			
682. 5/8" drywall - hung, taped, ready for texture	356.49 SF	2.20	22.59	161.38	968.25	(32.27)	935.98
5/8 for the ceiling							
683. Blown-in insulation - 10" depth - R26	356.49 SF	1.08	27.46	82.50	494.97	(16.49)	478.48
Blown-in for the ceiling							
684. Batt insulation - 6" - R19 - unfaced batt	112.00 SF	1.00	7.75	23.96	143.71	(4.79)	138.92
685. 1/2" drywall - hung, taped, ready for texture	508.46 SF	2.10	30.24	219.60	1,317.61	(43.92)	1,273.69
686. Texture drywall - smooth / skim coat For the ceiling	356.49 SF	1.33	3.48	95.52	573.13	(19.10)	554.03
•						9/4/2022	D 47
_5_ANDERSON-EYE-1					÷	8/4/2022	Page: 47



Totals: Glasses room

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Glasses room

	Anwill I	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
687. Clean the ceiling	356.49 SF	0.34	0.35	24.32	145.88	(0.00)	145.88
Ceiling/walls must be cleaned prior to app	lication of paint.						
688. Paint the ceiling - two coats	356.49 SF	1.00	8.34	72.96	437.79	(145.93)	291.86
689. Final cleaning - construction - Residential	712.97 SF	0.26	0.00	37.08	222.45	(0.00)	222.45
This final clean is for the drywall repair pr	ocess. Addition	al final clean line it	ems may be ne	cessary for otl	her repair proc	esses.	
Begin Carpet Repairs							
Removal							
690. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
691. Tear out trim and bag for disposal - up to Cat 3	63.24 LF	0.86	1.11	11.10	66.60	(0.00)	66.60
692. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
693. Tear out baseboard and bag for disposal - up to Cat 3	63.24 LF	0.86	1.11	11.10	66.60	(0.00)	66.60
694. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	356.49 SF	1.35	2.09	96.68	580.03	(0.00)	580.03
695. Carpet	409.96 SF	3.27	108.32	289.78	1,738.67	(869.35)	869.32
696. Baseboard - 3 1/4"	63.24 LF	3.28	10.24	43.52	261.19	(8.69)	252.50
697. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
698. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
699. Paint baseboard - two coats	63.24 LF	1.49	0.86	19.02	114.11	(38.04)	76.07
700. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
701. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51
To move contents back in.							
This final clean is for the drywall repair pr	ocess. Addition	al final clean line it	ems may be ne	cessary for ot	her repair proc	esses.	
Installation			,				

261.68

1,813.18

10,878.82

1,359.47


9,519.35



United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884



S_5_ANDERSON-EYE-1

Break room

Height: 8'

Page: 49

8/4/2022

290.50 SF Walls 383.00 SF Walls & Ceiling 10.28 SY Flooring 38.50 LF Ceil. Perimeter 92.50 SF Ceiling 92.50 SF Floor

36.00 LF Floor Perimeter

2' 6" X 7'

Opens into SIDE_HALLWA2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories		, .					
702. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA	88.02	0.00	17.60	105.62	(0.00)	105.62
703. Outlet or switch - Detach & reset	8.00 EA	16.28	0.00	26.04	156.28	(0.00)	156.28
704. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
705. Breaker panel - 200 amp	2.00 EA	140.43	0.00	56.18	337.04	(0.00)	337.04
Remove							
706. Breaker panel - 200 amp	2.00 EA	822.69	0.00	329.08	1,974.46	(329.07)	1,645.39
Reset							
Begin Drywall Repairs							
Removal							
707. Mask and prep for paint - plastic, paper, tape (per LF)	77.00 LF	1.44	2.03	22.58	135.49	(45.16)	90.33
708. Tear out wet drywall, cleanup, bag - Cat 3	383.00 SF	1.25	5.97	96.96	581.68	(0.00)	581.68
Walls/Ceiling							
709. Tear out and bag wet insulation - Category 3 water	332.50 SF	1.06	1.95	70.90	425.30	(0.00)	425.30
Ceiling & Exterior Walls							
Installation							
710. Apply anti-microbial agent to more than the walls and ceiling	475.50 SF	0.24	1.85	23.20	139.17	(0.00)	139.17
Application of antimicrobial to the water de	amaged space b	efore installation					
711. 5/8" drywall - hung, taped, ready for texture	92.50 SF	2.20	5.86	41.88	251.24	(8.38)	242.86
5/8 for the ceiling							
712. Blown-in insulation - 10" depth - R26	92.50 SF	1.08	7.13	21.40	128.43	(4.29)	124.14
Blown-in for the ceiling							
713. Batt insulation - 6" - R19 - unfaced batt	240.00 SF	1.00	16.61	51.32	307.93	(10.27)	297.66
714. 1/2" drywall - hung, taped, ready for texture	290.50 SF	2.10	17.28	125.48	752.81	(25.10)	727.71
715. Texture drywall - smooth / skim coat	92.50 SF	1.33	0.90	24.78	148.71	(4.95)	143.76
For the ceiling							
716. Clean the ceiling	92.50 SF	0.34	0.09	6.32	37.86	(0.00)	37.86
Ceiling/walls must be cleaned prior to appl	ication of paint.						



United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Break room


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
717. Paint the ceiling - two coats	92.50 SF	1.00	2.16	18.94	113.60	(37.87)	75.73
718. Final cleaning - construction - Residential	185.00 SF	0.26	0.00	9.62	57.72	(0.00)	57.72
This final clean is for the drywall repair pr	ocess. Addition	al final clean line it	ems may be ne	cessary for oth	er repair prod	cesses.	
Begin Carpet Repairs				-			
Removal							
719. Interior door unit	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
720. Tear out trim and bag for disposal - up to Cat 3	36.00 LF	0.86	0.63	6.32	37.91	(0.00)	37.91
721. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	6.01	0.00	1.20	7.21	(0.00)	7.21
722. Tear out baseboard and bag for disposal - up to Cat 3	36.00 LF	0.86	0.63	6.32	37.91	(0.00)	37.91
723. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	92.50 SF	1.35	0.54	25.08	150.50	(0.00)	150.50
724. Carpet	106.38 SF	3.27	28.11	75.20	451.17	(225.59)	225.58
725. Baseboard - 3 1/4"	36.00 LF	3.28	5.83	24.78	148.69	(4.95)	143.74
726. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
727. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
728. Paint baseboard - two coats	36.00 LF	1.49	0.49	10.82	64.95	(21.64)	43.31
729. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
730. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51
To move contents back in							

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Break room	111.35	1.157.94	6.947.37	756 19	6 191 18
I Utais. Di Cak I UVIII	111.35	1.157.94	0.947.17	/50.19	6.191 IX



S_5_ANDERSON-EYE-1

8/4/2022

Page: 50



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
731. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
Begin Drywall Repairs							
Removal							
732. Mask and prep for paint - plastic, paper, tape (per LF)	25.83 LF	1.44	0.68	7.58	45.46	(15.15)	30.31
733. Shelving - 24" - in place	10.00 LF	0.58	0.00	1.16	6.96	(0.00)	6.96
734. Tear out wet drywall, cleanup, bag - Cat 3	123.65 SF	1.25	1.93	31.30	187.79	(0.00)	187.79
Walls/Ceiling							
735. Tear out and bag wet insulation - Category 3 water	20.31 SF	1.06	0.12	4.32	25.97	(0.00)	25.97
Walls/Ceiling							
Installation						(0.00)	40.15
736. Apply anti-microbial agent to more than the walls and ceiling	143.96 SF	0.24	0.56	7.04	42.15	(0.00)	42.15
Application of antimicrobial to the water da							
737. 5/8" drywall - hung, taped, ready for texture	20.31 SF	2.20	1.29	9.20	55.17	(1.83)	53.34
5/8 for the ceiling				4.50	20.10	(0.04)	27.25
738. Blown-in insulation - 10" depth - R26	5 20.31 SF	1.08	1.56	4.70	28.19	(0.94)	27.25
Blown-in for the ceiling					0 (5 50	(0.01)	260.07
739. 1/2" drywall - hung, taped, ready for texture	103.33 SF		6.15	44.64	267.78	(8.91)	258.87
740. Shelving - 24" - in place	10.00 LF		6.45	25.70	154.15	(5.15)	149.00
741. Texture drywall - smooth / skim coat	20.31 SF	1.33	0.20	5.44	32.65	(1.09)	31.56
For the ceiling						(0.00)	0.21
742. Clean the ceiling	20.31 SF	0.34	0.02	1.38	8.31	(0.00)	8.31
Ceiling/walls must be cleaned prior to appl	ication of paint					40.04	14.40
743. Paint the ceiling - two coats	20.31 SF	1.00	0.47	4.16	24.94	(8.31)	16.63
744. Final cleaning - construction - Residential	40.63 SF		0.00	2.12	12.68	(0.00)	12.68
This final clean is for the drywall repair pro	ocess. Addition	ial final clean line it	ems may be ne	cessary for oth	er repair pro	cesses.	
Begin Carpet Repairs							
Removal						(0.00)	21.52
745. Interior door unit	1.00 EA		0.00	3.58	21.50	(0.00)	21.50
746. Tear out trim and bag for disposal - up to Cat 3	12.92 LF		0.23	2.26	13.60	(0.00)	13.60
747. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	1.20	7.21	(0.00)	7.2.1
748. Tear out baseboard and bag for disposal - up to Cat 3	12.92 LF		0.23	2.26	13.60	(0.00)	13.60
749. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	20.31 SF		0.12	5.50	33.04	(0.00)	33.04
750. Carpet	23.36 SF		6.17	16.52	99.08	(49.55)	49.53
751. Baseboard - 3 1/4"	12.92 LF	3.28	2.09	8.90	53.37	(1.78)	51.59

8/4/2022 Page: 51 S_5_ANDERSON-EYE-1



UCS

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Closet

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
752. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA	165.62	12.03	35.52	213.17	(7.10)	206.07
753. Interior door unit	1.00 EA	48.59	0.00	9.72	58.31	(2.91)	55.40
754. Paint baseboard - two coats	12.92 LF	1.49	0.18	3.90	23.33	(7.78)	15.55
755. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30
756. Paint door slab only - 2 coats (per side)	1.00 EA	38.60	0.78	7.88	47.26	(15.75)	31.51

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

•	 -				
Totals: Closet	41.74	255.22	1,531.12	139.41	1,391.71

Boss	office						Height: 8'
3, 9, 10, 1, 2	355.83 S	F Walls			162.71 SF	Ceiling	
	518.54 S	F Walls & Ce	iling		162.71 SF	Floor	
Boss office Side hallw	18.08 S	Y Flooring	_		46.17 LF	Floor Perimeter	r
7 Close	51.17 L	F Ceil. Perime	eter				
-3' 2" - 9' 2" - 1" 1"							
Window	3' 1" >	۲3'		Opens into	Exterior		
Window	3' 1" ን	۲3'		Opens into	Exterior		
Door	2' 6" እ	۲ <i>7</i> '		Opens into	WORKSH	ЮP	
Door	2' 6" 2	ζ 7'		Opens into	ROOM1		
DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories						<u> </u>	
757. Fluorescent light fixture - 6' & 8' - Detach & reset	2.00 EA	88.02	0.00	35.20	211.24	(0.00)	211.24
758. Outlet or switch - Detach & reset	16.00 EA	16.28	0.00	52.10	312.58	(0.00)	312.58
759. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99
Begin Drywall Repairs							
Removal							
760. Mask and prep for paint - plastic, paper, tape (per LF)	102.33 LF	1.44	2.69	30.02	180.07	(60.02)	120.05



United Claims Service, Inc. 26 Japanood Place

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Boss office

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
761. Tear out wet drywall, cleanup, bag -	518.54 SF	1.25	8.09	131.26	787.53	(0.00)	787.53
Walls/Ceiling							
762. Tear out and bag wet insulation - Category 3 water	258.71 SF	1.06	1.51	55.14	330.88	(0.00)	330.88
Ceiling & Exterior Wall							
Installation							
763. Apply anti-microbial agent to more han the walls and ceiling	681.25 SF	0.24	2.66	33.24	199.40	(0.00)	199.40
Application of antimicrobial to the water da	maged space b	efore installation of	new drywall a	ınd insulation.			
764. 5/8" drywall - hung, taped, ready for exture	162.71 SF	2.20	10.31	73.66	441.93	(14.73)	427.20
6/8 for the ceiling							
765. Blown-in insulation - 10" depth - R26	162.71 SF	1.08	12.53	37.64	225.90	(7.54)	218.36
Blown-in for the ceiling							
66. Batt insulation - 6" - R19 - unfaced patt	96.00 SF	1.00	6.65	20.54	123.19	(4.10)	119.09
67. 1/2" drywall - hung, taped, ready for exture	355.83 SF	2.10	21.16	153.68	922.08	(30.74)	891.34
68. Texture drywall - smooth / skim coat	162.71 SF	1.33	1.59	43.60	261.59	(8.72)	252.87
For the ceiling							
769. Clean the ceiling	162.71 SF	0.34	0.16	11.10	66.58	(0.00)	66.58
Ceiling/walls must be cleaned prior to appli	cation of paint						
770. Paint the ceiling - two coats	162.71 SF	1.00	3.81	33.30	199.82	(66.61)	133.21
771. Final cleaning - construction - Residential	325.42 SF	0.26	0.00	16.92	101.53	(0.00)	101.53
This final clean is for the drywall repair pro	cess. Addition	al final clean line ite	ems may be ne	cessary for oth	er repair proc	esses.	
Begin Carpet Repairs							
Removal							
772. Interior door unit	2.00 EA	17.92	0.00	7.16	43.00	(0.00)	43.00
773. Tear out trim and bag for disposal - up to Cat 3	46.17 LF	0.86	0.81	8.10	48.62	(0.00)	48.62
774. Door opening (jamb & casing) - 2"to36"wide - paint grade	2.00 EA	6.01	0.00	2.40	14.42	(0.00)	14.42
775. Tear out baseboard and bag for lisposal - up to Cat 3	46.17 LF	0.86	0.81	8.10	48.62	(0.00)	48.62
76. Tear out wet non-salv. gluedn. cpt, ut/bag - Cat 3 water	162.71 SF	1.35	0.95	44.14	264.75	(0.00)	264.75
777. Carpet	187.11 SF	3.27	49.44	132.26	793.55	(396.79)	396.76
778. Baseboard - 3 1/4"	46.17 LF	3.28	7.47	31.78	190.69	(6.36)	184.33
779. Door opening (jamb & casing) - 2"to36"wide - paint grade	2.00 EA	165.62	24.06	71.06	426.36	(14.20)	412.16
5_ANDERSON-EYE-1					8	8/4/2022	Page:



United Claims Service, Inc.

26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Boss office


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
780. Interior door unit	2.00 EA	48.59	0.00	19.44	116.62	(5.84)	110.78
781. Paint baseboard - two coats	46.17 LF	1.49	0.63	13.88	83.30	(27.76)	55.54
782. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA	32.40	0.95	13.16	78.91	(26.30)	52.61
783. Paint door slab only - 2 coats (per side)	2.00 EA	38.60	1.57	15.76	94.53	(31.51)	63.02

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Boss office 157.85 1,097.30 6,583.68 701.22 5,882.46



Contacts room

323.25 SF Walls 452.23 SF Walls & Ceiling 14.33 SY Flooring 40.41 LF Ceil. Perimeter

Height: 8'

128.98 SF Ceiling 128.98 SF Floor 40.41 LF Floor Perimeter

Mi	ssin	g١	W	all

6' 7" X 8'

Opens into FRONT_HALLW2

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Accessories							
784. Outlet or switch - Detach & reset	10.00 EA	16.28	0.00	32.56	195.36	(0.00)	195.36
785. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA	13.33	0.00	5.34	32.00	(0.00)	32.00
786. Fluorescent light fixture - 6' & 8' - Detach & reset	3.00 EA	88.02	0.00	52.82	316.88	(0.00)	316.88
Begin Drywall Repairs							
Removal							
787. Mask and prep for paint - plastic, paper, tape (per LF)	80.81 LF	1.44	2.13	23.70	142.20	(47.40)	94.80
788. Tear out wet drywall, cleanup, bag - Cat 3	452.23 SF	1.25	7.06	114.48	686.83	(0.00)	686.83
Walls/Ceiling							
789. Tear out and bag wet insulation - Category 3 water Walls/Ceiling	128.98 SF	1.06	0.75	27.50	164.97	(0.00)	164.97

Installation

S_5_ANDERSON-EYE-1

8/4/2022

Page: 54



United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Contacts room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
790. Apply anti-microbial agent to more than the walls and ceiling	581.22 SF	0.24	2.27	28.36	170.12	(0.00)	170.12
Application of antimicrobial to the water da	maged space b	efore installation of	new drywall a	nd insulation.			
791. 5/8" drywall - hung, taped, ready for texture	128.98 SF	2.20	8.17	58.40	350.33	(11.67)	338.66
5/8 for the ceiling							
792. Blown-in insulation - 10" depth - R26	128.98 SF	1.08	9.93	29.84	179.07	(5.97)	173.10
Blown-in for the ceiling							
793. Clean stud wall	323.25 SF	0.74	0.63	47.96	287.80	(0.00)	287.80
794. 1/2" drywall - hung, taped, ready for texture	323.25 SF	2.10	19.23	139.60	837.66	(27.93)	809.73
795. Texture drywall - smooth / skim coat	128.98 SF	1.33	1.26	34.56	207.36	(6.92)	200.44
For the ceiling							
796. Clean the ceiling	128.98 SF	0.34	0.13	8.80	52.78	(0.00)	52.78
Ceiling/walls must be cleaned prior to appli	cation of paint.						
797. Paint the ceiling - two coats	128.98 SF	1.00	3.02	26.40	158.40	(52.80)	105.60
798. Final cleaning - construction - Residential	386.95 SF	0.26	0.00	20.12	120.73	(0.00)	120.73
This final clean is for the drywall repair pro	cess. Addition	al final clean line it	ems may be ne	cessary for ot	her repair proc	esses.	
Begin Cabinetry Repair							
Removal							
799. Sink faucet - Kitchen	1. 00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
800. Sink - single	1.00 EA	17.92	0.00	3.58	21.50	(0.00)	21.50
801. 6" backsplash for flat laid countertop	7.00 LF	0.86	0.00	1.20	7.22	(0.00)	7.22
802. Countertop - flat laid plastic laminate	7.00 LF	4.12	0.00	5.76	34.60	(0.00)	34.60
303. Cabinetry - lower (base) units	7.00 LF	7.17	0.00	10.04	60.23	(0.00)	60.23
Installation							
804. Cabinetry - lower (base) units	7.00 LF	222.16	129.25	336.88	2,021.25	(202.11)	1,819.14
805. Countertop - flat laid plastic laminate	7.00 LF	40.57	19.97	60.80	364.76	(121.58)	243.18
806. 6" backsplash for flat laid countertop	7.00 LF	10.62	5.51	15.96	95.81	(31.94)	63.87
807. Sink - single	1.00 EA	91.87	0.00	18.38	110.25	(11.03)	99.22
Begin Carpet Repairs							
Removal							
308. Tear out trim and bag for disposal - up to Cat 3	40.41 LF	0.86	0.71	7.10	42.56	(0.00)	42.56
809. Door opening (jamb & casing) - 36"to60"wide - paint grade	1.00 EA		0.00	1.20	7.21	(0.00)	7.21
310. Tear out baseboard and bag for disposal - up to Cat 3	40.41 LF	0.86	0.71	7.10	42.56	(0.00)	42.56
311. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	128.98 SF	1.35	0.75	34.98	209.85	(0.00)	209.85
5 ANDERSON-EYE-1					(3/4/2022	Page



UCS

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529

Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Contacts room

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
812. Carpet	148.33 SF	3.27	39.19	104.84	629.07	(314.54)	314.53
813. Baseboard - 3 1/4"	40.41 LF	3.28	6.54	27.80	166.88	(5.56)	161.32
814. Door opening (jamb & casing) - 36"to60"wide - paint grade	1.00 EA	195.96	14.17	42.04	252.17	(8.40)	243.77
815. Paint baseboard - two coats	40.41 LF	1.49	0.55	12.16	72.92	(24.31)	48.61
816. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA	32.40	0.48	6.58	39.46	(13.16)	26.30

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Contacts room	272.41	1,350.42	8,102.29	885.32	7,216.97

Fro	nt hallway			Height: 8'					
B . B A B	349.17 S	F Walls			166.60 SF	Ceiling			
3'5" Bronzhaliweye'3"	515.77 S	F Walls & Ce	iling		166.60 SF	Floor			
A/C 8566 12' 7" 10' 8"	18.51 S	Y Flooring	_		42.08 LF	Floor Perimete	r		
	54.58 L	F Ceil. Perim	eter						
Door	2' 6" እ	Χ 7'		Opens into	BATHRO	OM 1			
Missing Wall	6' 7" X	K 8'		Opens into CONTACTS RO2					
Door	2' 6" 2	Χ <i>7</i> '		Opens into PAPER_ROOM					
Door	2' 6" 3	Κ <i>7</i> '		Opens into ELECTRIC_ROO					
Missing Wall	4' 7 1/16" X 8'			Opens into SIDE_HALLWA2					
Missing Wall	10' 8"	10' 8" X 8'			Opens into ENTRANCE2				
Door	2' 6" 2	K 7'		Opens into FILE_ROOM2					
Door	2' 6" 3	₹ 7'		Opens into A_C_ROOM					
Missing Wall	4' 7 1/	16" X 8'		Opens into GLASSES_ROO2					
DESCRIPTION	QUANTITY UN	IT PRICE	TAX	O&P	RCV	DEPREC.	ACV		
Accessories									
817. Light fixture - Detach & reset	3.00 EA	45.40	0.00	27.24	163.44	(0.00)	163.44		
818. Outlet or switch - Detach & reset	9.00 EA	16.28	0.00	29.30	175.82	(0.00)	175.82		
819. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA	13.33	0.00	2.66	15.99	(0.00)	15.99		
S_5_ANDERSON-EYE-1					:	8/4/2022	, Page: 5		

United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Front hallway

Regin Drywall Repairs Removal	DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
820. Mask and prep for paint - plastic, paper, tape (per LP) 821. Tear out wet drywall, cleanup, bag - 515.77 SF	Begin Drywall Repairs							
### 10.00 10	Removal							
Walls/Ceiling S22. Tear out and bag wet insulation - 166.60 SF 1.06 0.98 35.52 213.10 (0.00)	820. Mask and prep for paint - plastic,	109.17 LF	1.44	2.87			, ,	128.05
822. Tear out and bag wet insulation - 166.60 SF 1.06 0.98 35.52 213.10 (0.00) Category 3 water Walls/Ceiling Installation 823. Apply anti-microbial agent to more 682.37 SF 0.24 2.66 33.30 199.73 (0.00) Installation 824. Clean stud wall 515.77 SF 0.74 1.01 76.54 459.22 (0.00) 825. 5/8" drywall - hung, taped, ready for 166.60 SF 2.20 10.56 75.42 452.50 (15.09) Restrictive 826. Blown-in insulation - 10" depth - R26 166.60 SF 1.08 12.83 38.54 231.30 (7.71) Blown-in for the ceiling 827. 1/2" drywall - hung, taped, ready for 349.17 SF 2.10 20.77 150.82 904.85 (30.15) Restruce 828. Texture drywall - smooth / skim coat 166.60 SF 1.33 1.62 44.64 267.84 (8.92) For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling 1 66.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 831. Final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs Removal 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 133. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 136. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 137. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 138. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 139. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 130. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 130. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 131. Tear out trim and bag for disposal 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 132. Total with contractive the one-salv gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) 137. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)		515.77 SF	1.25	8.05	130.56	783.32	(0.00)	783.32
Category 3 water Walls/Celling 823. Apply anti-microbial agent to more 682.37 SF 0.24 2.66 33.30 199.73 (0.00) than the walls and celling Application of antimicrobial to the water damaged space before installation of new drywall and insulation. 824. Clean stud wall 515.77 SF 0.74 1.01 76.54 459.22 (0.00) 825. 5/8" drywall - hung, taped, ready for 166.60 SF 2.20 10.56 75.42 452.50 (15.09) texture 578 for the ceiling 826. Blown-in insulation - 10" depth - R26 166.60 SF 1.08 12.83 38.54 231.30 (7.71) Blown-in for the ceiling 827. 1/2" drywall - hung, taped, ready for 349.17 SF 2.10 20.77 150.82 904.85 (30.15) texture 828. Texture drywall - smooth / skim coat 166.60 SF 1.33 1.62 44.64 267.84 (8.92) For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 331. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 32" to36"wide - paint grade 833. Tar out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) to Cat 335. Tear out baseboard and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32" to36"wide - paint grade 835. Tear out baseboard and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	Walls/Ceiling							
Installation		166.60 SF	1.06	0.98	35.52	213.10	(0.00)	213.10
823. Apply anti-microbial agent to more 682.37 SF 0.24 2.66 33.30 199.73 (0.00) than the walls and ceiling Application of antimicrobial to the water damaged space before installation of new drywall and insulation. 824. Clean stud wall 515.77 SF 0.74 1.01 76.54 459.22 (0.00) 825. 5/8" drywall - hung, taped, ready for 166.60 SF 2.20 10.56 75.42 452.50 (15.09) texture 825. 5/8" drywall - hung, taped, ready for 166.60 SF 1.08 12.83 38.54 231.30 (7.71) Blown-in for the ceiling 826. Blown-in insulation - 10" depth - R26 166.60 SF 1.08 12.83 38.54 231.30 (7.71) Blown-in for the ceiling 827. 1/2" drywall - hung, taped, ready for 349.17 SF 2.10 20.77 150.82 904.85 (30.15) texture 828. Texture drywall - smooth / skim coat 166.60 SF 1.33 1.62 44.64 267.84 (8.92) For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs Removal 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) up to Cat 3 33. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 33. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 33. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 33. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	Walls/Ceiling							
Application of antimicrobial to the water damaged space before installation of new drywall and insulation. 824. Clean stud wall 515.77 SF 0.74 1.01 76.54 459.22 (0.00) 825. 5/8" drywall - hung, taped, ready for 166.60 SF 2.20 10.56 75.42 452.50 (15.09) texture 5/8 for the ceiling 826. Blown-in insulation - 10" depth - R26 166.60 SF 1.08 12.83 38.54 231.30 (7.71) Blown-in for the ceiling 827. 1/2" drywall - hung, taped, ready for 349.17 SF 2.10 20.77 150.82 904.85 (30.15) texture 828. Texture drywall - smooth / skim coat 166.60 SF 1.33 1.62 44.64 267.84 (8.92) For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 21°0.56" wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	823. Apply anti-microbial agent to more	682.37 SF	0.24	2.66	33.30	199.73	(0.00)	199.73
824. Clean stud wall 515.77 SF 0.74 1.01 76.54 459.22 (0.00) 825. 5/8" drywall - hung, taped, ready for 166.60 SF 2.20 10.56 75.42 452.50 (15.09) texture 5/8 for the ceiling 826. Blown-in insulation - 10" depth - R26 166.60 SF 1.08 12.83 38.54 231.30 (7.71) Blown-in for the ceiling 827. 1/2" drywall - hung, taped, ready for 349.17 SF 2.10 20.77 150.82 904.85 (30.15) texture 828. Texture drywall - smooth / skim coat 166.60 SF 1.33 1.62 44.64 267.84 (8.92) For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs Removal 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)		maged space be	efore installation of	new drywall a	nd insulation.			
825. 5/8" drywall - hung, taped, ready for 166.60 SF 2.20 10.56 75.42 452.50 (15.09) texture 5/8 for the ceiling 826. Blown-in insulation - 10" depth - R26 166.60 SF 1.08 12.83 38.54 231.30 (7.71) Blown-in for the ceiling 827. 1/2" drywall - hung, taped, ready for 349.17 SF 2.10 20.77 150.82 904.85 (30.15) texture 828. Texture drywall - smooth / skim coat 166.60 SF 1.33 1.62 44.64 267.84 (8.92) For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)						459.22	(0.00)	459.22
826. Blown-in insulation - 10" depth - R26	825. 5/8" drywall - hung, taped, ready for	166.60 SF	2.20	10.56	75.42	452.50	(15.09)	437.41
Blown-in for the ceiling 827. 1/2" drywall - hung, taped, ready for 349.17 SF 2.10 20.77 150.82 904.85 (30.15) texture 828. Texture drywall - smooth / skim coat 166.60 SF 1.33 1.62 44.64 267.84 (8.92) For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	5/8 for the ceiling							
827. 1/2" drywall - hung, taped, ready for 349.17 SF 2.10 20.77 150.82 904.85 (30.15) texture 828. Texture drywall - smooth / skim coat 166.60 SF 1.33 1.62 44.64 267.84 (8.92) For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Removal 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	826. Blown-in insulation - 10" depth - R26	166.60 SF	1.08	12.83	38.54	231.30	(7.71)	223.59
Rexidential Trial clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Removal Residential Solution door unit Soluti	Blown-in for the ceiling							
For the ceiling 829. Clean the ceiling 166.60 SF 0.34 0.16 11.36 68.16 (0.00) Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)		349.17 SF	2.10	20.77	150.82	904.85		874.70
Regional Repairs Removal 832. Interior door unit 5.00 EA 17.92 10.00 17.32 107.52 10.00 17.32 107.52 10.00 17.32 107.52 10.00 17.32 107.52 10.00 17.32 107.52 10.00 17.32 107.52 10.00 17.32 107.52 10.00 17.32 107.52 10.00 17.33 10.00 17.32 10.00 17.38 44.31 10.00 10.	828. Texture drywall - smooth / skim coat	166.60 SF	1.33	1.62	44.64	267.84	(8.92)	258.92
Ceiling/walls must be cleaned prior to application of paint. 830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	For the ceiling							
830. Paint the ceiling - two coats 166.60 SF 1.00 3.90 34.10 204.60 (68.19) 831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36" wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	829. Clean the ceiling	166.60 SF	0.34	0.16	11.36	68.16	(0.00)	68.16
831. Final cleaning - construction - 333.20 SF 0.26 0.00 17.32 103.95 (0.00) Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Removal 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 100 up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 120 "to36" wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 120 "to36" wide - paint grade 836. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 120 "to36" cut wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) 121 "to36" cut wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) 121 "to36" cut wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00)	Ceiling/walls must be cleaned prior to appl	cation of paint.						
Residential This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes. Begin Carpet Repairs **Removal** 832. Interior door unit	830. Paint the ceiling - two coats	166.60 SF	1.00	3.90	34.10	204.60	(68.19)	136.41
Begin Carpet Repairs Removal	Residential							103.95
Removal 832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - up to Cat 3 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 834. Door opening (jamb & casing) - 32"to36"wide - paint grade 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 835. Tear out baseboard and bag for disposal - up to Cat 3 42.08 LF 0.86 0.74 7.38 44.31 (0.00) 836. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water 166.60 SF 1.35 0.98 45.18 271.07 (0.00) 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	This final clean is for the drywall repair pro	cess. Additiona	al final clean line it	ems may be ne	cessary for oth	er repair prod	cesses.	
832. Interior door unit 5.00 EA 17.92 0.00 17.92 107.52 (0.00) 833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	Begin Carpet Repairs							
833. Tear out trim and bag for disposal - 42.08 LF 0.86 0.74 7.38 44.31 (0.00) up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	Removal							
up to Cat 3 834. Door opening (jamb & casing) - 5.00 EA 6.01 0.00 6.02 36.07 (0.00) 32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	832. Interior door unit	5.00 EA	17.92				• •	107.52
32"to36"wide - paint grade 835. Tear out baseboard and bag for 42.08 LF 0.86 0.74 7.38 44.31 (0.00) disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)								44.31
disposal - up to Cat 3 836. Tear out wet non-salv. gluedn. cpt, 166.60 SF 1.35 0.98 45.18 271.07 (0.00) cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)		5.00 EA					` ,	36.07
cut/bag - Cat 3 water 837. Carpet 191.59 SF 3.27 50.62 135.42 812.54 (406.28)	disposal - up to Cat 3						•	44.31
ost. Curpor								271.07
_5_ANDERSON-EYE-1 8/4/2022	837. Carpet	191.59 SF	3.27	50.62	135.42	812.54	(406.28)	406.26
	_5_ANDERSON-EYE-1					:	8/4/2022	Page:



Phone: (800) 827-8279 Fax: (800) 786-8884

CONTINUED - Front hallway

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
838. Baseboard - 3 1/4"	42.08 LF	3.28	6.81	28.96	173.79	(5.79)	168.00
839. Door opening (jamb & casing) - 32"to36"wide - paint grade	5.00 EA	165.62	60.15	177.66	1,065.91	(35.52)	1,030.39
840. Interior door unit	5.00 EA	48.59	0.00	48.60	291.55	(14.59)	276.96
841. Paint baseboard - two coats	42.08 LF	1.49	0.57	12.66	75.93	(25.31)	50.62
842. Paint door/window trim & jamb - 2 coats (per side)	5.00 EA	32.40	2.38	32.88	197.26	(65.75)	131.51
843. Paint door slab only - 2 coats (per side)	5.00 EA	38.60	3.92	39.38	236.30	(78.76)	157.54

To move contents back in.

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Installation

Totals: Front hallway	192.32	1,298.78	7,792.47	826.10	6,966.37
Total: Interior	5,186.41	28,340.22	189,714.67	17,451.31	172,263.36

Dumpster


DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Begin Supplement by Mike Knight on	03/16/2022						
844. Dumpster load - Approx. 30 yards, 5-7 tons of debris	3.00 EA	557.69	0.00	334.62	2,007.69	(0.00)	2,007.69

Allowance for one (1) dumpster for the roof and for the interior debris. Consideration for the removal/hauling of all construction/repair related debris.

End Supplement by Mike Knight on 03/16/2022

Totals: Dumpster	0.00	334.62	2,007.69	0.00	2,007.69
Line Item Totals: S_5_ANDERSON-EYE-1	7,297.91	38,523.78	250,816.22	32,019.09	218,797.13

S_5_ANDERSON-EYE-1 8/4/2022 Fage: 58





United Claims Service, Inc. 26 Japwood Place Garner, NC 27529 Phone: (800) 827-8279 Fax: (800) 786-8884

Summary for Loc 001 Bldg 001 113 E Locust St

Line Item Total	204,994.53
Material Sales Tax	6,940.27
P Ppty Material Tax	141.92
Storage Rental Tax	59.96
Subtotal	212,136.68
Overhead	19,261.89
Profit	19,261.89
P Ppty Cleaning Tax	155.76
Replacement Cost Value	\$250,816.22
Less Depreciation	(32,019.09)
Actual Cash Value	\$218,797.13
Less Deductible	(1,000.00)
Less Prior Payment(s)	(41,448.60)
Net Claim Remaining	\$176,348.53
Total Recoverable Depreciation	32,019.09
Net Claim Remaining if Depreciation is Recovered	\$208,367.62

Michael Knight

8/4/2022 Page: 60 S_5_ANDERSON-EYE-1



Phone: (800) 827-8279 Fax: (800) 786-8884

Grand Total Areas:

3,136.58	SF Walls SF Floor SF Long Wall	348.51	SF Ceiling SY Flooring SF Short Wall	991.80	SF Walls and Ceiling LF Floor Perimeter LF Ceil. Perimeter
,	Floor Area Exterior Wall Area	-,	Total Area Exterior Perimeter of Walls	7,924.33	Interior Wall Area
	Surface Area Total Ridge Length		Number of Squares Total Hip Length	0.00	Total Perimeter Length

Coverage	Item Total	%	ACV Total	%
Loc 001 Bldg 001 113 E Locust St	250,816.22	100.00%	218,797.13	100.00%
PWI	0.00	0.00%	0.00	0.00%
Total	250,816.22	100.00%	218,797.13	100.00%

S_5_ANDERSON-EYE-1 Page: 59 8/4/2022

WG

128 Poplar Street, Gadsden, TN 38337

Insured: Anderson Eye Clinic 113 E Locust St Property:

Dresden, TN 38225

Claim Number:

Policy Number:

Date Received:

Date Entered: 12/27/2021 12:00 AM

1/10/2022 3:07 PM Date Est. Completed:

TNJA8X JAN23

Restoration/Service/Remodel

ANDERSONEYECLINIC_A1 Estimate:

This damage assessment utilizes and abides to the following documentation:

- Manufacturer Installation Instructions

- Local Building and Zoning Code

- International Building Code (IBC)

- International Residential Code (IRC)

- International Energy Conservation Code (IECC)

Labor rates have been corrected to reflect their proper trade, where applicable.

Additional documentation will be provided upon request. This assessment only represents known damages at this time and can be amended.

Respectfully,

William Griffin, Public Insurance Adjuster


////// NOTICE ///////

The intent of this document is to include all amounts of loss required to restore the damages to replacement cost condition using a professional licensed General Contractor, who is required to abide by all state regulated building codes, employs or contracts office staff, schedulers and project type supervisors of all applicable specialty trade sub-contractors; performs all permit processes, complies with OSHA regulations, and maintains general liability insurance for this project, and worker's compensation for the employees/subcontractors that they supervise or that otherwise enter the job site while work is in progress. General Contractors overhead and profit is charged on all projects, as well as the job related overhead general conditions, as all contractors are required to follow adopted building codes and local codes and enforcement requirements. The default demolition general labor (DMO) in the "unit price" of Xactimate removal line items is not used on any specialty, licensed, and/or hazardous trade in this estimate. This is required to appropriately represent the cost of job-personnel overhead that is built into Xactimate's line item price. Overhead and labor adjustments have been made due to the current, or projected, economic and inflationary environment factors and pricing indexes that contractors are working under, and are subject to change as labor, equipment, and fuel prices, etc. fluctuate.

Date of Loss:

Date Inspected:

Price List:



WIG

21. Asphalt starter - laminated double

layer starter

128 Poplar Street, Gadsden, TN 38337



DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Tear Off							
All of the following are tear off line items General Liability insurances along with t burdens.	s and in Florida an the safety condition	yone who work ns present in th	s on a roof car e roofing trade.	ries the burden of These items have	roofing Workm been updated t	an's Compens o reflect the co	ation and orrect labor
1,221. Tear off, haul and dispose of comp. shingles - 3 tab	42.15 SQ		89.91	0.00	0.00	947.43	4,737.1
2. Remove Ridge cap - composition shingles	159.00 LF		1.77	0.00	0.00	70.35	351.7
1,222. Remove Continuous ridge vent - shingle-over style	159.00 LF		1.51	0.00	0.00	60.02	300.1
4. Remove Counterflashing - Apron flashing	5.00 LF		1.06	0.00	0.00	1.33	6.6
5. Step Flashing Removal	5.00 HR		0.00	81.39	0.00	101.74	508.6
1,224. Remove Exhaust cap - through roof - 6" to 8"	1.00 EA		16.13	0.00	0.00	4.03	20.1
1,225. Remove Flat roof exhaust vent / cap - gooseneck 12"	1.00 EA		16.13	0.00	0.00	4.03	20.1
1,226. Remove Flashing - pipe jack	1.00 EA		12.65	0.00	0.00	3.17	15.8
1,227. R&R Sheathing - OSB - 5/8"	224.00 SF		1.01	1.71	17.25	156.64	783.1
Dry In Process							
10. Prepare deck sheathing for felt	4,215.00 SF		0.00	0.32	4.11	338.23	1,691.1
11. Roofing felt - 15 lb.	46.37 SQ		0.00	23.61	32.51	281.83	1,409.1
12. Ice & water barrier	113.70 SF		0.00	1.22	5.32	36.01	180.0
13. Drip edge/gutter apron	330.00 LF		0.00	2.28	40.22	198.15	990.7
14. Step flashing	5.00 LF		0.00	7.20	0.96	9.24	46.2
15. Counterflashing - Apron flashing	5.00 LF		0.00	7.06	0.85	9.05	45.2
16. Exhaust cap - through roof - 6" to 8"	1.00 EA		0.00	77.69	4.35	20.51	102.5
17. Flat roof exhaust vent / cap - gooseneck 12"	1.00 EA		0.00	71.04	3.71	18.69	93.4
18. Flashing - pipe jack	6.00 EA		0.00	35.27	8.55	55.04	275.2
19. Prime & paint roof jack	1.00 EA		0.00	37.04	0.76	9.45	47.2
Material Staging							
20. Labor for staging of materials.	4.00 HR		0.00	81.39	0.00	81.39	406.9

ANDERSONEYECLINIC_A1 2/1/2023 ,Page: 2-

0.00

3.70

65.32

321.58

1,607.90

330.00 LF



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Roof

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Starter course comes in 78 LF bundles a	ınd is not included i	n the field shin	igle line item.				
22. 3 tab - 25 yr comp. shingle roofing - w/out felt	46.67 SQ		0.00	191.38	522.29	2,363.50	11,817.49
Includes a standard 10% cutting loss fac	ctor for a gable roo	f.					
23. Continuous ridge vent - shingle-over style	159.00 LF		0.00	7.44	61.85	311.21	1,556.02
24. Ridge cap - composition shingles	159.00 LF		0.00	3.36	21.39	138.91	694.54
Ridge cap rounded up to account for 28 under roofing, this is not included in wa	LF bundles and is t	not included in	the field shing	le line item. As per	r description in	the second lin	e item
25. Final clean up of jobsite.	4,215.00 SF		0.00	0.28	0.00	295.05	1,475.25
Removal line items only include cleaning	g for immediate are	a which is the	roof top. This a	loes not including	cleaning up ar	ound the groun	nds.
Totals: Roof					789.44	5,836.58	29,182.75

Soffit/Fascia/Gutters

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
26. R&R Soffit - wood	30.00 SF		0.51	5.79	6.84	48.97	244.81
27. R&R Fascia - 1" x 6" - #1 pine	48.00 LF		0.56	6.59	10.53	88.43	442.16
28. R&R Gutter / downspout - aluminum - up to 5"	201.00 LF		0.85	8.29	100.54	484.42	2,422.10
29. R&R Gutter guard/screen	141.00 LF		0.63	3.25	19.25	141.59	707.92
Totals: Soffit/Fascia/Gutters					137.16	763.41	3,816.99

Windows

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Begin Window Repairs							
Removal							
30. Remove Wood window - single hung, 9-12 sf	2.00 EA		56.88	0.00	0.00	28.44	142.20
31. Remove Wood window - double hung, 9-12 sf	4.00 EA		56.88	0.00	0.00	56.88	284.40
32. Remove Wood window - single hung, 20-28 sf	1.00 EA		70.24	0.00	0.00	17.56	87.80
33. Remove Specialty wood window unit, 63-70 sf	1.00 EA		70.24	0.00	0.00	17.56	87.80
Installation							
NDERSONEYECLINIC_A1					2/1	/2023	Page:



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Windows

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
34. 2" x 4" lumber - treated (.667 BF per LF)	126.65 LF		0.00	2.71	12.60	88.95	444.77
Material for window bucking							
35. Carpentry - General Laborer - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.20
Labor to remove and replace window buc	king						
36. Wood window - single hung, 9-12 sf	2.00 EA		0.00	568.01	92.32	307.08	1,535.42
37. Wood window - double hung, 9-12 sf	4.00 EA		0.00	668.63	223.89	724.60	3,623.01
38. Wood window - single hung, 20-28 sf	1.00 EA		0.00	882.05	73.70	238.95	1,194.70
39. Specialty wood window unit, 63-70 sf	1.00 EA		0.00	2,960.23	278.38	809.65	4,048.26
40. Add. charge for a retrofit window,3-11 sf - difficult	4.00 EA		0.00	150.86	5.23	152.16	760.83
41. Add. charge for a retrofit window, 12-23 sf - difficult	3.00 EA		0.00	207.56	7.02	157.42	787.12
42. Add. charge for a retrofit window, 63-70 sf - difficult	1.00 EA		0.00	266.35	3.42	67.44	337.21
43. Additional charge for wood window mullion - per LF	6.83 LF		0.00	19.70	10.70	36.32	181.57
44. Flashing - Sill flashing - moldable tape	126.65 LF		0.00	7.28	33.83	238.95	1,194.79
The entire opening of each window must	be flashed. This w	ould be install	led inside the w	indow frame ope	ning.		
45. R&R Metal Z flashing / drip cap	49.51 LF		0.99	2.33	3.57	41.99	209.93
Metal flashing required above all opening	s.						
46. Flashing - Sill flashing - moldable tape	126.65 LF		0.00	7.28	33.83	238.95	1,194.79
This is required to flash the outside windo	ws where the nail	flange is locat	ed.				
47. Caulking - acrylic	126.65 LF		0.00	2.50	1.73	79.58	397.94
To caulk around the windows							
48. Urethane foam sealant	126.65 LF		0.00	0.91	2.96	29.56	147.77
Non-expanding foam is required around t	he frames of all ne	w windows.					
Totals: Windows			 -		783.18	3,408.08	17,040.51

Siding

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL

Begin Siding Repairs



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Siding

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Tear Off							
49. Two ladders with jacks and plank (per day)	1.00 DA		0.00	116.63	0.00	29.15	145.78
50. Remove Siding - cedar shingle	155.00 SF		1.00	0.00	0.00	38.75	193.75
51. Remove House wrap (air/moisture barrier)	155.00 SF		0.07	0.00	0.00	2.72	13.57
Installation							
52. House wrap (air/moisture barrier)	155.00 SF		0.00	0.34	2.72	13.86	69.28
53. Siding - cedar shingle	155.00 SF		0.00	9.85	101.10	406.97	2,034.82
54. Final cleaning - construction - Residential	155.00 SF		0.00	0.28	0.00	10.85	54.25
Totals: Siding					103.82	502.30	2,511.45

Framing

QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1.31 CY		154.88	370.34	19.73	176.94	884.71
23.00 EA		0.00	3.28	2.62	19.51	97.57
52.17 LF		1.45	1.50	4.48	39.61	198.00
4.00 EA		0.00	17.50	6.83	19.20	96.03
2.00 EA		0.00	10.16	1.98	5.58	27.88
3.00 EA		0.00	15.84	4.63	13.03	65.18
7.00 EA		0.00	11.44	7.81	21.97	109.86
3.00 EA		0.00	8.69	2.54	7.15	35.76
2.00 EA		0.00	7.00	1.37	3.85	19.22
1.00 EA		0.00	6.27	0.61	1.72	8.60
12.00 EA		0.00	5.59	6.54	18.40	92.02
336.24 SF		0.56	1.35	17.70	164.98	824.89
336.24 SF		0.22	1.45	0.66	140.56	702.74
336.24 SF		0.00	0.49	1.31 41.52 2/1/2023		207.59
	1.31 CY 23.00 EA 52.17 LF 4.00 EA 2.00 EA 3.00 EA 7.00 EA 3.00 EA 1.00 EA 1.00 EA 12.00 EA 336.24 SF 336.24 SF	1.31 CY 23.00 EA 52.17 LF 4.00 EA 2.00 EA 3.00 EA 7.00 EA 3.00 EA 1.00 EA 1.00 EA 12.00 EA 336.24 SF 336.24 SF	1.31 CY 154.88 23.00 EA 0.00 52.17 LF 1.45 4.00 EA 0.00 3.00 EA 0.00 7.00 EA 0.00 3.00 EA 0.00 1.00 EA 0.00 1.00 EA 0.00 12.00 EA 0.00 12.00 EA 0.00 336.24 SF 0.56 336.24 SF 0.22	1.31 CY 154.88 370.34 23.00 EA 0.00 3.28 52.17 LF 1.45 1.50 4.00 EA 0.00 17.50 2.00 EA 0.00 10.16 3.00 EA 0.00 15.84 7.00 EA 0.00 11.44 3.00 EA 0.00 8.69 2.00 EA 0.00 7.00 1.00 EA 0.00 6.27 12.00 EA 0.00 5.59 336.24 SF 0.56 1.35 336.24 SF 0.22 1.45	1.31 CY 154.88 370.34 19.73 23.00 EA 0.00 3.28 2.62 52.17 LF 1.45 1.50 4.48 4.00 EA 0.00 17.50 6.83 2.00 EA 0.00 10.16 1.98 3.00 EA 0.00 15.84 4.63 7.00 EA 0.00 11.44 7.81 3.00 EA 0.00 8.69 2.54 2.00 EA 0.00 7.00 1.37 1.00 EA 0.00 6.27 0.61 12.00 EA 0.00 5.59 6.54 336.24 SF 0.56 1.35 17.70 336.24 SF 0.22 1.45 0.66	1.31 CY 154.88 370.34 19.73 176.94 23.00 EA 0.00 3.28 2.62 19.51 52.17 LF 1.45 1.50 4.48 39.61 4.00 EA 0.00 17.50 6.83 19.20 2.00 EA 0.00 10.16 1.98 5.58 3.00 EA 0.00 15.84 4.63 13.03 7.00 EA 0.00 11.44 7.81 21.97 3.00 EA 0.00 8.69 2.54 7.15 2.00 EA 0.00 7.00 1.37 3.85 1.00 EA 0.00 6.27 0.61 1.72 12.00 EA 0.00 5.59 6.54 18.40 336.24 SF 0.56 1.35 17.70 164.98 336.24 SF 0.22 1.45 0.66 140.56



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Framing

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
69. 2" x 4" x 10' #2 & better Fir / Larch (material only)	1.00 EA		0.00	7.21	0.70	1.98	9.89
70. Temporary shoring post - Screw jack (per day)	56.00 DA		0.00	40.17	0.00	562.38	2,811.90
8 screw jacks over the course of 1 week							
Totals: Framing				·····	79.51	1,238.38	6,191.84

Stucco

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
71. Scaffold - per section (per day)	4.00 DA		0.00	25.28	0.00	25.28	126.40
2 sections over the course of 2 days							
72. Scaffolding Setup & Take down - per hour	2.00 HR		0.00	38.02	0.00	19.01	95.05
Begin Stucco Repairs							
Removal							
73. Tarp - all-purpose poly - per sq ft (labor and material)	22.59 SF		0.00	0.76	0.66	4.47	22.30
74. Remove Metal lath & stucco	336.24 SF		0.75	0.00	0.00	63.05	315.23
75. Remove House wrap (air/moisture barrier)	36.24 SF		0.05	0.00	0.00	0.45	2.26
Installation							
76. Metal lath & stucco	336.24 SF		0.00	6.00	43.60	515.26	2,576.30
77. House wrap (air/moisture barrier)	336.24 SF		0.00	0.34	5.90	30.06	150.28
78. Clean stucco	336.24 SF		0.00	0.38	0.33	32.03	160.13
This line item is to allow for proper bond	ing of the re-dash o	coat.					
79. Stucco color coat (Redash) - coarse texture	336.24 SF		0.00	3.87	19.01	330.07	1,650.33
80. Seal & paint stucco	336.24 SF		0.00	1.53	10.16	131.16	655.77
81. Remove Tarp - all-purpose poly - per sq ft (labor and material)	336.24 SF		0.08	0.00	0.00	6.73	33.63
82. Final cleaning - construction - Residential	336.24 SF		0.00	0.28	0.00	23.54	117.69
Totals: Stucco					79.66	1,181.11	5,905.37

Interior Main Level

ANDERSONEYECLINIC_A1



128 Poplar Street, Gadsden, TN 38337

_i₂·6· <u> </u>	exit						Height: 8'
Back exit	332.5 12.2	0 SF Walls 0 SF Walls 2 SY Floori 3 LF Ceil. P	ng	110.00 SF Ceiling 110.00 SF Floor 26.83 LF Floor Perimeter			er
Missing Wall	9' 2	'' X 8'		-	GLASSES_F	ROO2	
Missing Wall - Goes to Floor	4' X	ζ 6' 8''		Opens into KITCHEN2			
Door	2' 6	5" X 7'		Opens into	Exterior		
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
83. Outlet or switch - Detach & reset	6.00 EA		0.00	16.63	0.00	24.95	124.73
84. Cold air return cover - Detach & reset	1.50 EA		0.00	19.15	0.00	7.18	35.91
85. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA		0.00	89.90	0.00	22.48	112.38
86. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
Begin Drywall Repairs							
Removal					0.00	20.02	190.10
87. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To remove contents.					0.00	12.20	61.93
88. Mask and prep for paint - plastic, paper, tape (per LF)	33.33 LF		0.00	1.46	0.88	12.39	
89. Floor protection - plastic and tape - 10 mil	110.00 SF		0.00	0.32	1.29	9.12	45.61
90. Tear out wet paneling, no bagging - Cat 3	222.50 SF		0.57	0.00	0.00	31.70	158.53
91. Tear out wet drywall, cleanup, bag - Cat 3	332.50 SF		1.30	0.00	5.19	109.37	546.81
Walls/Ceiling							450.62
92. Tear out and bag wet insulation - Category 3 water	332.50 SF		1.10	0.00	1.95	91.93	459.63
Walls/Ceiling							
Installation				0.25	1.20	21.11	105.54
93. Apply anti-microbial agent to the walls and ceiling	332.50 SF		0.00	0.25	1.30	21.11	105.54
Application of antimicrobial to the water		fore installation			7.51	61.06	324.27
94. 5/8" drywall - hung, taped, ready for texture	110.00 SF		0.00	2.29	7.51	64.86	J 24. 21
5/8 for the ceiling							
ANDERSONEYECLINIC_A1					2/1	1/2023	Page: 7



CONTINUED - Back exit

95. Blown-in insulation - 10" depth - R26 Blown-in for the ceiling 96. Batt insulation - 6" - R19 - unfaced 222.50 SF batt 97. 1/2" drywall - hung, taped, ready creaty for texture 98. Paneling 222.50 SF 99. Texture drywall - smooth / skim 110.00 SF coat For the ceiling 110.00 SF Ceiling/walls must be cleaned prior to application of paint. 101. Seal the ceiling w/latex based 110.00 SF stain blocker - one coat 110.00 SF	0.00 0.00 0.00 0.00 0.00	1.10 0.97 2.18 2.40 1.38	8.69 14.32 14.10 18.22 1.29	32.42 57.53 124.80 138.05	162.11 287.68 623.95
96. Batt insulation - 6" - R19 - unfaced 222.50 SF batt 97. 1/2" drywall - hung, taped, ready 222.50 SF for texture 98. Paneling 222.50 SF 99. Texture drywall - smooth / skim 110.00 SF coat For the ceiling 110.00 SF Ceiling/walls must be cleaned prior to application of paint. 101. Seal the ceiling w/latex based 110.00 SF stain blocker - one coat	0.00 0.00 0.00	2.18 2.40	14.10 18.22	124.80	
batt 97. 1/2" drywall - hung, taped, ready 222.50 SF for texture 98. Paneling 222.50 SF 99. Texture drywall - smooth / skim 110.00 SF coat For the ceiling 110.00 SF Ceiling/walls must be cleaned prior to application of paint. 101. Seal the ceiling w/latex based 110.00 SF stain blocker - one coat	0.00 0.00 0.00	2.18 2.40	14.10 18.22	124.80	
for texture 98. Paneling 222.50 SF 99. Texture drywall - smooth / skim coat For the ceiling 100. Clean the ceiling 110.00 SF Ceiling/walls must be cleaned prior to application of paint. 101. Seal the ceiling w/latex based stain blocker - one coat	0.00 0.00	2.40	18.22		623.95
99. Texture drywall - smooth / skim 110.00 SF coat For the ceiling 110.00 SF Ceiling/walls must be cleaned prior to application of paint. 101. Seal the ceiling w/latex based 110.00 SF stain blocker - one coat	0.00			138.05	
coat For the ceiling 100. Clean the ceiling 110.00 SF Ceiling/walls must be cleaned prior to application of paint. 101. Seal the ceiling w/latex based 110.00 SF stain blocker - one coat	0.00	1.38	1.29		690.27
100. Clean the ceiling 110.00 SF Ceiling/walls must be cleaned prior to application of paint. 101. Seal the ceiling w/latex based 110.00 SF stain blocker - one coat				38.27	191.36
Ceiling/walls must be cleaned prior to application of paint. 101. Seal the ceiling w/latex based 110.00 SF stain blocker - one coat					
101. Seal the ceiling w/latex based 110.00 SF stain blocker - one coat	2.22	0.38	0.11	10.48	52.39
stain blocker - one coat	2.22				
102. Paint the ceiling - two coats 110.00 SF	0.00	0.64	0.86	17.82	89.08
	0.00	1.03	2.68	29.00	144.98
103. Final cleaning - construction - 110.00 SF Residential	0.00	0.28	0.00	7.70	38.50
This final clean is for the drywall repair process. Additional final clean li	ne items may be	necessary for othe	r repair proces	ses.	
Begin Carpet Repairs					
Removal					
104. Mask and prep for paint - plastic, 33.33 LF paper, tape (per LF)	0.00	1.46	0.88	12.39	61.93
105. Remove Exterior door - metal - 1.00 EA insulated - flush or panel style	21.33	0.00	0.00	5.33	26.66
106. Tear out trim and bag for disposal 26.83 LF - up to Cat 3	0.89	0.00	0.47	6.09	30.44
107. Remove Door opening (jamb & 1.00 EA casing) - 32"to36"wide - paint grade	6.27	0.00	0.00	1.57	7.84
108. Tear out baseboard and bag for 26.83 LF disposal - up to Cat 3	0.89	0.00	0.47	6.09	30.44
109. Tear out wet non-salv. gluedn. 110.00 SF cpt, cut/bag - Cat 3 water	1.40	0.00	0.64	38.66	193.30
110. Tear out wet carpet pad, cut/bag - 110.00 SF Category 3 water	0.76	0.00	0.64	21.06	105.30
Installation					
111. Apply anti-microbial agent to the 110.00 SF floor	0.00	0.25	0.43	6.98	34.91
Application of antimicrobial to the water damaged space before installation	on of new drywal	ll and insulation.			
112. Carpet pad 110.00 SF	0.00	0.59	5.47	17.60	87.97
113. Carpet 126.50 SF	0.00	3.38	34.41	115.50	577.48
114. Baseboard - 3 1/4" 26.83 LF		3.55			105.00
NDERSONEYECLINIC_A1	0.00	3.33	4.92	25.05	125.22



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Back exit

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
115. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
116. Install Exterior door - metal - insulated - flush or panel style	1.00 EA		0.00	75.00	0.00	18.75	93.75
117. Paint baseboard - two coats	26.83 LF		0.00	1.52	0.37	10.30	51.45
118. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
119. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
120. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To move contents back in.							
121. Final cleaning - construction - Residential	110.00 SF		0.00	0.28	0.00	7.70	38.50
This final clean is for the drywall repair p	rocess. Additiona	final clean lin	e items may be	necessary for other	ner repair proce	sses.	
Totals: Back exit					141.33	1,289.57	6,447.58

_ -92	·—————————————————————————————————————	ok closet
	16' 9" -	Hally or
13.10	Glasses room	
4	11 8,	5" - X/C ro

Glasses room

508.46 SF Walls 864.94 SF Walls & Ceiling 39.61 SY Flooring 65.74 LF Ceil. Perimeter

356.49 SF Ceiling 356.49 SF Floor

Height: 8'

63.24 LF Floor Perimeter

Missing Wall Missing Wall Door

ANDERSONEYECLINIC_A1

9' 2" X 8' 4' 7 1/16" X 8' 2' 6" X 7'

Opens into BACK_EXIT Opens into FRONT_HALLW2 **Onens into WAITING ROO2**

Door	2' 0" X /			Opens into WAITING_ROO2				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
Accessories								
122. Outlet or switch - Detach & reset	6.00 EA		0.00	16.63	0.00	24.95	124.73	
123. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	14.02	0.00	7.01	35.05	
124. Remove Drinking fountain	1.00 EA		80.71	0.00	0.00	20.18	100.89	
Remove								
125. Install Drinking fountain	1.00 EA		0.00	164.95	0.00	41.24	206.19	
Install								
126. Fluorescent light fixture - 6' & 8' - Detach & reset	4.00 EA		0.00	89.90	0.00	89.90	449.50	
NDERSONEYECLINIC A1					2/1	/2023	Page: 9	



CONTINUED - Glasses room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Begin Drywall Repairs							
Removal							
127. Content Manipulation charge - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.20
To remove contents.							
128. Mask and prep for paint - plastic, paper, tape (per LF)	65.74 LF		0.00	1.46	1.73	24.43	122.14
129. Floor protection - plastic and tape - 10 mil	356.49 SF		0.00	0.32	4.17	29.57	147.82
130. Tear out wet paneling, no bagging - Cat 3	508.46 SF		0.57	0.00	0.00	72.45	362.27
131. Tear out wet drywall, cleanup, bag - Cat 3	864.94 SF		1.30	0.00	13.49	284.47	1,422.38
Walls/Ceiling							
132. Tear out and bag wet insulation - Category 3 water	864.94 SF		1.10	0.00	5.06	239.12	1,195.61
Walls/Ceiling							
Installation							
133. Apply anti-microbial agent to the walls and ceiling	864.94 SF		0.00	0.25	3.37	54.91	274.52
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ıll and insulation.			
134. 5/8" drywall - hung, taped, ready for texture	356.49 SF		0.00	2.29	24.33	210.17	1,050.86
5/8 for the ceiling							
135. Blown-in insulation - 10" depth - R26	356.49 SF		0.00	1.10	28.15	105.07	525.36
Blown-in for the ceiling							
136. Batt insulation - 6" - R19 - unfaced batt	508.46 SF		0.00	0.97	32.72	131.48	657.41
137. 1/2" drywall - hung, taped, ready for texture	508.46 SF		0.00	2.18	32.22	285.16	1,425.82
138. Paneling	508.46 SF		0.00	2.40	41.64	315.49	1,577.43
139. Texture drywall - smooth / skim coat	356.49 SF		0.00	1.38	4.17	124.04	620.17
For the ceiling							
140. Clean the ceiling	356.49 SF		0.00	0.38	0.35	33.96	169.78
Ceiling/walls must be cleaned prior to app	olication of paint.						
141. Seal the ceiling w/latex based stain blocker - one coat	356.49 SF		0.00	0.64	2.78	57.74	288.67
142. Paint the ceiling - two coats	356.49 SF		0.00	1.03	8.69	93.97	469.84
143. Final cleaning - construction - Residential	356.49 SF		0.00	0.28	0.00	24.95	124.77
NDERSONEYECLINIC_A1					2/1	1/2023	Page: 10





CONTINUED - Glasses room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	e items may be	necessary for other	er repair proces	sses.	
Begin Carpet Repairs							
Removal							
144. Mask and prep for paint - plastic, paper, tape (per LF)	65.74 LF		0.00	1.46	1.73	24.43	122.14
145. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
146. Tear out trim and bag for disposal - up to Cat 3	63.24 LF		0.89	0.00	1.11	14.35	71.74
147. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
148. Tear out baseboard and bag for disposal - up to Cat 3	63.24 LF		0.89	0.00	1.11	14.35	71.74
149. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	356.49 SF		1.40	0.00	2.09	125.29	626.47
150. Tear out wet carpet pad, cut/bag - Category 3 water	356.49 SF		0.76	0.00	2.09	68.25	341.27
Installation							
151. Apply anti-microbial agent to the floor	356.49 SF		0.00	0.25	1.39	22.63	113.14
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ll and insulation.			
152. Carpet pad	356.49 SF		0.00	0.59	17.73	57.01	285.07
153. Carpet	409.96 SF		0.00	3.38	111.52	374.30	1,871.48
154. Baseboard - 3 1/4"	63.24 LF		0.00	3.55	11.59	59.03	295.12
155. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
156. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
157. Paint baseboard - two coats	63.24 LF		0.00	1.52	0.86	24.25	121.23
158. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
159. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
160. Content Manipulation charge - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.20
To move contents back in.							
161. Final cleaning - construction - Residential	356.49 SF		0.00	0.28	0.00	24.95	124.77
This final clean is for the drywall repair p	orocess. Additiona	l final clean lii	ne items may be	e necessary for oth	er repair proce	sses.	

2/1/2023



173. Blown-in insulation - 10" depth -

ANDERSONEYECLINIC_A1

136.08 SF

128 Poplar Street, Gadsden, TN 38337

Kitel	hen						Height: 8'		
thro	311.6	7 SF Walls		·	136.08 SF (Ceiling			
Kitchen É		5 SF Walls	& Ceiling		136.08 SF F	_			
Knunen #		2 SY Floori	_	37.67 LF Floor Perimeter					
Block cli		7 LF Ceil. P	_						
12'									
Missing Wall - Goes to Floor	4' X	C 6' 8''		Opens into	BACK_EXI	Т			
Door	2' 6	2' 6" X 7' Opens into BOOK_CLOSET							
Door	2' 6	'' X 7'		Opens into	BATHROO	M2			
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL		
Accessories									
162. Outlet or switch - Detach & reset	12.00 EA		0.00	16.63	0.00	49.89	249.45		
163. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52		
164. Fluorescent light fixture - 6' & 8' - Detach & reset	3.00 EA		0.00	89.90	0.00	67.43	337.13		
Begin Drywall Repairs									
Removal									
165. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10		
To remove contents.									
166. Mask and prep for paint - plastic, paper, tape (per LF)	46.67 LF		0.00	1.46	1.23	17.33	86.70		
167. Floor protection - plastic and tape - 10 mil	136.08 SF		0.00	0.32	1.59	11.29	56.43		
168. Tear out wet paneling, no bagging - Cat 3	311.67 SF		0.57	0.00	0.00	44.42	222.07		
169. Tear out wet drywall, cleanup, bag - Cat 3	447.75 SF		1.30	0.00	6.98	147.27	736.33		
Walls/Ceiling	•								
170. Tear out and bag wet insulation - Category 3 water	447.75 SF		1.10	0.00	2.62	123.78	618.93		
Walls/Ceiling									
Installation									
171. Apply anti-microbial agent to the walls and ceiling	447.75 SF		0.00	0.25	1.75	28.42	142.11		
Application of antimicrobial to the water	damaged space bei	fore installatio	n of new drywa	ll and insulation.					
172. 5/8" drywall - hung, taped, ready for texture	136.08 SF		0.00	2.29	9.29	80.22	401.13		
5/8 for the ceiling									

0.00

1.10

10.75

40.11

2/1/2023

200.55





CONTINUED - Kitchen

211 (5.55						
211 (5 00						
311.67 SF		0.00	0.82	0.61	64.05	320.2
311.67 SF		0.00	0.97	20.06	80.60	402.9
311.67 SF		0.00	2.18	19.75	174.80	873.9
311.67 SF		0.00	2.40	25.53	193.38	966.9
136.08 SF		0.00	1.38	1.59	47.35	236.7
136.08 SF		0.00	0.38	0.13	12.96	64.8
plication of paint.						
136.08 SF		0.00	0.64	1.06	22.04	110.1
136.08 SF		0.00	1.03	3.32	35.87	179.3
136.08 SF		0.00	0.28	0.00	9.53	47.0
process. Additiona	l final clean lir	ne items may be	necessary for oth	er repair proces	ses.	
1.00 EA		18.67	0.00	0.00	4.67	23.
1.00 EA		7.46	0.00	0.00	1.87	9.:
1.00 EA		19.91				24.
13.00 LF		0.90	0.00			14.
13.00 LF		4.29				69.
13.00 LF		7.47				121.
8.00 LF		0.61				6.
21.00 LF		3.25	0.00	0.00	17.07	85.
					010.50	4.007
13.00 LF		0.00				4,097.
13.00 LF		0.00	40.91	37.09	142.22	711.
		Λ ΛΛ	10.70	10.24	37.34	186
13.00 LF 1.00 EA		0.00	100.15	0.00	25.04	125
	311.67 SF 136.08 SF 136.08 SF plication of paint. 136.08 SF 136.08 SF 136.08 SF 136.08 SF 136.08 SF 136.08 SF 136.08 LF 13.00 EA 1.00 EA 1.00 EA 1.00 EA 1.00 EA 1.00 LF 13.00 LF 13.00 LF 13.00 LF 13.00 LF	311.67 SF 136.08 SF 136.08 SF plication of paint. 136.08 SF 136.08 LE 13.00 LE 13.00 LF 13.00 LF 13.00 LF 13.00 LF 13.00 LF	311.67 SF 0.00 136.08 SF 0.00 136.08 SF 0.00 136.08 SF 0.00 136.	311.67 SF	311.67 SF	311.67 SF





128 Poplar Street, Gadsden, TN 38337

CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
195. Install P-trap assembly - ABS (plastic)	1.00 EA		0.00	46.74	0.00	11.68	58.42
196. Install Shelving - 24" - in place	8.00 LF		0.00	5.75	0.00	11.50	57.50
197. Install Shelving - wire (vinyl coated)	21.00 LF		0.00	5.87	0.00	30.82	154.09
198. Final cleaning - construction - Residential	136.08 SF		0.00	0.28	0.00	9.53	47.63
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	ne items may be	necessary for other	er repair proces	ses.	
Begin Carpet Repairs							
Removal							
199. Mask and prep for paint - plastic, paper, tape (per LF)	46.67 LF		0.00	1.46	1.23	17.33	86.70
200. Remove Interior door unit	2.00 EA		18.67	0.00	0.00	9.33	46.67
201. Tear out trim and bag for disposal - up to Cat 3	37.67 LF		0.89	0.00	0.66	8.55	42.74
202. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		6.27	0.00	0.00	3.13	15.67
203. Tear out baseboard and bag for disposal - up to Cat 3	37.67 LF		0.89	0.00	0.66	8.55	42.74
204. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	136.08 SF		1.40	0.00	0.80	47.83	239.14
205. Tear out wet carpet pad, cut/bag - Category 3 water	136.08 SF		0.76	0.00	0.80	26.05	130.27
Installation							
206. Apply anti-microbial agent to the floor	136.08 SF		0.00	0.25	0.53	8.63	43.18
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
207. Carpet pad	136.08 SF		0.00	0.59	6.77	21.77	108.83
208. Carpet	156.50 SF		0.00	3.38	42.57	142.90	714.44
209. Baseboard - 3 1/4"	37.67 LF		0.00	3.55	6.90	35.16	175.79
210. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		0.00	176.22	25.89	94.58	472.91
211. Install Interior door unit	2.00 EA		0.00	50.02	0.00	25.01	125.05
212. Paint baseboard - two coats	37.67 LF		0.00	1.52	0.51	14.45	72.22
213. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	33.18	0.98	16.84	84.18
214. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.57	1.62	20.18	100.94
215. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To move contents back in.							

ANDERSONEYECLINIC_A1


2/1/2023





CONTINUED - Kitchen

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
216. Final cleaning - construction - Residential	136.08 SF		0.00	0.28	0.00	9.53	47.63
This final clean is for the drywall repair	process. Additional	l final clean lis	ne items may be	e necessary for other	er repair proce	sses.	
Totals: Kitchen					495.74	2,998.72	14,993.47



115.67 SF Walls 137.82 SF Walls & Ceiling 2.46 SY Flooring 18.83 LF Ceil. Perimeter

22.15 SF Ceiling
22.15 SF Floor
13.83 LF Floor Per

13.83 LF Floor Perimeter

Height: 8'

Door Door 2' 6" X 7' 2' 6" X 7' Opens into KITCHEN2
Opens into WORKSHOP

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
217. Outlet or switch - Detach & reset	1.00 EA		0.00	16.63	0.00	4.15	20.78
218. Light fixture - Detach & reset	1.00 EA		0.00	46.37	0.00	11.60	57.97
Begin Drywall Repairs							
Removal							
219. Content Manipulation charge - per hour	1.00 HR		0.00	38.02	0.00	9.50	47.52
To remove contents.							
220. Mask and prep for paint - plastic, paper, tape (per LF)	18.83 LF		0.00	1.46	0.50	7.00	34.99
221. Floor protection - plastic and tape - 10 mil	22.15 SF		0.00	0.32	0.26	1.84	9.19
222. Remove Shelving - 24" - in place	24.00 LF		0.61	0.00	0.00	3.66	18.30
223. Tear out wet paneling, no bagging - Cat 3	115.67 SF		0.57	0.00	0.00	16.48	82.41
224. Tear out wet drywall, cleanup, bag - Cat 3	137.82 SF		1.30	0.00	2.15	45.34	226.66
Walls/Ceiling							
225. Tear out and bag wet insulation - Category 3 water	137.82 SF		1.10	0.00	0.81	38.10	190.51
Walls/Ceiling							

Installation



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Book closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
26. Apply anti-microbial agent to the valls and ceiling	137.82 SF		0.00	0.25	0.54	8.75	43.75
Application of antimicrobial to the wate	r damaged space be	fore installatio	n of new drywa	all and insulation.			
27. 5/8" drywall - hung, taped, ready or texture	22.15 SF		0.00	2.29	1.51	13.06	65.29
/8 for the ceiling							
28. Blown-in insulation - 10" depth - 226	22.15 SF		0.00	1.10	1.75	6.54	32.66
Blown-in for the ceiling							
29. Batt insulation - 6" - R19 - infaced batt	115.67 SF		0.00	0.97	7.44	29.91	149.55
30. 1/2" drywall - hung, taped, ready or texture	115.67 SF		0.00	2.18	7.33	64.87	324.36
31. Paneling	115.67 SF		0.00	2.40	9.47	71.77	358.85
32. Texture drywall - smooth / skim oat	22.15 SF		0.00	1.38	0.26	7.72	38.55
For the ceiling							
33. Shelving - 24" - in place	13.83 LF		0.00	13.01	9.79	47.43	237.15
34. Clean the ceiling	22.15 SF		0.00	0.38	0.02	2.10	10.54
Ceiling/walls must be cleaned prior to a	pplication of paint.						
35. Seal the ceiling w/latex based tain blocker - one coat	22.15 SF		0.00	0.64	0.17	3.60	17.95
36. Paint the ceiling - two coats	22.15 SF		0.00	1.03	0.54	5.83	29.18
37. Final cleaning - construction - Residential	22.15 SF		0.00	0.28	0.00	1.55	7.75
This final clean is for the drywall repair	process. Additiona	ıl final clean lii	ne items may be	e necessary for other	er repair process	ses.	
Begin Carpet Repairs							
Removal							
38. Mask and prep for paint - plastic, paper, tape (per LF)	18.83 LF		0.00	1.46	0.50	7.00	34.99
39. Remove Interior door unit	2.00 EA		18.67	0.00	0.00	9.33	46.67
40. Tear out trim and bag for disposal up to Cat 3	13.83 LF		0.89	0.00	0.24	3.14	15.69
41. Remove Door opening (jamb & asing) - 32"to36"wide - paint grade	2.00 EA		6.27	0.00	0.00	3.13	15.67
42. Tear out baseboard and bag for lisposal - up to Cat 3	13.83 LF		0.89	0.00	0.24	3.14	15.69
43. Tear out wet non-salv. gluedn. pt, cut/bag - Cat 3 water	22.15 SF		1.40	0.00	0.13	7.78	38.92
44. Tear out wet carpet pad, cut/bag - Category 3 water	22.15 SF		0.76	0.00	0.13	4.23	21.19
Installation							
IDERSONEYECLINIC_A1					2/1	/2023	Page: 1
					2/1	. 2023	



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Book closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
245. Apply anti-microbial agent to the floor	22.15 SF		0.00	0.25	0.09	1.40	7.03
Application of antimicrobial to the water of	lamaged space be	fore installation	n of new drywa	all and insulation.			
246. Carpet pad	22.15 SF		0.00	0.59	1.10	3.55	17.72
247. Carpet	25.48 SF		0.00	3.38	6.93	23.26	116.31
248. Baseboard - 3 1/4"	13.83 LF		0.00	3.55	2.54	12.91	64.55
249. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		0.00	176.22	25.89	94.58	472.91
250. Install Interior door unit	2.00 EA		0.00	50.02	0.00	25.01	125.05
251. Paint baseboard - two coats	13.83 LF		0.00	1.52	0.19	5.30	26.51
252. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	33.18	0.98	16.84	84.18
253. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.57	1.62	20.18	100.94
254. Content Manipulation charge - per hour	1.00 HR		0.00	38.02	0.00	9.50	47.52
To move contents back in.							
255. Final cleaning - construction - Residential	22.15 SF		0.00	0.28	0.00	1.55	7.75
This final clean is for the drywall repair pr	rocess. Additiona	l final clean lir	ne items may be	e necessary for other	er repair proces	ses.	
Totals: Book closet					83.12	652.63	3,263.20



162.50 SF Walls 193.06 SF Walls & Ceiling

Bathroom

3.40 SY Flooring 22.50 LF Ceil. Perimeter Height: 8'

30.56 SF Ceiling 30.56 SF Floor

20.00 LF Floor Perimeter

Door	"	••	2' 6" X 7'	Opens into KITCHEN2
Door			2' 6" X 7'	Opens into KITCHENZ

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
256. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
257. Toilet - Detach & reset	1.00 EA		0.00	212.08	0.81	53.22	266.11
258. Outlet or switch - Detach & reset	2.00 EA		0.00	16.63	0.00	8.32	41.58

Begin Drywall Repairs

<u>Removal</u>
ANDERSONEYECLINIC_A1

2/1/2023



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
259. Content Manipulation charge - per hour	0.50 HR		0.00	38.02	0.00	4.75	23.76
To remove contents.							
260. Mask and prep for paint - plastic, paper, tape (per LF)	22.50 LF		0.00	1.46	0.59	8.37	41.81
261. Floor protection - plastic and tape - 10 mil	30.56 SF		0.00	0.32	0.36	2.54	12.68
262. Tear out wet paneling, no bagging - Cat 3	162.50 SF		0.57	0.00	0.00	23.15	115.78
263. Tear out wet drywall, cleanup, bag - Cat 3	193.06 SF		1.30	0.00	3.01	63.50	317.49
Walls/Ceiling							
264. Tear out and bag wet insulation - Category 3 water	193.06 SF		1.10	0.00	1.13	53.38	266.88
Walls/Ceiling							
Installation							
265. Apply anti-microbial agent to the walls and ceiling	193.06 SF		0.00	0.25	0.75	12.26	61.28
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ill and insulation.			
266. 5/8" drywall - hung, taped, ready for texture	30.56 SF		0.00	2.29	2.09	18.02	90.09
5/8 for the ceiling							
267. Blown-in insulation - 10" depth - R26	30.56 SF		0.00	1.10	2.41	9.00	45.03
Blown-in for the ceiling							
268. Clean stud wall	162.50 SF		0.00	0.82	0.32	33.40	166.97
269. Batt insulation - 6" - R19 - unfaced batt	162.50 SF		0.00	0.97	10.46	42.02	210.11
270. 1/2" drywall - hung, taped, ready for texture	162.50 SF		0.00	2.18	10.30	91.15	455.70
271. Paneling	162.50 SF		0.00	2.40	13.31	100.83	504.14
272. Texture drywall - smooth / skim coat	30.56 SF		0.00	1.38	0.36	10.64	53.17
For the ceiling							
273. Clean the ceiling	30.56 SF		0.00	0.38	0.03	2.90	14.54
Ceiling/walls must be cleaned prior to app	plication of paint.						
274. Seal the ceiling w/latex based stain blocker - one coat	30.56 SF		0.00	0.64	0.24	4.95	24.75
275. Paint the ceiling - two coats	30.56 SF		0.00	1.03	0.74	8.05	40.27
276. Final cleaning - construction - Residential	30.56 SF		0.00	0.28	0.00	2.14	10.70

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

ANDERSONEYECLINIC_A1 2/1/2023 Page: 18



ANDERSONEYECLINIC_A1

128 Poplar Street, Gadsden, TN 38337

CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Begin Sink Repair							
Removal							
277. Remove Sink - wall mounted	1.00 EA		37.32	0.00	0.00	9.33	46.65
278. Remove P-trap assembly - ABS (plastic)	1.00 EA		7.46	0.00	0.00	1.87	9.33
Installation							
279. Install Sink - single	1.00 EA		0.00	93.47	0.00	23.37	116.84
280. Install P-trap assembly - ABS (plastic)	1.00 EA		0.00	46.74	0.00	11.68	58.42
281. Final cleaning - construction - Residential	30.56 SF		0.00	0.28	0.00	2.14	10.70
This final clean is for the drywall repair pr	ocess. Additiona	l final clean lir	ne items may be	necessary for other	er repair process	ses.	
Begin Carpet Repairs							
Removal						0.05	41.01
282. Mask and prep for paint - plastic, paper, tape (per LF)	22.50 LF		0.00	1.46	0.59	8.37	41.81
283. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
284. Tear out trim and bag for disposal - up to Cat 3	20.00 LF		0.89	0.00	0.35	4.54	22.69
285. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
286. Tear out baseboard and bag for disposal - up to Cat 3	20.00 LF		0.89	0.00	0.35	4.54	22.69
287. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	30.56 SF		1.40	0.00	0.18	10.75	53.71 29.26
288. Tear out wet carpet pad, cut/bag - Category 3 water	30.56 SF		0.76	0.00	0.18	5.85	29.20
Installation	** **		0.00	0.25	0.12	1.94	9.70
289. Apply anti-microbial agent to the floor	30.56 SF		0.00		0.12	1.54	<i>,</i> ,,,
Application of antimicrobial to the water of	iamaged space be	fore installation	n of new drywa				
290. Carpet pad	30.56 SF		0.00	0.59	1.52	4.88	24.43
291. Carpet	35.14 SF		0.00	3.38	9.56	32.09	160.42
292. Baseboard - 3 1/4"	20.00 LF		0.00	3.55	3.67	18.67	93.34
293. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
294. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
295. Paint baseboard - two coats	20.00 LF		0.00	1.52	0.27	7.67	38.34
296. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09

Page: 19

2/1/2023




ANDERSONEYECLINIC_A1

128 Poplar Street, Gadsden, TN 38337

CONTINUED - Bathroom

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
297. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
298. Content Manipulation charge - per hour	0.50 HR		0.00	38.02	0.00	4.75	23.76
To move contents back in.							
299. Final cleaning - construction - Residential	30.56 SF		0.00	0.28	0.00	2.14	10.70
This final clean is for the drywall repair p	process. Additiona	l final clean lir	ne items may be	necessary for other	er repair proces	ses.	
Totals: Bathroom					77.94	795.21	3,975.86



Window 8' 7" X 3' Opens into Exterior

Door 2' 6" X 7' Opens into Exterior

Missing Wall - Goes to neither Floor/Ceiling 5' 7" X 3' 3" Opens into FRONT_DESK2

Door 2' 6" X 7' Opens into GLASSES_ROO2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
300. Outlet or switch - Detach & reset	7.00 EA		0.00	16.63	0.00	29.10	145.51
301. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	14.02	0.00	7.01	35.05
302. Recessed light fixture - Detach & reset entire unit	2.00 EA		0.00	97.23	0.00	48.62	243.08
Begin Drywall Repairs							
Removal							
303. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To remove contents.							
304. Mask and prep for paint - plastic, paper, tape (per LF)	55.67 LF		0.00	1.46	1.47	20.69	103.44
305. Floor protection - plastic and tape - 10 mil	179.55 SF		0.00	0.32	2.10	14.90	74.46
306. Remove Ceiling fan & light	1.00 EA		18.78	0.00	0.00	4.70	23.48

2/1/2023





CONTINUED - Waiting room

307. Tear out wet paneling, no bagging - Cat 3 308. Tear out wet drywall, cleanup, bag - Cat 3 Walls/Ceiling 309. Tear out and bag wet insulation - 545.99 S Category 3 water Walls/Ceiling Installation 310. Apply anti-microbial agent to the walls and ceiling Application of antimicrobial to the water damaged sp 311. 5/8" drywall - hung, taped, ready for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 S R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 S unfaced batt	SF SF pace befo SF	ore installatio	0.57 1.30 1.10 0.00 n of new drywa 0.00 0.00	0.00 0.00 0.00 0.25 Il and insulation. 2.29	0.00 8.52 3.19 2.13 12.25	52.22 179.58 150.95 34.66 105.87	261.09 897.89 754.73 173.29 529.29
bag - Cat 3 Walls/Ceiling 309. Tear out and bag wet insulation - 545.99 S Category 3 water Walls/Ceiling Installation 310. Apply anti-microbial agent to the walls and ceiling Application of antimicrobial to the water damaged sp 311. 5/8" drywall - hung, taped, ready 179.55 S for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 S R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 S	SF pace befo SF	ore installatio	0.00 n of new drywa 0.00	0.00 0.25 Il and insulation. 2.29	3.19 2.13 12.25	150.95 34.66 105.87	754.75 173.29 529.29
309. Tear out and bag wet insulation - 545.99 S Category 3 water Walls/Ceiling Installation 310. Apply anti-microbial agent to the walls and ceiling Application of antimicrobial to the water damaged sp 311. 5/8" drywall - hung, taped, ready for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 S R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 S	SF pace befo SF SF	ore installatio	0.00 n of new drywa 0.00	0.25 Il and insulation. 2.29	2.13 12.25	34.66 105.87	173.29 529.29
Category 3 water Walls/Ceiling Installation 310. Apply anti-microbial agent to the walls and ceiling Application of antimicrobial to the water damaged sp 311. 5/8" drywall - hung, taped, ready 179.55 Sf for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 Sf R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 Sf	SF pace befo SF SF	ore installatio	0.00 n of new drywa 0.00	0.25 Il and insulation. 2.29	2.13 12.25	34.66 105.87	173.29 529.29
Installation 310. Apply anti-microbial agent to the walls and ceiling Application of antimicrobial to the water damaged sp 311. 5/8" drywall - hung, taped, ready for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 SR R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 SR	pace befo SF SF	ore installatio	n of new drywa 0.00	ll and insulation. 2.29	12.25	105.87	529.29
310. Apply anti-microbial agent to the walls and ceiling Application of antimicrobial to the water damaged sp 311. 5/8" drywall - hung, taped, ready for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 SR26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 SR	pace befo SF SF	ore installatio	n of new drywa 0.00	ll and insulation. 2.29	12.25	105.87	529.29
walls and ceiling Application of antimicrobial to the water damaged sp 311. 5/8" drywall - hung, taped, ready 179.55 S for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 S R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 S	pace befo SF SF	ore installatio	n of new drywa 0.00	ll and insulation. 2.29	12.25	105.87	529.29
311. 5/8" drywall - hung, taped, ready for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 S R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 S	SF	ore installatio	0.00	2.29			
for texture 5/8 for the ceiling 312. Blown-in insulation - 10" depth - 179.55 S R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 S	SF						
312. Blown-in insulation - 10" depth - 179.55 S R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 S			0.00	1.10	14.18	52.93	264.62
R26 Blown-in for the ceiling 313. Batt insulation - 6" - R19 - 366.44 S			0.00	1.10	14.18	52.93	264.6
313. Batt insulation - 6" - R19 - 366.44 S	SF						
515; 24 11 1115 4 1111111	SF						
			0.00	0.97	23.58	94.77	473.8
314. 1/2" drywall - hung, taped, ready 366.44 S for texture	SF		0.00	2.18	23.22	205.51	1,027.5
315. Paneling 366.44 S	SF		0.00	2.40	30.01	227.37	1,136.8
316. Texture drywall - smooth / skim 179.55 Scoat	SF		0.00	1.38	2.10	62.48	312.3
For the ceiling							
317. Clean the ceiling 179.55 S	SF		0.00	0.38	0.18	17.10	85.5
Ceiling/walls must be cleaned prior to application of	paint.						
318. Seal the ceiling w/latex based 179.55 Stain blocker - one coat	SF		0.00	0.64	1.40	29.08	145.3
319. Paint the ceiling - two coats 179.55 S	SF		0.00	1.03	4.38	47.33	236.6
320. Ceiling fan & light 1.00 E	EA		0.00	306.90	12.43	79.83	399.1
321. Final cleaning - construction - 179.55 S Residential			0.00	0.28	0.00	12.57	62.8
This final clean is for the drywall repair process. Ad	lditional	final clean lii	ne items may be	necessary for other	er repair proces	sses.	
Begin Carpet Repairs							
Removal							
322. Mask and prep for paint - plastic, paper, tape (per LF) 55.67 I			0.00	1.46	1.47	20.69	103.4
323. Remove Interior door unit 1.00 F	EA		18.67	0.00	0.00	4.67	23.3



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Waiting room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
324. Remove Exterior door - metal - insulated - flush or panel style	1.00 EA		21.33	0.00	0.00	5.33	26.66
325. Tear out trim and bag for disposal - up to Cat 3	50.67 LF		0.89	0.00	0.89	11.50	57.49
326. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		6.27	0.00	0.00	3.13	15.67
327. Tear out baseboard and bag for disposal - up to Cat 3	50.67 LF		0.89	0.00	0.89	11.50	57.49
328. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	179.55 SF		1.40	0.00	1.05	63.12	315.54
329. Tear out wet carpet pad, cut/bag - Category 3 water	179.55 SF		0.76	0.00	1.05	34.39	171.90
Installation							
330. Apply anti-microbial agent to the floor	179.55 SF		0.00	0.25	0.70	11.40	56.99
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ıll and insulation.			
331. Carpet pad	179.55 SF		0.00	0.59	8.93	28.71	143.57
332. Carpet	206.48 SF		0.00	3.38	56.17	188.53	942.60
333. Baseboard - 3 1/4"	50.67 LF		0.00	3.55	9.29	47.29	236.46
334. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		0.00	176.22	25.89	94.58	472.91
335. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
336. Install Exterior door - metal - insulated - flush or panel style	1.00 EA		0.00	75.00	0.00	18.75	93.75
337. Paint baseboard - two coats	50.67 LF		0.00	1.52	0.69	19.42	97.13
338. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	33.18	0.98	16.84	84.18
339. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.57	1.62	20.18	100.94
340. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To move contents back in.							
341. Final cleaning - construction - Residential	179.55 SF		0.00	0.28	0.00	12.57	62.84
This final clean is for the drywall repair p	orocess. Additiona	l final clean lii	ne items may be	e necessary for oth	er repair proce	sses.	
Totals: Waiting room					250.76	2,178.41	10,891.67

ANDERSONEYECLINIC_A1

2/1/2023



128 Poplar Street, Gadsden, TN 38337

8.9.
8' 5"
So Front Desk
6'1"
6"

Front Desk

87.31 SF Ceiling

213.60 SF Walls 300.92 SF Walls & Ceiling

31.25 LF Ceil. Perimeter

87.31 SF Floor

9.70 SY Flooring

31.25 LF Floor Perimeter

Height: 8'

Missing Wall - Goes to neither Floor/Ceiling

5' 7" X 3' 3"

Opens into WAITING_ROO2

Window

6' 1" X 3'

Opens into Exterior

Missing Wall

6' 3" X 8'

Opens into ROOM2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
342. Fluorescent light fixture - 6' & 8' - Detach & reset	2.00 EA		0.00	89.90	0.00	44.95	224.75
343. Outlet or switch - Detach & reset	6.00 EA		0.00	16.63	0.00	24.95	124.73
344. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
Begin Drywall Repairs							
Removal							
345. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To remove contents.							
346. Mask and prep for paint - plastic, paper, tape (per LF)	31.25 LF		0.00	1.46	0.82	11.60	58.05
347. Floor protection - plastic and tape - 10 mil	87.31 SF		0.00	0.32	1.02	7.23	36.19
348. Tear out wet paneling, no bagging - Cat 3	213.60 SF		0.57	0.00	0.00	30.44	152.19
349. Tear out wet drywall, cleanup, bag - Cat 3	300.92 SF		1.30	0.00	4.69	98.97	494.86
Walls/Ceiling							
350. Tear out and bag wet insulation - Category 3 water	300.92 SF		1.10	0.00	1.76	83.19	415.96
Walls/Ceiling							
Installation							
351. Apply anti-microbial agent to the walls and ceiling	300.92 SF		0.00	0.25	1.17	19.10	95.50
Application of antimicrobial to the water	damaged space be	fore installation	on of new dryw	all and insulation.			
352. 5/8" drywall - hung, taped, ready for texture	87.31 SF		0.00	2.29	5.96	51.47	257.37
5/8 for the ceiling							
353. Blown-in insulation - 10" depth - R26	87.31 SF		0.00	1.10	6.90	25.74	128.68
NDERSONEYECLINIC_A1					2/1	/2023	Page: 23



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Front Desk


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Blown-in for the ceiling			-				
354. Batt insulation - 6" - R19 - unfaced batt	213.60 SF		0.00	0.97	13.75	55.24	276.18
355. 1/2" drywall - hung, taped, ready for texture	213.60 SF		0.00	2.18	13.54	119.80	598.99
356. Paneling	213.60 SF		0.00	2.40	17.49	132.53	662.66
357. Texture drywall - smooth / skim coat	87.31 SF		0.00	1.38	1.02	30.37	151.88
For the ceiling							
358. Clean the ceiling	87.31 SF		0.00	0.38	0.08	8.32	41.58
Ceiling/walls must be cleaned prior to ap	plication of paint.						
359. Seal the ceiling w/latex based stain blocker - one coat	87.31 SF		0.00	0.64	0.68	14.14	70.70
360. Paint the ceiling - two coats	87.31 SF		0.00	1.03	2.13	23.01	115.07
361. Final cleaning - construction - Residential	87.31 SF		0.00	0.28	0.00	6.12	30.57
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	ne items may be	necessary for other	er repair proces	ses.	
Begin Carpet Repairs							
Removal							
362. Mask and prep for paint - plastic, paper, tape (per LF)	31.25 LF		0.00	1.46	0.82	11.60	58.05
363. Tear out trim and bag for disposal - up to Cat 3	31.25 LF		0.89	0.00	0.55	7.09	35.45
364. Remove Door opening (jamb & casing) - 36"to60"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
365. Tear out baseboard and bag for disposal - up to Cat 3	31.25 LF		0.89	0.00	0.55	7.09	35.45
366. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	87.31 SF		1.40	0.00	0.51	30.68	153.42
367. Tear out wet carpet pad, cut/bag - Category 3 water	87.31 SF		0.76	0.00	0.51	16.72	83.59
Installation							
368. Apply anti-microbial agent to the floor	87.31 SF		0.00	0.25	0.34	5.53	27.70
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ll and insulation.			
369. Carpet pad	87.31 SF		0.00	0.59	4.34	13.96	69.81
370. Carpet	100.41 SF		0.00	3.38	27.31	91.68	458.38
371. Baseboard - 3 1/4"	31.25 LF		0.00	3.55	5.73	29.16	145.83
372. Door opening (jamb & casing) - 36"to60"wide - paint grade	1.00 EA		0.00	208.31	15.23	55.88	279.42
373. Paint baseboard - two coats	31.25 LF		0.00	1.52	0.43	11.98	59.91
NDERSONEYECLINIC_A1	•				2/1	/2023	Page: 2



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Front Desk

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
374. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
375. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To move contents back in.							
376. Final cleaning - construction - Residential	87.31 SF		0.00	0.28	0.00	6.12	30.57
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	ne items may be	e necessary for other	er repair proce	sses.	
Totals: Front Desk					127.82	1,164.19	5,821.14



ANDERSONEYECLINIC_A1

161.17 SF Walls 188.67 SF Walls & Ceiling

3.06 SY Flooring 22.33 LF Ceil. Perimeter Height: 8'

27.50 SF Ceiling 27.50 SF Floor

19.83 LF Floor Perimeter

Door	2' 6" X 7'			Opens into FRONT_HALLW2						
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL			
Accessories		_								
377. Light fixture - Detach & reset	1.00 EA		0.00	46.37	0.00	11.60	57.97			
Begin Drywall Repairs										
Removal 378. Content Manipulation charge - per hour	0.50 HR		0.00	38.02	0.00	4.75	23.76			
To remove contents.										
379. Mask and prep for paint - plastic, paper, tape (per LF)	22.33 LF		0.00	1.46	0.59	8.30	41.49			
380. Floor protection - plastic and tape - 10 mil	27.50 SF		0.00	0.32	0.32	2.28	11.40			
381. Tear out wet paneling, no bagging - Cat 3	161.17 SF		0.57	0.00	0.00	22.97	114.84			
382. Tear out wet drywall, cleanup, bag - Cat 3	188.67 SF		1.30	0.00	2.94	62.05	310.26			
Walls/Ceiling										
383. Tear out and bag wet insulation - Category 3 water	188.67 SF		1.10	0.00	1.10	52.16	260.80			
Walls/Ceiling										
Installation										
ANDERSONEYECLINIC A1					2/1	1/2023	Page: 25			





CONTINUED - A/C room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
384. Apply anti-microbial agent to the walls and ceiling	188.67 SF		0.00	0.25	0.74	11.98	59.89
Application of antimicrobial to the water	damaged space be	fore installation	n of new drywa	ll and insulation.			
385. 5/8" drywall - hung, taped, ready for texture	27.50 SF		0.00	2.29	1.88	16.22	81.08
5/8 for the ceiling							
386. Blown-in insulation - 10" depth - R26	27.50 SF		0.00	1.10	2.17	8.12	40.54
Blown-in for the ceiling							
387. Batt insulation - 6" - R19 - unfaced batt	161.17 SF		0.00	0.97	10.37	41.68	208.38
388. 1/2" drywall - hung, taped, ready for texture	161.17 SF		0.00	2.18	10.21	90.39	451.95
389. Paneling	161.17 SF		0.00	2.40	13.20	100.00	500.01
390. Texture drywall - smooth / skim coat	27.50 SF		0.00	1.38	0.32	9.57	47.84
For the ceiling							
391. Clean the ceiling	27.50 SF		0.00	0.38	0.03	2.62	13.10
Ceiling/walls must be cleaned prior to ap	plication of paint.						
392. Seal the ceiling w/latex based stain blocker - one coat	27.50 SF		0.00	0.64	0.21	4.45	22.26
393. Paint the ceiling - two coats	27.50 SF		0.00	1.03	0.67	7.25	36.25
394. Final cleaning - construction - Residential	27.50 SF		0.00	0.28	0.00	1.93	9.63
This final clean is for the drywall repair p	process. Additiona	l final clean lir	ne items may be	necessary for other	er repair proces	ses.	
Begin Carpet Repairs							
Removal							
395. Mask and prep for paint - plastic, paper, tape (per LF)	22.33 LF		0.00	1.46	0.59	8.30	41.49
396. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
397. Tear out trim and bag for disposal - up to Cat 3	19.83 LF		0.89	0.00	0.35	4.51	22.51
398. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
399. Tear out baseboard and bag for disposal - up to Cat 3	19.83 LF		0.89	0.00	0.35	4.51	22.51
400. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	27.50 SF		1.40	0.00	0.16	9.67	48.33
401. Tear out wet carpet pad, cut/bag - Category 3 water	27.50 SF		0.76	0.00	0.16	5.27	26.33
Installation							

ANDERSONEYECLINIC_A1

2/1/2023



128 Poplar Street, Gadsden, TN 38337

CONTINUED - A/C room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
402. Apply anti-microbial agent to the floor	27.50 SF		0.00	0.25	0.11	1.75	8.74
Application of antimicrobial to the water of	lamaged space be	fore installatio	n of new drywa	all and insulation.			
403. Carpet pad	27.50 SF		0.00	0.59	1.37	4.40	22.00
404. Carpet	31.63 SF		0.00	3.38	8.60	28.88	144.39
405. Baseboard - 3 1/4"	19.83 LF		0.00	3.55	3.63	18.50	92.53
406. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
407. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
408. Paint baseboard - two coats	19.83 LF		0.00	1.52	0.27	7.60	38.01
409. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
410. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
411. Content Manipulation charge - per hour	0.50 HR		0.00	38.02	0.00	4.75	23.76
To move contents back in.							
412. Final cleaning - construction - Residential	27.50 SF		0.00	0.28	0.00	1.93	9.63
This final clean is for the drywall repair pr	rocess. Additiona	l final clean lii	ne items may be	necessary for other	er repair proces	ses.	
Totals: A/C room					74.58	642.93	3,214.39

10' 8" Entra	202.00	2 SF Walls		111.11 SF Ceiling 111.11 SF Floor				
∭			0. 0-11:					
Entrance &		3 SF Walls &	-					
	12.3	5 SY Floorii	ng	26.83 LF Floor Perimeter				
53-28-1	31.83	3 LF Ceil. P	erimeter					
11·1								
Door	2' 6" X 7' 2' 6" X 7'			Opens into FILE_ROOM2 Opens into Exterior				
Door								
Window	5' 3'	" X 3'		Opens into Exterior				
Missing Wall	10'	8" X 8'		Opens into FRONT_HALLW2				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
Accessories								
413. Light fixture - Detach & reset	1.00 EA		0.00	46.37	0.00	11.60	57.97	
414. Outlet or switch - Detach & reset	5.00 EA		0.00	16.63	0.00	20.79	103.94	
A14. Outlet or switch - Detach & reset NDERSONEYECLINIC_A1	3.00 EA		0.50	10.03		/2023	Pag	



CONTINUED - Entrance

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
415. Cold air return cover - Detach & reset	1.00 EA		0.00	19.15	0.00	4.79	23.94
Begin Drywall Repairs							
Removal							
416. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To remove contents.							
417. Mask and prep for paint - plastic, paper, tape (per LF)	31.83 LF		0.00	1.46	0.84	11.83	59.14
418. Floor protection - plastic and tape - 10 mil	111.11 SF		0.00	0.32	1.30	9.22	46.08
419. Tear out wet paneling, no bagging - Cat 3	203.92 SF		0.57	0.00	0.00	29.05	145.28
420. Tear out wet drywall, cleanup, bag - Cat 3	315.03 SF		1.30	0.00	4.91	103.61	518.06
Walls/Ceiling							
421. Tear out and bag wet insulation - Category 3 water	315.03 SF		1.10	0.00	1.84	87.09	435.46
Walls/Ceiling							
Installation							
422. Apply anti-microbial agent to the walls and ceiling	315.03 SF		0.00	0.25	1.23	19.99	99.98
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ill and insulation.			
423. 5/8" drywall - hung, taped, ready for texture	111.11 SF		0.00	2.29	7.58	65.51	327.53
5/8 for the ceiling							
424. Blown-in insulation - 10" depth - R26	111.11 SF		0.00	1.10	8.78	32.75	163.75
Blown-in for the ceiling							
425. Clean stud wall	203.92 SF		0.00	0.82	0.40	41.90	209.51
426. Batt insulation - 6" - R19 - unfaced batt	203.92 SF		0.00	0.97	13.12	52.73	263.65
427. 1/2" drywall - hung, taped, ready for texture	203.92 SF		0.00	2.18	12.92	114.37	571.84
428. Paneling	203.92 SF		0.00	2.40	16.70	126.53	632.64
429. Texture drywall - smooth / skim coat	111.11 SF		0.00	1.38	1.30	38.66	193.29
For the ceiling							
430. Clean the ceiling	111.11 SF		0.00	0.38	0.11	10.58	52.91
Ceiling/walls must be cleaned prior to app	olication of paint.						
431. Seal the ceiling w/latex based stain blocker - one coat	111.11 SF		0.00	0.64	0.87	18.00	89.98
NDERSONEYECLINIC_A1					2/1	/2023	Page: 28




128 Poplar Street, Gadsden, TN 38337

CONTINUED - Entrance

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
432. Paint the ceiling - two coats	111.11 SF		0.00	1.03	2.71	29.29	146.44
433. Final cleaning - construction - Residential	111.11 SF		0.00	0.28	0.00	7.78	38.89
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	e items may be	necessary for oth	er repair proces	sses.	
Begin Carpet Repairs							
Removal							
434. Mask and prep for paint - plastic, paper, tape (per LF)	31.83 LF		0.00	1.46	0.84	11.83	59.14
435. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
436. Tear out trim and bag for disposal - up to Cat 3	26.83 LF		0.89	0.00	0.47	6.09	30.44
437. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
438. Tear out baseboard and bag for disposal - up to Cat 3	26.83 LF		0.89	0.00	0.47	6.09	30.44
439. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	111.11 SF		1.40	0.00	0.65	39.06	195.26
440. Tear out wet carpet pad, cut/bag - Category 3 water	111.11 SF		0.76	0.00	0.65	21.28	106.37
Installation							
441. Apply anti-microbial agent to the floor	111.11 SF		0.00	0.25	0.43	7.05	35.26
Application of antimicrobial to the water	damaged space be	fore installation	n of new drywa	ll and insulation.			
442. Carpet pad	111.11 SF		0.00	0.59	5.53	17.77	88.85
443. Carpet	127.78 SF		0.00	3.38	34.76	116.67	583.33
444. Baseboard - 3 1/4"	26.83 LF		0.00	3.55	4.92	25.05	125.22
445. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
446. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
447. Paint baseboard - two coats	26.83 LF		0.00	1.52	0.37	10.30	51.45
448. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
449. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
450. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To move contents back in.							
451. Final cleaning - construction - Residential	111.11 SF		0.00	0.28	0.00	7.78	38.89
This final clean is for the drywall repair p	process. Additiona	l final clean lir	e items may be	necessary for oth	er repair proce	sses.	
Totals: Entrance					137.94	1,246.62	6,232.80
NDERSONEYECLINIC_A1					2/	1/2023	Page: 2



128 Poplar Street, Gadsden, TN 38337



Bathroom 1

Height: 8'

186.41 SF Walls 221.39 SF Walls & Ceiling 3.89 SY Flooring 25.49 LF Ceil. Perimeter 34.98 SF Ceiling 34.98 SF Floor

22.99 LF Floor Perimeter

Door	2' 6	" X 7'		Opens into FRONT_HALLW2			
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
452. Detach & Reset Soap/hand sanitizer dispenser - wall mounted	1.00 EA	14.14	0.00	0.00	0.00	3.53	17.67
453. Remove Paper towel dispenser	1.00 EA		14.94	0.00	0.00	3.73	18.67
Remove							
454. Install Paper towel dispenser	1.00 EA		0.00	19.39	0.00	4.85	24.24
<u>Install</u>							
455. Outlet or switch - Detach & reset	2.00 EA		0.00	16.63	0.00	8.32	41.58
456. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
457. Toilet - Detach & reset	1.00 EA		0.00	212.08	0.81	53.22	266.11
Begin Drywall Repairs							
Removal							
458. Content Manipulation charge - per hour	0.50 HR		0.00	38.02	0.00	4.75	23.76
To remove contents.							
459. Mask and prep for paint - plastic, paper, tape (per LF)	25.49 LF		0.00	1.46	0.67	9.47	47.36
460. Floor protection - plastic and tape - 10 mil	34.98 SF		0.00	0.32	0.41	2.90	14.50
461. Tear out wet paneling, no bagging - Cat 3	186.41 SF		0.57	0.00	0.00	26.57	132.82
462. Tear out wet drywall, cleanup, bag - Cat 3	221.39 SF		1.30	0.00	3.45	72.82	364.08
Walls/Ceiling							
463. Tear out and bag wet insulation - Category 3 water	221.39 SF		1.10	0.00	1.29	61.20	306.02
Walls/Ceiling							
Installation							
464. Apply anti-microbial agent to the walls and ceiling	221.39 SF		0.00	0.25	0.86	14.06	70.27
Application of antimicrobial to the water	damaged space bet	fore installatio	n of new drywa	all and insulation.			



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Bathroom 1


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
465. 5/8" drywall - hung, taped, ready for texture	34.98 SF		0.00	2.29	2.39	20.63	103.12
5/8 for the ceiling							
466. Blown-in insulation - 10" depth - R26	34.98 SF		0.00	1.10	2.76	10.31	51.55
Blown-in for the ceiling							
467. Clean stud wall	186.41 SF		0.00	0.82	0.36	38.31	191.53
468. Batt insulation - 6" - R19 - unfaced batt	186.41 SF		0.00	0.97	12.00	48.20	241.02
469. 1/2" drywall - hung, taped, ready for texture	186.41 SF		0.00	2.18	11.81	104.55	522.73
470. Paneling	186.41 SF		0.00	2.40	15.27	115.67	578.32
471. Texture drywall - smooth / skim coat	34.98 SF		0.00	1.38	0.41	12.17	60.85
For the ceiling							
472. Clean the ceiling	34.98 SF		0.00	0.38	0.03	3.32	16.64
Ceiling/walls must be cleaned prior to ap	plication of paint.						
473. Seal the ceiling w/latex based stain blocker - one coat	34.98 SF		0.00	0.64	0.27	5.67	28.33
474. Paint the ceiling - two coats	34.98 SF		0.00	1.03	0.85	9.22	46.10
475. Final cleaning - construction - Residential	34.98 SF		0.00	0.28	0.00	2.45	12.24
This final clean is for the drywall repair p	process. Additiona	l final clean li	ne items may b	e necessary for oth	er repair proces	sses.	
Begin Sink Repair							
Removal							
476. Remove Sink - wall mounted	1.00 EA		37.32	0.00	0.00	9.33	46.65
477. Remove P-trap assembly - ABS (plastic)	1.00 EA		7.46	0.00	0.00	1.87	9.33
Installation							116.04
478. Install Sink - single	1.00 EA		0.00	93.47	0.00	23.37	116.84
479. Install P-trap assembly - ABS (plastic)	1.00 EA		0.00	46.74	0.00	11.68	58.42
480. Final cleaning - construction - Residential	34.98 SF		0.00	0.28	0.00	2.45	12.24
This final clean is for the drywall repair	process. Additions	al final clean li	ne items may b	e necessary for oth	er repair proces	sses.	
Begin Tile Repairs							
Removal					0.73	0.47	47.36
481. Mask and prep for paint - plastic, paper, tape (per LF)	25.49 LF		0.00	1.46	0.67	9.47	23.34
482. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
NDERSONEYECLINIC_A1					2/	1/2023	Page:



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Bathroom 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
483. Tear out trim and bag for disposal - up to Cat 3	22.99 LF		0.89	0.00	0.40	5.22	26.08
484. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
485. Tear out baseboard and bag for disposal - up to Cat 3	22.99 LF		0.89	0.00	0.40	5.22	26.08
486. Tear out non-salvageable tile floor & bag - Cat 3 water	34.98 SF		5.07	0.00	0.65	44.51	222.51
Installation							
487. Apply anti-microbial agent to the floor	34.98 SF		0.00	0.25	0.14	2.22	11.11
Application of antimicrobial to the water d	lamaged space be	fore installatio	n of new drywa	ll and insulation.			
488. Tile floor covering	34.98 SF		0.00	8.80	16.47	81.07	405.36
489. Baseboard - 3 1/4"	22.99 LF		0.00	3.55	4.21	21.45	107.27
490. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
491. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
492. Paint baseboard - two coats	22.99 LF		0.00	1.52	0.31	8.81	44.06
493. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
494. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
495. Content Manipulation charge - per hour	0.50 HR		0.00	38.02	0.00	4.75	23.76
To move contents back in.							
496. Final cleaning - construction - Residential	34.98 SF		0.00	0.28	0.00	2.45	12.24
This final clean is for the drywall repair pr	ocess. Additional	final clean lir	ne items may be	necessary for other	er repair proces	ses.	
Totals: Bathroom 1					91.13	957.83	4,789.05



222 25 SE Wall

323.25 SF Walls 128.98 SF Ceiling 452.23 SF Walls & Ceiling 128.98 SF Floor

152.23 SF Walls & Ceiling 128.98 SF Floor
14.33 SY Flooring 40.41 LF Floor Perimeter

Height: 8'

40.41 LF Ceil. Perimeter

Missing Wall
6' 7" X 8'

Opens into FRONT_HALLW2

DESCRIPTION
QTY RESET REMOVE REPLACE TAX O&P TOTAL

ANDERSONEYECLINIC_A1 2/1/2023 Page: 32



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Contacts room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
497. Outlet or switch - Detach & reset	10.00 EA		0.00	16.63	0.00	41.58	207.88
498. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	14.02	0.00	7.01	35.05
499. Fluorescent light fixture - 6' & 8' - Detach & reset	3.00 EA		0.00	89.90	0.00	67.43	337.13
Begin Drywall Repairs							
Removal							
500. Content Manipulation charge - per hour	5.00 HR		0.00	38.02	0.00	47.53	237.63
To remove contents.							
501. Mask and prep for paint - plastic, paper, tape (per LF)	40.41 LF		0.00	1.46	1.06	15.02	75.08
502. Floor protection - plastic and tape - 10 mil	128.98 SF		0.00	0.32	1.51	10.70	53.48
503. Tear out wet paneling, no bagging - Cat 3	323.25 SF		0.57	0.00	0.00	46.07	230.32
504. Tear out wet drywall, cleanup, bag - Cat 3	452.23 SF		1.30	0.00	7.06	148.75	743.71
Walls/Ceiling							
505. Tear out and bag wet insulation - Category 3 water	452.23 SF		1.10	0.00	2.65	125.04	625.14
Walls/Ceiling							
Installation							1.40.60
506. Apply anti-microbial agent to the walls and ceiling	452.23 SF		0.00	0.25	1.76	28.71	143.53
Application of antimicrobial to the water	damaged space be	fore installation	n of new drywa	all and insulation.			
507. 5/8" drywall - hung, taped, ready for texture	128.98 SF		0.00	2.29	8.80	76.04	380.20
5/8 for the ceiling							
508. Blown-in insulation - 10" depth - R26	128.98 SF		0.00	1.10	10.19	38.02	190.09
Blown-in for the ceiling							
509. Clean stud wall	323.25 SF		0.00	0.82	0.63	66.42	332.12
510. Batt insulation - 6" - R19 - unfaced batt	323.25 SF		0.00	0.97	20.80	83.59	417.94
511. 1/2" drywall - hung, taped, ready for texture	323.25 SF		0.00	2.18	20.49	181.29	906.47
512. Paneling	323.25 SF		0.00	2.40	26.47	200.57	1,002.84
513. Texture drywall - smooth / skim coat	128.98 SF		0.00	1.38	1.51	44.88	224.38
For the ceiling							
NDERSONEYECLINIC_A1					2/	1/2023	Page: 33



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Contacts room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
514. Clean the ceiling	128.98 SF		0.00	0.38	0.13	12.28	61.42
Ceiling/walls must be cleaned prior to app	plication of paint.						
515. Seal the ceiling w/latex based stain blocker - one coat	128.98 SF		0.00	0.64	1.01	20.89	104.45
516. Paint the ceiling - two coats	128.98 SF		0.00	1.03	3.14	34.00	169.99
517. Final cleaning - construction - Residential	128.98 SF		0.00	0.28	0.00	9.03	45.14
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	ne items may be	necessary for oth	er repair proces	sses.	
Begin Cabinetry Repair							
Removal							
518. Remove Sink faucet - Kitchen	1.00 EA		18.67	0.00	0.00	4.67	23.34
519. Remove P-trap assembly - ABS (plastic)	1.00 EA		7.46	0.00	0.00	1.87	9.33
520. Remove Sink - single	1.00 EA		18.67	0.00	0.00	4.67	23.34
521. Remove 6" backsplash for flat laid countertop	7.00 LF		0.90	0.00	0.00	1.58	7.88
522. Remove Countertop - flat laid plastic laminate	7.00 LF		4.29	0.00	0.00	7.50	37.53
523. Remove Cabinetry - lower (base) units	7.00 LF		7.47	0.00	0.00	13.07	65.36
Installation							
524. Cabinetry - lower (base) units	7.00 LF		0.00	232.76	135.82	441.28	2,206.42
525. Countertop - flat laid plastic laminate	7.00 LF		0.00	40.91	19.97	76.60	382.94
526. 6" backsplash for flat laid countertop	7.00 LF		0.00	10.70	5.51	20.11	100.52
527. Install Sink - single	1.00 EA		0.00	93.47	0.00	23.37	116.84
528. Install P-trap assembly - ABS (plastic)	1.00 EA		0.00	46.74	0.00	11.68	58.42
529. Final cleaning - construction - Residential	128.98 SF		0.00	0.28	0.00	9.03	45.14
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	ne items may be	necessary for oth	er repair proces	sses.	
Begin Carpet Repairs							
Removal							
530. Mask and prep for paint - plastic, paper, tape (per LF)	40.41 LF		0.00	1.46	1.06	15.02	75.08
531. Tear out trim and bag for disposal - up to Cat 3	40.41 LF		0.89	0.00	0.71	9.17	45.84
532. Remove Door opening (jamb & casing) - 36"to60"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
533. Tear out baseboard and bag for disposal - up to Cat 3	40.41 LF		0.89	0.00	0.71	9.17	45.84
NDERSONEYECLINIC_A1					2/1	1/2023	Page: 3



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Contacts room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
534. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	128.98 SF		1.40	0.00	0.75	45.34	226.66
535. Tear out wet carpet pad, cut/bag - Category 3 water	128.98 SF		0.76	0.00	0.75	24.69	123.46
Installation							
536. Apply anti-microbial agent to the floor	128.98 SF		0.00	0.25	0.50	8.20	40.95
Application of antimicrobial to the water	damaged space b	efore installatio	n of new drywa	all and insulation.			
537. Carpet pad	128.98 SF		0.00	0.59	6.41	20.63	103.14
538. Carpet	148.33 SF		0.00	3.38	40.35	135.43	677.14
539. Baseboard - 3 1/4"	40.41 LF		0.00	3.55	7.41	37.72	188.59
540. Door opening (jamb & casing) - 36"to60"wide - paint grade	1.00 EA		0.00	208.31	15.23	55.88	279.42
541. Paint baseboard - two coats	40.41 LF		0.00	1.52	0.55	15.49	77.46
542. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
543. Content Manipulation charge - per hour	5.00 HR		0.00	38.02	0.00	47.53	237.63
To move contents back in.							
544. Final cleaning - construction - Residential	128.98 SF		0.00	0.28	0.00	9.03	45.14
This final clean is for the drywall repair p	rocess. Addition	al final clean lir	ne items may be	e necessary for oth	er repair proce	sses.	
Totals: Contacts room					343.43	2,363.57	11,817.33

6' 7"	Vorkshop				_		Height: 8'
Morkshop ok closet 50 Workshop ok 15' 9' 11' 7'	574.21 20.71	3 SF Walls 1 SF Walls 1 SY Floorin 7 LF Ceil. P	ng		186.38 SF C 186.38 SF F 50.17 LF F	-	er
Door		' X 7'		Opens into Opens into	BOOK_CLC	SET	
Window Window		' X 3' ' X 3'		Opens into			
Door	2' 6'	" X 7'		Opens into	BOSS_OFFI	CE2	
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							***
545. Outlet or switch - Detach & rese	et 16.00 EA		0.00	16.63	0.00	66.52	332.60
ANDERSONEYECLINIC_A1					2/1	/2023	Page: 35





CONTINUED - Workshop

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
546. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
547. Fluorescent light fixture - 6' & 8' - Detach & reset	4.00 EA		0.00	89.90	0.00	89.90	449.50
548. Cold air return cover - Detach & reset	1.00 EA		0.00	19.15	0.00	4.79	23.94
Begin Drywall Repairs							
Removal							
549. Content Manipulation charge - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.20
To remove contents.							
550. Mask and prep for paint - plastic, paper, tape (per LF)	55.17 LF		0.00	1.46	1.45	20.51	102.51
551. Floor protection - plastic and tape - 10 mil	186.38 SF		0.00	0.32	2.18	15.46	77.28
552. Remove Shelving - 24" - in place	84.00 LF		0.61	0.00	0.00	12.81	64.05
553. Tear out wet paneling, no bagging - Cat 3	387.83 SF		0.57	0.00	0.00	55.27	276.33
554. Tear out wet drywall, cleanup, bag - Cat 3	574.21 SF		1.30	0.00	8.96	188.86	944.29
Walls/Ceiling							
555. Tear out and bag wet insulation - Category 3 water	574.21 SF		1.10	0.00	3.36	158.74	793.73
Walls/Ceiling							
Installation							
556. Apply anti-microbial agent to the walls and ceiling	574.21 SF		0.00	0.25	2.24	36.45	182.24
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
557. 5/8" drywall - hung, taped, ready for texture	186.38 SF		0.00	2.29	12.72	109.88	549.41
5/8 for the ceiling							
558. Blown-in insulation - 10" depth - R26	186.38 SF		0.00	1.10	14.72	54.93	274.67
Blown-in for the ceiling							
559. Clean stud wall	387.83 SF		0.00	0.82	0.76	79.69	398.47
560. Batt insulation - 6" - R19 - unfaced batt	387.83 SF		0.00	0.97	24.96	100.29	501.45
561. 1/2" drywall - hung, taped, ready for texture	387.83 SF		0.00	2.18	24.58	217.52	1,087.57
562. Paneling	387.83 SF		0.00	2.40	31.76	240.64	1,203.19
563. Install Shelving - 24" - in place	84.00 LF		0.00	5.75	0.00	120.75	603.75

ANDERSONEYECLINIC_A1

2/1/2023

QTY



DESCRIPTION

128 Poplar Street, Gadsden, TN 38337

CONTINUED - Workshop

REMOVE REPLACE

RESET

O&P

TAX

TOTAL

Page: 37

	-					
564. Texture drywall - smooth / skim coat	186.38 SF	0.00	1.38	2.18	64.85	324.23
For the ceiling						
565. Clean the ceiling	186.38 SF	0.00	0.38	0.18	17.75	88.75
Ceiling/walls must be cleaned prior to ap	plication of paint.					
566. Seal the ceiling w/latex based stain blocker - one coat	186.38 SF	0.00	0.64	1.45	30.19	150.92
567. Paint the ceiling - two coats	186.38 SF	0.00	1.03	4.54	49.13	245.64
568. Final cleaning - construction - Residential	186.38 SF	0.00	0.28	0.00	13.05	65.24
This final clean is for the drywall repair p	rocess. Additional final clea	an line items may be no	ecessary for oth	er repair proces	sses.	
Begin Cabinetry Repair						
Removal						
569. Remove Sink faucet - Kitchen	1.00 EA	18.67	0.00	0.00	4.67	23.34
570. Remove P-trap assembly - ABS (plastic)	1.00 EA	7.46	0.00	0.00	1.87	9.33
571. Remove Sink - single	1.00 EA	18.67	0.00	0.00	4.67	23.34
572. Remove 6" backsplash for flat laid countertop	16.00 LF	0.90	0.00	0.00	3.60	18.00
573. Remove Countertop - flat laid plastic laminate	16.00 LF	4.29	0.00	0.00	17.16	85.80
574. Remove Cabinetry - lower (base) units	16.00 LF	7.47	0.00	0.00	29.88	149.40
575. Remove Cabinetry - upper (wall) units	7.00 LF	7.47	0.00	0.00	13.07	65.36
Installation						
576. Cabinetry - lower (base) units	16.00 LF	0.00	232.76	310.44	1,008.65	5,043.25
577. Countertop - flat laid plastic laminate	16.00 LF	0.00	40.91	45.65	175.06	875.27
578. 6" backsplash for flat laid countertop	16.00 LF	0.00	10.70	12.60	45.95	229.75
579. Install Sink - single	1.00 EA	0.00	93.47	0.00	23.37	116.84
580. Install P-trap assembly - ABS (plastic)	1.00 EA	0.00	46.74	0.00	11.68	58.42
581. Install Cabinetry - upper (wall) units	7.00 LF	0.00	33.76	0.00	59.08	295.40
582. Final cleaning - construction -	186.38 SF	0.00	0.28	0.00	13.05	65.24

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Begin Carpet/Vinyl Floor Repairs

Removal

ANDERSONEYECLINIC_A1 2/1/2023



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Workshop


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
583. Mask and prep for paint - plastic, paper, tape (per LF)	55.17 LF		0.00	1.46	1.45	20.51	102.51
584. Tear out trim and bag for disposal - up to Cat 3	50.17 LF		0.89	0.00	0.88	11.39	56.92
585. Remove Interior door unit	2.00 EA		18.67	0.00	0.00	9.33	46.67
586. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		6.27	0.00	0.00	3.13	15.67
587. Tear out baseboard and bag for disposal - up to Cat 3	50.17 LF		0.89	0.00	0.88	11.39	56.92
588. Tear out non-salv vinyl, cut & bag - Category 3 water	98.00 SF		1.95	0.00	0.57	47.93	239.60
589. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	186.38 SF		1.40	0.00	1.09	65.50	327.52
590. Tear out wet carpet pad, cut/bag - Category 3 water	186.38 SF		0.76	0.00	1.09	35.69	178.43
Installation							
591. Apply anti-microbial agent to the floor	186.38 SF		0.00	0.25	0.73	11.83	59.16
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ill and insulation.			
592. Carpet pad	186.38 SF		0.00	0.59	9.27	29.81	149.04
593. Carpet	214.33 SF		0.00	3.38	58.30	195.69	978.43
594. Vinyl floor covering (sheet goods)	98.00 SF		0.00	2.98	19.87	77.98	389.89
595. Baseboard - 3 1/4"	50.17 LF		0.00	3.55	9.20	46.83	234.13
596. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		0.00	176.22	25.89	94.58	472.91
597. Install Interior door unit	2.00 EA		0.00	50.02	0.00	25.01	125.05
598. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.57	1.62	20.18	100.94
599. Paint baseboard - two coats	50.17 LF		0.00	1.52	0.68	19.24	96.18
600. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	33.18	0.98	16.84	84.18
601. Content Manipulation charge - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.20
To move contents back in.							
602. Final cleaning - construction - Residential	186.38 SF		0.00	0.28	0.00	13.05	65.24
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	ne items may be	e necessary for other	er repair proce	sses.	
Totals: Workshop			***************************************		637.23	4,071.23	20,355.81

 $ANDERSONE YECLINIC_A1$

2/1/2023



128 Poplar Street, Gadsden, TN 38337



Paper room

269.08 SF Walls

349.24 SF Walls & Ceiling

8.91 SY Flooring

35.82 LF Ceil. Perimeter

Height: 8'

80.16 SF Ceiling 80.16 SF Floor

33.32 LF Floor Perimeter

aliway Door	2' 6	5" X 7'	Opens into FRONT_HALLW2				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
603. Outlet or switch - Detach & reset	5.00 EA		0.00	16.63	0.00	20.79	103.94
604. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA		0.00	89.90	0.00	22.48	112.38
605. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
Begin Drywall Repairs							
Removal							
606. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To remove contents.							
607. Mask and prep for paint - plastic, paper, tape (per LF)	35.82 LF		0.00	1.46	0.94	13.31	66.55
608. Floor protection - plastic and tape - 10 mil	80.16 SF		0.00	0.32	0.94	6.65	33.24
609. Tear out wet paneling, no bagging - Cat 3	269.08 SF		0.57	0.00	0.00	38.35	191.73
610. Tear out wet drywall, cleanup, bag - Cat 3	349.24 SF		1.30	0.00	5.45	114.87	574.33
Walls/Ceiling							
611. Tear out and bag wet insulation - Category 3 water	349.24 SF		1.10	0.00	2.04	96.55	482.75
Walls/Ceiling							
Installation 612. Apply anti-microbial agent to the walls and ceiling	349.24 SF		0.00	0.25	1.36	22.17	110.84
Application of antimicrobial to the water	damaged space be	efore installation	on of new dryw	all and insulation.			
613. 5/8" drywall - hung, taped, ready for texture	80.16 SF		0.00	2.29	5.47	47.27	236.31
5/8 for the ceiling							
614. Blown-in insulation - 10" depth - R26	80.16 SF		0.00	1.10	6.33	23.63	118.14
Blown-in for the ceiling							
615. Clean stud wall	269.08 SF		0.00	0.82	0.52	55.30	276.47
ANDERSONEYECLINIC_A1					2/	1/2023	Page: 3





ANDERSONEYECLINIC_A1

128 Poplar Street, Gadsden, TN 38337

CONTINUED - Paper room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
616. Batt insulation - 6" - R19 - unfaced batt	269.08 SF		0.00	0.97	17.32	69.58	347.91
617. 1/2" drywall - hung, taped, ready for texture	269.08 SF		0.00	2.18	17.05	150.92	754.56
618. Paneling	269.08 SF		0.00	2.40	22.04	166.96	834.79
619. Texture drywall - smooth / skim coat	80.16 SF		0.00	1.38	0.94	27.88	139.44
For the ceiling							
620. Clean the ceiling	80.16 SF		0.00	0.38	0.08	7.64	38.18
Ceiling/walls must be cleaned prior to app	plication of paint.						
621. Seal the ceiling w/latex based stain blocker - one coat	80.16 SF		0.00	0.64	0.62	12.98	64.90
622. Paint the ceiling - two coats	80.16 SF		0.00	1.03	1.95	21.13	105.64
623. Final cleaning - construction - Residential	80.16 SF		0.00	0.28	0.00	5.61	28.05
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	e items may be	necessary for other	er repair proces	ses.	
Begin Carpet Repairs							
Removal							
624. Mask and prep for paint - plastic, paper, tape (per LF)	35.82 LF		0.00	1.46	0.94	13.31	66.55
625. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
626. Tear out trim and bag for disposal - up to Cat 3	33.32 LF		0.89	0.00	0.59	7.57	37.81
627. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
628. Tear out baseboard and bag for disposal - up to Cat 3	33.32 LF		0.89	0.00	0.59	7.57	37.81
629. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	80.16 SF		1.40	0.00	0.47	28.17	140.86
630. Tear out wet carpet pad, cut/bag - Category 3 water	80.16 SF		0.76	0.00	0.47	15.35	76.74
Installation							
631. Apply anti-microbial agent to the floor	80.16 SF		0.00	0.25	0.31	5.09	25.44
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ll and insulation.			
632. Carpet pad	80.16 SF		0.00	0.59	3.99	12.82	64.10
633. Carpet	92.18 SF		0.00	3.38	25.08	84.17	420.82
634. Baseboard - 3 1/4"	33.32 LF		0.00	3.55	6.11	31.10	155.50
635. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
636. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52

2/1/2023



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Paper room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
637. Paint baseboard - two coats	33.32 LF		0.00	1.52	0.45	12.79	63.89
638. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
639. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
640. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To move contents back in.							
641. Final cleaning - construction - Residential	80.16 SF		0.00	0.28	0.00	5.61	28.05
This final clean is for the drywall repair pa	rocess. Additiona	ıl final clean lin	e items may be	e necessary for oth	er repair proce	sses.	
Totals: Paper room					136.29	1,292.70	6,463.11

Boss o	office						Height: 8'
3' 9" 10' 1"	355.8	3 SF Walls		<u>.</u>	162.71 SF C	Ceiling	
		4 SF Walls	& Ceiling		162.71 SF F	loor	
Boss office side hallw	18.0	8 SY Floorii	ng		46.17 LF F	loor Perimet	er
Č Člose	51.1	7 LF Ceil. P	erimeter				
F _{3' 2"} 1" 1" Window	3' 1'	" X 3'		Opens into	Exterior		
Window		" X 3'		Opens into			
Door	_	" X 7'		-	WORKSHO	P	
Door		" X 7'		Opens into		_	
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
642. Fluorescent light fixture - 6' & 8' - Detach & reset	2.00 EA		0.00	89.90	0.00	44.95	224.75
643. Outlet or switch - Detach & reset	16.00 EA		0.00	16.63	0.00	66.52	332.60
644. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
Begin Drywall Repairs							
Removal							
645. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To remove contents.							
646. Mask and prep for paint - plastic, paper, tape (per LF)	51.17 LF		0.00	1.46	1.35	19.02	95.08
NDERSONEYECLINIC_A1					2/1	/2023	Page:



ANDERSONEYECLINIC_A1

128 Poplar Street, Gadsden, TN 38337

CONTINUED - Boss office

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
647. Floor protection - plastic and tape - 10 mil	162.71 SF		0.00	0.32	1.90	13.50	67.47
648. Tear out wet paneling, no bagging - Cat 3	355.83 SF		0.57	0.00	0.00	50.70	253.52
649. Tear out wet drywall, cleanup, bag - Cat 3	518.54 SF		1.30	0.00	8.09	170.55	852.74
Walls/Ceiling							
650. Tear out and bag wet insulation - Category 3 water	518.54 SF		1.10	0.00	3.03	143.35	716.77
Walls/Ceiling							
Installation							
651. Apply anti-microbial agent to the walls and ceiling	518.54 SF		0.00	0.25	2.02	32.91	164.57
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ll and insulation.			
652. 5/8" drywall - hung, taped, ready for texture	162.71 SF		0.00	2.29	11.11	95.93	479.65
5/8 for the ceiling							
653. Blown-in insulation - 10" depth - R26	162.71 SF		0.00	1.10	12.85	47.97	239.80
Blown-in for the ceiling							
654. Batt insulation - 6" - R19 - unfaced batt	355.83 SF		0.00	0.97	22.90	92.02	460.08
655. 1/2" drywall - hung, taped, ready for texture	355.83 SF		0.00	2.18	22.55	199.57	997.83
656. Paneling	355.83 SF		0.00	2.40	29.14	220.78	1,103.91
657. Texture drywall - smooth / skim coat	162.71 SF		0.00	1.38	1.90	56.61	283.05
For the ceiling							
658. Clean the ceiling	162.71 SF		0.00	0.38	0.16	15.49	77.48
Ceiling/walls must be cleaned prior to ap	plication of paint.						
659. Seal the ceiling w/latex based stain blocker - one coat	162.71 SF		0.00	0.64	1.27	26.35	131.75
660. Paint the ceiling - two coats	162.71 SF		0.00	1.03	3.97	42.90	214.46
661. Final cleaning - construction - Residential	162.71 SF		0.00	0.28	0.00	11.39	56.95
This final clean is for the drywall repair p	rocess. Additiona	l final clean li	ne items may be	necessary for other	er repair proces	ses.	
Begin Carpet Repairs							
Removal							
662. Mask and prep for paint - plastic, paper, tape (per LF)	51.17 LF		0.00	1.46	1.35	19.02	95.08
663. Remove Interior door unit	2.00 EA		18.67	0.00	0.00	9.33	46.67

2/1/2023




128 Poplar Street, Gadsden, TN 38337

CONTINUED - Boss office

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
664. Tear out trim and bag for disposal - up to Cat 3	46.17 LF		0.89	0.00	0.81	10.47	52.37
665. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		6.27	0.00	0.00	3.13	15.67
666. Tear out baseboard and bag for disposal - up to Cat 3	46.17 LF		0.89	0.00	0.81	10.47	52.37
667. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	162.71 SF		1.40	0.00	0.95	57.19	285.93
668. Tear out wet carpet pad, cut/bag - Category 3 water	162.71 SF		0.76	0.00	0.95	31.16	155.77
Installation							
669. Apply anti-microbial agent to the floor	162.71 SF		0.00	0.25	0.63	10.32	51.63
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
670. Carpet pad	162.71 SF		0.00	0.59	8.09	26.02	130.11
671. Carpet	187.11 SF		0.00	3.38	50.90	170.83	854.16
672. Baseboard - 3 1/4"	46.17 LF		0.00	3.55	8.46	43.10	215.46
673. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		0.00	176.22	25.89	94.58	472.91
674. Install Interior door unit	2.00 EA		0.00	50.02	0.00	25.01	125.05
675. Paint baseboard - two coats	46.17 LF		0.00	1.52	0.63	17.70	88.51
676. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	33.18	0.98	16.84	84.18
677. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.57	1.62	20.18	100.94
678. Content Manipulation charge - per hour	4.00 HR		0.00	38.02	0.00	38.02	190.10
To move contents back in.							
679. Final cleaning - construction - Residential	162.71 SF		0.00	0.28	0.00	11.39	56.95
This final clean is for the drywall repair p	rocess. Additiona	ıl final clean li	ne items may b	e necessary for oth	er repair proce	sses.	
					224.31	2,006.79	10,033.94



128 Poplar Street, Gadsden, TN 38337



Electric room

Height: 8'

229.08 SF Walls 287.38 SF Walls & Ceiling 6.48 SY Flooring 30.82 LF Ceil. Perimeter

58.30 SF Floor28.32 LF Floor Perimeter

58.30 SF Ceiling

Door	2' 6	5" X 7'		Opens into FRONT_HALLW2				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
Accessories								
680. Light fixture - Detach & reset	1.00 EA		0.00	46.37	0.00	11.60	57.97	
681. Outlet or switch - Detach & reset	3.00 EA		0.00	16.63	0.00	12.47	62.36	
682. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52	
683. Remove Breaker panel - 200 amp	1.00 EA		143.42	0.00	0.00	35.85	179.27	
Remove								
684. Install Breaker panel - 200 amp	1.00 EA		0.00	840.25	0.00	210.07	1,050.32	
Reset								
Begin Drywall Repairs								
Removal								
685. Content Manipulation charge - per hour	1.00 HR		0.00	38.02	0.00	9.50	47.52	
To remove contents.								
686. Mask and prep for paint - plastic, paper, tape (per LF)	30.82 LF		0.00	1.46	0.81	11.45	57.26	
687. Floor protection - plastic and tape - 10 mil	58.30 SF		0.00	0.32	0.68	4.84	24.18	
688. Tear out wet paneling, no bagging - Cat 3	229.08 SF		0.57	0.00	0.00	32.65	163.23	
689. Tear out wet drywall, cleanup, bag - Cat 3	287.38 SF		1.30	0.00	4.48	94.52	472.59	
Walls/Ceiling								
690. Tear out and bag wet insulation - Category 3 water	287.38 SF		1.10	0.00	1.68	79.45	397.25	
Walls/Ceiling								
Installation								
691. Apply anti-microbial agent to the walls and ceiling	287.38 SF		0.00	0.25	1.12	18.25	91.22	
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ill and insulation.				
692. 5/8" drywall - hung, taped, ready for texture	58.30 SF		0.00	2.29	3.98	34.38	171.87	
5/8 for the ceiling								
NDERSONEYECLINIC_A1					2/	1/2023	Page: 4	



CONTINUED - Electric room


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
693. Blown-in insulation - 10" depth - R26	58.30 SF		0.00	1.10	4.60	17.18	85.91
Blown-in for the ceiling							
694. Clean stud wall	229.08 SF		0.00	0.82	0.45	47.09	235.39
695. Batt insulation - 6" - R19 - unfaced batt	229.08 SF		0.00	0.97	14.74	59.23	296.18
696. 1/2" drywall - hung, taped, ready for texture	229.08 SF		0.00	2.18	14.52	128.48	642.39
697. Paneling	229.08 SF		0.00	2.40	18.76	142.14	710.69
698. Texture drywall - smooth / skim coat	58.30 SF		0.00	1.38	0.68	20.29	101.42
For the ceiling							
699. Clean the ceiling	58.30 SF		0.00	0.38	0.06	5.56	27.77
Ceiling/walls must be cleaned prior to app	olication of paint.						
700. Seal the ceiling w/latex based stain blocker - one coat	58.30 SF		0.00	0.64	0.45	9.45	47.21
701. Paint the ceiling - two coats	58.30 SF		0.00	1.03	1.42	15.37	76.84
702. Final cleaning - construction - Residential	58.30 SF		0.00	0.28	0.00	4.08	20.40
This final clean is for the drywall repair p	rocess. Additiona	ıl final clean lii	ne items may be	necessary for other	er repair proces	ses.	
Begin Carpet Repairs							
Removal							
703. Mask and prep for paint - plastic, paper, tape (per LF)	30.82 LF		0.00	1.46	0.81	11.45	57.26
704. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
705. Tear out trim and bag for disposal - up to Cat 3	28.32 LF		0.89	0.00	0.50	6.43	32.13
706. Remove Door opening (jamb & casing) - 32"to36" wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
707. Tear out baseboard and bag for disposal - up to Cat 3	28.32 LF		0.89	0.00	0.50	6.43	32.13
708. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	58.30 SF		1.40	0.00	0.34	20.48	102.44
709. Tear out wet carpet pad, cut/bag - Category 3 water	58.30 SF		0.76	0.00	0.34	11.16	55.81
Installation						2.70	10.51
710. Apply anti-microbial agent to the floor	58.30 SF		0.00	0.25	0.23	3.70	18.51
Application of antimicrobial to the water	damaged space be	efore installation				0.00	46.63
711. Carpet pad	58.30 SF		0.00	0.59	2.90	9.33	46.63
712. Carpet	67.04 SF		0.00	3.38	18.24	61.21	306.05
.ndersoneyeclinic_A1					2/	1/2023	Page: 4



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Electric room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
713. Baseboard - 3 1/4"	28.32 LF		0.00	3.55	5.19	26.43	132.16
714. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
715. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
716. Paint baseboard - two coats	28.32 LF		0.00	1.52	0.39	10.87	54.31
717. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
718. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
719. Content Manipulation charge - per hour	1.00 HR		0.00	38.02	0.00	9.50	47.52
To move contents back in.							
720. Final cleaning - construction - Residential	58.30 SF		0.00	0.28	0.00	4.08	20.40
This final clean is for the drywall repair pr	rocess. Additiona	l final clean lir	ne items may be	necessary for oth	er repair proce	sses.	
Totals: Electric room					112.11	1,273.01	6,364.82



Patient room

Height: 8'

241.02 SF Walls 308.09 SF Walls & Ceiling 7.45 SY Flooring 32.24 LF Ceil. Perimeter

67.07 SF Floor

29.83 LF Floor Perimeter

67.07 SF Ceiling

Door 2' 5" X 7' Opens into SIDE_HALLWA2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
721. Light fixture - Detach & reset	1.00 EA		0.00	46.37	0.00	11.60	57.97
722. Outlet or switch - Detach & reset	8.00 EA		0.00	16.63	0.00	33.26	166.30
723. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
Begin Drywall Repairs							
Removal							
724. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To remove contents.							
725. Mask and prep for paint - plastic, paper, tape (per LF)	32.24 LF		0.00	1.46	0.85	11.99	59.91
NDERSONEYECLINIC_A1					2/1	/2023	Page: 46



CONTINUED - Patient room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
726. Floor protection - plastic and tape - 10 mil	67.07 SF		0.00	0.32	0.78	5.57	27.81
727. Tear out wet paneling, no bagging - Cat 3	241.02 SF		0.57	0.00	0.00	34.35	171.73
728. Tear out wet drywall, cleanup, bag - Cat 3	308.09 SF		1.30	0.00	4.81	101.33	506.66
Walls/Ceiling							
729. Tear out and bag wet insulation - Category 3 water	308.09 SF		1.10	0.00	1.80	85.18	425.88
Walls/Ceiling							
Installation							
730. Apply anti-microbial agent to the walls and ceiling	308.09 SF		0.00	0.25	1.20	19.55	97.77
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
731. 5/8" drywall - hung, taped, ready for texture	67.07 SF		0.00	2.29	4.58	39.55	197.72
5/8 for the ceiling							
732. Blown-in insulation - 10" depth - R26	67.07 SF		0.00	1.10	5.30	19.78	98.86
Blown-in for the ceiling							
733. Clean stud wall	241.02 SF		0.00	0.82	0.47	49.53	247.64
734. Batt insulation - 6" - R19 - unfaced batt	241.02 SF		0.00	0.97	15.51	62.33	311.63
735. 1/2" drywall - hung, taped, ready for texture	241.02 SF		0.00	2.18	15.27	135.17	675.86
736. Paneling	241.02 SF		0.00	2.40	19.74	149.55	747.74
737. Texture drywall - smooth / skim coat	67.07 SF		0.00	1.38	0.78	23.34	116.68
For the ceiling							
738. Clean the ceiling	67.07 SF		0.00	0.38	0.07	6.39	31.95
Ceiling/walls must be cleaned prior to ap	plication of paint.						
739. Seal the ceiling w/latex based stain blocker - one coat	67.07 SF		0.00	0.64	0.52	10.86	54.30
740. Paint the ceiling - two coats	67.07 SF		0.00	1.03	1.64	17.68	88.40
741. Final cleaning - construction - Residential	67.07 SF		0.00	0.28	0.00	4.70	23.48
This final clean is for the drywall repair p	process. Additiona	l final clean li	ne items may be	e necessary for oth	er repair proces	sses.	
Begin Carpet Repairs							
Removal 742. Mask and prep for paint - plastic, paper, tape (per LF)	32.24 LF		0.00	1.46	0.85	11.99	59.91
NDERSONEYECLINIC_A1					2/	1/2023	Page:



128 Poplar Street, Gadsden, TN 38337


CONTINUED - Patient room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
743. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
744. Tear out trim and bag for disposal - up to Cat 3	29.83 LF		0.89	0.00	0.52	6.77	33.84
745. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
746. Tear out baseboard and bag for disposal - up to Cat 3	29.83 LF		0.89	0.00	0.52	6.77	33.84
747. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	67.07 SF		1.40	0.00	0.39	23.58	117.87
748. Tear out wet carpet pad, cut/bag - Category 3 water	67.07 SF		0.76	0.00	0.39	12.85	64.21
Installation							
749. Apply anti-microbial agent to the floor	67.07 SF		0.00	0.25	0.26	4.27	21.30
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	ıll and insulation.			
750. Carpet pad	67.07 SF		0.00	0.59	3.34	10.73	53.64
751. Carpet	77.13 SF		0.00	3.38	20.98	70.43	352.11
752. Baseboard - 3 1/4"	29.83 LF		0.00	3.55	5.47	27.85	139.22
753. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
754. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
755. Paint baseboard - two coats	29.83 LF		0.00	1.52	0.41	11.43	57.18
756. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
757. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
758. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To move contents back in.							
759. Final cleaning - construction - Residential	67.07 SF		0.00	0.28	0.00	4.70	23.48
This final clean is for the drywall repair p	rocess. Additional	l final clean lir	ne items may be	necessary for other	er repair proce	sses.	
	-						
Totals: Patient room					120.69	1,158.16	5,790.28

ANDERSONEYECLINIC_A1



128 Poplar Street, Gadsden, TN 38337



Exam room 2

Height: 8'

354.50 SF Walls 484.00 SF Walls & Ceiling 14.39 SY Flooring 46.50 LF Ceil. Perimeter

129.50 SF Ceiling 129.50 SF Floor

44.00 LF Floor Perimeter

Door	2' 6	'' X 7'	Opens into SIDE_HALLWA2				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
760. Detach & Reset Soap/hand sanitizer dispenser - wall mounted	1.00 EA	14.14	0.00	0.00	0.00	3.53	17.67
761. Remove Paper towel dispenser	1.00 EA		14.94	0.00	0.00	3.73	18.67
Remove							
762. Install Paper towel dispenser	1.00 EA		0.00	19.39	0.00	4.85	24.24
Reset							
763. Outlet or switch - Detach & reset	10.00 EA		0.00	16.63	0.00	41.58	207.88
764. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
765. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA		0.00	89.90	0.00	22.48	112.38
Begin Drywall Repairs							
Removal							
766. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To remove contents.							
767. Mask and prep for paint - plastic, paper, tape (per LF)	46.50 LF		0.00	1.46	1.22	17.27	86.38
768. Floor protection - plastic and tape - 10 mil	129.50 SF		0.00	0.32	1.52	10.74	53.70
769. Tear out wet paneling, no bagging - Cat 3	354.50 SF		0.57	0.00	0.00	50.52	252.59
770. Tear out wet drywall, cleanup, bag - Cat 3	484.00 SF		1.30	0.00	7.55	159.19	795.94
Walls/Ceiling							
771. Tear out and bag wet insulation - Category 3 water	484.00 SF		1.10	0.00	2.83	133.80	669.03
Walls/Ceiling							
Installation					,		
772. Apply anti-microbial agent to the walls and ceiling	484.00 SF		0.00	0.25	1.89	30.72	153.61
Application of antimicrobial to the water	damaged space be	fore installation	on of new dryw	all and insulation.			



CONTINUED - Exam room 2


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
773. 5/8" drywall - hung, taped, ready for texture	129.50 SF		0.00	2.29	8.84	76.35	381.75
5/8 for the ceiling							
774. Blown-in insulation - 10" depth - R26	129.50 SF		0.00	1.10	10.23	38.17	190.85
Blown-in for the ceiling							
775. Batt insulation - 6" - R19 - unfaced batt	354.50 SF		0.00	0.97	22.81	91.67	458.35
776. 1/2" drywall - hung, taped, ready for texture	354.50 SF		0.00	2.18	22.47	198.82	994.10
777. Paneling	354.50 SF		0.00	2.40	29.03	219.95	1,099.78
778. Texture drywall - smooth / skim coat	129.50 SF		0.00	1.38	1.52	45.06	225.29
For the ceiling							
779. Clean the ceiling	129.50 SF		0.00	0.38	0.13	12.33	61.67
Ceiling/walls must be cleaned prior to app	plication of paint.						
780. Seal the ceiling w/latex based stain blocker - one coat	129.50 SF		0.00	0.64	1.01	20.97	104.86
781. Paint the ceiling - two coats	129.50 SF		0.00	1.03	3.16	34.14	170.69
782. Final cleaning - construction - Residential	129.50 SF		0.00	0.28	0.00	9.07	45.33
This final clean is for the drywall repair p	rocess. Additiona	l final clean lii	ne items may be	necessary for other	er repair proces	sses.	
Begin Carpet Repairs							
Removal							
783. Mask and prep for paint - plastic, paper, tape (per LF)	46.50 LF		0.00	1.46	1.22	17.27	86.38
784. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
785. Tear out trim and bag for disposal - up to Cat 3	44.00 LF		0.89	0.00	0.77	9.99	49.92
786. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
787. Tear out baseboard and bag for disposal - up to Cat 3	44.00 LF		0.89	0.00	0.77	9.99	49.92
788. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	129.50 SF		1.40	0.00	0.76	45.52	227.58
789. Tear out wet carpet pad, cut/bag - Category 3 water	129.50 SF		0.76	0.00	0.76	24.79	123.97
Installation							
790. Apply anti-microbial agent to the floor	129.50 SF		0.00	0.25	0.51	8.23	41.12
Application of antimicrobial to the water	damaged space be	fore installation	n of new drywa	all and insulation.			
791. Carpet pad	129.50 SF		0.00	0.59	6.44	20.71	103.56
NDERSONEYECLINIC_A1					2/	1/2023	Page:



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Exam room 2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
792. Carpet	148.93 SF		0.00	3.38	40.51	135.98	679.87
793. Baseboard - 3 1/4"	44.00 LF		0.00	3.55	8.07	41.07	205.34
794. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
795. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
796. Paint baseboard - two coats	44.00 LF		0.00	1.52	0.60	16.87	84.35
797. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
798. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
799. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To move contents back in.							
800. Final cleaning - construction - Residential	129.50 SF		0.00	0.28	0.00	9.07	45.33
This final clean is for the drywall repair p	rocess. Additiona	ıl final clean li	ne items may b	e necessary for oth	ner repair proce	sses.	
Totals: Exam room 2	100000 10000				188.86	1,709.51	8,547.49



Exam room 1 Height: 8'

362.50 SF Walls 496.18 SF Walls & Ceiling 14.85 SY Flooring

47.50 LF Ceil. Perimeter

133.68 SF Ceiling 133.68 SF Floor 45.00 LF Floor Perimeter

Door 2' 6" X 7' Opens into SIDE_HALLWA2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
801. Recessed light fixture - Detach & reset entire unit	2.00 EA		0.00	97.23	0.00	48.62	243.08
802. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA		0.00	89.90	0.00	22.48	112.38
803. Detach & Reset Soap/hand sanitizer dispenser - wall mounted	1.00 EA	14.14	0.00	0.00	0.00	3.53	17.67
804. Remove Paper towel dispenser	1.00 EA		14.94	0.00	0.00	3.73	18.67
Remove							
805. Install Paper towel dispenser	1.00 EA		0.00	19.39	0.00	4.85	24.24
Reset							
					211	/0.003	D 6:

ANDERSONEYECLINIC_A1

2/1/2023



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Exam room 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
806. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
807. Outlet or switch - Detach & reset	14.00 EA		0.00	16.63	0.00	58.20	291.02
Begin Drywall Repairs							
Removal							
808. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To remove contents.							
809. Mask and prep for paint - plastic, paper, tape (per LF)	47.50 LF		0.00	1.46	1.25	17.66	88.26
810. Floor protection - plastic and tape - 10 mil	133.68 SF		0.00	0.32	1.56	11.09	55.43
811. Tear out wet paneling, no bagging - Cat 3	362.50 SF		0.57	0.00	0.00	51.65	258.28
812. Tear out wet drywall, cleanup, bag - Cat 3	496.18 SF		1.30	0.00	7.74	163.18	815.95
Walls/Ceiling							
813. Tear out and bag wet insulation - Category 3 water	496.18 SF		1.10	0.00	2.90	137.18	685.88
Walls/Ceiling							
Installation							
814. Apply anti-microbial agent to the walls and ceiling	496.18 SF		0.00	0.25	1.94	31.50	157.49
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
815. Clean stud wall	496.18 SF		0.00	0.82	0.97	101.97	509.81
816. 5/8" drywall - hung, taped, ready for texture	133.68 SF		0.00	2.29	9.12	78.81	394.06
5/8 for the ceiling							
817. Blown-in insulation - 10" depth - R26	133.68 SF		0.00	1.10	10.56	39.41	197.02
Blown-in for the ceiling							
818. Batt insulation - 6" - R19 - unfaced batt	362.50 SF		0.00	0.97	23.33	93.73	468.69
819. 1/2" drywall - hung, taped, ready for texture	362.50 SF		0.00	2.18	22.97	203.32	1,016.54
820. Paneling	362.50 SF		0.00	2.40	29.69	224.92	1,124.61
821. Texture drywall - smooth / skim coat	133.68 SF		0.00	1.38	1.56	46.51	232.55
For the ceiling							
822. Clean the ceiling	133.68 SF		0.00	0.38	0.13	12.73	63.66
Ceiling/walls must be cleaned prior to app			_				00.00

ANDERSONEYECLINIC_A1

2/1/2023



CONTINUED - Exam room 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
823. Seal the ceiling w/latex based stain blocker - one coat	133.68 SF		0.00	0.64	1.04	21.65	108.25
824. Paint the ceiling - two coats	133.68 SF		0.00	1.03	3.26	35.24	176.1
825. Final cleaning - construction - Residential	133.68 SF		0.00	0.28	0.00	9.35	46.7
This final clean is for the drywall repair p	rocess. Additiona	l final clean lii	ne items may be	necessary for other	er repair process	ses.	
Begin Carpet Repairs							
Removal							
826. Mask and prep for paint - plastic, paper, tape (per LF)	47.50 LF		0.00	1.46	1.25	17.66	88.2
827. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.3
828. Tear out trim and bag for disposal - up to Cat 3	45.00 LF		0.89	0.00	0.79	10.22	51.0
829. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.8
830. Tear out baseboard and bag for disposal - up to Cat 3	45.00 LF		0.89	0.00	0.79	10.22	51.0
831. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	133.68 SF		1.40	0.00	0.78	46.99	234.
832. Tear out wet carpet pad, cut/bag - Category 3 water	133.68 SF		0.76	0.00	0.78	25.60	127.
Installation						0.40	42
833. Apply anti-microbial agent to the floor	133.68 SF		0.00	0.25	0.52	8.48	42.
Application of antimicrobial to the water	damaged space be	fore installation	on of new dryw	all and insulation.			
834. Carpet pad	133.68 SF		0.00	0.59	6.65	21.39	106.
835. Carpet	153.73 SF		0.00	3.38	41.82	140.35	701.
836. Baseboard - 3 1/4"	45.00 LF		0.00	3.55	8.25	42.01	210.
837. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.
838. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.
839. Paint baseboard - two coats	45.00 LF		0.00	1.52	0.61	17.25	86.
840. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.
841. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.
842. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.
To move contents back in.							
843. Final cleaning - construction - Residential	133.68 SF		0.00	0.28	0.00	9.35	46.
This final clean is for the drywall repair p	orocess. Additiona	ıl final clean li	ne items may b	e necessary for oth	er repair proces	ses.	
NDERSONEYECLINIC_A1					2/1	1/2023	Page



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Exam room 1

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Exam room l					194.50	1,915.91	9,579.34

Libra Libra	ıry			-,			Height: 8		
<u> </u>	546.3	3 SF Walls			217.61 SF (Ceiling			
o i i	763.9	4 SF Walls &	& Ceiling	217.61 SF Floor					
hallog o	24.1	8 SY Floorin	ng		67.67 LF Floor Perimeter				
2 <u>a</u> y 2 -	72.6	7 LF Ceil. P	erimeter						
ൃ⁻ Door	2' 6	" X 7'		Opens into	SIDE_HAL	LWA2			
Door	2' 6	'' X 7'		Opens into					
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAI		
Accessories									
844. Heat/AC register - Mechanically attached - Detach & reset	3.00 EA		0.00	14.02	0.00	10.52	52.5		
845. Recessed light fixture - Detach & reset entire unit	6.00 EA		0.00	97.23	0.00	145.85	729.2		
846. Fluorescent light fixture - 6' & 8' - Detach & reset	2.00 EA		0.00	89.90	0.00	44.95	224.7		
847. Outlet or switch - Detach & reset	22.00 EA		0.00	16.63	0.00	91.47	457.3		
Begin Drywall Repairs									
Removal									
848. Content Manipulation charge - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.2		
To remove contents.									
849. Mask and prep for paint - plastic, paper, tape (per LF)	72.67 LF		0.00	1.46	1.91	27.01	135.0		
850. Floor protection - plastic and tape - 10 mil	217.61 SF		0.00	0.32	2.55	18.05	90.2		
851. Tear out wet paneling, no bagging - Cat 3	546.33 SF		0.57	0.00	0.00	77.85	389.2		
852. Tear out wet drywall, cleanup, bag - Cat 3	763.94 SF		1.30	0.00	11.92	251.26	1,256.3		
Walls/Ceiling									
853. Tear out and bag wet insulation - Category 3 water	763.94 SF		1.10	0.00	4.47	211.20	1,056.0		
Walls/Ceiling									
Installation									
854. Apply anti-microbial agent to the walls and ceiling	763.94 SF		0.00	0.25	2.98	48.50	242.4		
NDERSONEYECLINIC_A1					2/1	1/2023	Page:		



ANDERSONEYECLINIC_A1

128 Poplar Street, Gadsden, TN 38337

CONTINUED - Library

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
855. 5/8" drywall - hung, taped, ready for texture	217.61 SF		0.00	2.29	14.85	128.30	641.48
5/8 for the ceiling							
856. Blown-in insulation - 10" depth - R26	217.61 SF		0.00	1.10	17.19	64.15	320.71
Blown-in for the ceiling							
857. Batt insulation - 6" - R19 - unfaced batt	546.33 SF		0.00	0.97	35.16	141.27	706.37
858. 1/2" drywall - hung, taped, ready for texture	546.33 SF		0.00	2.18	34.62	306.40	1,532.02
859. Paneling	546.33 SF		0.00	2.40	44.74	338.98	1,694.91
860. Texture drywall - smooth / skim coat	217.61 SF		0.00	1.38	2.55	75.72	378.57
For the ceiling							
861. Clean the ceiling	217.61 SF		0.00	0.38	0.21	20.72	103.62
Ceiling/walls must be cleaned prior to ap	plication of paint.						
862. Seal the ceiling w/latex based stain blocker - one coat	217.61 SF		0.00	0.64	1.70	35.25	176.22
863. Paint the ceiling - two coats	217.61 SF		0.00	1.03	5.30	57.36	286.80
864. Final cleaning - construction - Residential	217.61 SF		0.00	0.28	0.00	15.23	76.16
This final clean is for the drywall repair p	process. Additions	al final clean li	ne items may b	e necessary for other	er repair proces	sses.	
Begin Carpet Repairs							
Removal							
865. Mask and prep for paint - plastic, paper, tape (per LF)	72.67 LF		0.00	1.46	1.91	27.01	135.02
866. Remove Interior door unit	2.00 EA		18.67	0.00	0.00	9.33	46.67
867. Tear out trim and bag for disposal - up to Cat 3	67.67 LF		0.89	0.00	1.19	15.35	76.77
868. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		6.27	0.00	0.00	3.13	15.67
869. Tear out baseboard and bag for disposal - up to Cat 3	67.67 LF		0.89	0.00	1.19	15.35	7 6.77
870. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	217.61 SF		1.40	0.00	1.27	76.49	382.41
871. Tear out wet carpet pad, cut/bag - Category 3 water	217.61 SF		0.76	0.00	1.27	41.67	208.32
Installation							
872. Apply anti-microbial agent to the floor	217.61 SF		0.00	0.25	0.85	13.82	69.07
Application of antimicrobial to the water	damaged space be	efore installation	n of new dryw	all and insulation.			

Page: 55

2/1/2023



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Library

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
873. Carpet pad	217.61 SF		0.00	0.59	10.82	34.80	174.01
874. Carpet	250.25 SF		0.00	3.38	68.07	228.49	1,142.41
875. Baseboard - 3 1/4"	67.67 LF		0.00	3.55	12.40	63.15	315.78
876. Door opening (jamb & casing) - 32"to36"wide - paint grade	2.00 EA		0.00	176.22	25.89	94.58	472.91
877. Install Interior door unit	2.00 EA		0.00	50.02	0.00	25.01	125.05
878. Paint baseboard - two coats	67.67 LF		0.00	1.52	0.92	25.95	129.73
879. Paint door/window trim & jamb - 2 coats (per side)	2.00 EA		0.00	33.18	0.98	16.84	84.18
880. Paint door slab only - 2 coats (per side)	2.00 EA		0.00	39.57	1.62	20.18	100.94
881. Content Manipulation charge - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.20
To move contents back in.							
882. Final cleaning - construction - Residential	217.61 SF		0.00	0.28	0.00	15.23	76.16
This final clean is for the drywall repair p	process. Additiona	l final clean li	ne items may b	e necessary for otl	ner repair proce	sses.	
Totals: Library					308.53	2,988.50	14,942.31

reak room	Side hallway	Height: 8'
SE ility room	669.57 SF Walls	232.33 SF Ceiling
B 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	901.89 SF Walls & Ceiling	232.33 SF Floor
- 7.7.4 hallany	25.81 SY Flooring	80.89 LF Floor Perimeter
Paient room &	103.31 LF Ceil. Perimeter	
1' 9'E am r Exam room 2		
Missing Wall	4' 7 1/16" X 8'	Opens into FRONT_HALLW2
Door	2' 5" X 7'	Opens into PATIENT_ROO2
Door	2' 6" X 7'	Opens into EXAM_ROOM_2
Door	2' 6" X 7'	Opens into EXAM_ROOM_1
Door	2' 6" X 7'	Opens into LIBRARY2
Door	2' 6" X 7'	Opens into LIBRARY2
Door	2' 6" X 7'	Opens into Exterior
Door	2' 6" X 7'	Opens into BREAK_ROOM2
Door	2' 6" X 7'	Opens into UTILITY_ROO2
Door	2' 6" X 7'	Opens into BATHROOM 2



CONTINUED - Side hallway

∐ Subr	oom: Side hally	vay (1)					Height: 8'	
1' 6" 2 1' 5"	43.0	0 SF Walls		17.54 SF Ceiling				
	60.5	4 SF Walls	& Ceiling	17.54 SF Floor				
Side hallway (1)	1.95 SY Flooring				4.75 LF I	Floor Perimet	er	
2. 2. 2. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3. 3.	9.7	5 LF Ceil. P	erimeter					
Missing Wall	2' 4	" X 8'		Opens into SIDE_HALLWA2				
Door		'' X 7'		Opens into				
Door		'' X 7'		•	BOSS_OFF	ICE2		
Missing Wall	5' 5	" X 8'		Opens into	CLOSET2			
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
883. Outlet or switch - Detach & reset	6.00 EA		0.00	16.63	0.00	24.95	124.73	
884. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	14.02	0.00	7.01	35.05	
885. Smoke detector - Detach & reset	2.00 EA		0.00	44.90	0.00	22.45	112.25	
886. Light fixture - Detach & reset	2.00 EA		0.00	46.37	0.00	23.18	115.92	
887. Thermostat - Detach & reset	2.00 EA		0.00	46.89	0.00	23.45	117.23	
Begin Drywall Repairs								
Removal								
888. Content Manipulation charge - per hour	2.00 HR		0.00	38.02	0.00	19.01	95.05	
To remove contents.								
889. Mask and prep for paint - plastic, paper, tape (per LF)	113.06 LF		0.00	1.46	2.98	42.02	210.07	
890. Floor protection - plastic and tape - 10 mil	249.87 SF		0.00	0.32	2.92	20.72	103.60	
891. Tear out wet paneling, no bagging - Cat 3	712.57 SF		0.57	0.00	0.00	101.54	507.70	
892. Tear out wet drywall, cleanup, bag - Cat 3	962.44 SF		1.30	0.00	15.01	316.55	1,582.73	
Walls/Ceiling								
893. Tear out and bag wet insulation - Category 3 water	962.44 SF		1.10	0.00	5.63	266.07	1,330.38	
Walls/Ceiling								
Installation								
894. Apply anti-microbial agent to the walls and ceiling	962.44 SF		0.00	0.25	3.75	61.09	305.45	
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.				
895. 5/8" drywall - hung, taped, ready for texture	249.87 SF		0.00	2.29	17.05	147.32	736.5	
NDERSONEYECLINIC_A1					2/1	/2023	Page:	



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Side hallway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
5/8 for the ceiling							
896. Blown-in insulation - 10" depth - R26	249.87 SF		0.00	1.10	19.73	73.65	368.24
Blown-in for the ceiling							
897. Batt insulation - 6" - R19 - unfaced batt	712.57 SF		0.00	0.97	45.85	184.27	921.31
898. 1/2" drywall - hung, taped, ready for texture	712.57 SF		0.00	2.18	45.16	399.64	1,998.20
899. Paneling	712.57 SF		0.00	2.40	58.36	442.14	2,210.67
900. Texture drywall - smooth / skim coat	249.87 SF		0.00	1.38	2.92	86.93	434.67
For the ceiling							
901. Clean the ceiling	249.87 SF		0.00	0.38	0.24	23.80	118.99
Ceiling/walls must be cleaned prior to ap	plication of paint.						
902. Seal the ceiling w/latex based stain blocker - one coat	249.87 SF		0.00	0.64	1.95	40.47	202.34
903. Paint the ceiling - two coats	249.87 SF		0.00	1.03	6.09	65.87	329.33
904. Final cleaning - construction - Residential	249.87 SF		0.00	0.28	0.00	17.49	87.45
This final clean is for the drywall repair	process. Additiona	ıl final clean lir	ne items may be	e necessary for oth	er repair proces	sses.	
Begin Cabinetry Repair							
Removal							
905. Remove Cabinetry - upper (wall) units	14.00 LF		7.47	0.00	0.00	26.15	130.73
906. Remove Cabinetry - lower (base) units	9.00 LF		7.47	0.00	0.00	16.80	84.03
907. Remove Countertop - flat laid plastic laminate	9.00 LF		4.29	0.00	0.00	9.65	48.26
908. Remove 6" backsplash for flat laid countertop	9.00 LF		0.90	0.00	0.00	2.03	10.13
Installation							
909. Cabinetry - lower (base) units	9.00 LF		0.00	232.76	174.62	567.36	2,836.82
910. Countertop - flat laid plastic laminate	9.00 LF		0.00	40.91	25.68	98.47	492.34
911. 6" backsplash for flat laid countertop	9.00 LF		0.00	10.70	7.09	25.85	129.24
912. Cabinetry - upper (wall) units	14.00 LF		0.00	152.55	162.15	574.47	2,872.32
913. Final cleaning - construction - Residential	249.87 SF		0.00	0.28	0.00	17.49	87.45

This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.

Begin Carpet Repairs

ANDERSONEYECLINIC_A1

2/1/2023



CONTINUED - Side hallway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Removal			<u> </u>				
914. Mask and prep for paint - plastic, paper, tape (per LF)	113.06 LF		0.00	1.46	2.98	42.02	210.07
915. Remove Interior door unit	11.00 EA		18.67	0.00	0.00	51.35	256.72
916. Tear out trim and bag for disposal - up to Cat 3	85.64 LF		0.89	0.00	1.50	19.43	97.15
917. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	11.00 EA		6.27	0.00	0.00	17.25	86.22
918. Tear out baseboard and bag for disposal - up to Cat 3	85.64 LF		0.89	0.00	1.50	19.43	97.15
919. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	249.87 SF		1.40	0.00	1.46	87.82	439.10
920. Tear out wet carpet pad, cut/bag - Category 3 water	249.87 SF		0.76	0.00	1.46	47.85	239.21
Installation							
921. Apply anti-microbial agent to the floor	249.87 SF		0.00	0.25	0.97	15.87	79.31
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
922. Carpet pad	249.87 SF		0.00	0.59	12.42	39.95	199.79
923. Carpet	287.35 SF		0.00	3.38	78.17	262.36	1,311.77
924. Baseboard - 3 1/4"	85.64 LF		0.00	3.55	15.70	79.93	399.65
925. Door opening (jamb & casing) - 32"to36"wide - paint grade	11.00 EA		0.00	176.22	142.37	520.20	2,600.99
926. Install Interior door unit	11.00 EA		0.00	50.02	0.00	137.55	687.77
927. Paint baseboard - two coats	85.64 LF		0.00	1.52	1.17	32.85	164.19
928. Paint door/window trim & jamb - 2 coats (per side)	11.00 EA		0.00	33.18	5.38	92.60	462.96
929. Paint door slab only - 2 coats (per side)	11.00 EA		0.00	39.57	8.90	111.05	555.22
930. Content Manipulation charge - per hour	2.00 HR		0.00	38.02	0.00	19.01	95.05
To move contents back in.							
931. Final cleaning - construction - Residential	249.87 SF		0.00	0.28	0.00	17.49	87.45
This final clean is for the drywall repair p	rocess. Additiona	l final clean li	ne items may be	e necessary for oth	er repair proce	sses.	
Totals: Side hallway					871.16	5,361.90	26,809.02



128 Poplar Street, Gadsden, TN 38337

Fron	t hallway						Height: 8'
45" 6' 7" +8' 2" - '7", 3' 216 Suntroot	349.1	7 SF Walls			166.60 SF (Ceiling	
3'5" Required wood' 3"	515.7	7 SF Walls &	& Ceiling		166.60 SF I		
VC 8000 -12' 7" -10' 8" -		1 SY Floorin	_		42.08 LF I	Floor Perimet	er
	54.5	8 LF Ceil. P	erimeter				
Door	2' 6	'' X 7'		Opens into	BATHROO	M_1	
Missing Wall	6' 7	6' 7" X 8'			CONTACTS	S_RO2	
Door	2' 6" X 7'			Opens into	PAPER_RO	OM	
Door	2' 6	2' 6" X 7'			ELECTRIC	_ROO	
Missing Wall	4' 7 1/16" X 8'			Opens into	SIDE_HAL	LWA2	
Missing Wall	10' 8" X 8'			Opens into	ENTRANCI	E2	
Door	2' 6	2' 6" X 7'			FILE_ROO	M2	
Door	2' 6" X 7'			Opens into	A_C_ROOM	Л	
Missing Wall	4' 7	1/16" X 8'		Opens into	GLASSES_	ROO2	
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
932. Light fixture - Detach & reset	3.00 EA		0.00	46.37	0.00	34.78	173.89
933. Outlet or switch - Detach & reset	9.00 EA		0.00	16.63	0.00	37.42	187.09
934. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
Begin Drywall Repairs							
Removal							
935. Content Manipulation charge - per hour	0.50 HR		0.00	38.02	0.00	4.75	23.76
To remove contents.							
936. Mask and prep for paint - plastic, paper, tape (per LF)	54.58 LF		0.00	1.46	1.44	20.28	101.41
937. Floor protection - plastic and tape - 10 mil	166.60 SF		0.00	0.32	1.95	13.82	69.08
938. Tear out wet paneling, no bagging - Cat 3	349.17 SF		0.57	0.00	0.00	49.75	248.78
939. Tear out wet drywall, cleanup, bag - Cat 3	515.77 SF		1.30	0.00	8.05	169.65	848.20
Walls/Ceiling							
940. Tear out and bag wet insulation - Category 3 water	515.77 SF		1.10	0.00	3.02	142.59	712.96
Walls/Ceiling							
<u>Installation</u>	51 5 55 65				_		
941. Apply anti-microbial agent to the walls and ceiling	515.77 SF		0.00	0.25	2.01	32.73	163.68
ANDERSONEYECLINIC_A1					2/1	1/2023	Page: 60



CONTINUED - Front hallway


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Application of antimicrobial to the water	damaged space be	ore installatio	n of new drywa	ll and insulation.			
942. Clean stud wall	515.77 SF		0.00	0.82	1.01	105.98	529.92
943. 5/8" drywall - hung, taped, ready for texture	166.60 SF		0.00	2.29	11.37	98.23	491.11
5/8 for the ceiling							
944. Blown-in insulation - 10" depth - R26	166.60 SF		0.00	1.10	13.16	49.11	245.53
Blown-in for the ceiling							
945. Batt insulation - 6" - R19 - unfaced batt	349.17 SF		0.00	0.97	22.47	90.29	451.45
946. 1/2" drywall - hung, taped, ready for texture	349.17 SF		0.00	2.18	22.13	195.83	979.15
947. Paneling	349.17 SF		0.00	2.40	28.60	216.65	1,083.26
948. Texture drywall - smooth / skim coat	166.60 SF		0.00	1.38	1.95	57.97	289.83
For the ceiling							
949. Clean the ceiling	166.60 SF		0.00	0.38	0.16	15.87	79.34
Ceiling/walls must be cleaned prior to ap	plication of paint.						
950. Seal the ceiling w/latex based stain blocker - one coat	166.60 SF		0.00	0.64	1.30	26.98	134.90
951. Paint the ceiling - two coats	166.60 SF		0.00	1.03	4.06	43.92	219.58
952. Final cleaning - construction - Residential	166.60 SF		0.00	0.28	0.00	11.67	58.32
This final clean is for the drywall repair p	rocess. Additiona	l final clean li	ne items may be	e necessary for other	er repair proces	ses.	
Begin Carpet Repairs							
Removal							
953. Mask and prep for paint - plastic, paper, tape (per LF)	54.58 LF		0.00	1.46	1.44	20.28	101.41
954. Remove Interior door unit	5.00 EA		18.67	0.00	0.00	23.34	116.69
955. Tear out trim and bag for disposal - up to Cat 3	42.08 LF		0.89	0.00	0.74	9.55	47.74
956. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	5.00 EA		6.27	0.00	0.00	7.84	39.19
957. Tear out baseboard and bag for disposal - up to Cat 3	42.08 LF		0.89	0.00	0.74	9.55	47.74
958. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	166.60 SF		1.40	0.00	0.98	58.56	292.78
959. Tear out wet carpet pad, cut/bag - Category 3 water	166.60 SF		0.76	0.00	0.98	31.90	159.50
Installation					0.45	10.50	£2.00
960. Apply anti-microbial agent to the floor	166.60 SF		0.00	0.25	0.65	10.59	52.89
ANDERSONEYECLINIC_A1					2/1	1/2023	Page: 61



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Front hallway

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Application of antimicrobial to the water	damaged space be	fore installation	n of new drywa	ll and insulation.			
961. Carpet pad	166.60 SF		0.00	0.59	8.28	26.64	133.21
962. Carpet	191.59 SF		0.00	3.38	52.12	174.93	874.62
963. Baseboard - 3 1/4"	42.08 LF		0.00	3.55	7.71	39.28	196.37
964. Door opening (jamb & casing) - 32"to36"wide - paint grade	5.00 EA		0.00	176.22	64.72	236.46	1,182.28
965. Install Interior door unit	5.00 EA		0.00	50.02	0.00	62.53	312.63
966. Paint baseboard - two coats	42.08 LF		0.00	1.52	0.57	16.14	80.67
967. Paint door/window trim & jamb - 2 coats (per side)	5.00 EA		0.00	33.18	2.45	42.10	210.45
968. Paint door slab only - 2 coats (per side)	5.00 EA		0.00	39.57	4.05	50.49	252.39
969. Content Manipulation charge - per hour	0.50 HR		0.00	38.02	0.00	4.75	23.76
To move contents back in.							
970. Final cleaning - construction - Residential	166.60 SF		0.00	0.28	0.00	11.67	58.32
This final clean is for the drywall repair p	process. Additiona	l final clean lir	ne items may be	e necessary for other	er repair proce	sses.	
Totals: Front hallway					268.11	2,258.37	11,291.40



290.50 SF Walls

Break room

383.00 SF Walls & Ceiling 10.28 SY Flooring

38.50 LF Ceil. Perimeter

Height: 8'

92.50 SF Ceiling 92.50 SF Floor

36.00 LF Floor Perimeter

Door	2' 6" X 7'	Opens into SIDE HALLWA2
2001	- 0 11 .	opens med SIDE_INTED WITE

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							-
971. Fluorescent light fixture - 6' & 8' - Detach & reset	1.00 EA		0.00	89.90	0.00	22.48	112.38
972. Outlet or switch - Detach & reset	8.00 EA		0.00	16.63	0.00	33.26	166.30
973. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
974. Remove Breaker panel - 200 amp	2.00 EA		143.42	0.00	0.00	71.71	358.55
Remove							
975. Install Breaker panel - 200 amp NDERSONEYECLINIC_A1	2.00 EA		0.00	840.25	0.00 2/1	420.13 1/2023	2,100.63 Page: 62



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Break room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Reset							
Begin Drywall Repairs							
Removal							
976. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To remove contents.							
977. Mask and prep for paint - plastic, paper, tape (per LF)	38.50 LF		0.00	1.46	1.01	14.30	71.52
978. Floor protection - plastic and tape - 10 mil	92.50 SF		0.00	0.32	1.08	7.67	38.35
979. Tear out wet paneling, no bagging - Cat 3	290.50 SF		0.57	0.00	0.00	41.40	206.99
980. Tear out wet drywall, cleanup, bag - Cat 3	383.00 SF		1.30	0.00	5.97	125.98	629.85
Walls/Ceiling							
981. Tear out and bag wet insulation - Category 3 water	383.00 SF		1.10	0.00	2.24	105.89	529.43
Walls/Ceiling							
Installation							
982. Apply anti-microbial agent to the walls and ceiling	383.00 SF		0.00	0.25	1.49	24.31	121.55
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
983. 5/8" drywall - hung, taped, ready for texture	92.50 SF		0.00	2.29	6.31	54.53	272.67
5/8 for the ceiling							
984. Blown-in insulation - 10" depth - R26	92.50 SF		0.00	1.10	7.31	27.27	136.33
Blown-in for the ceiling							
985. Batt insulation - 6" - R19 - unfaced batt	290.50 SF		0.00	0.97	18.69	75.12	375.60
986. 1/2" drywall - hung, taped, ready for texture	290.50 SF		0.00	2.18	18.41	162.92	814.62
987. Paneling	290.50 SF		0.00	2.40	23.79	180.25	901.24
988. Texture drywall - smooth / skim coat	92.50 SF		0.00	1.38	1.08	32.19	160.92
For the ceiling							
989. Clean the ceiling	92.50 SF		0.00	0.38	0.09	8.81	44.05
Ceiling/walls must be cleaned prior to ap	plication of paint.						
990. Seal the ceiling w/latex based stain blocker - one coat	92.50 SF		0.00	0.64	0.72	14.98	74.90
991. Paint the ceiling - two coats	92.50 SF		0.00	1.03	2.26	24.39	121.93
ANDERSONEYECLINIC_A1					2/1	1/2023	Page: 63





CONTINUED - Break room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAI
992. Final cleaning - construction - Residential	92.50 SF		0.00	0.28	0.00	6.48	32.38
This final clean is for the drywall repair pa	rocess. Additiona	l final clean lir	e items may be	necessary for other	er repair proces	sses.	
Begin Carpet Repairs							
Removal							
993. Mask and prep for paint - plastic, paper, tape (per LF)	38.50 LF		0.00	1.46	1.01	14.30	71.5
994. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.3
995. Tear out trim and bag for disposal - up to Cat 3	36.00 LF		0.89	0.00	0.63	8.16	40.8
996. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.8
997. Tear out baseboard and bag for disposal - up to Cat 3	36.00 LF		0.89	0.00	0.63	8.16	40.8
998. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	92.50 SF		1.40	0.00	0.54	32.51	162.5
999. Tear out wet carpet pad, cut/bag - Category 3 water	92.50 SF		0.76	0.00	0.54	17.71	88.5
Installation							
1,000. Apply anti-microbial agent to the floor	92.50 SF		0.00	0.25	0.36	5.87	29.3
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
1,001. Carpet pad	92.50 SF		0.00	0.59	4.60	14.80	73.9
1,002. Carpet	106.38 SF		0.00	3.38	28.94	97.12	485.6
1,003. Baseboard - 3 1/4"	36.00 LF		0.00	3.55	6.60	33.60	168.0
1,004. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.4
1,005. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.5
1,006. Paint baseboard - two coats	36.00 LF		0.00	1.52	0.49	13.80	69.0
1,007. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.0
1,008. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.4
1,009. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.5
Γο move contents back in.							
1,010. Final cleaning - construction - Residential	92.50 SF		0.00	0.28	0.00	6.48	32.3
This final clean is for the drywall repair p	rocess. Additiona	l final clean lir	ne items may be	e necessary for other	er repair proce	sses.	

ANDERSONEYECLINIC_A1

2/1/2023



128 Poplar Street, Gadsden, TN 38337

Utilit	y room						Height: 8'
y (1) (0+2:6:4:4:4:4:4:4:4:4:4:4:4:4:4:4:4:4:4:4:	235.8	3 SF Walls			60.90 SF C	Ceiling	
	296.7	3 SF Walls &	& Ceiling		60.90 SF F		
Utility room	6.7	7 SY Floorin	ng		29.17 LF F	loor Perimet	er
司	31.6	7 LF Ceil. P	erimeter				
Ţ 							
Door 11	2' 6	5" X 7'		Opens into	SIDE_HALI	JWA2	
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Begin Drywall Repairs							
Removal							
1,011. Content Manipulation charge - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.20
To remove contents.							
1,012. Mask and prep for paint - plastic, paper, tape (per LF)	31.67 LF		0.00	1.46	0.83	11.76	58.83
1,013. Floor protection - plastic and tape - 10 mil	60.90 SF		0.00	0.32	0.71	5.05	25.25
1,014. Tear out wet paneling, no bagging - Cat 3	235.83 SF		0.57	0.00	0.00	33.60	168.02
1,015. Tear out wet drywall, cleanup, bag - Cat 3	296.73 SF		1.30	0.00	4.63	97.59	487.97
Walls/Ceiling							
1,016. Tear out and bag wet insulation - Category 3 water	296.73 SF		1.10	0.00	1.74	82.03	410.17
Walls/Ceiling							
Installation							
1,017. Apply anti-microbial agent to the walls and ceiling	296.73 SF		0.00	0.25	1.16	18.84	94.18
Application of antimicrobial to the water	damaged space be	fore installation	n of new drywa	all and insulation.			
1,018. 5/8" drywall - hung, taped, ready for texture	60.90 SF		0.00	2.29	4.16	35.91	179.53
5/8 for the ceiling							
1,019. Blown-in insulation - 10" depth - R26	60.90 SF		0.00	1.10	4.81	17.95	89.75
Blown-in for the ceiling							
1,020. Batt insulation - 6" - R19 - unfaced batt	235.83 SF		0.00	0.97	15.18	60.99	304.93
1,021. 1/2" drywall - hung, taped, ready for texture	235.83 SF		0.00	2.18	14.95	132.27	661.33
1,022. Paneling	235.83 SF		0.00	2.40	19.31	146.33	731.63
1,023. Texture drywall - smooth / skim coat	60.90 SF		0.00	1.38	0.71	21.19	105.94
ANDERSONEYECLINIC_A1					2/1	/2023	Page: 65



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Utility room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
For the ceiling							
1,024. Clean the ceiling	60.90 SF		0.00	0.38	0.06	5.80	29.00
Ceiling/walls must be cleaned prior to app	lication of paint.						
1,025. Seal the ceiling w/latex based stain blocker - one coat	60.90 SF		0.00	0.64	0.47	9.87	49.32
1,026. Paint the ceiling - two coats	60.90 SF		0.00	1.03	1.48	16.05	80.26
1,027. Final cleaning - construction - Residential	60.90 SF		0.00	0.28	0.00	4.27	21.32
This final clean is for the drywall repair pr	ocess. Additiona	l final clean li	ne items may be	e necessary for other	er repair proces	ses.	
Begin Carpet Repairs							
Removal							
1,028. Mask and prep for paint - plastic, paper, tape (per LF)	31.67 LF		0.00	1.46	0.83	11.76	58.83
1,029. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
1,030. Tear out trim and bag for disposal - up to Cat 3	29.17 LF		0.89	0.00	0.51	6.62	33.09
1,031. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
1,032. Tear out baseboard and bag for disposal - up to Cat 3	29.17 LF		0.89	0.00	0.51	6.62	33.09
1,033. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	60.90 SF		1.40	0.00	0.36	21.41	107.03
1,034. Tear out wet carpet pad, cut/bag - Category 3 water	60.90 SF		0.76	0.00	0.36	11.66	58.30
Installation							
1,035. Apply anti-microbial agent to the floor	60.90 SF		0.00	0.25	0.24	3.86	19.33
Application of antimicrobial to the water of	lamaged space be	fore installation	on of new drywa	all and insulation.			
1,036. Carpet pad	60.90 SF		0.00	0.59	3.03	9.73	48.69
1,037. Carpet	70.03 SF		0.00	3.38	19.05	63.95	319.70
1,038. Baseboard - 3 1/4"	29.17 LF		0.00	3.55	5.35	27.23	136.13
1,039. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
1,040. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
1,041. Paint baseboard - two coats	29.17 LF		0.00	1.52	0.40	11.18	55.92
1,042. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
1,043. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
1,044. Content Manipulation charge - per hour	8.00 HR		0.00	38.02	0.00	76.04	380.20

ANDERSONEYECLINIC_A1


2/1/2023



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Utility room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
To move contents back in.							
1,045. Final cleaning - construction - Residential	60.90 SF		0.00	0.28	0.00	4.27	21.32
This final clean is for the drywall repair p	orocess. Additiona	ıl final clean liı	ne items may be	e necessary for oth	er repair proce	esses.	
Totals: Utility room					115.08	1,114.41	5,571.97



222.83 SF Walls 279.75 SF Walls & Ceiling 6.32 SY Flooring

30.04 LF Ceil. Perimeter

Height: 8'

27.54 LF Floor Perimeter

56.91 SF Ceiling

56.91 SF Floor

Door	2' 6" X 7'			Opens into SIDE_HALLWA2				
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL	
Accessories								
1,046. Handicap grab bar - Detach & reset	0.50 EA		0.00	31.02	0.00	3.88	19.39	
1,047. Detach & Reset Soap/hand sanitizer dispenser - wall mounted	1.00 EA	14.14	0.00	0.00	0.00	3.53	17.67	
1,048. Remove Paper towel dispenser	1.00 EA		14.94	0.00	0.00	3.73	18.67	
Remove								
1,049. Install Paper towel dispenser	1.00 EA		0.00	19.39	0.00	4.85	24.24	
Install								
1,050. Outlet or switch - Detach & reset	2.00 EA		0.00	16.63	0.00	8.32	41.58	
1,051. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52	
1,052. Toilet - Detach & reset	1.00 EA		0.00	212.08	0.81	53.22	266.11	
1,053. Bathroom mirror - Detach & reset	15.00 SF		0.00	8.62	0.00	32.33	161.63	
Begin Drywall Repairs								
Removal								
1,054. Content Manipulation charge - per hour	1.00 HR		0.00	38.02	0.00	9.50	47.52	
To remove contents.								
1,055. Mask and prep for paint - plastic, paper, tape (per LF)	30.04 LF		0.00	1.46	0.79	11.17	55.82	
NDERSONEYECLINIC_A1					2/1	/2023	Page: 67	



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Bathroom 2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,056. Floor protection - plastic and tape - 10 mil	56.91 SF		0.00	0.32	0.67	4.72	23.60
1,057. Tear out wet paneling, no bagging - Cat 3	222.83 SF		0.57	0.00	0.00	31.75	158.76
1,058. Tear out wet drywall, cleanup, bag - Cat 3	279.75 SF		1.30	0.00	4.36	92.01	460.05
Walls/Ceiling							
1,059. Tear out and bag wet insulation - Category 3 water	279.75 SF		1.10	0.00	1.64	77.34	386.71
Walls/Ceiling							
Installation							
1,060. Apply anti-microbial agent to the walls and ceiling	279.75 SF		0.00	0.25	1.09	17.75	88.78
Application of antimicrobial to the water	damaged space be	fore installation	n of new drywa	all and insulation.			
1,061. Clean stud wall	279.75 SF		0.00	0.82	0.55	57.49	287.44
1,062. 5/8" drywall - hung, taped, ready for texture	56.91 SF		0.00	2.29	3.88	33.55	167.75
5/8 for the ceiling							
1,063. Blown-in insulation - 10" depth - R26	56.91 SF		0.00	1.10	4.49	16.77	83.86
Blown-in for the ceiling							
1,064. Clean stud wall	222.83 SF		0.00	0.82	0.43	45.78	228.93
1,065. Batt insulation - 6" - R19 - unfaced batt	222.83 SF		0.00	0.97	14.34	57.62	288.11
1,066. 1/2" drywall - hung, taped, ready for texture	222.83 SF		0.00	2.18	14.12	124.98	624.87
1,067. Paneling	222.83 SF		0.00	2.40	18.25	138.27	691.31
1,068. Texture drywall - smooth / skim coat	56.91 SF		0.00	1.38	0.67	19.80	99.01
For the ceiling							
1,069. Clean the ceiling	56.91 SF		0.00	0.38	0.06	5.42	27.11
Ceiling/walls must be cleaned prior to app	olication of paint.						
1,070. Seal the ceiling w/latex based stain blocker - one coat	56.91 SF		0.00	0.64	0.44	9.21	46.07
1,071. Paint the ceiling - two coats	56.91 SF		0.00	1.03	1.39	15.00	75.01
1,072. Final cleaning - construction - Residential	56.91 SF		0.00	0.28	0.00	3.98	19.91
This final clean is for the drywall repair p	rocess. Additiona	ıl final clean li	ne items may be	e necessary for oth	er repair proces	ses.	
Begin Sink Repair							
Removal							
1,073. Remove Sink - wall mounted	1.00 EA		37.32	0.00	0.00	9.33	46.65
ANDERSONEYECLINIC_A1					2/1	/2023	Page: 68



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Bathroom 2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,074. Remove P-trap assembly - ABS (plastic)	1.00 EA		7.46	0.00	0.00	1.87	9.33
Installation							
1,075. Install Sink - single	1.00 EA		0.00	93.47	0.00	23.37	116.84
1,076. Install P-trap assembly - ABS (plastic)	1.00 EA		0.00	46.74	0.00	11.68	58.42
1,077. Final cleaning - construction - Residential	56.91 SF		0.00	0.28	0.00	3.98	19.91
This final clean is for the drywall repair p	rocess. Additiona	l final clean lii	ne items may be	e necessary for other	er repair proces	ses.	
Begin Tile Repairs							
Removal							
1,078. Mask and prep for paint - plastic, paper, tape (per LF)	30.04 LF		0.00	1.46	0.79	11.17	55.82
1,079. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.34
1,080. Tear out trim and bag for disposal - up to Cat 3	27.54 LF		0.89	0.00	0.48	6.25	31.24
1,081. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.84
1,082. Tear out baseboard and bag for disposal - up to Cat 3	27.54 LF		0.89	0.00	0.48	6.25	31.24
1,083. Tear out non-salvageable tile floor & bag - Cat 3 water	56.91 SF		5.07	0.00	1.05	72.40	361.98
Installation							
1,084. Apply anti-microbial agent to the floor	56.91 SF		0.00	0.25	0.22	3.60	18.05
Application of antimicrobial to the water	damaged space be	fore installatio	n of new drywa	all and insulation.			
1,085. Tile floor covering	56.91 SF		0.00	8.80	26.80	131.90	659.51
1,086. Baseboard - 3 1/4"	27.54 LF		0.00	3.55	5.05	25.72	128.54
1,087. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
1,088. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
1,089. Paint baseboard - two coats	27.54 LF		0.00	1.52	0.38	10.57	52.81
1,090. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
1,091. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
1,092. Content Manipulation charge - per hour	1.00 HR		0.00	38.02	0.00	9.50	47.52
To move contents back in.							
1,093. Final cleaning - construction - Residential	56.91 SF		0.00	0.28	0.00	3.98	19.91
This final clean is for the drywall repair p	rocess. Additiona	l final clean li	ne items may be	e necessary for other	er repair proces	ses.	
NDERSONEYECLINIC_A1		-			2/1	1/2023	Page: 6



ANDERSONEYECLINIC_A1

128 Poplar Street, Gadsden, TN 38337

CONTINUED - Bathroom 2

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Totals: Bathroom 2					117.47	1,301.58	6,507.91
Close	t						Height: 8
	103.3	33 SF Walls			20.31 SF	Ceiling	
Closet 5	123.0	65 SF Walls	& Ceiling		20.31 SF	Floor	
		26 SY Floori 92 LF Ceil. P	-		12.92 LF	Floor Perime	eter
Missing Wall	5' 5	5" X 8'		Opens into	o ROOM1		
DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
Accessories							
1,094. Heat/AC register - Mechanically attached - Detach & reset	1.00 EA		0.00	14.02	0.00	3.50	17.52
Begin Drywall Repairs							
Removal							
1,095. Content Manipulation charge - per hour	1.00 HR		0.00	38.02	0.00	9.50	47.5
To remove contents.							
1,096. Mask and prep for paint - plastic, paper, tape (per LF)	12.92 LF		0.00	1.46	0.34	4.80	24.00
1,097. Floor protection - plastic and tape - 10 mil	20.31 SF		0.00	0.32	0.24	1.69	8.4
1,098. Remove Shelving - 24" - in place	10.00 LF		0.61	0.00	0.00	1.53	7.6
1,099. Tear out wet paneling, no bagging - Cat 3	103.33 SF		0.57	0.00	0.00	14.73	73.6
1,100. Tear out wet drywall, cleanup, bag - Cat 3	123.65 SF		1.30	0.00	1.93	40.67	203.3
Walls/Ceiling							
1,101. Tear out and bag wet insulation - Category 3 water	123.65 SF		1.10	0.00	0.72	34.18	170.9
Walls/Ceiling							
Installation							
1,102. Apply anti-microbial agent to the walls and ceiling	123.65 SF		0.00	0.25	0.48	7.85	39.2
Application of antimicrobial to the water	damaged space be	efore installatio	n of new drywa	all and insulation.			
1,103. 5/8" drywall - hung, taped, ready for texture	20.31 SF		0.00	2.29	1.39	11.98	59.88
5/8 for the ceiling							
NIDEDGONEVECT DITC A 1							

Page: 70

2/1/2023



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Closet


DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,104. Blown-in insulation - 10" depth - R26	20.31 SF		0.00	1.10	1.60	5.98	29.93
Blown-in for the ceiling							
1,105. Batt insulation - 6" - R19 - unfaced batt	103.33 SF		0.00	0.97	6.65	26.72	133.60
1,106. 1/2" drywall - hung, taped, ready for texture	103.33 SF		0.00	2.18	6.55	57.96	289.7
1,107. Paneling	103.33 SF		0.00	2.40	8.46	64.12	320.5
1,108. Shelving - 24" - in place	10.00 LF		0.00	13.01	7.08	34.30	171.4
1,109. Texture drywall - smooth / skim coat	20.31 SF		0.00	1.38	0.24	7.06	35.3
For the ceiling							
1,110. Clean the ceiling	20.31 SF		0.00	0.38	0.02	1.93	9.6
Ceiling/walls must be cleaned prior to app	olication of paint.						
1,111. Seal the ceiling w/latex based stain blocker - one coat	20.31 SF		0.00	0.64	0.16	3.29	16.4
1,112. Paint the ceiling - two coats	20.31 SF		0.00	1.03	0.50	5.36	26.7
1,113. Final cleaning - construction - Residential	20.31 SF		0.00	0.28	0.00	1.42	7.
This final clean is for the drywall repair p	rocess. Additiona	ıl final clean lii	ne items may be	e necessary for other	er repair process	ses.	
Begin Carpet Repairs							
Removal							
1,114. Mask and prep for paint - plastic, paper, tape (per LF)	12.92 LF		0.00	1.46	0.34	4.80	24.0
1,115. Remove Interior door unit	1.00 EA		18.67	0.00	0.00	4.67	23.3
1,116. Tear out trim and bag for disposal - up to Cat 3	12.92 LF		0.89	0.00	0.23	2.93	14.6
1,117. Remove Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		6.27	0.00	0.00	1.57	7.8
1,118. Tear out baseboard and bag for disposal - up to Cat 3	12.92 LF		0.89	0.00	0.23	2.93	14.0
1,119. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	20.31 SF		1.40	0.00	0.12	7.13	35.0
1,120. Tear out wet carpet pad, cut/bag Category 3 water	20.31 SF		0.76	0.00	0.12	3.89	19.
Installation							
1,121. Apply anti-microbial agent to the floor	20.31 SF		0.00	0.25	0.08	1.29	6.4
Application of antimicrobial to the water		fore installation					
1,122. Carpet pad	20.31 SF		0.00	0.59	1.01	3.25	16.2
1,123. Carpet	23.36 SF		0.00	3.38	6.35	21.33	106.6



128 Poplar Street, Gadsden, TN 38337

CONTINUED - Closet

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,124. Baseboard - 3 1/4"	12.92 LF	•	0.00	3.55	2.37	12.07	60.31
1,125. Door opening (jamb & casing) - 32"to36"wide - paint grade	1.00 EA		0.00	176.22	12.94	47.28	236.44
1,126. Install Interior door unit	1.00 EA		0.00	50.02	0.00	12.50	62.52
1,127. Paint baseboard - two coats	12.92 LF		0.00	1.52	0.18	4.96	24.78
1,128. Paint door/window trim & jamb - 2 coats (per side)	1.00 EA		0.00	33.18	0.49	8.42	42.09
1,129. Paint door slab only - 2 coats (per side)	1.00 EA		0.00	39.57	0.81	10.10	50.48
1,130. Content Manipulation charge - per hour	1.00 HR		0.00	38.02	0.00	9.50	47.52
To move contents back in.							
1,131. Final cleaning - construction - Residential	20.31 SF		0.00	0.28	0.00	1.42	7.11
This final clean is for the drywall repair process. Additional final clean line items may be necessary for other repair processes.							
Totals: Closet				X	61.63	498.61	2,493.01



ANDERSONEYECLINIC_A1

128 Poplar Street, Gadsden, TN 38337

CONTINUED - File room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,132. Outlet or switch - Detach & reset	13.00 EA		0.00	16.63	0.00	54.05	270.24
1,133. Heat/AC register - Mechanically attached - Detach & reset	2.00 EA		0.00	14.02	0.00	7.01	35.05
Begin Drywall Repairs							
Removal							
1,134. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To remove contents.							
1,135. Mask and prep for paint - plastic, paper, tape (per LF)	65.42 LF		0.00	1.46	1.72	24.31	121.54
1,136. Floor protection - plastic and tape - 10 mil	229.38 SF		0.00	0.32	2.68	19.02	95.10
1,137. Tear out wet paneling, no bagging - Cat 3	488.33 SF		0.57	0.00	0.00	69.59	347.94
1,138. Tear out wet drywall, cleanup, bag - Cat 3	717.71 SF		1.30	0.00	11.20	236.05	1,180.27
Walls/Ceiling							
1,139. Tear out and bag wet insulation - Category 3 water	717.71 SF		1.10	0.00	4.20	198.42	992.10
Walls/Ceiling							
Installation							
1,140. Apply anti-microbial agent to the walls and ceiling	717.71 SF		0.00	0.25	2.80	45.55	227.78
Application of antimicrobial to the water of	damaged space be	fore installatio	n of new drywa	ill and insulation.			
1,141. 5/8" drywall - hung, taped, ready for texture	229.38 SF		0.00	2.29	15.66	135.24	676.18
5/8 for the ceiling							
1,142. Blown-in insulation - 10" depth - R26	229.38 SF		0.00	1.10	18.12	67.61	338.05
Blown-in for the ceiling							
1,143. Batt insulation - 6" - R19 - unfaced batt	488.33 SF		0.00	0.97	31.42	126.27	631.37
1,144. 1/2" drywall - hung, taped, ready for texture	488.33 SF		0.00	2.18	30.95	273.88	1,369.39
1,145. Paneling	488.33 SF		0.00	2.40	39.99	303.00	1,514.98
1,146. Texture drywall - smooth / skim coat	229.38 SF		0.00	1.38	2.68	79.80	399.02
For the ceiling							
1,147. Clean the ceiling	229.38 SF		0.00	0.38	0.22	21.84	109.22
Ceiling/walls must be cleaned prior to app	olication of paint.						

2/1/2023






CONTINUED - File room

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,148. Seal the ceiling w/latex based stain blocker - one coat	229.38 SF	12-11-1	0.00	0.64	1.79	37.15	185.74
1,149. Paint the ceiling - two coats	229.38 SF		0.00	1.03	5.59	60.47	302.32
1,150. Final cleaning - construction - Residential	229.38 SF		0.00	0.28	0.00	16.05	80.28
This final clean is for the drywall repair p	process. Additiona	l final clean lir	ne items may be	necessary for other	her repair proce	esses.	
Begin Carpet Repairs							
Removal							
1,151. Mask and prep for paint - plastic, paper, tape (per LF)	65.42 LF		0.00	1.46	1.72	24.31	121.54
1,152. Tear out trim and bag for disposal - up to Cat 3	60.42 LF		0.89	0.00	1.06	13.72	68.55
1,153. Tear out baseboard and bag for disposal - up to Cat 3	60.42 LF		0.89	0.00	1.06	13.72	68.55
1,154. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	229.38 SF		1.40	0.00	1.34	80.61	403.08
1,155. Tear out wet carpet pad, cut/bag - Category 3 water	229.38 SF		0.76	0.00	1.34	43.91	219.58
<u>Installation</u>							
1,156. Apply anti-microbial agent to the floor	229.38 SF		0.00	0.25	0.90	14.57	72.82
Application of antimicrobial to the water	damaged space be	fore installation	n of new drywa	all and insulation.			
1,157. Carpet pad	229.38 SF		0.00	0.59	11.41	36.68	183.42
1,158. Carpet	263.78 SF		0.00	3.38	71.76	240.84	1,204.18
1,159. Baseboard - 3 1/4"	60.42 LF		0.00	3.55	11.08	56.39	281.96
1,160. Paint baseboard - two coats	60.42 LF		0.00	1.52	0.82	23.16	115.82
1,161. Content Manipulation charge - per hour	3.00 HR		0.00	38.02	0.00	28.52	142.58
To move contents back in.							
1,162. Final cleaning - construction - Residential	229.38 SF		0.00	0.28	0.00	16.05	80.28
This final clean is for the drywall repair p	process. Additiona	l final clean lii	ne items may be	e necessary for ot	her repair proc	esses.	
Totals: File room					271.51	2,396.31	11,981.51
Total: Main Level					5,968.63	48,804.05	244,015.11
Total: Interior					5,968.63	48,804.05	244,015.11

ANDERSONEYECLINIC_A1

Mitigation

2/1/2023





CONTINUED - Mitigation

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,228. Water Extraction & Remediation (Bid Item) Per PuroClean incurred cost.	1.00 EA		0.00	113,489.75	0.00	28,372.44	141,862.19
Totals: Mitigation					0.00	28,372.44	141,862.19

Temporary Repairs

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,229. Temporary Repairs (Bid Item)	1.00 EA		0.00	14,000.00	0.00	3,500.00	17,500.00
Line item for completed temporary roof re	pair.						
Totals: Temporary Repairs					0.00	3,500.00	17,500.00

General

DESCRIPTION	QTY	RESET	REMOVE	REPLACE	TAX	O&P	TOTAL
1,163. Provide box & tape - large size	127.00 EA	_	0.00	4.41	129.52	153.67	843.26
1,164. Provide box & tape - medium size	170.00 EA		0.00	3.30	129.74	153.93	844.67
1,165. Bubble Wrap - Add-on cost for fragile items	2,250.00 LF		0.00	0.17	88.45	104.95	575.90
1,166. Content Manipulation charge - per hour	104.00 HR		0.00	38.02	0.00	988.52	4,942.60
1,167. Equipment setup, take down, and monitoring (hourly charge)	10.00 HR		0.00	51.52	0.00	128.80	644.00
1,168. Air mover (per 24 hour period) - No monitoring	200.00 EA		0.00	25.25	0.00	1,262.50	6,312.50
1,169. Dehumidifier (per 24 hour period) - Large - No monitoring	65.00 EA		0.00	72.75	0.00	1,182.19	5,910.94
1,170. Generator Pick up (Bid Item)	1.00 EA		0.00	150.00	0.00	37.50	187.50
1,171. Generator - 10-30KW (per day - 24 hour) - no monitoring	5.00 DA		0.00	400.00	0.00	500.00	2,500.00
1,172. Generator Delivery charge (Bid Item)	1.00 EA		0.00	150.00	0.00	37.50	187.50
1,173. Generator Fuel Charge	225.00 GL		0.00	5.99	0.00	336.94	1,684.69
1,174. Commercial Supervision / Project Management - per hour	320.00 HR		0.00	69.41	0.00	5,552.80	27,764.00
1,175. Site Safety Supervisor	320.00 HR		0.00	69.41	0.00	5,552.80	27,764.00



128 Poplar Street, Gadsden, TN 38337

CONTINUED - General

DESCRIPTION QTY RESET REMOVE REPLACE TAX O&P TOTAL

OSHA regulation Title 29 CFR §1926.502(h)- Safety Monitoring Systems - www.osha.gov/Publications/Const_Res_Man/1926m_interps.html

1926.502(h)(1)(i)

The safety monitor shall be competent to recognize fall hazards;

1926.502(h)(1)(ii)

The safety monitor shall warn the employee when it appears that the employee is unaware of a fall hazard or is acting in an unsafe manner;

1926.502(h)(1)(iii)

The safety monitor shall be on the same walking/working surface and within visual sighting distance of the employee being monitored;

1926.502(h)(1)(iv)

Labor to move dumpster/material sheathir 1,188. Dumpster load - Approx. 40	ng from elevation to elev	vation 613.46	0.00			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
1,187. General Demolition - per hour	20.00 HR	45.10	0.00	0.00	225.50	1,127.50
1,186. Remove Sheathing - OSB - 1/2"	288.00 SF	0.56	0.00	0.00	40.32	201.60
Place under the dumpster to protect the as	phalt.					
1,185. Material Only Sheathing - OSB - 1/2"	288.00 SF	0.00	0.54	15.16	42.67	213.35
1,184. Remove Sheathing - OSB - 1/2"	800.00 SF	0.56	0.00	0.00	112.00	560.00
Asphalt protection from heavy equipment.						
1,183. Material Only Sheathing - OSB - 1/2"	800.00 SF	0.00	0.54	42.12	118.53	592.65
Additional labor to cart debris to the dum	pster area.					
1,182. General Demolition - per hour	32.00 HR	45.10	0.00	0.00	360.80	1,804.00
1,181. Temporary fencing - 1-4 months (per month)	382.00 LF	0.00	2.10	0.00	200.55	1,002.75
1,180. Barricade/warning sign/traffic cone - Min. equip. charge	4.00 EA	0.00	52.50	0.00	52.50	262.50
Progressive cleaning. 2 laborers, 1 hour p	oer day, 5 days a week, f	for 8 weeks.				
1,179. General Laborer - per hour	80.00 HR	0.00	38.02	0.00	760.40	3,802.00
1,178. Temporary construction office - portable (trailer)	1.00 MO	0.00	279.08	0.00	69.77	348.85
1,177. Job-site cargo container - pick up/del. (each way) 16'-40'	8.00 EA	0.00	99.40	0.00	198.80	994.00
$For \ HVAC \ units \ and \ building \ furnishings$						
1,176. Job-site cargo/storage container - 40' long - per month	8.00 MO	0.00	115.84	90.36	254.27	1,271.35

ANDERSONEYECLINIC_A1



128 Poplar Street, Gadsden, TN 38337

Summary for Contents

Line Item Total P Ppty Material Tax	1,503.57 146.60
Subtotal Overhead Profit P Ppty Cleaning Tax	1,650.17 247.53 165.02 201.11
Replacement Cost Value Net Claim	\$2,263.83 \$2,263.83

DISCLAIMER:

The information, opinions, and photos contained in this estimate are privileged and confidential and intended only for the use of the individual, entity, or others who have been specifically authorized to receive it. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this estimate in error, please notify us immediately. Be advised that William Griffin, his affiliates and subsidiaries, are not certified public accountants, attorneys, or legal professionals and do not provide advice, audits, attests, or any other public accounting or legal services - nor should any documents or statements be perceived or construed as such by anyone. All rights reserved.



128 Poplar Street, Gadsden, TN 38337

Recap by Category

O&P Items			Total	9/
CABINETRY			15,168.67	2.69%
Coverage: Dwelling	@	100.00% =	15,168.67	
CONT: GARMENT & SOFT GOODS CLN			1,121.07	0.20%
Coverage: Contents	@	100.00% =	1,121.07	
CLEANING			9,113.36	1.62%
Coverage: Dwelling	@	100.00% =	9,113.36	
CONCRETE & ASPHALT			638.85	0.119
Coverage: Dwelling	@	100.00% =	638.85	
CONTENT MANIPULATION			12,215.44	2.179
Coverage: Dwelling	@	100.00% =	12,215.44	
CONT: PACKING, HANDLNG, STORAGE			382.50	0.079
Coverage: Contents	@	100.00% =	382.50	
GENERAL DEMOLITION			55,313.07	9.80
Coverage: Dwelling	@	100.00% =	55,313.07	
DOORS			2,200.82	0.399
Coverage: Dwelling	@	100.00% =	2,200.82	
DRYWALL			28,786.29	5.10
Coverage: Dwelling	@	100.00% =	28,786.29	
ELECTRICAL			5,753.62	1.02
Coverage: Dwelling	@	100.00% =	5,753.62	
FLOOR COVERING - CARPET			13,631.10	2.42
Coverage: Dwelling	@	100.00% =	13,631.10	
FLOOR COVERING - CERAMIC TILE			808.63	0.14
Coverage: Dwelling	@	100.00% =	808.63	
FLOOR COVERING - VINYL			292.04	0.05
Coverage: Dwelling	@	100.00% =	292.04	
PERMITS AND FEES			1,647.75	0.29
Coverage: Dwelling	@	100.00% =	1,647.75	
FINISH CARPENTRY / TRIMWORK			12,477.29	2.21
Coverage: Dwelling	@	100.00% =	12,477.29	
FINISH HARDWARE			56.56	0.01
Coverage: Dwelling	@	100.00% =	56.56	
FRAMING & ROUGH CARPENTRY			4,929.20	0.87
Coverage: Dwelling	@	100.00% =	4,929.20	
HEAT, VENT & AIR CONDITIONING			567.39	0.10
Coverage: Dwelling	@	100.00% =	567.39	
INSULATION			11,252.16	1.99
Coverage: Dwelling	@	100.00% =	11,252.16	
LABOR ONLY			47,464.00	8.41
Coverage: Dwelling	@	100.00% =	47,464.00	
LIGHT FIXTURES			3,990.40	0.71
Coverage: Dwelling	@	100.00% =	3,990.40	

Main Level

Break room

Utility room

Boss office

Workshop

Kitchen

Back exit

Book close

William Griffin, Public Insurance Adjuster



128 Poplar Street, Gadsden, TN 38337

O&P Items			Total	%
MOISTURE PROTECTION			2,160.65	0.38%
Coverage: Dwelling	@	100.00% =	2,160.65	
PLUMBING	_		1,649.13	0.29%
Coverage: Dwelling	@	100.00% =	1,649.13	
PANELING & WOOD WALL FINISHES	•		19,018.36	3.37%
Coverage: Dwelling	@	100.00% =	19,018.36	
PAINTING	•		14,742.93	2.61%
Coverage: Dwelling	@	100.00% =	14,742.93	
ROOFING			15,403.01	2.73%
Coverage: Dwelling	@	100.00% =	15,403.01	
SCAFFOLDING	0		293.79	0.05%
Coverage: Dwelling	@	100.00% =	293.79	0.0270
SIDING	•	100.0070	1,809.13	0.32%
Coverage: Dwelling	@	100.00% =	1,809.13	0.52 /0
_	w.	100.0070	2,614.56	0.46%
SOFFIT, FASCIA, & GUTTER Coverage: Dwelling	@	100.00% =	2,614.56	0.40 /0
STUCCO & EXTERIOR PLASTER	w	100.0070 -	3,318.69	0.59%
	@	100.00% =	3,318.69	0.3970
Coverage: Dwelling	@	100.00% -	222.37	0.04%
TOILET & BATH ACCESSORIES	@	100.00% =	222.37	0.04%
Coverage: Dwelling	@	100.00% -		2.050/
TEMPORARY REPAIRS	•	100.000/ -	17,308.45	3.07%
Coverage: Dwelling	@	100.00% =	17,308.45	0.110/
WINDOWS - VINYL		100.000/	603.44	0.11%
Coverage: Dwelling	@	100.00% =	603.44	
WINDOWS - WOOD	_	100.000/	8,676.40	1.54%
Coverage: Dwelling	@	100.00% =	8,676.40	
WATER EXTRACTION & REMEDIATION			127,333.19	22.57%
Coverage: Dwelling		100.00% =	127,333.19	
O&P Items Subtotal			442,964.31	78.51%
Material Sales Tax			7,998.68	1.42%
Coverage: Dwelling	@	100.00% =	7,998.68	
P Ppty Material Tax			146.60	0.03%
Coverage: Contents	@	100.00% =	146.60	
Storage Rental Tax	_		90.36	0.02%
Coverage: Dwelling	@	100.00% =	90.36	
Overhead		22 424	67,680.38	12.00%
Coverage: Dwelling	@	99.63% =	67,432.85	
Coverage: Contents	@	0.37% =	247.53	0.0004
Profit Covernos Develling	<u> </u>	00.7207	45,121.01	8.00%
Coverage: Dwelling	@	99.63% =	44,955.99	
Coverage: Contents	@	0.37% =	165.02	0.0404
P Ppty Cleaning Tax	6	100.0007 -	201.11	0.04%
Coverage: Contents	<u>@</u>	100.00% =	201.11	
Total			564,202.45	100.00%
NDERSONEYECLINIC_A1			2/1/2023	Page:

William Griffin, Public Insurance Adjuster



128 Poplar Street, Gadsden, TN 38337

Summary for Building

Replacement Cost Value Net Claim	\$561,938.62 \$561,938.62
Profit	44,955.99
Overhead	67,432.85
Subtotal	449,549.78
Storage Rental Tax	90.36
Material Sales Tax	7,998.68
Line Item Total	441,460.74

NOTICE

Overhead and labor adjustments have been made to reflect the current, or projected, economic and inflationary environment factors and pricing indexes that contractors are working under, and are subject to change as labor, equipment, and fuel prices, etc. fluctuate. The standard for General Contractors in the Insurance and Restoration Industry generally need a minimum of thirty-eight to forty percent profit margin to break even. Even larger Restoration Contractors, like Belfor and ServPro, estimate jobs at much larger margins than twenty percent, when bidding projects. Farmers and other major Insurance Carriers have set these precedents comparing reconstruction cost to market value.

William Griffin, Public Insurance Adjuster



128 Poplar Street, Gadsden, TN 38337

Line Item Totals: ANDERSONEYECLINIC

8,436.75 112,801.39 564,202.45

Grand Total Areas:

7,924.33	SF Walls	3,136.58	SF Ceiling	11,060.91	SF Walls and Ceiling
3,136.58	SF Floor	348.51	SY Flooring	991.80	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	1,112.13	LF Ceil. Perimeter
3,136.58	Floor Area	3,373.76	Total Area	7,924.33	Interior Wall Area
2,097.08	Exterior Wall Area	285.17	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		

Coverage	Item Total	%	ACV Total	%
Dwelling	561,938.62	99.60%	561,938.62	99.60%
Other Structures	0.00	0.00%	0.00	0.00%
Contents	2,263.83	0.40%	2,263.83	0.40%
Total	564,202.45	100.00%	564,202.45	100.00%

Law offices
LOGAN-THOMPSON, P.C. Laune Harnel

James F. Logan, Jr. James S. Thompson-Kenneth I. Muler Rebert S. Thompson Philip M. Jacobs * Robert G. Norred, Jr. * Matthew G. Coleman *Also heensed in Georgia **Satired

Professional Corporation 30 Second Street, NW P. O. Box 191

Cleveland, TN 37364-0191

Laurie Harrod McNelly Timothy D. Hewatt Bill B. Moss (1938-2014) James S. Webb (1931-2016) T: (423)476-2251 F: (423)472-0211 F: (423)476-2252

www.LoganThempsonLaccrons

rnorred a loganthompsonlaw.com

July 11, 2022

CERTIFIED MAIL, RETURN RECEIPT REQUESTED AND REGULAR U.S. MAIL

Dr. Gwin Anderson Gina Alice Anderson Stallings 113 E. Locust Street Dresden, TN 38225

Via email: gwin.anderson@gmail.com

Re: Amended Notice of Non-Payment - \$140,876.80

Gentlemen:

Pursuant to Tenn. Code Ann. §66-11-145 this Notice of Non-Payment will advise you that as of today's date. Atkins Services, LLC ("Atkins"), as contractor, has not received payment in the total amount of \$140.876.80 from you, the contractually represented owner, for the work Atkins was employed by you to complete, including improvements to certain real property which you purportedly own in Weakley County, Tennessee, known and designated as: 113 E. Locust St. - \$113,489.75; 119 Poplar St. - \$1,727.69; 121 Poplar St. - \$8.010.78; 106 S. Church St., Apt. 1 - \$3,179.25 106 S. Church St., Apt. 2 - \$810.34; 106 S. Church St., Apt. 3 - \$1.349.50; 106 S. Church St., Apt. 4 - \$810.34; 106 S. Church St., Apt. 5 - \$2,164.25; 106 S. Church St. Apt. 6 - \$4,051.70 and 106 S. Church St., Apt. 7 - \$5,283.20. Atkins supplied certain services and supplies which were used to improve your property described above. The last date materials and labor were supplied by Atkins at the property was January, 2022.

Payment of this \$140,876.80 balance needs to be received at this time or my office has been directed to take legal action to collect this balance due. This action may include the filing of a Notice of Lien on the property described herein.

Dr. Gwin Anderson Page 2

Atkins as contractor further seeks relief pursuant to Tennessee Prompt Payment Act (T.C.A. §66-34-101 et seq.) for your failure as owner, to make payments in accordance with the contractual agreement between you and Atkins. If you fail to pay the outstanding Balance of \$140.876.80 within ten days after receiving this notice. Atkins will seek all damages allowable under T.C.A. §66-34-101 et seq. Demand is further made for attorney's fees and late charges under the contract.

Sincerely,

Atkins Services, LLC

Robert G. Norred, Jr.,

Their Attorney

RGNjr:bjm

ce: Atkins Services, LLC via email: sanderson@puroelean.com

The rest Cost "twenth to 6" provides for the Limitshing to you of the tellowing intornation; in Tails in 1 for solution made to either a debt; (i) Aby internation obtained will be used for that Costcory and 3, there is consider, within thirty days after receipt of the native, impacts the result, of the debt, the new conference will assume the debt is valid. If the communes in the a the debt will not not appear that the debt, or any posture of the rest, and studed, the mebb confector will obtain verification of the debt, or any posture of a supplied a substantial the transfer and a copy of the verification or using ert will be really conference with considering any substantial transfer and the consumer which request within the transfer and first the consumer and a copy of the sensitive or the rest of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and address or the sensitive of the consumer with the name and the consumer with the name and the consumer with the name and the consumer with the consumer with the consumer with the name and the consumer with the consumer

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

Client:

Eye Clinic

Property:

113 E Locust St

Dresden, TN 38225

Operator:

PUROCLEA

Estimator:

Eli Dykes

Type of Estimate:

Tornado

Date Entered:

12/27/2021

Date Assigned:

Date Est. Completed:

1/10/2022

Date Job Completed:

Price List:

TNJA8X_DEC21

Labor Efficiency:

Restoration/Service/Remodel

Estimate:

2021-12-27-1711

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

2021-12-27-1711

Main Level


Main Level

Provide box & tape - large size Provide box & tape - medium size Content Manipulation charge - per hour techs for 20 hours packing out and movi	127.00 EA 170.00 EA 180.00 HR ing items to storage p 1.00 MO 2,250.00 LF	0.00 0.00 0.00 oods. 0.00	4.11 3.06 34.35 270.00	0.00 0.00 0.00	521.97 520.20 6,183.00
3. Content Manipulation charge - per hour	180.00 HR ing items to storage p 1.00 MO	0.00 pods.	34.35	0.00	
hour	ing items to storage p	oods. 0.00			6,183.00
9 techs for 20 hours packing out and movi	1.00 MO	0.00	270.00	0.00	
			270.00	0.00	
4. Porta Potty	2,250.00 LF	0.00		0.00	270.00
5. Bubble Wrap - Add-on cost for fragile items		5.00	0.23	0.00	517.50
6. Admistrative Estimator	10.00 HR	0.00	50.00	0.00	500.00
7. Dumpster fee 30 yard dumpsters	3.00 EA	0.00	1,440.00	0.00	4,320.00
8. Equipment setup, take down, and monitoring (hourly charge)	15.00 HR	0.00	42.67	0.00	640.05
9. Utillity Buggy with dump bed to take trash to dumpster	1.00 MO	0.00	2,000.00	0.00	2,000.00
10. Tarp - all-purpose poly - per sq ft (lab/mat) - CAT	3,000.00 SF	0.00	2.50	0.00	7,500.00
Tarped roof first time. Storm came in had	to Re tarp roof due t	o high winds.			
11. Air mover (per 24 hour period) - No monitoring	120.00 EA	0.00	25.00	0.00	3,000.00
12. Dehumidifier (per 24 hour period) - Large - No monitoring	65.00 EA	0.00	72.50	0.00	4,712.50
5 Dehus for 5 days on stabilization. 8 air r	movers for 5 days for	drying.			
13. Generator Pick up (Bid Item)	1.00 EA	0.00	150.00	0.00	150.00
14. Generator - 10-30KW (per day - 24 hour) - no monitoring	5.00 DA	0.00	400.00	0.00	2,000.00
15. Generator Delivery charge (Bid Item)	1.00 EA	0.00	150.00	0.00	150.00
16. Generator Fuel Charge	225.00 GL	0.00	5.99	0.00	1,347.75
17. (SPM) Senior Project Manger - CAT	100.00 HR	0.00	105.00	0.00	10,500.00
SPM - Harrison. 5 Hours a day for 20 day	rs.				
18. Command Center - CAT	20.00 DA	0.00	500.00	0.00	10,000.00
53' Mosbile storage/Office					
19. (PM) - Project Manger - CAT	190.00 HR	0.00	90.00	0.00	17,100.00
9.5 Hours a day for 20 days.					
20. Foreman - CAT	190.00 EA	0.00	58.87	0.00	11,185.30
021-12-27-1711				1/13/2022	Page: 2

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Main Level

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Jorge 1 foreman for 9.5 hours for	10 days. Nick 1 foreman for	9.5 hours for 10 days.			
Total: Main Level				0.00	83,118.27



Back Exit

269.33 SF Walls 378.83 SF Walls & Ceiling

12.17 SY Flooring 33.67 LF Ceil. Perimeter Height: 8'

109.50 SF Ceiling 109.50 SF Floor

33.67 LF Floor Perimeter

Missing Wall

9' X 8'

Opens into GLASSES_ROOM

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
21. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	109.50 SF	1.17	0.00	0.00	128.12
22. Tear out wet drywall, cleanup, bag - Cat 3	109.50 SF	1.10	0.00	0.00	120.45
23. Tear out and bag wet insulation - Category 3 water	189.50 SF	0.93	0.00	0.00	176.24
24. Remove Outlet or switch cover	8.00 EA	0.57	0.00	0.00	4.56
25. Cold air return cover - Detach & reset	1.50 EA	0.00	17.64	0.00	26.46
Detach only 3 Covers					
26. Remove Interior door unit	2.00 EA	17.05	0.00	0.00	34.10
27. Tear out baseboard and bag for disposal - up to Cat 3	33.67 LF	0.76	0.00	0.00	25.59
28. Tear out trim and bag for disposal - up to Cat 3	33.67 LF	0.76	0.00	0.00	25.59
29. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
30. Tear out wet paneling, no bagging - Cat 3	269.33 SF	0.48	0.00	0.00	129.28
31. Apply anti-microbial agent to the floor	109.50 SF	0.00	0.22	0.00	24.09
Totals: Back Exit				0.00	831.88

1/13/2022 Page: 3 2021-12-27-1711



Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848



Glasses Room


Height: 8'

468.00 SF Walls 741.50 SF Walls & Ceiling 30.39 SY Flooring 58.50 LF Ceil. Perimeter 273.50 SF Ceiling 273.50 SF Floor 58.50 LF Floor Perimeter

Missing Wall
Missing Wall

9' X 8' 4' X 8' Opens into BACK_EXIT
Opens into FRONT_HALLWA

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
32. Tear out wet drywall, cleanup, bag - Cat 3	409.50 SF	1.10	0.00	0.00	450.45
33. Tear out and bag wet insulation - Category 3 water	409.50 SF	0.93	0.00	0.00	380.84
34. Remove Outlet or switch cover	6.00 EA	0.57	0.00	0.00	3.42
35. Cold air return cover - Detach & reset	2.00 EA	0.00	17.64	0.00	35.28
Detach only 4 Covers					
36. Content Manipulation charge - per hour	2.00 HR	0.00	34.35	0.00	68.70
37. Remove Drinking fountain	1.00 EA	73.75	0.00	0.00	73.75
38. Tear out baseboard and bag for disposal - up to Cat 3	58.50 LF	0.76	0.00	0.00	44.46
39. Remove Interior door unit	2.00 EA	17.05	0.00	0.00	34.10
40. Apply anti-microbial agent to the floor	273.50 SF	0.00	0.22	0.00	60.17
41. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Glasses Room				0.00	1,288.57



Kitchen

368.00 SF Walls 500.00 SF Walls & Ceiling 14.67 SY Flooring

46.00 LF Ceil. Perimeter

Height: 8'
132.00 SF Ceiling
132.00 SF Floor

46.00 LF Floor Perimeter

DESCRIPTION QTY REMOVE REPLACE TAX TOTAL

1/13/2022

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Kitchen


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
42. Tear out baseboard and bag for disposal - up to Cat 3	46.00 LF	0.76	0.00	0.00	34.96
43. Content Manipulation charge - per hour	1.00 HR	0.00	34.35	0.00	34.35
44. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
45. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	132.00 SF	1.17	0.00	0.00	154.44
46. Tear out trim and bag for disposal - up to Cat 3	46.00 LF	0.76	0.00	0.00	34.96
47. Tear out wet drywall, cleanup, bag - Cat 3	132.00 SF	1.10	0.00	0.00	145.20
48. Tear out and bag wet insulation - Category 3 water	212.00 SF	0.93	0.00	0.00	197.16
49. Remove Outlet or switch cover	12.00 EA	0.57	0.00	0.00	6.84
50. Clean stud wall	500.00 SF	0.00	0.67	0.00	335.00
51. Tear out wet paneling, no bagging - Cat 3	368.00 SF	0.48	0.00	0.00	176.64
52. Cold air return cover - Detach & reset	0.50 EA	0.00	17.64	0.00	8.82
Detach Only 1 cover					
53. Remove Shelving - 24" - in place	8.00 LF	0.55	0.00	0.00	4.40
54. Remove Shelving - wire (vinyl coated)	21.00 LF	2.97	0.00	0.00	62.37
55. Sink - double basin - Detach	1.00 EA	0.00	24.33	0.00	24.33
56. Remove Plumbing fixture supply line	2.00 EA	4.55	0.00	0.00	9.10
57. Remove P-trap assembly - ABS (plastic)	1.00 EA	6.81	0.00	0.00	6.81
58. Cabinet - lower (base) unit - Detach	13.00 LF	0.00	15.43	0.00	200.59
59. Content Manipulation charge - per hour	1.50 HR	0.00	34.35	0.00	51.53
Tear out down 10' desk and remove					
60. Apply anti-microbial agent to the floor	132.00 SF	0.00	0.22	0.00	29.04
61. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Kitchen			4.410	0.00	1,670.99

Page: 5 2021-12-27-1711 1/13/2022

A. PuroClean

Atkins Services, LLC/PuroClean Property Damage Experts

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848




Book Closet

Height: 8'

144.00 SF Walls 164.00 SF Walls & Ceiling 2.22 SY Flooring 18.00 LF Ceil. Perimeter 20.00 SF Ceiling 20.00 SF Floor 18.00 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
62. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	20.00 SF	1.17	0.00	0.00	23.40
63. Tear out wet drywall, cleanup, bag - Cat 3	20.00 SF	1.10	0.00	0.00	22.00
64. Tear out and bag wet insulation - Category 3 water	20.00 SF	0.93	0.00	0.00	18.60
65. Tear out baseboard and bag for disposal - up to Cat 3	18.00 LF	0.76	0.00	0.00	13.68
66. Tear out trim and bag for disposal - up to Cat 3	18.00 LF	0.76	0.00	0.00	13.68
67. Tear out wet paneling, no bagging - Cat 3	144.00 SF	0.48	0.00	0.00	69.12
68. Remove Shelving - 24" - in place	24.00 LF	0.55	0.00	0.00	13.20
69. Remove Outlet or switch cover	1.00 EA	0.57	0.00	0.00	0.57
70. Remove Interior door unit	2.00 EA	17.05	0.00	0.00	34.10
71. Content Manipulation charge - per hour	1.00 HR	0.00	34.35	0.00	34.35
72. Remove Closet rod	18.00 LF	0.46	0.00	0.00	8.28
73. Apply anti-microbial agent to the floor	20.00 SF	0.00	0.22	0.00	4.40
74. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Book Closet				0.00	392.78



170.67 SF Walls

197.33 SF Walls & Ceiling

2.96 SY Flooring

21.33 LF Ceil. Perimeter

Height: 8'


26.67 SF Ceiling 26.67 SF Floor

21.33 LF Floor Perimeter

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Bathroom

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
75. Tear out baseboard and bag for disposal - up to Cat 3	21.33 LF	0.76	0.00	0.00	16.21
76. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
77. Tear out trim and bag for disposal - up to Cat 3	21.33 LF	0.76	0.00	0.00	16.21
78. Tear out wet drywall, cleanup, bag - Cat 3	26.67 SF	1.10	0.00	0.00	29.34
79. Tear out and bag wet insulation - Category 3 water	50.67 SF	0.93	0.00	0.00	47.12
80. Remove Outlet or switch cover	2.00 EA	0.57	0.00	0.00	1.14
81. Clean stud wall	197.33 SF	0.00	0.67	0.00	132.21
82. Tear out wet paneling, no bagging - Cat 3	170.67 SF	0.48	0.00	0.00	81.92
83. Cold air return cover - Detach & reset	0.50 EA	0.00	17.64	0.00	8.82
Detach Only 1 cover					
84. Toilet - Detach	1.00 EA	0.00	37.73	0.00	37.73
85. Remove Plumbing fixture supply line	3.00 EA	4.55	0.00	0.00	13.65
86. Remove Sink - wall mounted	1.00 EA	34.11	0.00	0.00	34.11
87. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	26.67 SF	1.17	0.00	0.00	31.20
88. Apply anti-microbial agent to the floor	26.67 SF	0.00	0.22	0.00	5.87
89. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Bathroom				0.00	609.98



Waiting Room

464.00 SF Walls 672.00 SF Walls & Ceiling 23.11 SY Flooring

58.00 LF Ceil. Perimeter

Height: 8'

208.00 SF Ceiling 208.00 SF Floor

58.00 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
90. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	208.00 SF	1.17	0.00	0.00	243.36

1/13/2022 Page: 7 2021-12-27-1711

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Waiting Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
91. Tear out wet drywall, cleanup, bag - Cat 3	208.00 SF	1.10	0.00	0.00	228.80
92. Tear out and bag wet insulation - Category 3 water	208.00 SF	0.93	0.00	0.00	193.44
93. Remove Outlet or switch cover	7.00 EA	0.57	0.00	0.00	3.99
94. Cold air return cover - Detach & reset	3.50 EA	0.00	17.64	0.00	61.74
Detach only 7 Covers					
95. Tear out baseboard and bag for disposal - up to Cat 3	58.00 LF	0.76	0.00	0.00	44.08
96. Tear out trim and bag for disposal - up to Cat 3	58.00 LF	0.76	0.00	0.00	44.08
97. Tear out wet paneling, no bagging - Cat 3	464.00 SF	0.48	0.00	0.00	222.72
98. Wood window unit - Detach & reset	2.00 EA	0.00	114.12	0.00	228.24
Detach Only 2 windows					
99. Remove Interior door unit	2.00 EA	17.05	0.00	0.00	34.10
100. Remove Ceiling fan & light	1.00 EA	17.17	0.00	0.00	17.17
101. Apply anti-microbial agent to the floor	208.00 SF	0.00	0.22	0.00	45.76
102. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Waiting Room				0.00	1,504.88



288.00 SF Walls 368.00 SF Walls & Ceiling

Front Desk

8.89 SY Flooring 36.00 LF Ceil. Perimeter Height: 8'

80.00 SF Ceiling 80.00 SF Floor

36.00 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
103. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	80.00 SF	1.17	0.00	0.00	93.60
104. Tear out wet drywall, cleanup, bag - Cat 3	80.00 SF	1.10	0.00	0.00	88.00


1/13/2022

Page: 8

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Front Desk

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
105. Tear out and bag wet insulation - Category 3 water	144.00 SF	0.93	0.00	0.00	133.92
106. Remove Outlet or switch cover	6.00 EA	0.57	0.00	0.00	3.42
107. Cold air return cover - Detach & reset	1.00 EA	0.00	17.64	0.00	17.64
Detach only 2 Covers					
108. Tear out baseboard and bag for disposal - up to Cat 3	36.00 LF	0.76	0.00	0.00	27.36
109. Tear out trim and bag for disposal - up to Cat 3	36.00 LF	0.76	0.00	0.00	27.36
110. Tear out wet paneling, no bagging - Cat 3	288.00 SF	0.48	0.00	0.00	138.24
111. Wood window unit - Detach & reset	1.50 EA	0.00	114.12	0.00	171.18
Detach Only 3 windows					
112. Content Manipulation charge - per hour	2.50 HR	0.00	34.35	0.00	85.88
Tear out down 16' desk and remove					
113. Apply anti-microbial agent to the floor	80.00 SF	0.00	0.22	0.00	17.60
114. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Front Desk				0.00	941.60



14	11.33	SF Walls
15	8.83	SF Walls & Ceiling
	1.94	SY Flooring
1	7 67	LF Ceil Perimeter

Height: 8' 17.50 SF Ceiling 17.50 SF Floor 17.67 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
115. Tear out wet drywall, cleanup, bag - Cat 3	17.50 SF	1.10	0.00	0.00	19.25
116. Tear out and bag wet insulation - Category 3 water	17.50 SF	0.93	0.00	0.00	16.28
117. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05


Page: 9 1/13/2022 2021-12-27-1711



Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - A/C Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
118. Tear out baseboard and bag for disposal - up to Cat 3	17.67 LF	0.76	0.00	0.00	13.43
119. Tear out trim and bag for disposal - up to Cat 3	17.67 LF	0.76	0.00	0.00	13.43
120. Apply anti-microbial agent to the floor	17.50 SF	0.00	0.22	0.00	3.85
121. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: A/C Room	<u></u>	· · · · · · · · · · · · · · · · · · ·		0.00	220.69



Height: 8' **Entrance**

> 400.00 SF Walls 550.00 SF Walls & Ceiling 16.67 SY Flooring 50.00 LF Ceil. Perimeter

150.00 SF Ceiling 150.00 SF Floor 50.00 LF Floor Perimeter


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
122. Tear out baseboard and bag for disposal - up to Cat 3	50.00 LF	0.76	0.00	0.00	38.00
123. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	150.00 SF	1.17	0.00	0.00	175.50
124. Tear out trim and bag for disposal - up to Cat 3	50.00 LF	0.76	0.00	0.00	38.00
125. Tear out wet drywall, cleanup, bag - Cat 3	150.00 SF	1.10	0.00	0.00	165.00
126. Tear out and bag wet insulation - Category 3 water	150.00 SF	0.93	0.00	0.00	139.50
127. Remove Outlet or switch cover	5.00 EA	0.57	0.00	0.00	2.85
128. Clean stud wall	550.00 SF	0.00	0.67	0.00	368.50
129. Tear out wet paneling, no bagging - Cat 3	400.00 SF	0.48	0.00	0.00	192.00
130. Cold air return cover - Detach & reset	1.50 EA	0.00	17.64	0.00	26.46
Detach only 3 Covers					
131. Wood window unit - Detach & reset	0.50 EA	0.00	114.12	0.00	57.06
Detach Only					

Page: 10 1/13/2022 2021-12-27-1711

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Entrance

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
132. Apply anti-microbial agent to the floor	150.00 SF	0.00	0.22	0.00	33.00
133. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Entrance				0.00	1,373.27



Bathroom 1

170.67 SF Walls 197.33 SF Walls & Ceiling 2.96 SY Flooring 21.33 LF Ceil. Perimeter

Height: 8'

26.67 SF Ceiling 26.67 SF Floor


21.33 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
134. Tear out baseboard and bag for disposal - up to Cat 3	21.33 LF	0.76	0.00	0.00	16.21
135. Remove Soap/hand sanitizer dispenser - wall mounted	1.00 EA	6.81	0.00	0.00	6.81
136. Remove Paper towel dispenser	1.00 EA	13.65	0.00	0.00	13.65
137. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
138. Tear out trim and bag for disposal - up to Cat 3	21.33 LF	0.76	0.00	0.00	16.21
139. Tear out wet drywall, cleanup, bag - Cat 3	26.67 SF	1.10	0.00	0.00	29.34
140. Tear out and bag wet insulation - Category 3 water	138.67 SF	0.93	0.00	0.00	128.96
141. Remove Outlet or switch cover	2.00 EA	0.57	0.00	0.00	1.14
142. Clean stud wall	197.33 SF	0.00	0.67	0.00	132.21
143. Tear out wet paneling, no bagging - Cat 3	170.67 SF	0.48	0.00	0.00	81.92
144. Cold air return cover - Detach & reset	1.00 EA	0.00	17.64	0.00	17.64
Detach Only 2 cover					
145. Toilet - Detach	1.00 EA	0.00	37.73	0.00	37.73
146. Remove Plumbing fixture supply line	3.00 EA	4.55	0.00	0.00	13.65
147. Tear out non-salv. tile & bag for disposal 021-12-27-1711	80.00 SF	2.12	0.00	0.00 1/13/2022	169.60 Page: 11

Atkins Services, LLC **PuroClean Propery Damage Experts** 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Bathroom 1

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
148. Tear out non-salvageable tile floor & bag - Cat 3 water	26.67 SF	4.22	0.00	0.00	112.55
149. Remove Sink - wall mounted	1.00 EA	34.11	0.00	0.00	34.11
150. Apply anti-microbial agent to the floor	26.67 SF	0.00	0.22	0.00	5.87
151. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Bathroom 1				0.00	972.05



Contacts Room

368.00 SF Walls 494.00 SF Walls & Ceiling 14.00 SY Flooring 46.00 LF Ceil. Perimeter

Height: 8'

126.00 SF Floor 46.00 LF Floor Perimeter

126.00 SF Ceiling


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
152. Tear out baseboard and bag for disposal - up to Cat 3	46.00 LF	0.76	0.00	0.00	34.96
153. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	126.00 SF	1.17	0.00	0.00	147.42
154. Tear out trim and bag for disposal - up to Cat 3	46.00 LF	0.76	0.00	0.00	34.96
155. Tear out wet drywall, cleanup, bag - Cat 3	494.00 SF	1.10	0.00	0.00	543.40
156. Tear out and bag wet insulation - Category 3 water	254.00 SF	0.93	0.00	0.00	236.22
157. Remove Outlet or switch cover	10.00 EA	0.57	0.00	0.00	5.70
158. Clean stud wall	494.00 SF	0.00	0.67	0.00	330.98
159. Cold air return cover - Detach & reset	2.00 EA	0.00	17.64	0.00	35.28
Detach only 4 Covers					
160. General Laborer - per hour	2.00 HR	0.00	34.35	0.00	68.70
Remove 7' sink					
161. Apply anti-microbial agent to the floor	126.00 SF	0.00	0.22	0.00	27.72
162. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
021-12-27-1711				1/13/2022	Page: 12



Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Contacts Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Totals: Contacts Room				0.00	1,602.74



Work Shop

433.33 SF Walls 614.58 SF Walls & Ceiling

20.14 SY Flooring 54.17 LF Ceil. Perimeter Height: 8'

181.25 SF Ceiling 181.25 SF Floor

54.17 LF Floor Perimeter


Rathroom Blook Close					
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
163. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	56.00 SF	1.17	0.00	0.00	65.52
164. Tear out wet drywall, cleanup, bag - Cat 3	181.25 SF	1.10	0.00	0.00	199.38
165. Tear out and bag wet insulation - Category 3 water	293.25 SF	0.93	0.00	0.00	272.72
166. Remove Outlet or switch cover	16.00 EA	0.57	0.00	0.00	9.12
167. Cold air return cover - Detach & reset	1.00 EA	0.00	17.64	0.00	17.64
Detach only 2 Covers					
168. Tear out baseboard and bag for disposal - up to Cat 3	54.17 LF	0.76	0.00	0.00	41.17
169. Tear out trim and bag for disposal - up to Cat 3	54.17 LF	0.76	0.00	0.00	41.17
170. Tear out wet paneling, no bagging - Cat 3	433.33 SF	0.48	0.00	0.00	208.00
171. Cabinet - lower (base) unit - Detach	16.00 LF	0.00	15.43	0.00	246.88
172. Content Manipulation charge - per hour	1.00 HR	0.00	34.35	0.00	34.35
173. Tear out non-salv vinyl, cut & bag - Category 3 water	98.00 SF	1.63	0.00	0.00	159.74
174. Cabinet - upper (wall) unit - Detach	7.00 LF	0.00	13.20	0.00	92.40
175. Remove Shelving - 24" - in place	84.00 LF	0.55	0.00	0.00	46.20
176. General Laborer - per hour	2.00 HR	0.00	34.35	0.00	68.70
Remove 6' Sink					
021-12-27-1711				1/13/2022	Page: 1



Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Work Shop

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
177. Apply anti-microbial agent to the floor	181.25 SF	0.00	0.22	0.00	39.88
178. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Work Shop				0.00	1,680.27



Height: 8' **Paper Room**

> 224.00 SF Walls 269.00 SF Walls & Ceiling 5.00 SY Flooring 28.00 LF Ceil. Perimeter

45.00 SF Ceiling 45.00 SF Floor 28.00 LF Floor Perimeter


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
179. Tear out baseboard and bag for disposal - up to Cat 3	28.00 LF	0.76	0.00	0.00	21.28
180. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
181. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	45.00 SF	1.17	0.00	0.00	52.65
182. Tear out trim and bag for disposal - up to Cat 3	28.00 LF	0.76	0.00	0.00	21.28
183. Tear out wet drywall, cleanup, bag - Cat 3	45.00 SF	1.10	0.00	0.00	49.50
184. Tear out and bag wet insulation - Category 3 water	109.00 SF	0.93	0.00	0.00	101.37
185. Remove Outlet or switch cover	5.00 EA	0.57	0.00	0.00	2.85
186. Clean stud wall	269.00 SF	0.00	0.67	0.00	180.23
187. Tear out wet paneling, no bagging - Cat 3	224.00 SF	0.48	0.00	0.00	107.52
188. Cold air return cover - Detach & reset	0.50 EA	0.00	17.64	0.00	8.82
Detach Only 1 cover					
189. Content Manipulation charge - per hour	1.00 HR	0.00	34.35	0.00	34.35
190. Apply anti-microbial agent to the floor	45.00 SF	0.00	0.22	0.00	9.90
191. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40

1/13/2022 Page: 14 2021-12-27-1711

Atkins Services, LLC **PuroClean Propery Damage Experts** 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Paper Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Totals: Paper Room				0.00	744.20



Boss Office

369.33 SF Walls 502.25 SF Walls & Ceiling

14.77 SY Flooring 46.17 LF Ceil. Perimeter Height: 8'

132.92 SF Ceiling 132.92 SF Floor


46.17 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
192. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	132.92 SF	1.17	0.00	0.00	155.52
193. Tear out wet drywall, cleanup, bag - Cat 3	132.92 SF	1.10	0.00	0.00	146.21
194. Tear out and bag wet insulation - Category 3 water	236.92 SF	0.93	0.00	0.00	220.34
195. Remove Outlet or switch cover	16.00 EA	0.57	0.00	0.00	9.12
196. Cold air return cover - Detach & reset	1.50 EA	0.00	17.64	0.00	26.46
Detach only 3 Covers					
197. Tear out baseboard and bag for disposal - up to Cat 3	46.17 LF	0.76	0.00	0.00	35.09
198. Tear out trim and bag for disposal - up to Cat 3	46.17 LF	0.76	0.00	0.00	35.09
199. Tear out wet paneling, no bagging - Cat 3	369.33 SF	0.48	0.00	0.00	177.28
200. Remove Interior door unit	2.00 EA	17.05	0.00	0.00	34.10
201. Content Manipulation charge - per hour	1.00 HR	0.00	34.35	0.00	34.35
202. General Laborer - per hour	2.00 HR	0.00	34.35	0.00	68.70
Remove 7' Desk					
203. Wood window unit - Detach & reset	0.50 EA	0.00	114.12	0.00	57.06
Detach Only					
204. Apply anti-microbial agent to the floor	132.92 SF	0.00	0.22	0.00	29.24
205. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
				1/12/2022	Dage: 1

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Boss Office

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Totals: Boss Office				0.00	1,165.96



250.67 SF Walls 310.67 SF Walls & Ceiling 6.67 SY Flooring


31.33 LF Ceil. Perimeter

Height: 8' 60.00 SF Ceiling

60.00 SF Floor 31.33 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
206. Tear out baseboard and bag for disposal - up to Cat 3	31.33 LF	0.76	0.00	0.00	23.81
207. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
208. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	60.00 SF	1.17	0.00	0.00	70.20
209. Tear out trim and bag for disposal - up to Cat 3	31.33 LF	0.76	0.00	0.00	23.81
210. Tear out wet drywall, cleanup, bag - Cat 3	60.00 SF	1.10	0.00	0.00	66.00
211. Tear out and bag wet insulation - Category 3 water	92.00 SF	0.93	0.00	0.00	85.56
212. Remove Outlet or switch cover	3.00 EA	0.57	0.00	0.00	1.71
213. Clean stud wall	310.67 SF	0.00	0.67	0.00	208.15
214. Tear out wet paneling, no bagging - Cat 3	250.67 SF	0.48	0.00	0.00	120.32
215. Cold air return cover - Detach & reset	1.00 EA	0.00	17.64	0.00	17.64
Detach Only 2 cover					
216. Remove Breaker panel - 200 amp	3.00 EA	137.85	0.00	0.00	413.55
217. Apply anti-microbial agent to the floor	60.00 SF	0.00	0.22	0.00	13.20
218. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Electric Room				0.00	1,198.40

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848



Patient Room


Height: 8'

277.33 SF Walls 349.67 SF Walls & Ceiling 8.04 SY Flooring 34.67 LF Ceil. Perimeter

72.33 SF Floor 34.67 LF Floor Perimeter

72.33 SF Ceiling

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
219. Tear out baseboard and bag for disposal - up to Cat 3	34.67 LF	0.76	0.00	0.00	26.35
220. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	72.33 SF	1.17	0.00	0.00	84.63
221. Tear out trim and bag for disposal - up to Cat 3	34.67 LF	0.76	0.00	0.00	26.35
222. Tear out wet drywall, cleanup, bag - Cat 3	72.33 SF	1.10	0.00	0.00	79.56
223. Tear out and bag wet insulation - Category 3 water	184.33 SF	0.93	0.00	0.00	171.43
224. Remove Outlet or switch cover	8.00 EA	0.57	0.00	0.00	4.56
225. Clean stud wall	349.67 SF	0.00	0.67	0.00	234.28
226. Tear out wet paneling, no bagging - Cat 3	277.33 SF	0.48	0.00	0.00	133.12
227. Cold air return cover - Detach & reset	0.50 EA	0.00	17.64	0.00	8.82
228. Apply anti-microbial agent to the floor	72.33 SF	0.00	0.22	0.00	15.91
229. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Patient Room				0.00	922.41



Exam Room 2

Height: 8'

389.33 SF Walls 532.67 SF Walls & Ceiling 15.93 SY Flooring 48.67 LF Ceil. Perimeter


143.33 SF Ceiling 143.33 SF Floor 48.67 LF Floor Perimeter

TAX **TOTAL** REPLACE **REMOVE QTY** DESCRIPTION

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Exam Room 2

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
230. Tear out baseboard and bag for disposal - up to Cat 3	48.67 LF	0.76	0.00	0.00	36.99
231. Remove Soap/hand sanitizer dispenser - wall mounted	1.00 EA	6.81	0.00	0.00	6.81
232. Remove Paper towel dispenser	1.00 EA	13.65	0.00	0.00	13.65
233. Content Manipulation charge - per hour	1.00 HR	0.00	34.35	0.00	34.35
234. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
235. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	143.33 SF	1.17	0.00	0.00	167.70
236. Tear out trim and bag for disposal - up to Cat 3	48.67 LF	0.76	0.00	0.00	36.99
237. Tear out wet drywall, cleanup, bag - Cat 3	143.33 SF	1.10	0.00	0.00	157.66
238. Tear out and bag wet insulation - Category 3 water	255.33 SF	0.93	0.00	0.00	237.46
239. Remove Outlet or switch cover	10.00 EA	0.57	0.00	0.00	5.70
240. Clean stud wall	532.67 SF	0.00	0.67	0.00	356.89
241. Tear out wet paneling, no bagging - Cat 3	389.33 SF	0.48	0.00	0.00	186.88
242. Cold air return cover - Detach & reset	0.50 EA	0.00	17.64	0.00	8.82
Detach Only 1 cover					
243. Apply anti-microbial agent to the floor	143.33 SF	0.00	0.22	0.00	31.53
244. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Exam Room 2				0.00	1,435.8



Exam Room 1

368.00 SF Walls 494.00 SF Walls & Ceiling 14.00 SY Flooring

46.00 LF Ceil. Perimeter

126.00 SF Ceiling 126.00 SF Floor 46.00 LF Floor Perimeter

REPLACE TAX **TOTAL** REMOVE QTY DESCRIPTION


> 1/13/2022 Page: 18

Height: 8'

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Exam Room 1

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
245. Tear out baseboard and bag for disposal - up to Cat 3	46.00 LF	0.76	0.00	0.00	34.96
246. Remove Soap/hand sanitizer dispenser - wall mounted	1.00 EA	6.81	0.00	0.00	6.81
247. Remove Paper towel dispenser	1.00 EA	13.65	0.00	0.00	13.65
248. Content Manipulation charge - per hour	1.00 HR	0.00	34.35	0.00	34.35
249. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
250. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	126.00 SF	1.17	0.00	0.00	147.42
251. Tear out trim and bag for disposal - up to Cat 3	46.00 LF	0.76	0.00	0.00	34.96
252. Tear out wet drywall, cleanup, bag - Cat 3	126.00 SF	1.10	0.00	0.00	138.60
253. Tear out and bag wet insulation - Category 3 water	310.00 SF	0.93	0.00	0.00	288.30
254. Cold air return cover - Detach & reset	0.50 EA	0.00	17.64	0.00	8.82
Detach only 1 cover					
255. Remove Outlet or switch cover	14.00 EA	0.57	0.00	0.00	7.98
256. Clean stud wall	494.00 SF	0.00	0.67	0.00	330.98
257. Tear out wet paneling, no bagging - Cat 3	368.00 SF	0.48	0.00	0.00	176.64
258. Apply anti-microbial agent to the floor	126.00 SF	0.00	0.22	0.00	27.72
259. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Exam Room 1				0.00	1,405.64



560.00 SF Walls 794.00 SF Walls & Ceiling 26.00 SY Flooring 70.00 LF Ceil. Perimeter

234.00 SF Ceiling 234.00 SF Floor 70.00 LF Floor Perimeter

DESCRIPTION	OTY	REMOVE	REPLACE	TAX	TOTAL
DEBCIGITION	•				


Height: 8'

PuroClean Property Damage Experts

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Library

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
260. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	234.00 SF	1.17	0.00	0.00	273.78
261. Tear out wet drywall, cleanup, bag - Cat 3	234.00 SF	1.10	0.00	0.00	257.40
262. Tear out and bag wet insulation - Category 3 water	434.00 SF	0.93	0.00	0.00	403.62
263. Remove Outlet or switch cover	22.00 EA	0.57	0.00	0.00	12.54
264. Cold air return cover - Detach & reset	1.00 EA	0.00	17.64	0.00	17.64
Detach only 2 Covers					
265. Tear out baseboard and bag for disposal - up to Cat 3	70.00 LF	0.76	0.00	0.00	53.20
266. Tear out trim and bag for disposal - up to Cat 3	70.00 LF	0.76	0.00	0.00	53.20
267. Tear out wet paneling, no bagging - Cat 3	560.00 SF	0.48	0.00	0.00	268.80
268. Remove Interior door unit	2.00 EA	17.05	0.00	0.00	34.10
269. Content Manipulation charge - per hour	2.00 HR	0.00	34.35	0.00	68.70
270. Apply anti-microbial agent to the floor	234.00 SF	0.00	0.22	0.00	51.48
271. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Library				0.00	1,631.86



Laboratory Room

352.00 SF Walls 469.00 SF Walls & Ceiling 13.00 SY Flooring 44.00 LF Ceil. Perimeter

Height: 8'

117.00 SF Ceiling 117.00 SF Floor 44.00 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
272. Content Manipulation charge - per hour	5.00 HR	0.00	34.35	0.00	171.75
273. Apply anti-microbial agent to the floor	117.00 SF	0.00	0.22	0.00	25.74
274. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
021-12-27-1711				1/13/2022	Page: 20

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Laboratory Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Totals: Laboratory Room				0.00	334.89

Side hallway

Height: 8'

TOTAL

Page: 21

1/13/2022



2021-12-27-1711

476.00 SF Walls 587.33 SF Walls & Ceiling 12.37 SY Flooring 59.50 LF Ceil. Perimeter

111.33 SF Ceiling 111.33 SF Floor

59.50 LF Floor Perimeter

Missing Wall Missing Wall	4' X 8 4' X 8		Opens into FR Opens into BA	CK_HALL
DESCRIPTION	QTY	REMOVE	REPLACE	TAX
275. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	111.33 SF	1.17	0.00	0.00
276. Tear out wet drywall, cleanup,	111.33 SF	1.10	0.00	0.00

275. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	111.33 SF	1.17	0.00	0.00	130.26
276. Tear out wet drywall, cleanup, bag - Cat 3	111.33 SF	1.10	0.00	0.00	122.46
277. Tear out and bag wet insulation - Category 3 water	111.33 SF	0.93	0.00	0.00	103.54
278. Remove Outlet or switch cover	6.00 EA	0.57	0.00	0.00	3.42
279. Cold air return cover - Detach & reset	0.50 EA	0.00	17.64	0.00	8.82
Detach only 1 Covers					
280. Tear out baseboard and bag for disposal - up to Cat 3	59.50 LF	0.76	0.00	0.00	45.22
281. Tear out trim and bag for disposal - up to Cat 3	59.50 LF	0.76	0.00	0.00	45.22
282. Tear out wet paneling, no bagging - Cat 3	476.00 SF	0.48	0.00	0.00	228.48
283. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
284. Smoke detector - Detach & reset	0.50 EA	0.00	43.15	0.00	21.58
Detach Only					
285. Light fixture - Detach & reset	0.50 EA	0.00	44.56	0.00	22.28
286. Thermostat - Detach & reset	0.50 EA	0.00	43.19	0.00	21.60
detach Only					
287. Cabinet - upper (wall) unit - Detach	14.00 LF	0.00	13.20	0.00	184.80

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Side hallway

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
288. Cabinet - lower (base) unit - Detach	9.00 LF	0.00	15.43	0.00	138.87
289. Apply anti-microbial agent to the floor	111.33 SF	0.00	0.22	0.00	24.49
290. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Side hallway				0.00	1,255.49

Front Hallway

Height: 8'

889.33 SF Walls 1,110.67 SF Walls & Ceiling 24.59 SY Flooring 111.17 LF Ceil. Perimeter

221.33 SF Ceiling 221.33 SF Floor

111.17 LF Floor Perimeter

Missing Wall Missing Wall 4' X 8' 4' X 8' Opens into GLASSES_ROOM Opens into SIDE_HALLWAY


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
291. Tear out baseboard and bag for disposal - up to Cat 3	111.17 LF	0.76	0.00	0.00	84.49
292. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	221.33 SF	1.17	0.00	0.00	258.96
293. Tear out trim and bag for disposal - up to Cat 3	111.17 LF	0.76	0.00	0.00	84.49
294. Tear out wet drywall, cleanup, bag - Cat 3	221.33 SF	1.10	0.00	0.00	243.46
295. Tear out and bag wet insulation - Category 3 water	221.33 SF	0.93	0.00	0.00	205.84
296. Remove Outlet or switch cover	9.00 EA	0.57	0.00	0.00	5.13
297. Clean stud wall	1,110.67 SF	0.00	0.67	0.00	744.15
298. Tear out wet paneling, no bagging - Cat 3	889.33 SF	0.48	0.00	0.00	426.88
299. Cold air return cover - Detach & reset	1.00 EA	0.00	17.64	0.00	17.64
Detach only 2 Covers					
300. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
301. Apply anti-microbial agent to the floor	221.33 SF	0.00	0.22	0.00	48.69
021-12-27-1711				1/13/2022	Page: 22

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

Break Room

CONTINUED - Front Hallway

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
302. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Front Hallway				0.00	2,274.18



288.00 SF Walls 369.00 SF Walls & Ceiling

9.00 SY Flooring 36.00 LF Ceil. Perimeter Height: 8'

81.00 SF Ceiling 81.00 SF Floor 36.00 LF Floor Perimeter

TAX **TOTAL** REPLACE DESCRIPTION QTY **REMOVE** 94.77 0.00 0.00 303. Tear out wet non-salv. gluedn. 81.00 SF 1.17 cpt, cut/bag - Cat 3 water 89.10 0.00 0.00 81.00 SF 1.10 304. Tear out wet drywall, cleanup, bag - Cat 3 142.29 0.00 153.00 SF 0.93 0.00 305. Tear out and bag wet insulation -Category 3 water 0.00 4.56 0.57 0.00 306. Remove Outlet or switch cover 8.00 EA 17.64 0.00 17.64 0.00 307. Cold air return cover - Detach & 1.00 EA reset Detach only 2 Covers 27.36 0.00 0.00 36.00 LF 0.76 308. Tear out baseboard and bag for disposal - up to Cat 3 27.36 0.00 0.00 36.00 LF 0.76 309. Tear out trim and bag for disposal - up to Cat 3 0.00 138.24 0.00 288.00 SF 0.48 310. Tear out wet paneling, no bagging - Cat 3 0.00 17.05 0.00 17.05 1.00 EA 311. Remove Interior door unit 275.70 0.00 0.00 137.85 312. Remove Breaker panel - 200 amp 2.00 EA 0.00 17.82 0.22 313. Apply anti-microbial agent to the 0.00 81.00 SF floor 0.00 137.40 0.00 34.35 4.00 HR 314. Content Manipulation charge per hour 0.00 989.29 Totals: Break Room

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848



Back Hall

Height: 8'

340.00 SF Walls 416.67 SF Walls & Ceiling 8.52 SY Flooring 42.50 LF Ceil. Perimeter

76.67 SF Floor 42.50 LF Floor Perimeter

76.67 SF Ceiling

Missing Wall

4' X 8'

Opens into SIDE_HALLWAY

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
315. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	76.67 SF	1.17	0.00	0.00	89.70
316. Tear out wet drywall, cleanup, bag - Cat 3	76.67 SF	1.10	0.00	0.00	84.34
317. Tear out and bag wet insulation - Category 3 water	76.67 SF	0.93	0.00	0.00	71.30
318. Remove Outlet or switch cover	2.00 EA	0.57	0.00	0.00	1.14
319. Tear out baseboard and bag for disposal - up to Cat 3	42.50 LF	0.76	0.00	0.00	32.30
320. Tear out trim and bag for disposal - up to Cat 3	42.50 LF	0.76	0.00	0.00	32.30
321. Apply anti-microbial agent to the floor	76.67 SF	0.00	0.22	0.00	16.87
322. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Back Hall				0.00	465.35

Totals: Back Hall



Utility Room

Height: 8'

256.00 SF Walls 319.00 SF Walls & Ceiling 7.00 SY Flooring 32.00 LF Ceil. Perimeter


63.00 SF Ceiling 63.00 SF Floor 32.00 LF Floor Perimeter

II II DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
323. Tear out and bag wet insulation - Category 3 water	319.00 SF	0.93	0.00	0.00	296.67
324. Apply anti-microbial agent to the floor	63.00 SF	0.00	0.22	0.00	13.86
325. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
021-12-27-1711				1/13/2022	Page: 24

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Utility Room

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
				, 	
Totals: Utility Room				0.00	447.93



Bathroom 2

266.67 SF Walls 333.33 SF Walls & Ceiling 7.41 SY Flooring 33.33 LF Ceil. Perimeter

Height: 8' 66.67 SF Ceiling

66.67 SF Floor 33.33 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
326. Tear out baseboard and bag for disposal - up to Cat 3	33.33 LF	0.76	0.00	0.00	25.33
327. Remove Soap/hand sanitizer dispenser - wall mounted	1.00 EA	6.81	0.00	0.00	6.81
328. Remove Paper towel dispenser	1.00 EA	13.65	0.00	0.00	13.65
329. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
330. Tear out trim and bag for disposal - up to Cat 3	33.33 LF	0.76	0.00	0.00	25.33
331. Tear out wet drywall, cleanup, bag - Cat 3	66.67 SF	1.10	0.00	0.00	73.34
332. Tear out and bag wet insulation - Category 3 water	138.67 SF	0.93	0.00	0.00	128.96
333. Handicap grab bar - Detach & reset	0.50 EA	0.00	28.73	0.00	14.37
334. Remove Outlet or switch cover	2.00 EA	0.57	0.00	0.00	1.14
335. Clean stud wall	333.33 SF	0.00	0.67	0.00	223.33
336. Tear out wet paneling, no bagging - Cat 3	266.67 SF	0.48	0.00	0.00	128.00
337. Cold air return cover - Detach & reset	1.00 EA	0.00	17.64	0.00	17.64
Detach Only 2 cover					
338. Toilet - Detach	1.00 EA	0.00	37.73	0.00	37.73
339. Remove Plumbing fixture supply line	3.00 EA	4.55	0.00	0.00	13.65
340. Tear out non-salv. tile & bag for disposal	72.00 SF	2.12	0.00	0.00	152.64
341. Tear out non-salvageable tile	66.67 SF	4.22	0.00	0.00	281.35
floor & bag - Cat 3 water 021-12-27-1711				1/13/2022	Page: 25



Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

Closet

CONTINUED - Bathroom 2

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
342. Remove Sink - wall mounted	1.00 EA	34.11	0.00	0.00	34.11
343. Bathroom mirror - Detach & reset	15.00 SF	0.00	7.99	0.00	119.85
344. Apply anti-microbial agent to the floor	66.67 SF	0.00	0.22	0.00	14.67
345. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: Bathroom 2				0.00	1,466.35

144.00 SF Walls 162.00 SF Walls & Ceiling 2.00 SY Flooring 18.00 LF Ceil. Perimeter

18.00 SF Ceiling 18.00 SF Floor 18.00 LF Floor Perimeter

Height: 8'

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
346. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	18.00 SF	1.17	0.00	0.00	21.06
347. Tear out wet drywall, cleanup, bag - Cat 3	18.00 SF	1.10	0.00	0.00	19.80
348. Tear out and bag wet insulation - Category 3 water	18.00 SF	0.93	0.00	0.00	16.74
349. Cold air return cover - Detach & reset	1.00 EA	0.00	17.64	0.00	17.64
Detach only 2 Covers					
350. Tear out baseboard and bag for disposal - up to Cat 3	18.00 LF	0.76	0.00	0.00	13.68
351. Tear out trim and bag for disposal - up to Cat 3	18.00 LF	0.76	0.00	0.00	13.68
352. Tear out wet paneling, no bagging - Cat 3	144.00 SF	0.48	0.00	0.00	69.12
353. Remove Interior door unit	1.00 EA	17.05	0.00	0.00	17.05
354. Remove Shelving - 24" - in place	10.00 LF	0.55	0.00	0.00	5.50
355. Apply anti-microbial agent to the floor	18.00 SF	0.00	0.22	0.00	3.96
356. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40


1/13/2022 Page: 26 2021-12-27-1711



Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

CONTINUED - Closet

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Totals: Closet				0.00	335.63



File Room

560.00 SF Walls 789.44 SF Walls & Ceiling 25.49 SY Flooring 70.00 LF Ceil. Perimeter

Height: 8' 229.44 SF Ceiling

229.44 SF Floor 70.00 LF Floor Perimeter

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
357. Tear out wet non-salv. gluedn. cpt, cut/bag - Cat 3 water	229.44 SF	1.17	0.00	0.00	268.44
358. Tear out wet drywall, cleanup, bag - Cat 3	229.44 SF	1.10	0.00	0.00	252.38
359. Tear out and bag wet insulation - Category 3 water	229.44 SF	0.93	0.00	0.00	213.38
360. Remove Outlet or switch cover	13.00 EA	0.57	0.00	0.00	7.41
361. Cold air return cover - Detach & reset	2.00 EA	0.00	17.64	0.00	35.28
Detach only 4 Covers					
362. Remove Interior door unit	2.00 EA	17.05	0.00	0.00	34.10
363. Tear out baseboard and bag for disposal - up to Cat 3	70.00 LF	0.76	0.00	0.00	53.20
364. Tear out trim and bag for disposal - up to Cat 3	70.00 LF	0.76	0.00	0.00	53.20
365. Content Manipulation charge - per hour	3.00 HR	0.00	34.35	0.00	103.05
366. Apply anti-microbial agent to the floor	229.44 SF	0.00	0.22	0.00	50.48
367. Content Manipulation charge - per hour	4.00 HR	0.00	34.35	0.00	137.40
Totals: File Room				0.00	1,208.32
Total: Main Level				0.00	113,489.75
Line Item Totals: 2021-12-27-1711			-	0.00	113,489.75

1/13/2022 Page: 27 2021-12-27-1711

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

Grand Total Areas:

9,696.00 3,149.11	SF Walls SF Floor	=	SF Ceiling SY Flooring	•	SF Walls and Ceiling LF Floor Perimeter
-	SF Long Wall		SF Short Wall	•	LF Ceil. Perimeter
3,149.11	Floor Area	3,413.36	Total Area	9,696.00	Interior Wall Area
3,223.50	Exterior Wall Area	358.17	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		

Coverage	Item Total	%	ACV Total	<u>%</u>
Dwelling	56,054.78	49.39%	56,054.78	49.39%
Other Structures	0.00	0.00%	0.00	0.00%
Contents	57,434.97	50.61%	57,434.97	50.61%
Total	113,489.75	100.00%	113,489.75	100.00%

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

Summary for Dwelling

	Summary for Dweiling	
Line Item Total		56,054.78
Replacement Cost Value		\$56,054.78
Net Claim		\$56,054.78
	Eli Dykes	


PuroClean Atkins Services, LLC/PuroClean Property Damage Experts

Atkins Services, LLC PuroClean Propery Damage Experts 2405 Buchanan Rd SE Cleveland, TN 37323 (423) 790-3500 Tax ID# 46-5652848

Summary for Contents

	Summary for Contents	
Line Item Total		57,434.97
Replacement Cost Value		\$57,434.97
Net Claim		\$57,434.97
	Eli Dykes	

≅ (>





Ben Perry, MBA

Coastal Claims Services, Inc.

2650 N. Dixie Freeway, New Smyrna Beach, FL 32168

Office (386) 314-0074 Cell (229) 560-2713 Fax (386) 961-4344 Email benp@coastalclaims.net

Current Role

Owner / Director of Appraisal Division Coastal Claims Services, Inc

Previous Relevant Experience

Real Estate Agent Florida Homes Realty & Mortgage

Commercial Real Estate Development Analyst Ambling University Development Group

Construction Quality Control Manager - Commercial Projects Ambling Construction Company

Guess & Lovell Surveying and Mapping / Lovell Engineering Associates Land Surveyor

Active Licenses

FL Public Adjuster: W204249 FL Home Inspector: HI12763 IA Public Adjuster: 17333367 IN Public Adjuster: 3681782 SC Public Adjuster: 17333367 WI Public Adjuster: 17333367

Active Certifications / Designations

InterNACHI Certified Professional Inspector
InterNACHI - Owens Corning - Lowes Roof Technician
Claims Adjuster Certified Professional
Xactware Xactimate Certified Level 2

Active Memberships

InterNACHI - International Association of Home Inspectors
AIA - American Institute of Architects
ICC - International Code Council
WIND - Windstorm Insurance Network

Andrew J. Fraraccio

570 New Waverly Place, Suite 220, Cary, NC 27518 Tel: 919.345.0548 / Fax: 866.369.1755 / email: andvf@intrustclaims.com

Property Loss Consulting / Appraiser / Umpire / Loss of Business Income

Profile:

Mr. Fraraccio carries 28 years of experience as independent insurance appraiser, umpire, adjuster, and property loss/business interruption consultant. Mr. Fraraccio also provides a diverse range of constructionrelated services with expertise in restoration and reconstruction of existing custom-built real property, and personal property. Mr. Fraraccio has served as an expert appraiser and umpire in hundreds of loss disputes nationally on behalf of individuals, insurers, and business-owners. He is responsible for Calculating Loss of Business Income, Project Management, Cost-Estimating, Scope Development, Damage Evaluations, Building Code-Compliance, Appraisal-Umpire Appointment, and Litigation Expertise. Among numerous selected achievements, Mr. Fraraccio served as umpire and appraiser for hundreds of large losses nationally, for commercial and residential structures, and contents. In addition, he settled several thousand business interruption losses and disputes throughout the United States, spanning 3 decades.

Additional Selected Achievements

Mr. Fraraccio developed and presented lectures and educational seminars to insurance carriers, law firms, and associations regarding property loss dispute resolution, appraisal, and arbitration. These educational seminars involve extensive research including state statutes and case laws, nationally. He is a nationallyrecognized expert in litigated insurance claim disputes. He was also retained as an expert to settle scores of flood litigation claims for the NFIP and Write-Your-Own (WYO) insurance carriers.

Mr. Fraraccio has set industry standards in estimating software through research and Development of Digital Documentation Systems; also known as MS/B estimating system. He also set industry standards in the formatting and language used in captioned reports throughout the industry. He founded and principally operates Intrust Claim Servicing, Inc., a nationally-recognized dispute resolution and loss consulting firm.

Education:

Electronics Technology Degree: (3.84/4.0 G.P.A.): United Electronics Institute, Tampa, FL (1986) University of South Florida: Business Management Courses (1986-1990)

St. Petersburg Jr. College: Business Management Courses (1991-1992)

Manatee Jr. College: Business Management Courses, Technical-Writing, Physics 1-3, CAD and other engineering-related courses (1982-1983, 1988-1990)

Mr. Fraraccio's education and career experience also include Insurance Law, Electronic Engineering, and Research and Development.

Licenses/Certifications: Umpire Certification - FL WIND Network

Appraiser Certification - FL WIND Network

Independent Adjuster License, State of North Carolina (License #NPN 1290237)

Independent Adjuster License, State of Florida Independent Adjuster License, State of Texas Independent Adjuster License, State of Alabama Independent Adjuster License, State of Georgia Independent Adjuster License, State of Louisana Independent Adjuster License, State of Mississippi

IICRC WRT Certification / IICRC Fire and Smoke Restoration Certification

State Farm Flood Certification

Former Member of National Association of Independent Insurance Adjusters (NAIIA)

FEMA (DHS) Contractor Certification (Badge Number 7608306526)

National Flood Insurance Program (NFIP) Large Commercial Certification (FCN 06010133)

Experience:

3/2001 to Present: Intrust Claim Servicing, Inc. (ICS, Inc.)

CEO/Umpire/Appraiser

Responsible for handling everyday operations and management of this national loss consulting, independent appraisal and umpire services firm. These responsibilities include consulting and settling multi-million dollar large loss disputes, hiring appraisers and umpires, training of management, field adjusters, case managers, software implementation and website management. Estimation for commercial and residential property damages resultant from these perils: water, fire/smoke, wind, mold, flood, vandalism, collapse, earth quake, and construction defects.

10/2011 - Present: Advanced Adjusting, LTD.

General Adjuster/Consultant

Handled hundreds of large-loss flood claims for the NFIP and WYO carriers. Also, led the litigation team, handling and managing dozens of flood claims in litigation. Provided detailed protocols for, and settled many complex large losses for the company. Produced detailed scopes, exhibited estimating skills, produced presentations in negotiations with Attorneys and Public Adjusters for successful loss settlements.

1/2007 to 12/2019: Insurance Claims Group, Inc.

Consultant: Appraiser/Umpire

Provided detailed protocols for settling many large losses for the company. Also settled many large losses in the capacity of appraiser. Detailed scope, estimating skills, presentation and negotiation to appraisers and appraisal-umpires in successful loss settlements. Provided these services to insurance carriers, individuals, and business-owners.

5/2010 - 3/2011: Worley Catastrophe

Consultant: Large Loss/Business Interruption

BP Oil Spill: Advised and handled tens of thousands of large loss commercial Business Interruption claims throughout the Gulf of Mexico states (Texas, Louisiana, Mississippi, Alabama and Florida). Also supervised claims examiners and managed as liaison for several Florida panhandle offices.

5/1993 to 3/2001: Self-employed Independent Insurance Adjuster

During this 9 year period, Mr. Fraraccio worked as a daily claims adjuster and a catastrophe adjuster with an impeccable record for the following companies:

Claim Adjustment Specialists, Inc., Global Claim Services, Inc., Catastrophe Specialists, Inc., B & H Claims Service, IMS Catastrophe Adjusters, Pilot Catastrophe Services, Inc., National Catastrophe Adjusters, Inc. (NCA), T.M. Mayfield & Co., Catastrophe Insurance Adjusters, Reid, Jones, McRorie & Williams, United Gates and Pylant, N&C Claims, Inc., Equity Claims, Inc., Resource Services, Inc., Worley Catastrophe Response, Insurance Claims Group, Inc.

Mr. Fraraccio's professional experience with the above-listed companies covers claims concerning liability, appraisal losses, flood, hurricane, wind/hail, earthquake, freeze, and all other perils common throughout the continental United States.

Estimating Software: Xactimate / National Cost Estimator / Marshall & Swift / Simsol / Blue Book International

Benevolence: Mr. Fraraccio consistently volunteers his time and donates financial resources both

locally and globally through various missions, helping the less fortunate improve their

quality of life.



Curriculum Vitae

My involvement in family owned, small businesses began at a young age. I began working in the building trades at the age of fifteen. I became involved in large scale, historic renovations at the age of twenty as a "working" jobsite foreman. From age twenty through twenty-five, I became proficient at physically performing all of the building trades. This eventually led to a partnership in a fledgling real estate development firm. I became involved with the insurance industry seemingly by accident. I was assisting a storm restoration company on an insurance adjustment where in which Donan Engineering was involved. Soon after I spent the following two years performing ladder assists/consulting for Donan Engineering (while simultaneously acting as a Field Supervisor for a storm restoration company). This began what has become my entire career focus. While I still am engaged in real estate investments, my primary focus over the last (12) years has overwhelmingly been in the insurance industry. I have been fortunate enough to study under some of this industry's brightest minds (on both sides of the proverbial fence). The experience I have gained from working under RRCs, RROs, PEs, Attorneys and private business owners is what has allowed me to become proficient at settling large losses. There is still much that I have to learn, but I have been involved in hundreds of large commercial projects.

I am licensed as a Public Adjuster, but I do not utilize my licensing in the majority of cases I am involved in. I consider myself to be an extremely fair and reasonable individual. Most of my professional peers (on both sides) would tell you that I am both respectful and fair. Since 2013, the overwhelming majority of the claims I have adjusted, were settled without the aid of the Courts. I try my best to always maintain an unmatched work ethic, a tremendous sense of fair play, and am always willing to widen my professional knowledge from those who are more experienced. Above all else, I believe that if opposing parties meet on the common ground of good faith, any disagreement can be reconciled.

Currently, approximately 50% of my workload is processed via Appraisal. I find the "Alternative Dispute Resolution" process to be a more proficient way to handle losses because both interested parties are removed from the process. Additionally, I appear on the "Umpire List" of a number Independent Adjusters. I thoroughly support every position in each Appraisal and Adjustment. Even as someone who has spent most of my career representing the consumer, I believe that unnecessarily high estimates/awards lead to damaging the entire system (thus the consumer will inevitably suffer those consequences).

Education

2002-2003 Lincoln College

2003-2004 College of Dupage

Professional Experience

1998-2000 RJB Design

-General laborer

2000-2005 Gaynors Inc/Mr. Scotts LLC

-Assistant Management/Jack of all trades for different family businesses. Work responsibilities consisted of labor, restaurant/bar management, customer relations, small scale renovations of rental properties.

2005-2007 <u>JMZ/JFMB Properties</u>

-Job site floater on all active builds. Regularly performed roofing, carpentry, electrical, plumbing and demolition work.

-Rental Property Site Technician. I serviced more than 200 rental units in historic buildings that had not yet been renovated.

2007-2014 Urban Equity Properties

-Partner/Site Foreman. We focused on large scale, complete renovations of historic preservation properties, while also converting them to modern mixed-use developments. UEP is still a commanding presence in the Real Estate development markets of the Midwest.

2009-2011 Rockton City Council

-Councilman for the City of Rockton, IL

2010-2012 <u>Donan Engineering</u>

-Sub-contracted Consultant/Ladder Assist under Chris Hayes SE of Donan Engineering

2010-2013 <u>Hytek Exteriors/GC</u>

-Field Supervisor. Eventually became the Sales Manager and was the top grossing commercial salesman companywide from 2011-2013.

2013-Current Spartan Public Adjustments LLC

-Owner/Primary Adjuster. Spartan PA is a Public Adjusting firm with a focus on the complex (and often large) insurance claims that other firms would release (or that would otherwise result in a lengthy legal battle). www.SpartanPA.com

2014-Current The Heracles Group LLC

-Owner. The Heracles Group is a Real Estate development and management company with a focus on affordable, historic housing, with tenant service that is unmatched.

2017-Current The David Group LLC

-Claims Consultant. The David Group focuses primarily on claims consulting and all forms of alternative dispute resolution within the insurance restoration industry. We also offer our clients training in ethics, sales and logistical services within the industry. www.TDGroup.us

Additional Points of Recognition

- -I am a P.L.A.N. Certified Appraiser and Umpire
- I have been involved in hundreds of commercial projects to date.
- I have been involved in projects/claims with a total cost in excess of 12M.
- I take a "hands on" approach to every file. I conduct my own destructive testing and produce detailed property analysis reports (and estimates) for many of my customers.
- I have upset people at times with my practical approach to public adjusting. There have been several occasions where I have talked commercial clients out of filing insurance claims when they clearly have been misguided by an outside influence. I believe that this industry has been become needlessly adversarial (on both sides). Unfortunately, it is the consumer who often suffers as a result.
- I have completed both the level 1 and level 2 Xactimate training. I am proficient at writing both residential and commercial property adjustment/Appraisal estimates.
- I have been a part of as many as (60) Appraisals in a calendar year.
- I have been certified in Lead removal in the State of Illinois
- I have been certified in Asbestos removal in the State of Illinois
- I have been licensed to practice as a Public Adjuster in (12) states.
- I have been licensed (and am proficient) in nearly all of the building trades.
- I have completed to date (3) Certified Commercial Roofing Manufacturer Courses.
- -I have worked directly with (3) different State Historic Preservation boards on large projects.
- Spartan Public Adjustments LLC/ Zachary M Baker to date has had zero disciplinary action taken against it from any of the Department of Insurances/Attorney General Offices in any of the states where we have been licensed.
- I am technologically "savvy". I can efficiently utilize all Windows related programs. I have also built several desktop computers.

Professional References

-Attorney Raymond J Melton has been successfully representing clients in and out of the courtroom for more than 20 years; he has tried more than 60 cases to jury verdict. Ray handles matters involving civil litigation including real estate, corporate litigation, real estate transactions and defends insurance carriers in. He regularly handles large, complex, multi-million-dollar transactions on behalf of his clients. Attorney Melton can attest to my ability, moral compass, and depth of industry related knowledge. We have work opposite of each other and now regularly work together on large loss cases. Attorney Melton is a Partner at the Chicago based Law Firm of Smith Amundsen. Point of Contact: Mr. Ray Melton (Partner) (312) 350-8740

-Urban Equity Properties is a large real estate development firm that Spartan PA has done work for a number of times over the years. We have successfully negotiated several, millions of dollars' worth of claims for them.

Point of Contact: Mr. Justin Fern (Founding Principal) (815)505-5178

-Pivotal Recruiting is one of the largest recruiting service providers for the storm restoration industry. We have worked closely with some of the same clients for years. The owner has referred me to several clients of his and has witnessed the proficiency of my work at both firms.

Point of Contact: Matthew Snow (Owner) (773) 991-9975

-Hytek General Contracting is a commercial and residential roofing firm with offices in Chicago, Detroit, and Rockford, IL. We have successfully negotiated Insurance settlements for their customers (and their affiliated companies) consistently for the last few years. They continue to be a valued customer of ours.

Point of Contact: Mr. Joshua Wilson (630)776-3945

-RAC Adjustments, Inc. provides a comprehensive range of services including commercial and residential property adjusting, workers' compensation, vehicle appraising, catastrophe adjusting, special investigations, telephone adjusting, and third-party administration. I have been on the opposing end of adjustments opposite of their owner on several claims. He will attest to my character and ability as a Public Adjuster.

Point of Contact: Mr. Darrell S. Roum (Owner) (815)967-3201

-TNT Property Group is a large real estate development and management firm. Over the course of (5) years, we successfully obtained funding for complete replacements on every property they both owned and managed. Many of their developments are large multifamily properties (200+ unit properties) and large-scale commercial properties. As a result of our long standing, successful relationship, Mr. Tarandy had our firm do extensive work for his extended professional network.

Point of Contact: Mr. Mike Tarandy (Majority Owner) (773)671-3758

-McDermaid Roofing & Insulating Co.is the oldest commercial/union roofer in the City of Rockford, IL (and one of the largest in the State of Illinois). I have helped several of their large clients with clams related issues and have had a relationship with the company for more than (10) years.

Point of Contact: Paul Naretta (Owner) (815) 222-0074

-Kaney Aerospace is both an aerospace corporation/contractor and a property holdings firm that is still currently a customer of ours. They have several Industrial and Commercial properties (many of them in high security settings as a result of the airport and their dealings as an aerospace manufacturer). I have secured to date over (2) million in Insurance settlements for them (and have additional settlements of potentially 1.2M pending as a result of storms that occurred in 2020).

Point of Contact: Mr. Greg Steele (Property Agent/Manager) (815)978-5369

- -Windsor West Townhomes is a large condominium/townhome development of more than (90) 3-4 bedroom townhomes. They initially received compensation of approximately \$22k from their Insurance Carrier after a large storm. We were retained and secured an (approximate) additional \$950k for them. Point of Contact: Mr. Jon Pantano (Former President) (630)639-6592
- -Meiborg Brothers Inc is a trucking and logistics firm headquartered in the Midwest. They are a current customer of ours, and I have successfully negotiated large property loss settlements for them several times in the past as well.

Point of Contact: Mr. Zach Meiborg (President/CEO) (779)210-3867

-TNG Contractors INC is a Commercial and Industrial builder headquartered in Nashville, TN. They have built many of the new hotels and gas stations in the Middle Tennessee area. We continue to work with them and all of their affiliated companies (and customers) on a regular basis. We have also negotiated large property settlements on Commercial properties owned by the Principal.

Point of Contact: Mr. Akbar Arab (Owner) (615)394-4196

-Summit Exteriors is a residential/commercial roofing company based in Illinois. Their owner is a former Independent Adjuster and Xactimate educator. I have resolved several large loss files with him over the past (10) years.

Point of Contact: Joshua Jacobson (Owner) (815) 847-8850

*Further references are available upon request. Some of our other large clients are listed below: VishioForry PLLC, Safe Harbor Public Adjusters, NRG Restore, Attorney Scott Green, Kevin Patel, Blackhawk Motors, Shanahowe Transportation, Stenstrom Companies Ltd, Reg Ellen Machine Tool Corp, Victory Sports Complex, Ayushi Inc, First Baptist Church of Missouri, Abidon Inc Properties, McClenny, Moseley & Associates, Dr. Carl Patrnchak and Associates, Comprehensive Community Solutions, Villa Vista Condominiums, Dowling Investments North LLC, Fratelli Investments LLC, Gaynor's Restaurants Group, The Hard Corporation Inc, Howard Johnson Hotels, Kramer Photographers, Golden Markets LLC, TriView Property Management LLC, Victory Church.

MARY JO O'NEAL, Sr. GA Adjuster P.L.A.N. Certified Appraiser & Umpire, NFIP, CEA

2226 General Raines Dr., Murfreesboro, TN 37129 615-849-6400 Maryjo6400@aol.com

SUMMARY OF QUALIFICATIONS

- Certified Appraiser with P.L.A.N. (Property Loss Appraisal Network)
- Citizens of Florida Commercial GA Adjuster
- 19 yrs experience Independent Catastrophe Adjuster for various insurance companies with strengths in knowledge of various policies, state guidelines and policy limits.
- 31 yrs experience in the construction industry with outstanding customer service skills and a high level of ethics and professionalism.
- 42 yrs experience in Residential and Commercial Real Estate sales with extensive client communication and service skills, Nashville Metropolitan Area
- Enthusiastic team player/builder, outstanding communicator and negotiator, one-on-one and groups, written and oral.
- Creative problem solving: maximizing resources and time management.
- Computer skills in Xactimate, Simsol and MS Office products, including paperless file transfer protocols & wireless communication systems.
- State adjuster licenses: Florida, Texas, Louisiana & Georgia
- California Earthquake Accreditation (CEA) Certified.
- National Flood Insurance Program (NFIP) Certified large commercial, dwelling, mobile home, small commercial
- National Incident Management Systems (NIMS) and Incident Command System (ICS) training.
- E-RAILSAFE approved (certification to drive in rail yards)

PROFESSIONAL EXPERIENCE

- 4 yrs experience as Senior Adjuster & Appraiser representing various carriers:
 Allstate, Encompass, and Esurance.
- Court appointed and/or selected umpire on numerous commercial & residential disputed claims throughtout Tennessee and surrounding states with awards in excess of \$1.4 million. Invoked as umpire position to settle disputed claims on new auto dealerships, large chain restaurants, multi-unit condominium complexes, large building products retail center, large furniture retail stores, large city owned office & public works buildings, garage maintenance facilities and fire stations.
- Flood catastrophe adjuster, certified since 2007 with 6 yrs flood adjusting experience in the field.
 Adjusted numerous claims in excess of \$1,000,000.00 in various states including TN, TX, LA, GA & MS
- Flood certified for Large commercial, dwelling, mobile home and small commercial claims.
- Evaluated damages, completed estimates, negotiated with policyholders or their contractors and settled claims in a professional manor with minimum or no supervision or file rejection.
- Managed multiple claim assignments, accomplished 1st contacts and set reserves within required time
- Consistently maintained priority of customer service skills along with time management in a highly pressurized, multi-tasking environment under emergency conditions.
- Experience Sinkhole claims settling for Citizens of FL.
- Completed Citizens of FL Large Commercial Desk Adjuster training as a Commercial GA adjuster.
- Experienced in adjusting commercial liability claims involving in-depth investigation of large commercial claims to establish cause or fault as well as bodily injury claims.
- Catastrophic Insurance Adjuster for Hurricanes Charlie, Francis, Jean, Katrina, Wilma, Gustov, Ike. Irene, Sandy, Harvey, Irma, Michael etc., and Tropical Storm Dolly.
- Participated in settling claim assignments as an appraiser as well as selected as an umpire on various claims.
- Catastrophic Insurance Adjuster for Hurricanes, Hail, and Tornado events in TX, IN, KY, TN, MN, MO, FL, KS, NC, VA, NJ, LA, IA MS and Flood events in TN, MS, LA, TX, FL and IL.

Liability Claims Adjuster (Personal Injury, Commercial, Residential & Automotive)

CONSTRUCTION & REAL ESTATE

- Shared responsibility in floor plan selections and design with architectural changes, to setting and maintaining
 the construction budgets, overseeing the construction process and accomplishing the goal of higher profitability
 for the contracts.
- Assisted contractors with the overseeing of all phases of the building process while developing a working knowledge of residential construction.
- Managed multiple listings for sellers and builders/contractors while assisting multiple buyers in the selection, negotiation, loan qualification and closing process of all real estate transactions.
- Accomplished multi-million dollar sales awards several years in a row. Customer service as the main focus, with high ethical standards, professionalism and self-motivation attributing key factors.

HISTORY

2003 - Present

Adjusted for various independent adjusting companies since 2003 including, but not limited to, Worley Co., EA Renfroe, Eberls, Pacesetter Claims, Team One, Bradley Stinson & Assoc., NCA, Administrative Strategies, Colonial Claims, RJMW & CIS Specialty Claims.

1976 - 2018

Key Concepts Real Estate 2017 - Present Bob Parks Realty, Murfreesboro, TN 2013 - 2017 Encore Real Estate Assoc. 2007 - 2010 Prudential - Rowland Real Estate 1999 - 2007 Bob Parks Realty, Murfreesboro, TN 1997 - 1999 Crye-Leike Realty, Murfreesboro, TN 1995 - 1997 Prudential Real Estate Assoc. 1987 - 1995 Mayes Real Estate 1979 - 1987 **General Contractor** 1976 - 1989

EDUCATION & TRAINING

Certificate of Completion — Citizens of Florida Commercial DA Training Program (as a Commercial GA Adjuster)
Certificate, Flood Certified, (NFIP) Large Commercial, Dwelling, Mobil Home & Small Commercial
Certificate, Property Damage Course, Epps Insurance Training Program, Dallas, TX
Certificate, Earthquake Accreditation
Donan Engineering Roof Systems Course
Certificate, Insurance License for the State of Tennessee
Certificate, Auto Adjusting - Allstate
Certification of Completion - Adjusting Auto Flood & Hail Losses training
Certificate of Completion - Allstate Auto Adjusting Certification
Business Education, Middle Tennessee State University

ADJUSTING LICENSE & CERTIFICATION

NFIP Certified FCN#05080114 (Including LG Commercial) CEA California Earthquake Certified Florida state adjusters License #E141507 Texas state adjusters License #1263631 Georgia state adjusters License #3335254

Real Estate Fundamentals & Law, University of Tennessee

Louisiana State Adjusters License #522698 Allstate Auto Adjusting Certification Tennessee Real Estate Affiliate Broker License Tennessee Insurance License

Tower Hill (wind & flood) (dwelling & commercial)

Nationwide (Wind, Hail & Flood)

Citizens Of Florida

Shelter

SPECIFIC INSURANCE ADJUSTING EXPERIENCE &/or CERTIFICATIONS

State Farm
USAA
Alistate (Property & Auto)
Citizens of Florida (GA Commercial & Property)
St Paul Travelers
USF&G
QBE & QBE 1st

St Paul Travelers
USF&G
USF&G
QBE & QBE 1st
Liberty Mutual – LMAC (Core Adj.)

Safeco
Farm Bureau
American Family
Guard Insurance (Commercial property loss claims)

NFIP Direct & various flood carriers & WYO co.'s Farmer's (Fire Ins. Exchange) Flood Consumers Insurance Co. & Continental Western Ins. Co. (commercial liability and auto liability claims)



319 Vann Drive E214

Jackson, TN. 38305 PH: 731-787-7082 FX: 888-400-5523

www.afconstruction.net

CHRISTOPHER WILLIAMSON TN LIC

GC Limit: \$1.5M / Umpire / Appraiser

REFERENCES:

Commercial:

- 1. Airways Motel, 576 Airways Blvd, Jackson, TN.- 731-424-3030
- 2. Bartlett City Hall, 6400 Stage Road, Bartlett, TN Frank Madlinger 901-820-0820
- 3. Baymont Inn, 465 Vann Drive, Jackson, TN. 731-661-9995, Metal Roof 5 yr warranty. Alex Bhakta 731-293-9674
- 4. Optimist Club, 95 Hayes Branch Trail, Jackson, TN BJ Construction 731-225-3978
- 5. Cat West, 14196 Ft. Campbell, Oak Grove, KY -270-439-0823 Wayne Baldwin -931-378-3775
- 6. Country Hearth Inn, 2009 W. Reelfoot, Union City, TN.- Raj Patel, 731-885-7774
- 7. Days Inn of Dyersburg, 2600 Lake Road, Dyersburg, TN- V. Patel 731-287-0888
- 8. Deerfield Inn, 414 E. Main St. Adamsville, TN. Owner Prakash Patel 731-632-2100
- Denmark Community Center, 533 Denmark Jackson Rd, Denmark, TN.- Floyd Golden 731-217-7995
- 10. Econolodge, 732 W. Church St, Lexington, TN. 731-968-017- Bob Patel, 731-394-0908
- 11. Guest House Inn, 1890 Hwy 45 Bypass, Jackson, TN, 731-664-4312
- 12. Hot Spot, 1291 N. Highland, Jackson, TN.- Al 731-444-4052
- 13. Knights Inn of Paris, 409 Tyson Avenue, Paris, TN.- Ashok Patel 731-642-1822
- 14. Knights Inn, 21305 Hwy 22 North, Parkers Crossroads, TN. Sam Patel, 731-307-7576
- 15. Magnolia Landing, 100 Magnolia Landing Court, Jackson, TN Chiquita Perry 731-427-6995
- Moore's Chapel Baptist Church, 10 Napoleon Luther Drive, Milan, TN.-Sarah Smith 731-613-2384
- 17. Park Place Apartments, 100 Boardwalk Cove, Jackson, TN.-Keesha 731-265-0900
- 18. Park Ridge Apartments, 100 Park Ridge Drive, Jackson, TN.-Keesha 731-265-0900
- 19. Park Trace Apartments, 100 Parkwood Trace, Jackson, TN.-Tina 731-421-2710
- 20. Scottish Inn, 15947 Hwy 13 South, Hurricane Mills, TN.-Mr. Patel 731-968-5235
- 21. Wreck-O-Mended, 1150 Egg Hill Rd, Alamo, TN-731-487-2282
- 22. Days Inn, 13845 Hwy 641 North, Holladay, TN 38341 Jay Patel 731-438-2226.
- 23. Raleigh Assembly of God -Memphis, TN -Pastor Allan -901-386-5055.
- 24. Edward D. Jones David Byrum 423-506-4622 Humboldt, Tennessee

*** Ceritied Installer in all types of roofing systems.



DAVID W. HILSDON, P.E. 7975 SODERLUND DRIVE MILLINGTON, TN 38053

CONSULTING ENGINEER (901) 485-1071 Vox & Txt davidwhilsdonpe@gmail.com

SCHEDULE OF PROFESSIONAL SERVICE FEES AS EXPERT WITNESS

Effective Date: July 3, 2022

Re: Professional Engineer Expert Forensic Witness - retainer, case investigation,

evaluation, preparation, deposition, mediation, arbitration & court

appearance/testimony, travel, expenses, etc.

Non-Refundable Initial Commencement Retainer Fees for case file creation, preparation, correspondence, review & initial research:

Fixed Fee Non-Refundable Litigation Commencement Retainer of \$1,250.00.

Fees for case preparation, correspondence, review, research and travel Beyond initial non-refundable Commencement Retainer:

Time (per tenth of hour

STAFF:

Principal Engineer (P.E.)	\$225/hour*
Senior Engineer (P.E.)	\$210/hour*
Junior Engineer (P.E.)	\$180/hour*
Engineer Intern (E.I.)	\$165/hour*
Forensic Technician	\$100/hour*
Administration	\$ 65/hour*

^{*}Minimum Trip Fee / Staff member \$1,000/Day

OUTSOURCED SERVICES:

Technical Consultants	Cost plus 15%
Third Party Services	Cost plus 15%

Fees for Depositions & Court Appearances:

1/2 Day - (8:00 until 12:00 Noon or fraction thereof) @ \$1,000 minimum per 1/2 Day. Plus Expenses.

Full Day - (8:00 A.M. past Noon until 5:00 P.M. or fraction thereof) @ \$1,450 minimum per Full Day, continuing after 5:00 PM at \$225 per hour rate. Plus Expenses.

Expenses:

- a. Travel @ \$0.65/Mile (Auto)
- b. Travel @ cost plus 25% (Airline, Public)
- c. Tolls & Parking @ cost plus 25%
- b. Room & Meals @ cost plus 25%
- c. Postage & Envelope @ cost plus 25%
- d. Scan Docs to file (pdf format) & Email: 24" x 36" @ \$10.00/sheet; 8.5" x 11" @ \$0.50/sheet
- e. Reproduction, copies, prints: 24"x 36" @ \$15.00/sheet; 8.5"x11" B&W @\$0.25/sheet 8.5" x 11" Color @ \$0.75/sheet
- f. Vehicle, Equipment, tool rental @ cost plus 25%
- g. Outsourced Services cost plus 15%

*** END ***

HEIDELBERG & MULLENS, INC

INSURANCE CLAIMS CONSULTING, APPRAISAL, & UMPIRE SERVICES

William Scott Heidelberg, President

PH: 731.225.4187



Background

Mr, Heidelberg has a long history in residential and commercial general construction. He has lengthy experience in construction techniques and materials, having been self-employed in the industry since 1991. Mr. Heidelberg started in the construction industry as a framing employee for a residential development company in 1989 and continued form his own construction company in 1991, in which he performed as a sub-contractor and general contractor for twenty years.

Mr. Heidelberg has been a licensed independent insurance adjuster since 2005 and has adjusted thousands of claims that range from simple residential to extremely complex commercial and industrial claims. He has been an advocate for both the insurer as an IA and an advocate for the insured as a restoration contractor.

Mr. Heidelberg has been trained in applied electricity, heating, ventilating and air conditioning, as well as plumbing by a major mechanical contractor and held a related position for more than five years. He is knowledgeable in codes for building and mechanical trades.

Mr. Heidelberg currently performing inspections, documentation, and analysis of peril related damage, maintenance related damage, building envelope related failures and damage including roofs, cladding, windows, doors and water proofing systems. He is currently accepting assignments as appraiser for insurers and insureds in simple and complex disputes. He is currently accepting appointments as umpire in simple and complex appraisals. He is experienced in premises liability evaluation and surveys pertaining to insurance underwriting. These inspections encompass residential, commercial, industrial, civic, religious, hospitality, and multifamily residential building types.

Professional Construction Experience

Mid-South Services. Inc, Jackson, Tennessee 2007-2010

- Operating Partner
- Specializing in renovations of residential dwelling and insurance restoration construction.
- Wind, Water and Fire Mitigation and Restoration.
- Exterior and Interior.

Sales

Jackson Construction, Jackson, Tennessee 1994-2007

- General construction duties including framing and finishing carpentry, tile installation, plumbing, HVAC and electrical.
- New Luxury Dwelling Construction Project Management
- Cantilever Construction on Steep Grades
- Multi-Family Dwelling Construction
- Planning and Design of Developments
- Large-Scale and Small-Scale Commercial Restaurant and Bar Renovation
- Restaurant and Bar Design and Layout
- Commercial Restroom Construction
- Commercial Assembly Place Building Codes Specialist

Restoration Specialists, Inc, Jackson, Tennessee 1998 – 2004

- Owner/operator.
- Specializing in renovations of residential dwelling and insurance restoration construction.
- Wind, Water and Fire Mitigation and Restoration

McIntosh Development 1989 – 1991

• General construction duties including framing and finishing carpentry

S.M. Lawrence Company, Inc Mechanical Contractors 1986-1991

- Residential HVAC, electrical, and plumbing. Installation of residential HVAC systems.
- Commercial HVAC, electrical and plumbing, including zone systems
- · Commercial design and installation of HVAC systems
- Industrial design, installation and maintenance of HVAC systems and controls systems, including heavy load industrial chiller systems, variable air volume systems and pneumatic control systems.
- Troubleshooting, electrical and HVAC systems and diagnostics of performance.
- Residential, Commercial and Industrial Air Balancing
- Troubleshooting, electrical and HVAC systems and diagnostics of performance.
- Residential, Commercial and Industrial Air Balancing
- Certified by American Standard, Trane and Carrier as an installer and technician.
- Memphis State University in Co-op program with SML Inc. (Mechanical Engineering)

Professional Insurance Claims Experience

Licensed Independent Insurance Adjuster 2005 - Present

 Kentucky, Indiana, Arkansas, Oklahoma, Texas, Louisiana, Mississippi, Alabama, Florida, Georgia, South Carolina, North Carolina, and Connecticut.

- Eligible in any state.
- Thousands of successfully closed claims including residential property, commercial property, industrial, liability, retail liability, marine, total loss fire and water related, total loss commercial losses, bio-hazard losses.
- Hundreds of successfully closed large loss residential and commercial claims including shopping centers, churches and industrial/warehousing buildings. Several claims in excess of \$2,000,000.00 loss.
- Participation as an independent insurance adjuster in every major tropical event since 2005 in the US, as well as most wind and hail events during this time. Participation in wildfire catastrophe as well.
- Trainer

Professional Alternative Dispute Resolution Experience

- Appraiser, Carrier and insured appointed, 2012 2021
- 500+ appointments by insurers, 100+ appointments by insureds.
- Umpire, 2015 2021
- Years of experience successfully settling claims in litigation for insurers.
- Years of experience in working on behalf of insurance carriers, with attorneys, public adjusters, and forensic engineers to find fair and honest settlements for my clients.
- Years of ADR carrier training
- Fair, ethical, and honest professional practices
- Policy knowledge
- Estimating software expertise.
- Trainer

Education and Certifications

- State Farm Certified
- NFIP
- USAA Certified
- TWIA Certified
- IICRC FSRT, WRT
- Licensed General Contractor (retired)
- Memphis State University, Non-traditional student. Mechanical Engineering
- HVAC Trade School
- Jackson State Community College, General Education.